

ASS. REC. BY:

REP:

CS/CTI19006991/Ktd3<sup>52</sup>

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Alfred Toh

of

CTI

Date/Time:

22/4/19 @ 9.42am

Estimated Cost:

Bill to:

TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJU 8820T

Insured:

at Workshop m/s

Cheng Hwe

Tel:

64812001

of

Blk 10 Amk Ind. Park 2A # 01-04

Policy No:

Claim No:

SNM19D201959C01/0

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/4/2019

CA /  REA / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11.21am @ 22/4/19

Person Contacted:

Jinglyn

Vehicle:

IN  OUT

Date/Time

Action/Instruction (✓) Estimate

23/4 @ 14:10 App mandate request: recommend total loss

Submit extensive total loss report.

ASS. REC. BY:

REF: C12 / CS1071 1900 6991 / ktd3

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop n/s \_\_\_\_\_ Cheng Hoe

of \_\_\_\_\_ Amk

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|                                     |                                     |
|-------------------------------------|-------------------------------------|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| N/S                                 | O/S                                 |
| <input type="checkbox"/>            | <input type="checkbox"/>            |

Bal. or Market Value: 818k 50k

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: STU 8820 T Yr Regn: 10, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or A) Wagon

Make: Toy Picnic c.c. 1998

Colour: Ch. Red A/C: Insured / Std / NI / NA

Sp. Reading: \_\_\_\_\_ T/Radio: Insured / Std / NI / NA

Eng No: \_\_\_\_\_

C/No: JTEG1123B 00 002704

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205 / 60 R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 18/4/19 D.O.I. 22/4/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The veh caught fire, the cause of fire

The UIC / Chassis frame / Body Structure affected due to collision.

Probably due to short circuit at the engine compartment.

Date / Time Action / Instruction

1 File pass to

Market value: 56k

LTN: 812,910/-

NV: 43090

RECEIVED 25 APR 2019

Date/Time, File Pass to?

: Prel. Report

1) 24/4 Typist

: Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

\_\_\_\_\_ \$ + RS. \_\_\_\_\_ \$

\_\_\_\_\_ Pairs

\_\_\_\_\_ Others

TOTAL

Report Format : OD-TL

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

## Nivitha (LKK Auto)

---

**From:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>  
**Sent:** Monday, 22 April 2019 9:42 AM  
**To:** Alvin Sing; \*Cheryl wifEy; chmotor@singnet.com.sg; assignments@lkkauto.com; SUR  
**Cc:** Chee So Chow; Chong Boon Sen; Eddie Sim; Alfred Toh; Alice Ng; ivy.limls@ssgroup.sg; ryan.pohlk@ssgroup.sg; June Phua; Ong Chin Kiat  
**Subject:** RE: DMPCSN3056591800 - SJU8820T PARKED & FOUND DAMAGED BY FIRE (SNM19D201759C01/0)  
**Attachments:** OD CHINA.pdf

Claim Ref: SNM19D201759C01/0

Attn: Sing Chun Siong (Alvin)

Hi Mr Alvin Sing

We refer to your emails pertaining to the above matter.

We shall be appointing M/s LKK Auto Consultants Pte Ltd shall be conducting survey on the damaged vehicle.

***Aside to M/s LKK Auto Consultants Pte Ltd, please assist to arrange for the survey.***

Aside to M/s Cheng Hoe Motor Pte Ltd., please assist to upload the estimates in Merimen.

*Aside to Boon Sen/Chin Kiat, please assist to follow up on the matter.*

**Best Regards**

**Alfred Toh**  
Senior Executive  
Claims Department  
China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road #XX-00 Springleaf Tower Singapore 079909  
DID : (65) 6389 6183  
FAX: (65) 6224 7478

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** Alvin Sing [mailto:alvinsing81@gmail.com]  
**Sent:** Sunday, 21 April, 2019 9:40 PM  
**To:** Alice Ng <alice.ng@sg.cntaiping.com>  
**Cc:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; \*Cheryl wifEy <cherylcjf@gmail.com>  
**Subject:** Re: DMPCSN3056591800

Resending attachment again.

On Sun, 21 Apr 2019, 21:33 Alvin Sing, <alvinsing81@gmail.com> wrote:

Dear all

I have visited the appointed workshop on Sat, 20 Apr 19, and have lodged my claim (see attached).

I suppose China Taiping would have received a copy of my claim and would have started processing it.

As this incident has created a lot of inconvenience to me and my family (which includes my now 6 months pregnant wife) on our daily routine, we would like to appeal to China Taiping to expedite this claim and provide us a satisfactory conclusion/resolution.

We would also appreciate it if there could be someone from China Taiping who could reach out to us to advise us more on the claim process, the timeline to expect, compensation liable and also if there could be alternate transport arrangement that would be offered. It is extremely disheartening that there had been no follow-up call nor formal contact from China Taiping since the incident.

Therefore, i sincerely hoped that this email would allow the insurer to make good its promise which is striving to help your policyholder get back to life as quickly and smoothly as possible following an unfortuante incident.

I hope i would not be disappointed again.

Regards

Sing Chun Siong

 OD CHINA.pdf

On Sat, 20 Apr 2019, 12:21 Alice Ng, <[alice.ng@sg.cntaiping.com](mailto:alice.ng@sg.cntaiping.com)> wrote:

Dear All,

Please assist.

**Alice Ng**

Deputy Manager

Personal Lines Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6145 | F: (65) 6225 3592

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** Chun Siong Sing [mailto:[Alvinsing81@gmail.com](mailto:Alvinsing81@gmail.com)]  
**Sent:** Friday, 19 April, 2019 12:18 AM  
**To:** Personal Dept of China Taiping Insurance <[e-personal@sg.cntaiping.com](mailto:e-personal@sg.cntaiping.com)>  
**Subject:** Have a new submission from contact

## Dear Admin

Have a new submission from user form contact us

Information:

Are you an existing China Taiping Insurance Singapore customer?: Yes

Enter Policy Number: DMPCSN3056591800

First Name: Chun Siong

Last Name (Surname): Sing

Preferred contact method?: Phone

Email: [Alvinsing81@gmail.com](mailto:Alvinsing81@gmail.com)

Phone Number : +65 98411601

Enquiry Type : Claims

Messages: Car caught fire when parked at carpark. SDCF and SPF was notified and fire was put out without further damage to other vehicles. Please advise next course of action immediately. Tks!

Thanks

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## Denise Tay (LKKAuto)

---

**From:** Alfred Toh <alfred.toh@sg.cntaiping.com>  
**Sent:** Wednesday, 24 April 2019 2:07 PM  
**To:** assignments; SUR  
**Cc:** Alfred Toh; Ong Chin Kiat; Eddie Sim  
**Subject:** CTL CLAIM - SJU8820T (SNM19D201759C01/0)  
**Attachments:** 20190424140457.pdf

Dear Sirs

Understand that there is a renewal of COE on SJU8820T.

Please assist to check the market value with renewal of COE.

**Best Regards**

**Alfred Toh**  
**Senior Executive**  
**Claims Department**  
**China Taiping Insurance (Singapore) Pte. Ltd.**  
**3 Anson Road #XX-00 Springleaf Tower Singapore 079909**  
**DID : (65) 6389 6183**  
**FAX: (65) 6224 7478**

**W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG**

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Ong Chin Kiat

Date: 24 Apr 2019

### Preliminary Advice

|                    |  |                         |                    |
|--------------------|--|-------------------------|--------------------|
| Vehicle No         | : SJU8820T   | Accident Date           | : 18/04/2019       |
| Make               | : TOYOTA PICNIC  | Policy No.              | : DMPCSN3056591800 |
| Assignment Date    | : 22/04/2019   | Excess                  | : S\$750.00        |
| Date of Inspection | : 22/04/2019   | Est. Duration of Repair | : 0.00             |
| Inspection At      | : CHENG HOE MOTOR PTE LTD (YISHUN)<br>BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A<br>SINGAPORE 768761 |                         |                    |

#### Point of Impact / General Description of Damages

The vehicle sustained impact / damages ..... portion and parts claimed are consistent to the accident.

|                             |      |            |
|-----------------------------|------|------------|
| Repairer's Estimate (Gross) | :S\$ | TOTAL LOSS |
| Revised Amount              | :S\$ | TOTAL LOSS |
| Check Items (Estimated)     | :S\$ | 0.00       |
| Total                       | :S\$ | 0.00       |
| Lump Sum Repair             | :S\$ |            |

#### **Total Loss Consideration**

|                    |      |           |
|--------------------|------|-----------|
| New for Old Value  | :S\$ |           |
| Pre-Accident Value | :S\$ | 56,000.00 |
| COE / PARF Rebate  | :S\$ | 12,910.00 |
| Salvage Value      | :S\$ |           |
| Margin for Repair  | :S\$ | 5,090.00  |

#### Remarks

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

Address: BLK 342C YISHUN RING RD #13-852B  
 Postcode: 783342  
 Was driver an employee of the Insured's Company: NO  
 If No, Relationship of the Driver with the Insured: DRIVER  
 Vehicle Registration Number of Driver's Own Vehicle: -  
 Insurance Company of Driver's Own Vehicle: -

General Information of the Accident  
 Type of Accident: FIRE, EXPLOSION OR LIGHTNING  
 Weather Conditions: SHELTERED  
 Road Surface: DRY

Other Information  
 Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident: 1  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? NO  
 Have you been approached by relevant personnel (including accident claims assistance)? NO  
 Number of Passengers (including Driver): 0

Details of Police Station  
 Was the accident reported to the police? YES  
 If Yes, Please state which Police Station: WOODLANDS NPC  
 Police Station Name: ROAD: 3 WOODLANDS DRIVE 05, POSTCODE: 737680, COUNTRY: SINGAPORE  
 Police Station Address: TEL NO. - FAX NO:  
 Police Station Contact: NO  
 Was notice of standard Prosecution given? NO  
 If Yes, against whom?

Circumstances of Accident  
 REFER TO POLICE REPORT ATTACHED.  
 Attachments:  
 Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recording? NO

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to assist in the claims process.
2. This Form must be completed by the Driver/Insured, and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any false representation or misreading of material facts may allow the insurer to rescind the policy.
4. The Insured and representative of the Insured (wherever applicable) is not an admission of policy liability on the part of the insurance company.
5. Any false or misleadingly be submitted to the Police for investigation.
6. This report will be forwarded by the Insured to the Police for investigation.
7. By the completion of this report to the Insurer, you hereby consent to the archiving of this report in the event and its copies of this report being made available at any time.

ACCIDENT STATEMENT

Date of Report: 20/04/2019 10:46  
 Date of Accident: 18/04/2019 22:56  
 Exact Location Of Accident: BLK 342C YISHUN RING RD BASEMENT CAR PARK  
 Country/State of Loss: SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number: SUJ8920T  
 Insured/Policyholder: SING CHUN SONG(SHEN JUNHONG)  
 Name Of Registered Owner: SING CHUN SONG(SHEN JUNHONG)  
 NRIC No: SA108774J  
 Email Address: ALVINSING81@GMAIL.COM  
 Mobile Phone No: (LOCAL) +65-99411601  
 Alternative Phone No: OTHER: 99411601

Vehicle Particulars

Manufacturer: TOYOTA  
 Model: PICNIC-2.8 W/D ROOF RACK (A)  
 Exact Purpose for which vehicle was being used at time of accident: PARKED  
 Are you claiming under your own insurance policy for repair to your vehicle? YES  
 If No, Please state action to be taken:

Insurance Company

Vehicle Category: PRIVATE CAR  
 Name of Insurance Company: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.  
 Type Of Coverage: COMPREHENSIVE  
 Fuel Policy: NO  
 Policy Number: DMPCSK3056591800  
 Cover Note Number:

Driver

Name of Driver: SING CHUN SONG(SHEN JUNHONG)  
 NRIC No: SA108774J  
 Date Of Birth: 04/03/1981  
 Occupation: INDOOR  
 Date Of Driving Pass: 16/04/2006  
 Driving Experience: 13 YEARS AND 0 MONTHS  
 Gender: MALE  
 Mobile Number: (LOCAL) +65-96411001  
 Fax Number:  
 Contact Number:  
 Email Address: ALVINSING81@GMAIL.COM

**SKETCH PLAN**

VEHICLE NO.: SJU 8820T  
INSURER : China  
DATE & TIME: 18/04/19 @ 22:50hrs

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

 20/4/19  
Reporting Centre Personnel's Signature  
Name: (YS)  
NRIC/FIN No.:

SKETCH PLAN

BIK 342C Yishun  
 Ring Rd Basement  
 Car Park

SUBJECT (parked, caught fire)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to On-line Police Report No: L/20190420/7003

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature: Date & Time: \_\_\_\_\_  
 Driver's Signature: \_\_\_\_\_ (If driver is not the policyholder) Date & Time: \_\_\_\_\_  
 Reporting Centre Personnel's Signature: Name: (KS) NRIC/FIN No.: \_\_\_\_\_

Claim Own Policy   
  Claim Third Party   
  Reporting Only  
 Claim OD/TP at other workshop ( \_\_\_\_\_ )


**SINGAPORE  
POLICE FORCE**


L/20190420/7003

1 of 2

**POLICE REPORT (NP299)**

Report No. L/20190420/7003

Police Station Of Origin  
Woodlands Division HQ  
1 Woodlands Street 12 SINGAPORE 738622  
Tel No:1800-4660000

|  |  |                     |
|--|--|---------------------|
| Date/Time Report Made<br>20/04/2019 10:41                    | Vide Report No.  | Station Diary No.   |
| Name Of Informant<br>SING CHUN SIONG                         | Address<br>APT BLK 342C YISHUN RING ROAD #13-1938<br>SINGAPORE 763342              |                     |
| ID Type / ID No.<br>NRIC NO / S8106774J                      | Contact No.<br>Home/Office:  | Mobile:<br>98411601 |
| Nationality<br>SINGAPORE CITIZEN                             | Email Address<br>alvlsing81@gmail.com  |                     |
| Occupation<br>Administration manager                         | Sex<br>Male  | Age<br>38           |
| Institution/School Name                                      | Date of Birth<br>04/03/1981  | Race<br>Chinese     |
| Date/Time Of Incident<br>18/04/2019 22:50 - 19/04/2019 00:00 | Location Of Incident<br>APT BLK 342C YISHUN RING ROAD #13-1938<br>SINGAPORE 763342 |                     |

**Brief details.**

Was alerted that my car caught fire when parked at my carpark by the police. When I arrived to the scene, police and scdf were already keeping the fire under control and there were no damages to other cars. Police informed that they were alerted by a member of public around 1050 after seeing smoke and fire from my car Bannnoet. I have also provided my statement to the police and have informed that I did not offend anyone. I also confirmed that my car was serviced on 28 March 19 and car is in good condition. As part of the claim process, my insurer has asked for a police report, L/20190418/0206.

|  |  |
|--|--|
| Signature Of Officer Recording The Report:<br>Not applicable | Signature Of Informant:<br>The identity of the person making this report has been authenticated by SingPass. No signature is required. |
| Signature Of Interpreter:<br>Not applicable                  | Date/Time:<br>20/04/2019 10:41   |
| Officer In-Charge Of Case:                                   | Classification Of Case:  |

Authentication Stamp



**SINGAPORE  
POLICE FORCE**



L/20190420/7003

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. L/20190420/7003

Please assist with the report urgently.

| Subjects Involved         |   |              |           |
|---------------------------|---|--------------|-----------|
| Victim                    |   |              |           |
| Person Name               | SING CHUN SIONG   |              |           |
| ID Type                   | NRIC NO   | ID No        | S8106774J |
| Gender                    | Male  | Age          | 38        |
| Race                      | Chinese   | Language     | English   |
| Occupation                | Administration manager  | Address Type |           |
| Address                   | APT BLK 342C YISHUN RING<br>ROAD #13-1938 SINGAPORE<br>763342 | Mobile No    | 98411601  |
| Is Informant A<br>Victim? | Yes   |              |           |
| Person Name               | SING CHUN SIONG (Informant)                                   |              |           |

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In-Charge Of Case:

Signature Of Informant:  
The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:  
20/04/2019 10:41

Classification Of Case:

Authentication Stamp

> Back to OneMotoring

**Enquire PARF/COE Rebate for Registered Vehicle**


| <b>Vehicle Owner Particulars</b>    |                           |
|-------------------------------------|---------------------------|
| Owner ID Type:                      | Singapore NRIC            |
| Owner ID:                           | 6774J                     |
| <b>Vehicle Details</b>              |                           |
| Vehicle No.:                        | SJU8820T                  |
| Vehicle to be Exported:             | No                        |
| Intended Deregistration Date:       | 20 Apr 2019               |
| Vehicle Make:                       | TOYOTA                    |
| Vehicle Model:                      | PICNIC AUTO W/O ROOF RACK |
| Primary Colour:                     | Red                       |
| Manufacturing Year:                 | 2009                      |
| Engine No.:                         | 1AZH376271                |
| Chassis No.:                        | JTEGH23B000027047         |
| Maximum Power Output:               | 110.0 kW (147 bhp)        |
| Open Market Value:                  | \$24,216.00               |
| Original Registration Date:         | 19 Oct 2009               |
| First Registration Date:            | 19 Oct 2009               |
| Transfer Count:                     | 2                         |
| Actual ARF Paid:                    | \$24,216.00               |
| <b>Intended PARF Rebate Details</b> |                           |
| PARF Eligibility:                   | Yes                       |
| PARF Eligibility Expiry Date:       | 18 Oct 2019               |
| PARF Rebate Amount:                 | \$12,108.00               |
| <b>Intended COE Rebate Details</b>  |                           |
| COE Expiry Date:                    | 30 Apr 2029               |
| COE Category:                       | E - Open Category         |
| COE Period(Years):                  | 10                        |
| PQP Paid:                           | \$35,411.00               |
| COE Rebate Amount:                  | \$802.00                  |
| <b>Total Rebate Amount:</b>         | <b>\$12,910.00</b>        |

The information contained herein is correct as at 20 Apr 2019

OK

Repairer Estimates

Page 1 of 2

**CHENG HOE MOTOR PTE LTD**

Bik 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761  
Tel : 67556142 Fax : 67557719  
Email: chmotor@singnet.com.sg

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

|                     |                               |                       |             |
|---------------------|-------------------------------|-----------------------|-------------|
| Claim Type:         | OD (OWN DAMAGE)               | Ref. No:              | OD-CHINA    |
| Policy No:          | DMPCSN3056591800              | Date of Loss:         | 18/04/2019  |
| Vehicle Reg. No.:   | SJU8820T                      | Driveable?            |             |
| Driver Age/Info:    | 38 / MALE                     | Party At Fault:       | UNKNOWN     |
| TP Injury Involved? | NO                            | Third Party Involved? | NO          |
| Insured/Claimant:   | SING CHUN SIONG(SHEN JUNHONG) | Contact No:           | +6598411601 |
| Driver:             | SING CHUN SIONG(SHEN JUNHONG) |                       |             |

|                 |                                      |                    |                   |
|-----------------|--------------------------------------|--------------------|-------------------|
| Make/Model:     | TOYOTA PICNIC, 2.0 W/O ROOF RACK (A) | Vehicle Reg. Date: | 19/10/2009        |
| Vehicle Colour: | RED                                  |                    |                   |
| Engine No:      | 1AZH376271                           | Chassis No:        | JTEGH23B000027047 |
| Odometer:       | 0 KM                                 |                    |                   |

Paint Type:  
Total Loss? **YES**  
Est. Duration of Repair (day) 0

*Not Washed*  
*Loss*

Description of Accident/Loss: REFER TO POLICE REPORT ATTACHED.

Remarks: VEHICLE LAYING AT AMK

Present Location: CHENG HOE MOTOR PTE LTD (ANG MO KIO)

| LKK Auto Consultants hence notify the Repairer of the following: |   | Amount       |
|--|---|--------------|
| <b>COST OF CLAIMS</b>  |   |              |
| Parts  | • To resurvey before/after spray painting<br>• To display damaged part(s) during resurvey<br>• Parts prices are subject to confirmation | 0.00         |
| Miscellaneous Items  | • Third party survey is on a "Without Prejudice" basis  | 0.00         |
| Labour   | • No illegal modification(s) is allowed   | 50.00        |
| Paintwork Labour   | • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company                                      | 0.00         |
| Towing   |   | 0.00         |
| Acknowledged by Repairer   |   |              |
| Signature:   | <b>Gross Total (\$\$)</b>   | <b>50.00</b> |
| Date:  | <b>+ GST 7.00% (\$\$)</b>   | <b>3.50</b>  |
| <b>Nett Amount (\$\$)</b>  |   | <b>53.50</b> |

This claim is handled by: NG CHENG CHOO

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

## Repairer Estimates

Page 2 of 2

**REPAIR DETAILS**

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Apr 2019)

Parts: M1-MPV TOYOTA PICNIC 2.0 W/O ROOF RACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/SJU8820T/22/04/2019 11:49

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*

## Estimates on Parts

There are no new parts selected.

Cheng Hoe Motor Pte Ltd/SJU8820T/22/04/2019 11:49. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

| No                       | Particulars             | Lab.Type | Amount |
|--------------------------|-------------------------|----------|--------|
| <b>Labour Items</b>      |                         |          |        |
| 1                        | To towing (Bill attach) | New      | 50.00  |
|                          |                         |          | 50.00  |
| Gross Labour Cost (\$\$) |                         |          | 50.00  |

Cheng Hoe Motor Pte Ltd/SJU8820T/22/04/2019 11:49. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

張建福 (機件) 拖車服務  
TEO KIAN HOCK (CHEE CHEN) TOWING SERVICES

Mailing Address: 40 Cactus Road, Singapore 809597

Tel: 6858 4067 Fax: 6854 0407

廿四小時服務 24 HOURS SERVICE

Reg. No. 413736/00L

CASH SALE WORK ORDER

No. 6022

Date: 20/04/2019

賣號

Messrs: 清河

車號

Vehicle No: S3U 8820T

車型

Model No:

由

From: 342c fishun

到

To: Rank

時間 (日/夜)

Time (day/night):

其他

Others: Acc m/c P

CASH \$: 50

CHEQUE:

經手人

Authorised by: [Signature]

收貨人

Received by:

注意: 本公司對所托之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

| Case | Notified                                    | Est Submitted                           | Adj Assigned   | Adj Rpt  | Adj Submitted                              | Ins Auth'ed | Status  |
|------|---|---|--|--|--|-------------|---|
| Main | 22 Apr 2019<br><a href="#">Sendback Est</a> | 22 Apr 2019<br>11:49<br><b>S\$50.00</b> | 22 Apr 2019<br>15:22<br><a href="#">Edit Adj Rpt</a> | <b>S\$0.00</b><br><a href="#">Edit Estimates</a> | <b>S\$0.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

|                   |  |                        |   |
|-------------------|--|------------------------|---|
| Insured:          | <b>SING CHUN SIONG(SHEN JUNHONG)</b> , ID: S8106774J, Tel: +6598411601, Email: alvinsing81@gmail.com                           |                        |   |
| Vehicle Reg. No.: | <b>SJU8820T</b>  | Date of Loss:          | 18/04/2019 22:00 - :59<br>[113 Months and 30 Days From LTA Reg Date (Man Yr)] |
| Claim Type:       | <b>OD / SNM19D201759</b>   | Policy/Cover Note No.: | DMPCSN3056591800 (Comprehensive)  |
|                   |  | Excess:                | S\$750.00   |
| Repairer:         | <b>Cheng Hoe Motor Pte Ltd (Yishun)</b> Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142         |                        |   |
| Handling Insurer: | <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Ong Chin Kiat</b> ]              |                        |   |
| Adjuster:         | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 02/05/2019] |                        |   |
| Driver/Custodian: | SING CHUN SIONG(SHEN JUNHONG) (38 / Male) , NRIC: S8106774J, Tel: +6598411601 Email: alvinsing81@gmail.com                     |                        |   |

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- CHINA\_TAIPING (25/04/2019): **Alert - Adj Mandate Approved (S\$0.00) - SJU8820T - Claim Handler: Ong Chin Kiat**
- CHINA\_TAIPING (24/04/2019): **Alert - Adj Mandate Approved (S\$0.00) - SJU8820T - Claim Handler: Ong Chin Kiat**

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |



## Claim Documents

SJU8820T (SNM19D201759)

OD

Apr 18 2019 10:00PM

[SING CHUN SIONG(SHEN JUNHONG)]

Cheng Hoe Motor Pte Ltd

Upload Documents   Upload Photos   Compose New Letter

View View in Browser ▾

| Assessment Reports |                |                                   | 1 per page ▾ | <input checked="" type="checkbox"/> |
|--------------------|----------------|-----------------------------------|--------------|-------------------------------------|
| No                 | Finalized On   | Cheng Hoe Motor Pte Ltd (Yishun)  | Thumbnail    | Print                               |
| 1                  | 20/04/19 15:03 | <b>Accident Statement</b>         | Load HTM     |                                     |
| 2                  | 22/04/19 11:49 | <b>Repairer Estimates</b>         | Load HTM     |                                     |
| No                 | Finalized On   | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail    | Print                               |
| 1                  | 23/04/19 14:09 | <b>Adjuster Immediate Advice</b>  | Load HTM     |                                     |
| 2                  | 24/04/19 14:39 | <b>Adjuster Immediate Advice</b>  | Load HTM     |                                     |

| Photos/Images |                 |   | 3 per page ▾                                 | <input checked="" type="checkbox"/> |
|---------------|-----------------|---|--|-------------------------------------|
| No            | Finalized On    | Cheng Hoe Motor Pte Ltd (Yishun)                            | Thumbnail                                    | Print                               |
| 1             | 20/04/19 14:56  | <b>Accident Photo</b><br>[Linked Accident Report Documents] | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 2             | 20/04/19 14:56  | <b>Accident Photo</b><br>[Linked Accident Report Documents] | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 3             | 20/04/19 14:56  | <b>Accident Photo</b><br>[Linked Accident Report Documents] | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 4             | 20/04/19 14:56  | <b>Accident Photo</b><br>[Linked Accident Report Documents] | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 5             | 20/04/19 14:56  | <b>Accident Photo</b><br>[Linked Accident Report Documents] | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 6             | 20/04/19 14:56  | <b>Accident Photo</b><br>[Linked Accident Report Documents] | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 7             | 20/04/19 14:58  | <b>SCENE</b><br>[Linked Accident Report Documents]          | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 8             | 20/04/19 14:58  | <b>SCENE</b><br>[Linked Accident Report Documents]          | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                           | Thumbnail                                    | Print                               |
| 1             | 23/04/19 14:09  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 2             | 23/04/19 14:09  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 3             | 23/04/19 14:09  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 4             | 23/04/19 14:09  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 5             | 23/04/19 14:09  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 6             | 23/04/19 14:09  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 7             | 23/04/19 14:09  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 8             | 23/04/19 14:09  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 9             | 23/04/19 14:09  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 10            | 23/04/19 14:09  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 11            | 23/04/19 14:09  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 12            | 23/04/19 14:09  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 13            | 23/04/19 14:09  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 14            | 23/04/19 14:09  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 15            | 23/04/19 14:09  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 16            | 23/04/19 14:09  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 17            | 23/04/19 14:09  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 18            | 23/04/19 14:09  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |

| Assessment Reports   |                 |   | 1 per page | <input checked="" type="checkbox"/> |
|----------------------|-----------------|---|------------|-------------------------------------|
| No                   | Finalized On    | Cheng Hoe Motor Pte Ltd (Yishun)                            | Thumbnail  | Print                               |
| <b>Documentation</b> |                 |   | 1 per page | <input checked="" type="checkbox"/> |
| No                   | Finalized On    | Cheng Hoe Motor Pte Ltd (Yishun)                            | Thumbnail  | Print                               |
| 1                    | 20/04/19 13:07  | <b>Sketch Plan</b><br>[Linked Accident Report Documents]    | Load JPG   | <input checked="" type="checkbox"/> |
| 2                    | 20/04/19 13:07  | <b>Sketch Plan #2</b><br>[Linked Accident Report Documents] | Load JPG   | <input checked="" type="checkbox"/> |
| 3                    | 20/04/19 13:07  | <b>PR</b><br>[Linked Accident Report Documents]             | Load JPG   | <input checked="" type="checkbox"/> |
| 4                    | 20/04/19 13:07  | <b>PR</b><br>[Linked Accident Report Documents]             | Load JPG   | <input checked="" type="checkbox"/> |
| 5                    | 20/04/19 13:07  | <b>IC &amp; DL</b><br>[Linked Accident Report Documents]    | Load JPG   | <input checked="" type="checkbox"/> |
| No                   | Finalized On    | China Taiping Insurance (Singapore) Pte. Ltd. (HQ)          | Thumbnail  | Print                               |
| 1                    | 22/04/19 15:21  | <b>email to LKK - OD survey assignment</b>                  | Load PDF   |                                     |
| 2                    | 23/04/19 09:26  | <b>MV for SJU8820T - \$58K (STA)</b>                        | Load PDF   |                                     |
| 3                    | 24/04/19 14:30  | <b>LTA REPLY TO INSURED ON RENEWAL OF COE</b>               | Load PDF   |                                     |
| No                   | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                           | Thumbnail  | Print                               |
| 1                    | 25/04/19 15:57  | <b>LTA REBATE</b>   | Load PDF   |                                     |

## Linked Accident Report Documents

| Assessment Reports   |                |                                  | 1 per page | <input checked="" type="checkbox"/> |
|----------------------|----------------|----------------------------------|------------|-------------------------------------|
| No                   | Finalized On   | Cheng Hoe Motor Pte Ltd (Yishun) | Thumbnail  | Print                               |
| 1                    | 20/04/19 15:03 | <b>Accident Statement</b>        | Load HTM   |                                     |
| <b>Photos/Images</b> |                |                                  | 3 per page | <input checked="" type="checkbox"/> |
| No                   | Finalized On   | Cheng Hoe Motor Pte Ltd (Yishun) | Thumbnail  | Print                               |
| 1                    | 20/04/19 14:56 | <b>Accident Photo</b>            | Load JPG   | <input checked="" type="checkbox"/> |
| 2                    | 20/04/19 14:56 | <b>Accident Photo</b>            | Load JPG   | <input checked="" type="checkbox"/> |
| 3                    | 20/04/19 14:56 | <b>Accident Photo</b>            | Load JPG   | <input checked="" type="checkbox"/> |
| 4                    | 20/04/19 14:56 | <b>Accident Photo</b>            | Load JPG   | <input checked="" type="checkbox"/> |
| 5                    | 20/04/19 14:56 | <b>Accident Photo</b>            | Load JPG   | <input checked="" type="checkbox"/> |
| 6                    | 20/04/19 14:56 | <b>Accident Photo</b>            | Load JPG   | <input checked="" type="checkbox"/> |
| 7                    | 20/04/19 14:58 | <b>SCENE</b>                     | Load JPG   | <input checked="" type="checkbox"/> |
| 8                    | 20/04/19 14:58 | <b>SCENE</b>                     | Load JPG   | <input checked="" type="checkbox"/> |
| <b>Documentation</b> |                |                                  | 1 per page | <input checked="" type="checkbox"/> |
| No                   | Finalized On   | Cheng Hoe Motor Pte Ltd (Yishun) | Thumbnail  | Print                               |
| 1                    | 20/04/19 13:07 | <b>Sketch Plan</b>               | Load JPG   | <input checked="" type="checkbox"/> |
| 2                    | 20/04/19 13:07 | <b>Sketch Plan #2</b>            | Load JPG   | <input checked="" type="checkbox"/> |
| 3                    | 20/04/19 13:07 | <b>PR</b>                        | Load JPG   | <input checked="" type="checkbox"/> |
| 4                    | 20/04/19 13:07 | <b>PR</b>                        | Load JPG   | <input checked="" type="checkbox"/> |
| 5                    | 20/04/19 13:07 | <b>IC &amp; DL</b>               | Load JPG   | <input checked="" type="checkbox"/> |

## Documents Checklist

| DOCUMENTS CHECKLIST                          | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. |       |      |       |

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Repairer  Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI19006991/KTD3S2  
**Date:** 25/04/2019

### REFERENCE

Insured/Claimant: SING CHUN SIONG(SHEN JUNHONG) Policy No: DMPCSN3056591800  
Date of Loss: 18/04/2019 Nature of Claim: OD Claim No: SNM19D201759

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJU8820T**  
Make & Model: TOYOTA PICNIC, 2.0 W/O ROOF RACK (A) Engine No: 1AZH376271  
Reg. Date: 19/10/2009 (Man. Year: 2009) Chassis No: JTEGH23B000027047  
Colour: Metallic Red Odometer: 0 km  
Engine Capacity: 1998 cc  
Market Value/New Car Price: S\$56,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16  
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                | Repairer's   | Adjuster's  | Difference   | Diff %        |
|-------------------------------|--------------|-------------|--------------|---------------|
| Parts                         | 0.00         | 0.00        | 0.00         |               |
| Miscellaneous Items           | 0.00         | 0.00        | 0.00         |               |
| Labour                        | 50.00        | 0.00        | 50.00        | 100.00        |
| Paintwork Labour              | 0.00         | 0.00        | 0.00         |               |
| Towing                        | 0.00         | 0.00        | 0.00         |               |
| <b>Gross Total (S\$)</b>      | <b>50.00</b> | <b>0.00</b> | <b>50.00</b> | <b>100.00</b> |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>3.50</b>  | <b>0.00</b> | <b>3.50</b>  | <b>100.00</b> |
| <b>Nett Amount (S\$)</b>      | <b>53.50</b> | <b>0.00</b> | <b>53.50</b> | <b>100.00</b> |

### INSPECTION

Date of Assignment: 22/04/2019 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)  
Date Inspected: 22/04/2019 Inspected At: Cheng Hoe Motor Pte Ltd  
10 ANG MO KIO IND PARK 2A  
#01-04 ANG MO KIO AUTOPOINT  
SINGAPORE 568047  
Estimated Period of Repair: 0.0 days

**Adjuster:** KENNETH KONG

**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

**TOTAL LOSS ASPECT**

|                            |             |
|----------------------------|-------------|
| Market Value :             | \$56,000.00 |
| OMV :                      | \$24,216.00 |
| PARF Rebate (1) :          | \$12,108.00 |
| Quota Premium Paid :       | \$35,411.00 |
| COE Rebate (2) :           | \$802.00    |
| Total Rebate (1) + (2) = : | \$12,910.00 |

The total amount incurred will be Market Value \$56,000.00 minus Total Rebate \$12,910.00 = \$43,090.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 25 Apr 2019)

**Parts:**      M1-MPV      TOYOTA PICNIC 2.0 W/O ROOF RACK (A) (Catalogue:Merimen Singapore 1.0)

**Labour:**      Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SJU8820T)

**Validity:**      These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars              | Lab.Type | Repairer's   | Amount      |
|--------------------------------|--------------------------|----------|--------------|-------------|
| <u>Labour Items</u>            |                          |          |              |             |
| 1                              | To towing (Bill attach ) | New      | 50.00        | 0.00        |
| <b>Gross Labour Cost (S\$)</b> |                          |          | <b>50.00</b> | <b>0.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >