

ASS. REC. BY:

REF:

CS/SPF19007021/Jgd3er

Special Instruction:

Surveyor:

Hue Jie

ASSIGNMENT (Office)

From (Person):

Abdul Rahman

of

SPF

Date/Time:

18/4/19 @ 4.19pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLK 3396M

Insured:

QX 555M

at Workshop m/a

World Auto

Tel:

63621776

of

1 krunji loop

Policy No:

Claim No:

AEMD/105/009/2018/196

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/12/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time:

10:00am @ 22/4/19

Person Contacted:

Gen Bing

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLK 3396M-CS3/LCR17009729/Mgbe2-1

DOA 13/5/17

QX 555M-CS/SPF18017055/Gisbe2

DOA: -

Do Not Finalise

Vehicle: Huac Jie

REF: SPF

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLK3396M Yr Regn: 13 Jan 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Toyota Prius c.c. 1798

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 200521 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTDKB3FU403543588

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 20/12/18 D.O.I. 22/4/19

Survey held at World Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Paye: \$300 - \$1000

Weekend = 0 days

Total repair days: 2 days

is \$400, 2 days.

RECEIVED 23 MAY 2019

22/5/2019

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 2

1) 23/5/2019  
Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

2)

Add Fee: ☐ : Site Insp (\$

) \$ + P.S. \$ SI

☐ : Interview (\$

) Photos

☐ : Tech. Invs (\$

) Others

☐ : Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$ 400)

TOTAL

220

## Nivitha (LKK Auto)

---

**From:** Abdul Rahman MOHAMAD SALIM (SPF)  
<Abdul\_Rahman\_Mohamad\_Salim@spf.gov.sg>  
**Sent:** Thursday, 18 April 2019 4:19 PM  
**To:** Admin-D (LKKAuto)  
**Cc:** Rosalyn TAN (SPF); Frankie THAY (SPF); Hafizul Farhan RAHMAT (SPF)  
**Subject:** SLK3396M- TP CLAIMS AGAINST QX701H DOA: 03/04/2019

Your Ref : SLK3396M  
Our Ref : AEMD/105/009/2018/196

Dear Nivitha,

**RTA involving police veh QX555M and other veh SLK3396M on 3 Apr 2019**

Your preceding mail noted and refers wrt refer to the above matter.

Please assign a Pre-Repair Inspection for Vehicle **SLK3396M** at the following address:

**World Auto Pte Ltd**  
**No. 1 Kranji Loop**  
**Singapore 739535**

For appointment, please contact **Daniel : 63621776**

Thanks.

Abdul Rahman (Mr)  
Accident Claims Officer  
Automotive Engineering & Management Division  
Police Logistics Department  
Singapore Police Force  
DID: (65) 6478 4840 | FAX: (65) 6478 4848



**HOME TEAM**  
TRANSFORMATION 2025  
*One Home, One Team*  
*Building Our Future Together*

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	4597K
<b>Vehicle Details</b>	
Vehicle No.:	SLK3396M
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	2ZRR989931
Chassis No.:	JTDKB3FU403543588
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$31,008.00
Original Registration Date:	13 Jan 2017
First Registration Date:	13 Jan 2017
Transfer Count:	1
Actual ARF Paid:	\$5,412.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jan 2027
PARF Rebate Amount:	\$4,059.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	12 Jan 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,089.00
COE Rebate Amount:	\$43,303.00
<b>Total Rebate Amount:</b>	<b>\$47,362.00</b>

The information contained herein is correct as at 23 Apr 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	21/12/2018 12:10
Date Of Accident	20/12/2018 14:10
Exact Location Of Accident	BEDOK NORTH ST 3 (BLK 527 CARPARK)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLK3396M
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62414992
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS-1.8 HYBRID CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995006
Cover Note Number	
Driver	
Name of Driver	CHONG JIT SOON
NRIC No	S1804188Z
Date Of Birth	02/06/1967
Occupation	OUTDOOR
Date Of Driving Pass	03/01/1995
Driving Experience	23 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83324559
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	NOADDRESS
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	KAKI BUKIT NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 526 BEDOK NORTH STREET 3 #01-448 , POSTCODE: 460526 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4429999 - FAX NO: 62444377
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE SEE ATTACHED SKETCH

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO OVERWRITTEN
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX555M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	



Nature Of Damage  
No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

BLK 527 (car park) Bedok North St 3





### Sketch Plan #2

**Describe Circumstances of the Accident**

Ref: to police report

### Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre  
Personnel

## Sketch Plan #3



**SINGAPORE  
POLICE FORCE**



T/20181220/2106

Police Station Of Origin:  
Kaki Bukit NPP  
526 Bedok North Street 3 #01-448  
SINGAPORE 460526  
Tel No: 1800-4429999

1 of 3

Report No. T/20181220/2106

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/12/2018 16:42		Vide Report No.: G/20181220/0120		Station Diary No.: 19	
<b>Informant's Particulars</b>					
Name of Informant: CHONG JIT SOON			Address: APT BLK 528 BEDOK NORTH STREET 3 #15-542 SINGAPORE 460528		
ID Type / ID No.: NRIC No / S1804188Z			Contact No.: Home/Office: Mobile: 83324559		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 51	Date of Birth: 02/06/1967	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: PRIVATE HIRED DRIVER			Driving Licence Information: Class: 3 Date of Expiry:		

<b>General Information of the Accident</b>				
Type of Accident:	Non-Injury Government Property	Drink Drive: No	Date/Time of Accident: 20/12/2018 14:10	Type of Location: X-Junction
Location: Along Road 1 BEDOK NORTH STREET 3				
In the carpark vicinity of Blk 527 Bedok North Street 3 Lamp Post Number: C3				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
QX555M	Car	HYUNDAI	AVANTE 1.6 AT ABS D/AB 2WD 4DR	White	Slightly Damaged	3
SLK3396M	Car	TOYOTA	PRIUS HYBRID 1.8 CVT	Silver	Slightly Damaged	1

## Sketch Plan #4



**SINGAPORE  
POLICE FORCE**



T/20181220/2106

2 of 3

Police Station Of Origin:  
Kaki Bukit NPP  
526 Bedok North Street 3 #01-448  
SINGAPORE 460526  
Tel No: 1800-4429999

Report No. T/20181220/2106

## CONTINUATION OF REPORT

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	CHONG JIT SOON	ID No.	S1804188Z
Related Vehicle	SLK3396M (Car)	Contact No.	83324559
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 20/12/2018 at around 1410hrs, I was driving my vehicle bearing plate number: SLK3396M in the carpark vicinity of Bedok North Street 3 near to Blk 527 Bedok North Street 3, I was driving out of the carpark and I notice that the police vehicle bearing vehicle plate number: QX555M that was coming on my left side. As I was travelling on the straight road out of the carpark, and I felt an impact in the vehicle and saw the police vehicle had collided into the left side of my vehicle. I went down and made a check on my vehicle and there were scratches on my left rear bumper. The police vehicle's plate had dropped off due to the accident and there were scratches on the front bumper. Traffic police came to the incident location and attended to the accident. My in-vehicle camera's memory card was handed over to the traffic police officer and I was issued the Singapore Police Force Acknowledgement slip. I was also issued Annex A (NP122) by the police officer. I wish to state that I am not injured.

Sketch Plan #5



SINGAPORE  
POLICE FORCE



T/20181220/2106

Police Station Of Origin:  
Kaki Bukit NPP  
526 Bedok North Street 3 #01-448  
SINGAPORE 460526  
Tel No: 1800-4429999

3 of 3

Report No: T/20181220/2106

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 3 TAN MENG LIANG

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

20/12/2018 16:42

Officer In Charge Of Case:

TP / AEIT /

Sgt 2 SHARIFAH NOR FARIZAN BINTE SYED  
MOHD SAID




Contact No.: 65476172

Authentication Stamp

NP168

Classification Of Case:

# Sketch Plan #6



# WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

SINGAPORE POLICE FORCE

Estimate : ES190063

Attention : Motor Claim Department

Date : 16/04/2019

Vehicle Num. : SLK 3396M (LCR)

Make/Model : TOYOTA PRIUS HYBRID

Chassis/Eng# :

Accident Date : 20/12/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
<b>LIST ITEMS :</b>				
1.	1	REAR BUMPER <i>Repair x</i>		423.90
2.	1	REAR BUMPER LOWER SIDE SPOILER LH <i>Repair x</i>		148.40
3.	1	REAR BUMPER SIDE RETAINER LH <i>nn x</i>		111.50
List TotalS\$ :				683.80
25.00% Discount S\$ :				170.95
				512.85
<b>SPECIAL NETT ITEMS :</b>				
1.	1SET	REAR BUMPER CLIP <i>nn x</i>		30.00
Special Nett Total S\$ :				30.00
<b>LABOUR :</b>				
REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, STRAIGHTEN PANELS WHERE NECESSARY AND REPLACE ABOVE PARTS				250 500.00
PUTTY AND SPRAY PAINT ALL AFFECTED AREAS				300 700.00
Labour Total S\$ :				1,200.00

for WORLD AUTO PTE LTD

LKK Auto Consultant & one of the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$ : 1,742.85

=====

Hwee Jie - LKK

22/4/19

4/5 2days

*[Signature]*

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION			Ref : CS/SPF19007021/Jqd3e2	
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333 ATTN : ABDUL RAHMAN			Date : 03-06-2019 Code : SPF	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	QX 555M	Veh. Inspected	SLK 3396M	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/105/009/2018/196	Excess (\$)	0.00	
Assign From	ABDUL RAHMAN	Assign Date	18/04/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU403543588	Colour	SILVER	
Odometer	200521	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	PIRELLI	6 mm	
L/H Front Tyre	195/65 R15	PIRELLI	6 mm	
R/H Rear Tyre	195/65 R15	PIRELLI	6 mm	
L/H Rear Tyre	195/65 R15	PIRELLI	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	20/12/2018	Inspection Date	22/04/2019	
Survey held at	1 KRANJI LOOP			
Repairer	WORLD AUTO PTE LTD			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 3396M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	423.90	-
1	REAR BUMPER LOWER SIDE SPOILER LH	TO REPAIR SEE LABOUR	148.40	-
1	REAR BUMPER SIDE RETAINER LH	NOT NECESSARY	111.50	-
	LESS 25% DISCOUNT		-170.95	-
			512.85	-
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	30.00	-
			30.00	-
	<b><u>LABOUR</u></b>			
	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, STRAIGHTEN PANELS WHERE NECESSARY AND REPLACE ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR BUMPER LOWER SIDE SPOILER LH.		500.00	250.00
	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS.		700.00	300.00
			1,200.00	550.00
	<b>GRAND TOTAL</b>		<b>1,742.85</b>	<b>550.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>400.00</b>

Report Ref No. CS/SPF19007021/Jqd3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$300-\$1,000

ONG HWEE JIE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.