

ASS. REC. BY:

REF:CS3/CTI19007029/ITICD3024 Special Instruction:

minimum

Surveyor: Tan Rikh

**ASSIGNMENT (Office)**

From (Person): Elaine Chong of CTI Date/Time: 22.4.19 13.15p.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SB 4367M Insured: GBB 8762Y

at Workshop m/s CAR AUTO Tel: 9725 4442

of NO 8 Kaki Bukit Ave 4 #01-07

Policy No: DMCSN 3062821600 Claim No: SVM19D201714102

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 16.4.2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS rcwp H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 22.4.19 Person Contacted: Desmond Vehicle IN / OUT

Date/Time	Action/Instruction ( X ) Estimate
	SB 4367M - NA / AIG 19006809 / 24 D.O.A - 16/04/2019
	GBB 8762Y - NA / AIG 19006809 / 24 D.O.A - 16/04/2019
	Dismantle: 24/4/2019

TAUFEKHA


REF: CT1

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 of Workshop no: \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claim No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? Yes or No  
 GIA / FR Score: \_\_\_\_\_ Consistent? Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res: Yes or No  
 Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

N/S	O/S

Veh No: SLB 4367M (1 Reg) 2016, April.  
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Toyota, Prius Hybrid cc 1798  
 Colour: Blue AC: Insured / Std / NI / NA  
 Sp. Reading: 30202 TRadio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JTDKB3F4703513923  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Nil / S/M/T / STD A/Rim or  
 Tyre Size: F: 205/55R16  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) / SUMI /  
 TOYO / YOKO or  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: 6 mm R/Bal: 6 mm  
 L/Bal: 6 mm L/Bal: 6 mm  
 D.O.A: \_\_\_\_\_ D.O.I: 22/4/19  
 Survey held at: MS Car Wash #01-07  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 Frt o/s  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: \_\_\_\_\_ Action / Instruction: \_\_\_\_\_  
 \$3000-14000, 8 Adey's  
  
 23/4/2019  
 RECEIVED 26 APR 2019.

Date/Time, File Pass to/  : Prelt. Report  
 : Final Report

Days Of Repair:  
 Resurvey No. of Trip:

Add Fee:  Site trap (\$)  Interview (\$)  Tech. Invs (\$)  Workshop (\$)

Survey Fee:	150
Transportation	
Site + P/S	
Others	
TOTAL	150

Report Format :  
 Lump Sum / L.B.I. (\$)

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Apr 2019		22 Apr 2019 13:15 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:				
Main Claimant:	THOMAS M WEINLAND @THOMAS MORRISON WEINLAND, ID: S2740128G			
Vehicle Reg. No.:	SLB4367M	Date of Loss:	16/04/2019 14:00 - :59	
Claim Type:	TP / SNM19D201714C02	Policy/Cover Note No.:	DMCVSN3062821600	
Vehicle Reg. No. (Insured):	GBB8762Y	Policy No. (Claimant):	2100459096-03	
		Excess:	S\$500.00	
Repairer:	- Not Applicable - (-)			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]			
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/05/2019]			

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

## Nivitha (LKK Auto)

---

**From:** Elaine Cheong <elaine.cheong@sg.cntaiping.com>  
**Sent:** Monday, 22 April 2019 1:16 PM  
**To:** William Lee; 'assignments'  
**Cc:** 'Ashley'; 'MS Group Office'; 'MS Car Auto'  
**Subject:** RE: OUR REF; SNM19D201714 - GBB8762Y & yr Ref: MKR/307/8848/2019/as.wl;

**WITHOUT PREJUDICE**  
**SAVE AS TO COSTS**

Dear William,

We refer to your email of 22.04.19.

Please be advised that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards,

**Elaine Cheong**  
Executive (Motor Claims)  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389 6530  
Fax: 6224 7478 / 6224 7175  
Email: [elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

---

**From:** William Lee [mailto:william@roypartners.com.sg]  
**Sent:** Monday, 22 April, 2019 12:28 PM  
**To:** Elaine Cheong <elaine.cheong@sg.cntaiping.com>  
**Cc:** 'Ashley' <ashley@roypartners.com.sg>; 'MS Group Office' <msgrouppoffice@gmail.com>; 'MS Car Auto' <mscarautopl@gmail.com>  
**Subject:** RE: OUR REF; SNM19D201714 - GBB8762Y & yr Ref: MKR/307/8848/2019/as.wl;  
**Importance:** High

Dear Sirs,

We refer to your email below.

Our client reject your list of proposed motor surveyors and propose Mr. Patrick Ng from CarLink Consultancy and Mr Dave from Sincere Appraisal as the Single Joint Expert.

Pursuant to the new NIMA protocol, kindly let us know within **2 working days** of receipt of our letter whether you agree or has any objections to the motor surveyor proposed by our client, failing which you are deemed to have agreed to the appointment of any of the motor surveyors proposed by our client.

Thanks & regards,

**William Lee**

M/s Roy & Partners  
101 Cecil Street  
#11-09 Tong Eng Building  
Singapore 069533  
Tel : 6536 8466 Fax : 6536 1963  
Email : [william@roypartners.com.sg](mailto:william@roypartners.com.sg)

*IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.*

---

**From:** Elaine Cheong [<mailto:elaine.cheong@sg.cntaiping.com>]  
**Sent:** Monday, 22 April, 2019 11:12 AM  
**To:** William Lee <[william@roypartners.com.sg](mailto:william@roypartners.com.sg)>  
**Cc:** 'Ashley' <[ashley@roypartners.com.sg](mailto:ashley@roypartners.com.sg)>  
**Subject:** RE: OUR REF; SNM19D201714 - GBB8762Y & yr Ref: MKR/307/8848/2019/as.wl;

**WITHOUT PREJUDICE**

Dear William,

We refer to your email of 22.04.19.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

**Elaine Cheong**

Executive (Motor Claims)  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6530

Fax: 6224 7478 / 6224 7175

Email: [elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

---

**From:** William Lee [<mailto:william@roypartners.com.sg>]

**Sent:** Monday, 22 April, 2019 10:33 AM

**To:** Angie Foo <[angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)>; Elaine Cheong <[elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)>; Alfred Toh <[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>; Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>

**Cc:** 'Ashley' <[ashley@roypartners.com.sg](mailto:ashley@roypartners.com.sg)>

**Subject:** RE: OUR REF; SNM19D201714 - GBB8762Y & yr Ref: MKR/307/8848/2019/as.wl;

**Importance:** High

Dear Sirs

We refer to your email below.

Kindly be noted that we do not receive any reply from you, our client shall proceed to repair the motor car SLB 4367M without further reference to you.

Thanks & regards,

**William Lee**

M/s Roy & Partners

101 Cecil Street

#11-09 Tong Eng Building

Singapore 069533

Tel : 6536 8466 Fax : 6536 1963

Email : [william@roypartners.com.sg](mailto:william@roypartners.com.sg)

*IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.*

---

**From:** Angie Foo [<mailto:angie.foo@sg.cntaiping.com>]

**Sent:** Thursday, 18 April, 2019 4:38 PM

**To:** Elaine Cheong <[elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)>; Alfred Toh <[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>; Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>; William Lee <[william@roypartners.com.sg](mailto:william@roypartners.com.sg)>

**Subject:** OUR REF; SNM19D201714 - GBB8762Y & yr Ref: MKR/307/8848/2019/as.wl;

**Importance:** High

Dear Elaine,

Please conduct PRS –SLB4367M urgently –( SNM19D201714-GBB8762Y-FILE HAD ALREADY GIVEN TO YOU ON 17.4.19 BY JAI WEI)

Officer In Charge –ELAINE CHEONG -6389 6530

**Angie Foo**

Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 63896186 - F: (65) 6224 7478

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Claims Dept of CTI  
**Sent:** Thursday, 18 April, 2019 3:50 PM  
**To:** Elaine Cheong  
**Cc:** Angie Foo  
**Subject:** FW: Our Ref: MKR/307/8848/2019/as.wl; Your Ref: Your insured vehicle no. GBB 8762Y;  
**Importance:** High

---

**From:** William Lee [<mailto:william@roypartners.com.sg>]  
**Sent:** Thursday, 18 April 2019 3:48 PM  
**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>  
**Cc:** 'Ashley' <[ashley@roypartners.com.sg](mailto:ashley@roypartners.com.sg)>; 'MS Car Auto' <[mscarautopl@gmail.com](mailto:mscarautopl@gmail.com)>; 'MS Group Office' <[mgroupoffice@gmail.com](mailto:mgroupoffice@gmail.com)>  
**Subject:** RE: Our Ref: MKR/307/8848/2019/as.wl; Your Ref: Your Insured vehicle no. GBB 8762Y;  
**Importance:** High

Dear Sirs,

We refer to the email below.

Kindly be noted that we have sent pre-repair inspection notice dated 16<sup>th</sup> April 2019 but we yet to receive any reply from our PRI notice.

If we do not receive any reply from you by today, our client shall proceed to repair the motor car SLB 4367M without further reference to you.

Thanks & regards,

**William Lee**

M/s Roy & Partners  
101 Cecil Street  
#11-09 Tong Eng Building  
Singapore 069533  
Tel : 6536 8466 Fax : 6536 1963  
Email : [william@roypartners.com.sg](mailto:william@roypartners.com.sg)

*IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.*

---

**From:** William Lee [mailto:william@roypartners.com.sg]  
**Sent:** Tuesday, 16 April, 2019 5:48 PM  
**To:** 'China Taiping - 2 Days' <claimsdept@sg.cntaiping.com>  
**Cc:** 'Ashley' <ashley@roypartners.com.sg>; 'MS Car Auto' <mscarautopl@gmail.com>; 'MS Group Office' <msgrouppoffice@gmail.com>  
**Subject:** Our Ref: MKR/307/8848/2019/as.wl; Your Ref: Your insured vehicle no. GBB 8762Y;  
**Importance:** High

Our Ref: MKR/307/8848/2019/as.wl;  
Your Ref: Your insured vehicle no. GBB 8762Y;

Dear Sirs,

**Attn: Motor claims department**

**CLAIMANT:** THOMAS M WEINLAND @ THOMAS MORRISON WEINLAND (OWNER OF SLB 4367M)  
**ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SLB 4367M AND GBB 8762Y ALONG DOVER HOSPICE CARPARK ON 16.04.2019 AT ABOUT 1430 HOURS.**

We refer to the above matter.

We act for Thomas M Weinland @ Thomas Morrison Weinland, the owner of motor car No. **SLB 4367M**.

We are instructed by our client to notify you of a road traffic accident on 16.04.2019 at about 2.30 pm along Dover Hospice Carpark involving our client's motor car registration number **SLB 4367M** and motor vehicle registration number **GBB 8762Y** driven by your insured at the material time. A copy of the Singapore Accident Statement is attached.

As a result of the accident, our client's motor car **SLB 4367M** has been damaged. Before our client proceed to repair the damaged motor car, please let us know within **two (2) working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of our client's motor car **SLB 4367M** at our client's repairer workshop, M/s MS Car Auto Pte Ltd at No. 8 Kaki Bukit Ave 4 #01-07 Premier @ Kaki Bukit Singapore 415875, Your said surveyor may contact Mr. Desmond at 9725 4442. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motorcycle without further reference to you.

Thanks & regards,

**William Lee**  
M/s Roy & Partners  
101 Cecil Street  
#11-09 Tong Eng Building  
Singapore 069533  
Tel : 6536 8466 Fax : 6536 1963  
Email : [william@roypartners.com.sg](mailto:william@roypartners.com.sg)

*IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.*

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0128G
Vehicle Details	
Vehicle No.:	SLB4367M
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	2ZRR844529
Chassis No.:	JTDKB3FU703513923
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$37,865.00
Original Registration Date:	08 Apr 2016
First Registration Date:	08 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$15,011.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Apr 2026
PARF Rebate Amount:	\$11,258.00
Intended COE Rebate Details	
COE Expiry Date:	07 Apr 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,604.00
COE Rebate Amount:	\$33,082.00
<b>Total Rebate Amount:</b>	<b>\$44,340.00</b>

The information contained herein is correct as at 26 Apr 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/04/2019 19:39
Date Of Accident	16/04/2019 14:30
Exact Location Of Accident	DOVER PARK HOSPICE CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB4367M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	THOMAS M WEINLAND @THOMAS MORRISON WEINLAND
NRIC No	S2740128G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97537750
Alternative Phone No	OFFICE-97537750

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID 1.8 CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100459096-03
Cover Note Number	

### Driver

Name of Driver	THOMAS M WEINLAND @THOMAS MORRISON WEINLAND
NRIC No	S2740128G
Date Of Birth	12/05/1961
Occupation	INDOOR
Date Of Driving Pass	22/11/2006
Driving Experience	12 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97537750
Fax Number	
Contact Number	OFFICE-97537750
Email Address	NOEMAIL

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to revoke policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

*x Manjit Vindal*  
Policyholder's Signature  
Date & Time: 16/09/2017 16:30

\_\_\_\_\_  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

*[Signature]*  
Reporting Centre Person's Signature  
Name:  
NIC/PIN No.:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Apr 2019		22 Apr 2019 13:15	<b>S\$0.00</b>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>THOMAS M WEINLAND @THOMAS MORRISON WEINLAND, ID: S2740128G</b>								
Vehicle Reg. No.:	<b>SLB4367M</b>	Date of Loss:	16/04/2019 14:00 - :59 [36 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D201714C02</b>	Policy/Cover Note No.:	DMCVSN3062821600						
Vehicle Reg. No. (Insured):	<b>GBB8762Y</b>	Policy No. (Claimant):	2100459096-03						
		Excess:	S\$500.00						
Repairer:	<b>- Not Applicable - (-)</b>								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]</b>								
Claimant's Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000</b>								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 02/05/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SLB4367M (SNM19D201714C02)  
[GBB8762Y]

TP

THOMAS M WEINLAND @THOMAS MORRISON WEINLAND

Apr 16 2019 2:00PM

[-]

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
<b>Assessment Reports</b>									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubl)		Thumbnail	Print					
1	16/04/19 20:00	Accident Statement		Load HTM						
<b>Photos/Images</b>									3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubl)		Thumbnail	Print					
1	16/04/19 19:57	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
2	16/04/19 19:57	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
3	16/04/19 19:57	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
4	16/04/19 19:57	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
5	16/04/19 19:57	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
6	16/04/19 19:57	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
7	16/04/19 19:57	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
8	16/04/19 19:57	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
9	16/04/19 19:57	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	26/04/19 11:47	General View		Load JPG	<input checked="" type="checkbox"/>					
2	26/04/19 11:47	General View		Load JPG	<input checked="" type="checkbox"/>					
3	26/04/19 11:47	General View		Load JPG	<input checked="" type="checkbox"/>					
4	26/04/19 11:47	General View		Load JPG	<input checked="" type="checkbox"/>					
5	26/04/19 11:47	General View		Load JPG	<input checked="" type="checkbox"/>					
6	26/04/19 11:47	General View		Load JPG	<input checked="" type="checkbox"/>					
7	26/04/19 11:47	General View		Load JPG	<input checked="" type="checkbox"/>					
8	26/04/19 11:47	General View		Load JPG	<input checked="" type="checkbox"/>					
9	26/04/19 11:47	General View		Load JPG	<input checked="" type="checkbox"/>					
10	26/04/19 11:47	General View		Load JPG	<input checked="" type="checkbox"/>					
11	26/04/19 11:47	General View		Load JPG	<input checked="" type="checkbox"/>					
12	26/04/19 11:47	General View		Load JPG	<input checked="" type="checkbox"/>					
13	26/04/19 11:47	General View		Load JPG	<input checked="" type="checkbox"/>					
14	26/04/19 11:47	General View		Load JPG	<input checked="" type="checkbox"/>					
15	26/04/19 11:47	General View		Load JPG	<input checked="" type="checkbox"/>					
16	26/04/19 11:48	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
17	26/04/19 11:48	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
18	26/04/19 11:48	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
19	26/04/19 11:48	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
20	26/04/19 11:48	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
21	26/04/19 11:48	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
22	26/04/19 11:48	Photographs of Damaged Parts		Load JPG						

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
				<input checked="" type="checkbox"/>
23	26/04/19 11:48	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
24	26/04/19 11:48	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
25	26/04/19 11:48	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
26	26/04/19 11:48	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
27	26/04/19 11:48	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
28	26/04/19 11:48	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
29	26/04/19 11:48	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
30	26/04/19 11:48	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
31	26/04/19 11:48	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
32	26/04/19 11:48	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
33	26/04/19 11:48	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
34	26/04/19 11:48	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
35	26/04/19 11:48	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
36	26/04/19 11:48	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/04/19 13:18	PRS - SLB4367M	Load PDF	
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	16/04/19 19:57	Accident Sketch Plan <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
2	16/04/19 19:57	Accident Sketch Plan <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>

### Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	16/04/19 20:00	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	16/04/19 19:57	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	16/04/19 19:57	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	16/04/19 19:57	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	16/04/19 19:57	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	16/04/19 19:57	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	16/04/19 19:57	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	16/04/19 19:57	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	16/04/19 19:57	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	16/04/19 19:57	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	16/04/19 19:57	Accident Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	16/04/19 19:57	Accident Sketch Plan	Load JPG	<input checked="" type="checkbox"/>

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)  
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119007029/T1QD3E2

Date: 10/05/2019

#### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSN3062821600	
Claimant Vehicle No: SLB4367M	Insured Vehicle No: GBB8762Y	
Date of Loss: 16/04/2019	Nature of Claim: TP	Claim No: SNM19D201714C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB4367M	Engine No:	2ZRR844529
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 S CVT (A)	Chassis No:	JTDKB3FU703513923
Reg. Date:	08/04/2016 (Man. Year: 2016)	Odometer:	30202 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment:	22/04/2019	
Date Inspected:	22/04/2019 Inspected At:	MS CAR AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @ KAKI BUKIT SINGAPORE 415875
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

## REPAIR DETAILS

Reference	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 10 May 2019)
<b>Parts:</b> 144	TOYOTA PRIUS HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLB4387M)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.


## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >

Accident Sketch Plan



**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

My car was left in the carpark lot GBB8762Y was trying to park his van but was not careful and drove and hit my car.

**DECLARATION**

I/We declare the foregoing particulars are true in every respect.

*Thomas M. 401110*  
 Policyholder's Signature  
 Date & Time:  
 16/04/19 16:30

\_\_\_\_\_  
 Driver's Signature  
 (if driver is not the policyholder)  
 Date & Time:

*[Signature]*  
 Reporting Centre Personnel's Signature  
 Name:  
 NSIC/IN No.:

Address	69 FABER DRIVE
Postcode	129390
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB8762Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	