

ASSIGNMENT (Office)

REF

CS3/LPC19007036/Ards 02

Special Instruction

ASSIGNMENT (Office)

From (Person)

Carole poh

of

JPC

Date/Time

16/4/19 @ 4:50pm

Estimated Cost

Bill to

OD (TP) WS/TP RES/OD RES/LEVA/INV/MTCS

To Request Vehicle No.

SLC5284G

Insured

SJ89662X

at Workshop no.

70h Motor

Tel.

97419594

of

160 Sin Ming Drive #05-16

Policy No.

Claim No.

18/17/19/VPOS/021687

Sum Insured

Excess

Make of Veh.

D.O.A

13/4/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

R.O.D. Endorsement

Date/Time

Person Contacted

Abby

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SLC5284G-X

SJ89662X-X

30/4/19

@ 4:29pm Yi San said vehicle still under repair

22/5/19

Submit PRS report


PRS
bul.

REF: LPC

C26924

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TR / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Toh Motor
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt.: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLC5284G Yr Regn: 18 May 2016
 Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Honda vezel c.c. 1496
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 69771 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: RU11108000

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 215/60R16
 R: 11

BS: ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm

D.O.A. _____ D.O.A. 22-04-19
 Survey held at w/s 1pm

Des. of Damages ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction
\$7000 - \$8000

RECEIVED 22 MAY 2019

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2) 2/5 - typist

Report Format :

Lump Sum / I.B.I.: (\$ _____)

Days Of Repair:

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

450

Nivitha (LKK Auto)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Monday, 22 April 2019 11:08 AM
To: assignments
Subject: FW: ACCIDENT INVOLVING VEHICLES SLC 5284G & SJS 9962X & SJT 3611T ALONG RIVER VALLEY ROAD NEAR TO CLARK QUAY ON 13th April 2019. [External Confidential]

Best Regards,
Summer Lee | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: GERALD POH WEE BIN [mailto:geraldpoh@lonpac.com]
Sent: Tuesday, 16 April, 2019 4:50 PM
To: assignments@lkkauto.com
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: FW: ACCIDENT INVOLVING VEHICLES SLC 5284G & SJS 9962X & SJT 3611T ALONG RIVER VALLEY ROAD NEAR TO CLARK QUAY ON 13th April 2019. [External Confidential]

Lonpac External - Confidential
Our Ref: 18/19/19/VP05/021687

Dear Nivitha,

Please proceed accordingly.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

Lonpac External - Confidential data is for use by authorised external parties only.

-----Original Message-----

From: abbylim@jcngroup.com [mailto:abbylim@jcngroup.com]
Sent: Tuesday, 16 April, 2019 4:44 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG
Subject: Re: ACCIDENT INVOLVING VEHICLES SLC 5284G & SJS 9962X & SJT 3611T ALONG RIVER VALLEY ROAD NEAR TO CLARK QUAY ON 13th April 2019. [External Confidential]

Hi Gerald,

You may proceed to appoint as per your list and let us know .

On 2019-04-16 16:04, GERALD POH WEE BIN wrote:

> Lonpac External - Confidential

>

>

> WITHOUT PREJUDICE

>

> Dear Abby,

>

> We intend to conduct a pre-repair survey of your client's vehicle and
> attached the list of motor surveyors from LKK Auto Consultants Pte Ltd
> for your attention.

>

> Please revert.

>

>

> Best Regards

> Gerald Poh

> Senior Claims Executive | Lonpac Insurance Bhd

> 300 Beach Road, #17-04/07 The Concourse, Singapore 199555

> Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

>

>

> Lonpac External - Confidential data is for use by authorised external
> parties only.

>

>

> -----Original Message-----

> From: abbylim@jcgrp.com [mailto:abbylim@jcgrp.com]

> Sent: Tuesday, 16 April, 2019 3:26 PM

> To: MT_Claim_SG

> Cc: tohmotorclaims@gmail.com

> Subject: ACCIDENT INVOLVING VEHICLES SLC 5284G & SJS 9962X & SJT 3611T

> ALONG RIVER VALLEY ROAD NEAR TO CLARK QUAY ON 13th April 2019.

> Importance: High

>

> Hi Mdm/ Sir,

>

>

> ACCIDENT INVOLVING VEHICLES SLC 5284G & SJS 9962X & SJT 3611T ALONG

> RIVER VALLEY ROAD NEAR TO CLARK QUAY ON 13th April 2019.

>

> 1. We act for the Owner of Vehicle No. SLC 5284G, whose vehicle was
> damaged as a result of an accident with your Insured, the Driver of
> Vehicle No. SJS 9962X on 13/04/2019.

>

> 2. As a result of the accident, our client's vehicle has been damaged.

> Please kindly revert to us once you/Insurer have received this notice

> and a Pre-Repair Inspection will be arrange within the next 02 working

> days before we carry out any repairs to the mentioned vehicle.

>

> 3. If we do not receive any reply or instruction from you/Insurer
> within
> the stipulated timeline, our client/we shall proceed to repair the
> mentioned vehicle without further reference to you/Insurer.
>
> Please kindly contact @ 9748-3351 Ash Toh should you require more
> information.
>
> Venue for vehicle to be inspected as follows:
>
> 160 Sin Ming Drive
> #05-16 Sing Ming Autocity
> Singapore 575722
>
>
>
> Regards
>
>
>
>
> Abby Lim
> JCN GROUP

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2692H
Vehicle Details	
Vehicle No.:	SLC5284G
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	L15B4028001
Chassis No.:	RU11108000
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,946.00
Original Registration Date:	18 May 2016
First Registration Date:	18 May 2016
Transfer Count:	0
Actual ARF Paid:	\$9,946.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 May 2026
PARF Rebate Amount:	\$7,459.00
Intended COE Rebate Details	
COE Expiry Date:	17 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,504.00
COE Rebate Amount:	\$32,149.00
Total Rebate Amount:	\$39,608.00

The information contained herein is correct as at 23 Apr 2019

OK



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT				
LONPAC INSURANCE BHD		Ref: CS3/LPC19007036/Gvd3n2		
300 BEACH ROAD		Date: 23-05-2019		
#17-04/07 THE CONCOURSESINGAPORE 199555		Code: LPC2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SJS 9662X	Veh. Inspected	SLC 5284G	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/19/19/VP05/021687	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	16/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU11108000	Colour	BLACK	
Odometer	69771 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.			
5. General Information				
Accident Date	13/04/2019	Inspect Date / Time	22/04/2019 (01:00 PM)	
Survey held at	TOH MOTOR ENTERPRISE 160 SIN MING DRIVE #05-16 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC19007036/Gvd3n2

Inspected By



XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever in contract or tort is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.