

ASS. REC. BY:

REF: CS<sup>3</sup> CTI 19007047 / Bcid 302 | Special Instruction:Surveyor: Mr LimASSIGNMENT (Office)From (Person): Chong Boon Sen of CTI Date/Time: 22.4.2019 2.56pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLE 6289 B Insured: \_\_\_\_\_at Workshop m/s TQM AutoPro Tel: 90927279of 160 Sin Ming Drive # 01-14Policy No: DMPCSN30351818000 Claim No: SNM19D201750C02

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 18.4.2019  
(Client's Record)CA / REV / REP. / REV 24 HRS "WP" H.O.D. Endorsement: \_\_\_\_\_Date/Time: 22.4.2019 4.26 p.m Person Contacted: Alan Vehicle IN/OUT

Date/Time	Action/Instruction ( X ) Estimate
	SLE 6289E - X
	GT 50972 - 2A / CTI 19006969 / K4 D.O.A. - 12/04 / 2019
<u>24/4/19</u>	<u>@ 4:19pm Alan said no est provided</u>
	<u>Demand: 24/4/2019</u>

REF:


CTI

## ASSIGNMENT

From: \_\_\_\_\_ Date: 22/4/19  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SLE 6289 B  
 at Workshop m/s Team Autopro  
 of 160 Sir Ming Drive #01-14  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rport: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 10 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Veh No: SLE 6289 B Yr Regn: 28/7/2016  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
 Make: Subaru Forester 2.0 C.C. 1995  
 Colour: Brown A/C: Insured / Std / NI / NA  
 Sp. Reading: #0154 T/Radio: Insured / Std / NI / NA  
 Eng/No: FB20Y307404  
 C/No: JF155KC59G0732A  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 225/60/17  
 R: 225/60/17  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 18/4/19 D.O.I. 22/4/19  
 Survey held at Team Autopro  
 Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

11,000  
Range 9,000 - 8,000

M. Haniffa  
24/4/2019

MV 81,000/2  
PV 53,000/2  
NV 27,400/2

Team Autopro  
24/4/19

Date/Time, File Pass to?

 : Prel. ReportDays Of Repair: 10

1)

 : Final ReportResurvey No. of Trip: 1Survey Fee: 150

Date/Time, File Return to?

Transportation

2)

Add Fee:  : Site Insp (\$)

) S + RS. SI

 : Interview (\$)

) Photos

 : Tech. Invs (\$)

) Others

 : Weekend (\$)

)

Report Format : PRE

Lump Sum / I.B.I: (\$)

TOTAL

150

## Nivitha (LKK Auto)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Monday, 22 April 2019 2:56 PM  
**To:** William Lee  
**Cc:** 'Ashley'; 'TeamAutoPro North'; assignments  
**Subject:** RE: Our Ref: SNM19D201750-SGH6106P & Yr Ref: MKR/404/8857/2019/as.wl; - vehicle no. SLE 6289A; (PRS)

Without prejudice

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

### Chong Boon Sen

Claims Executive  
Department

#### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平狮城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** William Lee [mailto:william@roypartners.com.sg]  
**Sent:** Monday, 22 April, 2019 12:23 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Cc:** 'Ashley' <ashley@roypartners.com.sg>; 'TeamAutoPro North' <teamautopl@gmail.com>  
**Subject:** RE: Our Ref: SNM19D201750-SGH6106P & Yr Ref: MKR/404/8857/2019/as.wl; - vehicle no. SLE 6289A; (PRS)  
**Importance:** High

Dear Sirs,

We refer to your email below.

Our client reject your list of proposed motor surveyors and propose Mr. Ananda Kumar Biswas S/O B N Biswas of United Appraisal and Management Pte Ltd and Ms. Tan Ling Ling, Candy of Impact Analysis Consultants as the Single Joint Expert.

Pursuant to the new NIMA protocol, kindly let us know within **2 working days** of receipt of our letter whether you agree or has any objections to the motor surveyor proposed by our client, failing which you are deemed to have agreed to the appointment of any of the motor surveyors proposed by our client.

Thanks & regards,

**William Lee**

M/s Roy & Partners  
101 Cecil Street  
#11-09 Tong Eng Building  
Singapore 069533  
Tel : 6536 8466 Fax : 6536 1963  
Email : [william@roypartners.com.sg](mailto:william@roypartners.com.sg)

*IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.*

---

**From:** Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]  
**Sent:** Monday, 22 April, 2019 8:48 AM  
**To:** William Lee <[william@roypartners.com.sg](mailto:william@roypartners.com.sg)>  
**Subject:** RE: Our Ref: SNM19D201750-SGH6106P & Yr Ref: MKR/404/8857/2019/as.wl; - vehicle no. SLE 6289A; (PRS)

Without Prejudice

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Angie Foo**Sent:** Thursday, 18 April, 2019 7:44 PM**To:** William Lee <[william@roypartners.com.sg](mailto:william@roypartners.com.sg)>; Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>;  
Alfred Toh <[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>; Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>**Subject:** Our Ref: SNM19D201750-SGH6106P & Yr Ref: MKR/404/8857/2019/as.wl; - vehicle no. SLE  
6289A; (PRS)**Importance:** High

Dear Boon Sen,

Please conduct PRS –SLE6289A - soonest possible –(SNM19D201750-SGH6106P-FILE TO BOON SEN)

Officer In Charge –Chong Boon Sen- 6389 6171

Regards.

**Angie Foo**

Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 63896186 - F: (65) 6224 7478

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Claims Dept of CTI**Sent:** Thursday, 18 April, 2019 5:18 PM**To:** Angie Foo**Subject:** FW: Our Ref: MKR/404/8857/2019/as.wl; Your Ref: Your insured vehicle no. SLE 6289A; (PRS)**Importance:** High

---

**From:** William Lee [<mailto:william@roypartners.com.sg>]**Sent:** Thursday, 18 April 2019 5:16 PM**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>**Cc:** 'Ashley' <[ashley@roypartners.com.sg](mailto:ashley@roypartners.com.sg)>; 'TeamAutoPro North' <[teamautopl@gmail.com](mailto:teamautopl@gmail.com)>



Email: [sm@idac.com.sg](mailto:sm@idac.com.sg)  
Tel no: 6555 6888 Fax no: 6454 3279

### Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 18/4/2019 (dd/mm/yy) Time of Accident: 15:15 (24-HR-FORMAT)  
Vehicle No.: SLE 6289 B Vehicle Make & Model: Subaru FORESTER 2.0  
Exact location of Accident: SLE BKE before woodlands Ave 12  
Policyholder's Name / IC No.: Ong Choon Kian Eric S7126973F  
Driver's Name / IC No.: Ong Choon Kian Eric S7126973F (As Above)   
Driver's Contact No.: 9298 9524 Company Contact No: \_\_\_\_\_  
Driver's Address: Blk 204A Punggol Field #16-294 S(821204)  
Insurance Company: FWD Email address (if any): \_\_\_\_\_

Relationship between Owner & Driver: Owner or Others specify: \_\_\_\_\_

#### What do you wish to claim? (Please TICK one only)

Own Insurance /  Other Vehicle (The one you want to claim against) /  Reporting (For Record Purpose)

#### Exact purpose for which the vehicle was being used at time of accident?

Private use /  Work purpose

Occupation (nature of job)  Indoor/  Outdoor

No. of Passengers (Including Driver): 01

Passenger Name : \_\_\_\_\_  
Passenger Name : \_\_\_\_\_

Gender : \_\_\_\_\_  
Gender : \_\_\_\_\_

#### Weather condition & Road conditions? (On the day of accident)

Clear & Dry /  Raining & Wet /  After-Rain & Wet /  Drizzling & Wet / Others: \_\_\_\_\_

Was there any video captured by your Car Camera?  Yes /  No

Any Injuries:  Yes /  No (If YES) Injured Person' Name: \_\_\_\_\_

Injuries Sustain: \_\_\_\_\_ Injured Person in Which Vehicle: \_\_\_\_\_

Police Report filed:  Yes /  No (If YES) Which Police Station: \_\_\_\_\_

### The Other Party(s) Details:

1. Driver's Name / IC No: \_\_\_\_\_ Vehicle No: SGH 6106 P (B)

Driver's Contact No: \_\_\_\_\_ Insurance Company (If any): \_\_\_\_\_

2. Driver's Name / IC No: \_\_\_\_\_ Vehicle No: GT 5089 Z (C)

Driver's Contact No: \_\_\_\_\_ Insurance Company (If any): \_\_\_\_\_

\*Independent Witness (If Any): \_\_\_\_\_ Contact No: \_\_\_\_\_

Preferred Workshop Name: \_\_\_\_\_ Contact No: \_\_\_\_\_

\*If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.

SKETCH PLAN

SLE BKE before woodlands Ave 12

Vehicle A: SLE 6289 B

Vehicle B: S G H 6106 P

Vehicle C: GT 5089 Z

Vehicle D: GBC 490 D

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date & time, I vehicle A stopped as vehicle D stopped too. Suddenly vehicle B hit onto my vehicle rear portion. The impact is so huge it caused my vehicle to propel forward and hit onto vehicle C rear portion. Would like to state that I felt 2 impact from this accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

[Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6973F
Vehicle Details	
Vehicle No.:	SLE6289B
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Apr 2019
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0I-L CVT AWD SR
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	FB20Y307404
Chassis No.:	JF1S15KC5GG073234
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$15,840.00
Original Registration Date:	28 Jul 2016
First Registration Date:	28 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$15,840.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jul 2026
PARF Rebate Amount:	\$11,880.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jul 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,508.00
COE Rebate Amount:	\$41,739.00
<b>Total Rebate Amount:</b>	<b>\$53,619.00</b>

The information contained herein is correct as at 24 Apr 2019

OK

Avg dep 11,100/yr

MV 81,000/2  
 PV 53,600/2  
 NY 27,400/2

*[Signature]*  
 24/4/19



**Subaru Forester 2.0XT** - N.A 30-Jun-2016 1,998 cc - SUV **SOLD**

Cheapest & Most Beautiful Forester 2.0XT Turbo With STI AeroKit! Full Agent Service History & Warranty Till June 2021. 100% Accident-Free. Genuine Low Mileage. Flawless Paintwork & Like Brand New Leat...

PREMIUM AD

Posted: 03-Feb-2019 Tags: 2016 Subaru Forester, 2016 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru



**Subaru Forester 2.0XT** - N.A 19-Jul-2016 1,998 cc - SUV **SOLD**

1 Owner Only! Spacious SUV With Powerful Engine, Accident Free, Fully Serviced And Maintained By Agent. High Trade In Provided. Call Now To View Before It's Gone! Viewing By Appointment Only.

360 VR Cars

Posted: 18-Mar-2019 Tags: 2016 Subaru Forester, 2016 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru



**Subaru Forester 2.0XT** - N.A 19-Jul-2016 1,998 cc - SUV **SOLD**

Serious Direct Owner Sales, Spacious SUV With Powerful Engine, 100% Maintained By Motor Image. Accident Free

DIRECT OWNER

Posted: 18-Mar-2019 Tags: 2016 Subaru Forester, 2016 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru



**Save on petrol with UOB One card!**

Enjoy huge petrol savings of up to 24%, attractive cashback on your monthly spend, and 1-year annual fee waiver. Apply now and start enjoying today.

Find out more!



**Subaru Forester 2.0XT** - N.A 26-Jul-2016 1,998 cc - SUV **SOLD**

Flawless Condition By Previous Fussy Only Owner, Agent Serviced With Agent Warranty, High Trade In Available Here Only. Lowest Interest In The Market.

PREMIUM AD

Hua Yang Credit Pte Ltd

Posted: 15-Feb-2019 Tags: 2016 Subaru Forester, 2016 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru



**Subaru Forester 2.0XT** - N.A 28-Jul-2016 1,998 cc - SUV **SOLD**

Comes With Agent Warranty Till July 2021 For Peace Of Mind! Reliable Japanese SUV Equipped With A 2L Turbocharged Engine Mated To A CVT Gearbox Ensuring You Adequate Power On The Move And Superb Stabi...

PREMIUM AD

Select By Performance Premium Selection

Posted: 16-Mar-2019 Tags: 2016 Subaru Forester, 2016 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru



**Subaru Forester 2.0i-L** \$81,800 \$10,150 /yr 29-Jul-2016 1,995 cc 50,000 km SUV **Available**

Latest Addition~! 1 Owner, Low Mileage 50,000km And Last Agent Service In March 2019, 4 Door Sound Proof With Powered Speaker, Smooth Silent Drive, Boot Space Unused With Sliding Shade, Guarantee Cond...

Posted: 14-Apr-2019 Tags: 2016 Subaru Forester, 2016 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru



**Subaru Forester 2.0i-L** - N.A 29-Jul-2016 1,995 cc - SUV **SOLD**

1 Careful Owner; Seldom Driven; Regularly Servicing At Motor Image.

DIRECT OWNER

Posted: 06-Apr-2019 Tags: 2016 Subaru Forester, 2016 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru



**Subaru Forester 2.0i-L** \$105,800 \$13,470 /yr 29-Jul-2016 1,995 cc 54,000 km SUV **Available**

Genuine Lowest Mileage! Agent 5 Years Warranty With Service Records! One Of The Best SUVs, The 2016 Subaru Forester Have A Good Value, With Remarkable Interior Volume, Fuel Economy, And Top Safety Sco...

Atlantic Automobile Pte Ltd

Posted: 07-Mar-2019 Tags: 2016 Subaru Forester, 2016 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru



**Subaru Forester 2.0i-L** \$80,388 \$9,950 /yr 13-Aug-2016 1,995 cc 59,863 km SUV **Available**

1 Owner. New Model. Loan Available. Fully Agent Service With Warranty. 100% Accident Free. Perfect Gearbox, Smooth Engine With Super Undercarriage. Nice Bidded Number. Vehicle Always Park Under Shelte...

Posted: 19-Apr-2019 Tags: 2016 Subaru Forester, 2016 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru



**Subaru Forester 2.0i-L** - N.A 13-Aug-2016 1,995 cc - SUV **SOLD**

One Owner Unit, Well Taken Care Of. Agent Unit Coupled With Agent Warranty Till Aug 19! Worry-Free Purchase! New Tires Changed In 2018. Upgraded Spark Plugs To HKS For Better Response And Fuel Consump...

PREMIUM AD

Cars 88 Pte Ltd

Posted: 22-Mar-2019 Tags: 2016 Subaru Forester, 2016 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru



**Subaru Forester 2.0i-L** - N.A 13-Aug-2016 1,995 cc - SUV **SOLD**

1 Owner. Well Taken Care Of. 18inch Rims And Changed Tyres To Bridgestone Alenza In 2018. Upgraded Spark Plugs To HKS For Better Response/FC. Slight Gash At Front Left Bumper, Easily Rectifiable At Pa...

DIRECT OWNER

Posted: 17-Mar-2019 Tags: 2016 Subaru Forester, 2016 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru

Compare

MYT219052172 / Yew Tee Automobile Tech Pte Ltd - Kaki Bukit  
 ENTRY DATE & TIME: 22/04/2019 19:19  
 SUBMITTED BY: Toh Lei Ming

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/04/2019 19:19
Date Of Accident	18/04/2019 15:15
Exact Location Of Accident	SLE BKE BEFORE WOODLANDS AVE 12
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE6289B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ONG CHOON KIAN ERIC
NRIC No	S7126973F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92989524
Alternative Phone No	Office-92989524

### Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER 2.0
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2019-00002597
Cover Note Number	

### Driver

Name of Driver	ONG CHOON KIAN ERIC
NRIC No	S7126973F
Date Of Birth	16/08/1971
Occupation	INDOOR
Date Of Driving Pass	01/12/1997
Driving Experience	21 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92989524

Fax Number	
Contact Number	OFFICE-92989524
E-Mail Address	NOEMAIL
Address	APT BLK 204A PUNGGOL FIELD #16-294
Postcode	821204
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

**General Information of the Accident**

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

REFER TO ATTACHED

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SGH6106P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

5/10/2019

E-FILE

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

GT5089Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

GBC490D

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

SKETCH PLANIMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:




Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name  
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



SLE BRE before woodlands Ave 12  
 Vehicle A: SLE 6289B  
 Vehicle B: SGH 6106P  
 Vehicle C: GT 5089Z  
 Vehicle D: GBC 490D

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On the stated date & time, I Vehicle A stopped as Vehicle D stopped too. Suddenly Vehicle B hit onto my Vehicle rear portion. The impact is so huge it caused my vehicle to propel forward and hit onto vehicle C rear portion. Would like to state that I felt 2 impact from this accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name  
 NRIC/FIN No:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

#### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 May 2019		09 May 2019 14:57	<b>S\$0.00</b>	<b>S\$0.00</b> View Rpt		<b>Pending for Survey Report</b>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

#### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	<b>ONG CHOON KIAN ERIC</b> , ID: S7126973F		
Vehicle Reg. No.:	<b>SLE6289B</b>	Date of Loss:	18/04/2019 15:00 - :59 [32 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / SNM19D201750C02</b>	Policy/Cover Note No.:	DMPCSN30351818000
Vehicle Reg. No. (Insured):	<b>SGH6106P</b>	Policy No. (Claimant):	PNPV2019-00002597
		Excess:	S\$0.00
Repairer:	<b>Team Autopro Pte Ltd (Sin Ming)</b> 385 Sin Ming Drive, #01-02 Vicom Inspection Centre, 575718 Sin Ming - Tel: 62581955		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]		
Claimant's Insurer:	<b>FWD Singapore Pte. Ltd. (HQ)</b> - Tel: 6727 5700		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Lim Teow Guan</b> ] ... [Final Rpt due 21/05/2019]		

#### ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

#### ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

### Claim Documents

**\*SLE6289B (SNM19D201750C02)**  
**[SGH6106P]**  
**TP**  
**ONG CHOON KIAN ERIC**  
**Apr 18 2019 3:00PM**  
**[-]**  
**Team Autopro Pte Ltd**

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>	
<b>Assessment Reports</b>						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)		Thumbnail	Print		
1	22/04/19 19:24	<b>Accident Statement</b>			Load HTM		
<b>Photos/Images</b>						3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)		Thumbnail	Print		
1	22/04/19 19:24	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>			Load JPG	<input checked="" type="checkbox"/>	
2	22/04/19 19:24	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>			Load JPG	<input checked="" type="checkbox"/>	
3	22/04/19 19:24	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>			Load JPG	<input checked="" type="checkbox"/>	
4	22/04/19 19:24	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>			Load JPG	<input checked="" type="checkbox"/>	
5	22/04/19 19:24	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>			Load JPG	<input checked="" type="checkbox"/>	
6	22/04/19 19:24	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>			Load JPG	<input checked="" type="checkbox"/>	
7	22/04/19 19:24	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>			Load JPG	<input checked="" type="checkbox"/>	
8	22/04/19 19:24	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>			Load JPG	<input checked="" type="checkbox"/>	
9	22/04/19 19:24	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>			Load JPG	<input checked="" type="checkbox"/>	
10	22/04/19 19:24	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>			Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	10/05/19 10:12	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
2	10/05/19 10:12	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
3	10/05/19 10:12	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
4	10/05/19 10:12	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
5	10/05/19 10:12	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
6	10/05/19 10:12	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
7	10/05/19 10:12	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
8	10/05/19 10:12	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
9	10/05/19 10:12	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
10	10/05/19 10:12	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
11	10/05/19 10:12	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
12	10/05/19 10:12	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
13	10/05/19 10:12	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
14	10/05/19 10:12	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
15	10/05/19 10:12	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
16	10/05/19 10:12	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
17	10/05/19 10:12	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
18	10/05/19 10:12	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
19	10/05/19 10:12	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
20	10/05/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
21	10/05/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
22	10/05/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
23	10/05/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
24	10/05/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
25	10/05/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
26	10/05/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
27	10/05/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
28	10/05/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
29	10/05/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
30	10/05/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
31	10/05/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
32	10/05/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
33	10/05/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
34	10/05/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
35	10/05/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
36	10/05/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
37	10/05/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
38	10/05/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
39	10/05/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
40	10/05/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
41	10/05/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
42	10/05/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
43	10/05/19 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
44	10/05/19 10:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	10/05/19 10:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	10/05/19 10:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	10/05/19 10:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	10/05/19 10:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	10/05/19 10:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	10/05/19 10:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	10/05/19 10:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	10/05/19 10:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	10/05/19 10:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	10/05/19 10:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	10/05/19 10:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	10/05/19 10:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	10/05/19 10:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	10/05/19 10:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	10/05/19 10:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	10/05/19 10:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	10/05/19 10:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	10/05/19 10:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	10/05/19 10:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	10/05/19 10:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	10/05/19 10:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
66	10/05/19 10:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
67	10/05/19 10:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
68	10/05/19 10:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
69	10/05/19 10:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
70	10/05/19 10:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
71	10/05/19 10:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
72	10/05/19 10:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
73	10/05/19 10:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
74	10/05/19 10:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
75	10/05/19 10:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
76	10/05/19 10:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
77	10/05/19 10:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
78	10/05/19 10:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
79	10/05/19 10:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	09/05/19 14:58	pri contact	Load PDF	

No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	22/04/19 19:24	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	22/04/19 19:24	Sketch Plan #2 [Linked Accident Report Documents]	Load TIF	

### Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	22/04/19 19:24	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	22/04/19 19:24	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	22/04/19 19:24	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	22/04/19 19:24	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	22/04/19 19:24	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	22/04/19 19:24	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	22/04/19 19:24	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	22/04/19 19:24	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	22/04/19 19:24	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	22/04/19 19:24	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	22/04/19 19:24	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	22/04/19 19:24	Sketch Plan	Load TIF	
2	22/04/19 19:24	Sketch Plan #2	Load TIF	

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119007047/BCD3E2  
Date: 10/05/2019

#### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN30351818000
Claimant Vehicle No : SLE6289B	Insured Vehicle No : SGH6106P
Date of Loss: 18/04/2019	Nature of Claim: TP
	Claim No: SNM19D201750C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLE6289B	Engine No: FB20Y307404
Make & Model: SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Chassis No: JF1SJ5KC5GG073234
Reg. Date: 28/07/2016 (Man. Year: 2016)	Odometer: 40154 km
Colour: Brown	
Engine Capacity: 1995 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): <b>Market Value/New Car Price</b>	

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size: 225/60 R17	Rear Tyre Size: 225/60 R17
Front Left Side: Yokohama 6 mm	Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm	Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment: 09/05/2019	
Date Inspected: 22/04/2019	Inspected At: 160 Sin Ming Drive #01-14 Repairer : Team Autopro Pte Ltd (Sin Ming)
Estimated Period of Repair: 10.0 days	

**Adjuster:** Lim Teow Guan

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

[https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen\\_...](https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_...) 10/5/2019



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$9,000.00 -\$11,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 10 May 2019)
<b>Parts:</b> M1-SUV	SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLE6289B)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

### Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >