

FORM 7001

ASS. REC. BY:

REF:

CS3/ALG/19007051/T1cd354

Special Instruction:

SMV/VEH:

ASSIGNMENT (Office)

From (Person):

Taufik
Chin Lee Yeng

of

ALG

Date/Time: 22/4/19 @ 10.51am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV7CS

To Inspect Vehicle No:

SJU 7657E

Insured:

SLB 7237K

at Workshop m/s

Sin Sang Hong Spray

Tel:

9627 8521

of

BLK 3023A ubi Rd T # 01-63

Policy No:

Claim No:

834640227486

Sum Insured:

Excess:

Make of Vch:

D.O.A

15/4/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time:

11.47am @ 22/4/19

Person Contacted:

Andy

Vehicle IN/OUT

Date/Time

Action/Instruction (x) Estimate

SJU 7657E - CS/CTI/8015138/T1rd3e2

D.O.A: 15/8/18

SLB 7237K - *

Discontinue: 23/4/2019

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 22/4/2019 10:51:37 AM
Attachments:  PRI-SJU7657E-SSH.PDF

Hi LKK,

Kindly assist to survey, vehicle is in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

TOMMY CHOO, MARK GO LLC

Advocates & Solicitors

UEN NO : 201523418E

(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16
MANHATTAN HOUSE
SINGAPORE 169876
TEL : (65) 6532 2455
FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: thling@tomg.com.sg

Our Ref: TCMG/SJU7657E/0419/SSH

Your Ref: SLB 7237 K

18 April 2019

BY E-MAIL ONLY
(shengyang.lim@aig.com)

M/s AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
AIG Building
Singapore 079120
Singapore 068811

Attn: Motor Claims Department

Dear Sirs,

PRE-REPAIR INSPECTION NOTICE

We act for **Chua Chin Tiam**, the owner and/or driver of motor vehicle no. **SJU 7657 E**, which was involved in an accident along Carpark entry of Block 316 Tampines Street 33 on 15 April 2019 at 18:35 hrs.

We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. **SLB 7237 K** for damages and/or injuries, costs and disbursements as a result of your insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s Sin Seng Hong Spray Painting & Service, (3023A #01-63, Ubi Road 1, Singapore 408717 - Andy Yeo @ 9627 8521).

If we do not hear from you within the next **two (2) working days**, we shall deem that you have waived the requirement for the pre-repair inspection.

Yours faithfully,



MR LING LEONG HUI

cc. M/s Sin Seng Hong Spray Painting & Svc
(Yref: SJU7657E)

BY E-MAIL ONLY

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/04/2019 11:33
Date Of Accident	15/04/2019 18:35
Exact Location Of Accident	CARPARK ENTRY OF BLK 316 TAMPINES STREET 33
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJU7657E
Insured/Policyholder	
Name Of Registered Owner	CHUA CHIN TIAM
NRIC No	S2595953A
Email Address	CHRISPANG1314@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93882553
Alternative Phone No	OFFICE-93882553

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-1.8 L 5AT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00278431
Cover Note Number	

Driver

Name of Driver	PANG HOON KIEW
NRIC No	S7075445B
Date Of Birth	15/06/1970
Occupation	INDOOR
Date Of Driving Pass	18/03/2005
Driving Experience	14 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91999190
Fax Number	
Contact Number	
Email Address	CHRISPANG1314@GMAIL.COM

Address	BLK 317 TAMPINES STREET 33 #10-62
Postcode	520317
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

STATEMENT RECORDED BY LEONG KEAT - PROGRESSIVE CAR CARE PTE LTD (6741 5336)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLB7237K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MUHAMMAD FARID BIN MUSTAFAH
NRIC/Passport Number	S9019132B
Contact Number	91456791
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	PANG HOON KIEW
------	----------------

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

BACK & NECK PAIN

SJU7657E

YES

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

Vehicle

A - SJU 7637 E

B - SLB 7237 E

Legend

Vehicle

Motorcycle

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling out from carpark of G/L 216 Pangkajene St. 33 near entrance. A vehicle is drive in from the entrance lost control and drive into my lane hit onto my vehicle front right portion. He got send me a message to apologize.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
 Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against own policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

 Policyholder's Signature
 Date & Time:

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5953A
Vehicle Details	
Vehicle No.:	SJU7657E
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	HONDA CIVIC 1.8L 5AT
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	R18A14016696
Chassis No.:	JHMFD16309S203192
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$26,585.00
Original Registration Date:	28 Dec 2009
First Registration Date:	28 Dec 2009
Transfer Count:	1
Actual ARF Paid:	\$26,585.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2019
PARF Rebate Amount:	\$13,292.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$18,267.00
COE Rebate Amount:	\$1,224.00
Total Rebate Amount:	\$14,516.00

The information contained herein is correct as at 22 Apr 2019

OK



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

[Home](#) » [Used Cars](#) » [Direct Owners](#) » [Honda Civic 1.8A VTi-S](#)

Honda Civic 1.8A VTi-S

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)

Price

\$22,500

Depreciation

\$12,030 /yr

[View models with similar depre](#)

Reg Date

26-Dec-2009

(8mths 3days COE left)

Mileage

163,000 km (17.5k /yr)

Manufactured

2008

Road Tax

\$978 /yr

Transmission

Auto

Dereg Value

\$15,594 as of today (change)

OMV

\$28,716

COE

\$18,267

ARF

\$28,716

Engine Cap

1,799 cc

Power

103.0 kW (138 bhp)

Curb Weight

1,219 kg

No. of Owners

3

Type of Vehicle

Mid-Sized Sedan

Features

[View specs of the Honda Civic \(2006-2012\)](#)

Accessories

New Radiator. New Front And Back Suspension, New Headlights, New Engine Mounting And Brake Pads! Aircon Servicing Done!

Description

Best Buy! Quality Pre-Owned At A Affordable And Reasonable Price! Well Maintained And Regularly Serviced! Straight Chassis. No Leaks! Interior Leather Well Maintained!

Category

PARF Car, Direct Owner Sale

Status

[Compare](#)



[Shortlist](#)

[Report Error](#)

Seller Information

Contact Person(

Contact No.

Enquiry

ESSENTIAL TR

» Indemnity fo

» Receipt

» Ownership Tr



GET
PAI

sgCarMart Con

Front Portion

NAC	INC	Item	CON	AC	Q6
1001	991886	Frt Number Plate	DD	/	
1002	991887	Frt Number Plate Base	DD	/	
1003	991889	Frt Number Plate Garnish	DD	/	
1004	991300	Frt Bumper	DD	/	
1005	992341	Frt Bumper Clips	MEC	/	6
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	DIS	/	2
1008	991433	Frt Bumper Reinforcement	DD	/	
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille	CRA	/	
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover	CRA	/	
1019	995079	Frt LH Bumper Fog Lamp	CRA	/	
1020	995080	Frt RH Bumper Fog Lamp	CRA	/	
1021	991793	Frt Grille	CRA	/	
1022	991328	Frt Grille Emblem	CRA	/	
1023	991799	Frt Grille Chrome Moulding	MEC	/	
1024	991222	Frt Apron Panel	CUT	/	
1025	992013	Frt Support Panel	BT	/	
1026	992025	Frt Support Panel Top Garnish Cover	CRA	/	
1027	992416	Horn			
1028	991277	Frt Brace Panel	BT	/	
1029	995153	Frt LH Headlamp Assy	CRA	/	
1030	991821	Frt RH Headlamp Assy	CRA	/	
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	Buc	/	
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock	BT	/	
1036	990285	Bonnet Insulator	BT	/	
1037	990273	Bonnet Finge	BT	/	2
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser	DD	/	
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)	BT	/	
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)	DD	/	
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator	DD	/	
1053	992738	Radiator Cowling	CRA	/	
1054	992742	Radiator Fan Assy	BT	/	
1055	992745	Radiator Fan Clutch	BT	/	
1056	992758	Radiator Hose Top	BT	/	
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct	AT	/	
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

No of Items:

Abstract

Vehicle No. _____

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			2
1074	995052	Wiper Washer Tank Motor			2
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender	SCR	R	
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			2
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender	BUC		
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Inner Garnish	MIS		
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield	CRA		
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish	CUT		
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
		Frt RH Door	SCR	R	

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Apr 2019 Edit Reg		22 Apr 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	MUSTAFAH BIN ABDULLAH, ID: S1309232Z		
Main Claimant:	PANG HOON KIEW, ID: S7075445B		
Vehicle Reg. No.:	SJU7657E	Date of Loss:	15/04/2019 00:00 - :59 [111 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8346402274SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SLB7237K	Policy No. (Claimant):	
		Excess:	
Repairer:	Sin Seng Hong Spray Painting & Service (HQ) BLK 3022A UBI ROAD 1 #01-53, 408716 Ubi - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Wilson-KL] Wilson-KL.Tan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 02/05/2019]		
Claimant's Solicitor:	TOMMY CHOO, MARK GO LLC - Tel: 65322455		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG (23/04/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJU7657E (8346402274SG)
[SLB7237K]

TP

PANG HOON KIEW

Apr 15 2019 12:00AM

[MUSTAFAH BIN ABDULLAH]

Sin Seng Hong Spray Painting & Service

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser ▾		
Photos/Images															3 per page ▾			☒		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print		
1	02/05/19 14:18		General View													Load JPG		☒		
2	02/05/19 14:18		General View													Load JPG		☒		
3	02/05/19 14:18		General View													Load JPG		☒		
4	02/05/19 14:18		General View													Load JPG		☒		
5	02/05/19 14:18		General View													Load JPG		☒		
6	02/05/19 14:18		General View													Load JPG		☒		
7	02/05/19 14:18		General View													Load JPG		☒		
8	02/05/19 14:18		General View													Load JPG		☒		
9	02/05/19 14:18		General View													Load JPG		☒		
10	02/05/19 14:18		General View													Load JPG		☒		
11	02/05/19 14:18		General View													Load JPG		☒		
12	02/05/19 14:18		General View													Load JPG		☒		
13	02/05/19 14:18		General View													Load JPG		☒		
14	02/05/19 14:18		General View													Load JPG		☒		
15	02/05/19 14:18		General View													Load JPG		☒		
16	02/05/19 14:18		General View													Load JPG		☒		
17	02/05/19 14:18		General View													Load JPG		☒		
18	02/05/19 14:18		General View													Load JPG		☒		
19	02/05/19 14:18		General View													Load JPG		☒		
20	02/05/19 14:18		General View													Load JPG		☒		
21	02/05/19 14:18		General View													Load JPG		☒		
22	02/05/19 14:18		General View													Load JPG		☒		
23	02/05/19 14:18		General View													Load JPG		☒		
24	02/05/19 14:18		General View													Load JPG		☒		
25	02/05/19 14:18		General View													Load JPG		☒		
26	02/05/19 14:18		General View													Load JPG		☒		
27	02/05/19 14:18		General View													Load JPG		☒		
28	02/05/19 14:18		General View													Load JPG		☒		
29	02/05/19 14:18		General View													Load JPG		☒		
30	02/05/19 14:18		General View													Load JPG		☒		
31	02/05/19 14:18		General View													Load JPG		☒		
32	02/05/19 14:18		General View													Load JPG		☒		
33	02/05/19 14:18		General View													Load JPG		☒		
34	02/05/19 14:18		General View													Load JPG		☒		
35	02/05/19 14:18		General View													Load JPG		☒		

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	02/05/19 14:18	General View	 Load JPG	☒
37	02/05/19 14:18	General View	 Load JPG	☒
38	02/05/19 14:18	General View	 Load JPG	☒
39	02/05/19 14:18	General View	 Load JPG	☒
40	02/05/19 14:18	General View	 Load JPG	☒
41	02/05/19 14:18	General View	 Load JPG	☒
42	02/05/19 14:18	General View	 Load JPG	☒
43	02/05/19 14:18	General View	 Load JPG	☒
44	02/05/19 14:18	General View	 Load JPG	☒
45	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
46	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
47	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
48	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
49	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
50	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
51	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
52	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
53	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
54	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
55	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
56	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
57	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
58	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
59	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
60	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
61	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
62	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
63	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
64	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
65	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
66	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
67	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
68	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
69	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
70	20/06/19 11:25	Photographs of Damaged Parts	 Load JPG	☒
Documentation			1 per page ▼	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	23/04/19 09:28	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19007051/T1CD3S2
Date: 20/06/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : SJU7657E **Insured Vehicle No :** SLB7237K
 Date of Loss: 15/04/2019 Nature of Claim: TP Claim No: 8346402274SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJU7657E**
 Make & Model: HONDA CIVIC, 1.8 L (A) Engine No: R18A14016696
 Reg. Date: 28/12/2009 (Man. Year: 2009) Chassis No: JHMFD16309S203192
 Colour: Blue Odometer: 230490 km
 Engine Capacity: 1799 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
 Front Left Side: Viking 6 mm Rear Left Side: Viking 6 mm
 Front Right Side: Viking 6 mm Rear Right Side: Viking 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 22/04/2019
 Date Inspected: 22/04/2019 Inspected At: Sin Seng Hong Spray Painting & Service (HQ)
 BLK 3022A UBI ROAD 1 #01-53
 Singapore 408716
 Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Dented	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Cut	0.00 F	*- F
3	1		*FRT NUMBER PLATE GARNISH	Dented	0.00 F	*- F
4	1		*FRT BUMPER	Dented	0.00 F	*- F
5	6		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
6	2		*FRT BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
7	1		*FRT BUMPER REINFORCEMENT	Dented	0.00 F	*- F
8	1		*FRT BUMPER GRILLE	Cracked	0.00 F	*- F
9	1		*FRT RH BUMPER FOG LAMP COVER	Cracked	0.00 F	*- F
10	1		*FRT RH BUMPER FOG LAMP	Cracked	0.00 F	*- F
11	1		*FRT GRILLE	Cracked	0.00 F	*- F
12	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
13	1		*FRT GRILLE CHROME MOULDING	Cut	0.00 F	*- F
14	1		*FRT SUPPORT PANEL	Bent	0.00 F	*- F
15	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Cracked	0.00 F	*- F
16	1		*HORN	*Check	0.00 F	*- F
17	1		*FRT BRACE PANEL	Bent	0.00 F	*- F
18	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
19	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
20	1		*BONNET	Buckled	0.00 F	*- F
21	1		*BONNET LOCK	Bent	0.00 F	*- F
22	1		*BONNET INSULATOR	*Check	0.00 F	*- F
23	2		*BONNET HINGE	Bent	0.00 F	*- F
24	1		*BONNET RUBBER	*Check	0.00 F	*- F
25	1		*AIR CON CONDENSER	Dented	0.00 F	*- F
26	1		*AIR CON FAN ASSY	*Check	0.00 F	*- F
27	1		*AIR CON SUCTION PIPE (LOW PRESSURE)	Bent	0.00 F	*- F
28	1		*AIR CON SUCTION HOSE	*Check	0.00 F	*- F
29	1		*AIR CON DISCHARGE PIPE (HIGH PRESSURE)	Dented	0.00 F	*- F
30	1		*AIR CON DISCHARGE HOSE	*Check	0.00 F	*- F
31	1		*AIR CON LIQUID PIPE	*Check	0.00 F	*- F
32	1		*RADIATOR	Dented	0.00 F	*- F
33	1		*RADIATOR COWLING	Cracked	0.00 F	*- F
34	1		*RADIATOR FAN ASSY	Cut	0.00 F	*- F
35	1		*RADIATOR FAN CLUTCH	Jammed	0.00 F	*- F
36	1		*RADIATOR HOSE TOP	Bent	0.00 F	*- F
37	1		*AIR DUCT	Cut	0.00 F	*- F
38	1		*WIPER WASHER TANK	*Check	0.00 F	*- F
39	1		*WIPER WASHER TANK MOTOR	*Check	0.00 F	*- F
40	1		*FRT LH FENDER	Repair	0.00 F	*- F
41	1		*FRT LH FENDER INNER SHIELD	*Check	0.00 F	*- F
42	1		*FRT RH FENDER	Buckled	0.00 F	*- F
43	1		*FRT RH FENDER TRIANGLE GARNISH	Missing	0.00 F	*- F
44	1		*FRT RH FENDER INNER SHIELD	Cracked	0.00 F	*- F
45	1		*WIPER PANEL GARNISH	Cut	0.00 F	*- F
46	1		*FRT RH DOOR	Repair	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)

0.00

0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >