

ASS. REC. BY:

REF:

CS3/ALG19007052/11cd301

Special Instruction:

ASSIGNMENT (Office)

Loan (Person):

ching lee ying

of

AIG

Date/Time:

22/4/19 @ 10.52am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKA 74262

Insured:

SLZ 4025Z

at Workshop m/a

8AT Motor

Tel:

9859 9677

of

24 Defn line 12

Policy No:

Claim No:

707687690686

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/04/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:41am @ 22/4/19

Person Contacted:

jessie

Vehicle:

IN / OUT

Date/Time

Action/Instruction (x) Estimate

SKA 74262 - x

SLZ 4025Z - x...

Dismantle: 23/4/2019

2017/4
Revenue

Tanfildr

REF:

ALL

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____
at Workshop m/s _____
of _____

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA 7 PR Seen.

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

PRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SKA7426Z Yr Regn: 2011 March
Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Wish

C.C

1797

Colour

Bronze

A/C:

Insured / Std / NI / NA

Sp. Reading

118629

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

2GE 2000 75068

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/450K12

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

finer 39.

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.L.

22/4/19

Survey held at

SAT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

23/4/2019 12:00-15:00, 5 days, 24 Defr line 12

23/4/2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Report Format :

DAR

Lump Sum / L.B.I. (\$)

Survey Fee:

Transportation

5 + RS, 31

Photos

Others

TOTAL

180
11
191

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 22/4/2019 10:52:42 AM
Attachments:  [tmp9062.tif](#)

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



883 North Bridge Road
#11-03 Southbank
Singapore 198785
T: 6292 5838
F: 6292 5838
(UEN No. 201333127N)
(GST Reg No. 201333127N)

Our Ref : CY.SKA7426Z.19.SAT.wp(PT)

Your Ref : Your insured vehicle **SLZ 4025Z**

18 April 2019

Michelle Anne Ng Chai Ping
c/o AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Department)
78 Shenton Way
#07-16
Singapore 079120

By Fax No: 8835 7416

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SKA 7426Z & SLZ 4025Z PARTY VEHICLE ON 14.04.2019 AT 08:15HRS ALONG BEDOK NORTH ROAD OPEN CARPARK

We are instructed by Poon Wai Leong to notify you of a road traffic accident on 10.04.2019 @ 09:15hrs along Bedok North Road Open Carpark involving our client's customer's vehicle registration number SKA 7426Z and vehicle registration number SLZ 4025Z driven by you at the material time. A copy of the Singapore accident statement report is enclosed.


As the result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

At the same time, our proposed list of surveyors is appended as below:

1. Lim Chang Liang
2. Lim Yong Tian, Sebastian

As the appointed workshop is a small workshop, we are unable to provide you with more than the above listed motor surveyors. We trust you will able to choose a surveyor from above.

Yours faithfully,


C. Yogarajah LLC
Enc

cc: M/s. SAT Motors
24 Defu Lane 12, Singapore 539131
Jonathan (9126 9987) / Jessie (9859 9677)
Fax No. 6749 1141

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8320D
Vehicle Details	
Vehicle No.:	SKA7426Z
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8X A
Primary Colour:	Brown
Manufacturing Year:	2010
Engine No.:	2ZR0656980
Chassis No.:	ZGE200075068
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$23,364.00
Original Registration Date:	29 Mar 2011
First Registration Date:	29 Mar 2011
Transfer Count:	1
Actual ARF Paid:	\$23,364.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Mar 2021
PARF Rebate Amount:	\$12,850.00
Intended COE Rebate Details	
COE Expiry Date:	28 Mar 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$57,002.00
COE Rebate Amount:	\$10,956.00
Total Rebate Amount:	\$23,806.00

The information contained herein is correct as at 26 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/04/2019 15:20
Date Of Accident	14/04/2019 09:15
Exact Location Of Accident	BEDOK NORTH ROAD OPEN CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA7426Z
Insured/Policyholder	
Name Of Registered Owner	POON WAI LEONG (PAN WEILIANG)
NRIC No	S8238320D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96956591
Alternative Phone No	OFFICE-96956591

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH 1.8X A
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No. Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT111686
Cover Note Number	21/12/2018 - 20/12/2019

Driver

Name of Driver	POON WAI LEONG (PAN WEILIANG)
NRIC No	S8238320D
Date Of Birth	03/11/1982
Occupation	INDOOR
Date Of Driving Pass	27/01/2004
Driving Experience	15 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96956591
Fax Number	
Contact Number	OFFICE-96956591
Email Address	NOEMAIL

Address	BLK 28 FERNWOOD TERRACE #10-01
Postcode	458556
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : YE YUYING GENDER: : FEMALE
Passenger 2	NAME: : POON JAN JYU HANNAH GENDER: : FEMALE
Passenger 3	NAME: : POON JAN QI BREANNE GENDER: : FEMALE
Passenger 4	NAME: : POON JAN TONG ELLENN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE STATED DATE & TIME, I WAS DRIVING MY VEHICLE A (SKA7426Z) IN BEDOK NORTH ROAD OPEN CARPARK WHEN VEHICLE B (SLZ4025Z) WAS DRIVING OUT OF THE PARKING LOT AND I COULD NOT REACT IN TIME. I FELT AN IMPACT AND REALISED THAT I HAD A HEAD-ON COLLISION WITH VEHICLE B.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLZ4025Z
Vehicle Make/Model/Colour	
Details Of Properties	

Vehicle Category

PRIVATE CAR

Name of Driver

MICHELLE ANNE NG CHAI PING

NRIC/Passport Number

S7005944D

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

15/4/19

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature


Name:

NRIC/FIN No.:



Sketch Plan Pg. 2

SKETCH PLAN



Van A SKA74262

B. SLZ40252

Location: Bedok North Road, Spring
Corporation

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to CILA report

You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a Fourteen (14) days clause whereby the claim must be made within the stipulated time-frame from the day of occurrence.

Reporting Only

Claim OD

☒ Claim TP

Claim OD/TP at other workshop

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

15/4/19

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



MOTOR CAR (Frt)

Front Portion

Vehicle No: **SKA 7426Z**

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper			
1005	992341	Frt Bumper Clips			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

Front Fender splash shield clip 6 nss

Front Fender splash shield RH nss

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Apr 2019 Edit Reg		22 Apr 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	MICHELLE ANNE NG CHAI PING, ID: S7005944D								
Main Claimant:	POON WAI LEONG (PAN WEILIANG), ID: S8238320D								
Vehicle Reg. No.:	SKA7426Z	Date of Loss:	14/04/2019 09:00 - :59 [96 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 7076876906SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SLZ4025Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Sat Motors (HQ) 24 Defu Lane 12, 539131 Defu Lane - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 02/05/2019]								
Claimant's Solicitor:	C YOGARAJAH LLC - Tel: 62925838								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (23/04/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKA7426Z (7076876906SG)**
[SLZ4025Z]


































TP

POON WAI LEONG (PAN WEILIANG)

Apr 14 2019 9:00AM

[MICHELLE ANNE NG CHAI PING]

Sat Motors

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View In Browser	
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	26/04/19 12:14	General View													Load JPG	<input checked="" type="checkbox"/>		
2	26/04/19 12:14	General View													Load JPG	<input checked="" type="checkbox"/>		
3	26/04/19 12:14	General View													Load JPG	<input checked="" type="checkbox"/>		
4	26/04/19 12:14	General View													Load JPG	<input checked="" type="checkbox"/>		
5	26/04/19 12:14	General View													Load JPG	<input checked="" type="checkbox"/>		
6	26/04/19 12:14	General View													Load JPG	<input checked="" type="checkbox"/>		
7	26/04/19 12:14	General View													Load JPG	<input checked="" type="checkbox"/>		
8	26/04/19 12:14	General View													Load JPG	<input checked="" type="checkbox"/>		
9	26/04/19 12:14	General View													Load JPG	<input checked="" type="checkbox"/>		
10	26/04/19 12:14	General View													Load JPG	<input checked="" type="checkbox"/>		
11	26/04/19 12:14	General View													Load JPG	<input checked="" type="checkbox"/>		
12	26/04/19 12:14	General View													Load JPG	<input checked="" type="checkbox"/>		
13	26/04/19 12:14	General View													Load JPG	<input checked="" type="checkbox"/>		
14	26/04/19 12:14	General View													Load JPG	<input checked="" type="checkbox"/>		
15	26/04/19 12:14	General View													Load JPG	<input checked="" type="checkbox"/>		
16	26/04/19 12:14	General View													Load JPG	<input checked="" type="checkbox"/>		
17	26/04/19 12:14	General View													Load JPG	<input checked="" type="checkbox"/>		
18	26/04/19 12:14	General View													Load JPG	<input checked="" type="checkbox"/>		
19	26/04/19 12:14	General View													Load JPG	<input checked="" type="checkbox"/>		
20	26/04/19 12:14	General View													Load JPG	<input checked="" type="checkbox"/>		
21	26/04/19 12:14	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>		
22	26/04/19 12:14	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>		
23	26/04/19 12:14	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>		
24	26/04/19 12:14	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>		
25	26/04/19 12:14	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>		
26	26/04/19 12:14	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>		
27	26/04/19 12:14	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>		
28	26/04/19 12:14	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>		
29	26/04/19 12:14	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>		
30	26/04/19 12:14	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>		
31	26/04/19 12:14	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>		
32	26/04/19 12:14	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>		
Documentation															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail	Print		
1	23/04/19 08:57	OI GIA REPORT													Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
<div></div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer	
<small>Note: Remarks are private unless you show it to other parties.</small>	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19007052/T1CD3E2

Date: 26/06/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SKA7426Z

Insured Vehicle No : SLZ4025Z

Date of Loss: 14/04/2019

Nature of Claim: TP

Claim No: 7076876906SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKA7426Z

Make & Model: TOYOTA WISH, 1.8 X (A)

Engine No: 2ZR0656980

Reg. Date: 29/03/2011 (Man. Year: 2010)

Chassis No: ZGE200075068

Colour: Bronze

Odometer: 118629 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17

Rear Tyre Size:

215/50 R17

Front Left Side: Firenza 6 mm

Rear Left Side:

Firenza 6 mm

Front Right Side: Firenza 6 mm

Rear Right Side:

Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 22/04/2019

Date Inspected: 22/04/2019

Inspected At:

Sat Motors (HQ)
24 Defu Lane 12
Singapore 539131

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Dented	0.00 F	*- F
2	10		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*FRT BUMPER SIDE RETAINER RH	Distorted	0.00 F	*- F
4	1		*FRT RH HEADLAMP ASSY	Cut	0.00 F	*- F
5	6		*FRONT FENDER SPLASH SHIELD CLIP	Necessary	0.00 F	*- F
6	1		*FRT RH FENDER	Repair	0.00 F	*- F
7	1		*FRT RH FENDER INNER SHIELD	Cracked	0.00 F	*- F
8	1		*FRT RH WHEEL RIM	Repair	0.00 F	*- F
9	1		*FRT RH WHEEL BEARING	Bent	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >