

ASS. REC. BY

Sally Yip

Rasu)

REF C2/ASM19007055/RISD302

Date of Instruction

ASSIGNMENT (Office)

Phone(Person)

Kitty Teo

of

ASM(CAXA)

Date/Time

22/4/19

Estimated Cost

Bill to

① / TP / WS / TP RES / OD RES / RYA / INV / MV / CS

To Inspect Vehicle No

SFH 2125Y

Insured

at Workshop n/o

K. Kim Hin

Tel

64527018

of

160 Sin Ming Drive #02-20

Policy No

Claim No

89M01K03

Sum Insured

Excess

NIL

Make of Veh

(Client's Record)

D.O.A

8/4/19

CA / REV

REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time

11:29 am @ 22/4/19

Person Contacted

Angie/Sandra

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

ple Get Audatex

SFH 2125Y-X

25/04/19

@ 15:34 p.m. revised & requested authorize repair to Kitty Teo via smart claim.

25/04/19

@ 16:18 pm authorize approved by Insurance.

25/04/19

@ 16:42 pm revert authorize repair to Sandra (off repair) via email.

<< Service Request Details

Claim

S9M01K03

Reference

None 

Loss Date

April 8, 2019

Report Date

Apr 22, 2019 9:26:00 AM

Request Date

April 22, 2019

Due Date

April 29, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SFH2125Y

MODEL
E200

Service Address

7.1.1

Primary Contact/Insured

BONG MOI @ MONG LAI SANG
BLK 170 BISHAN STREET 13, #05-63, 570170, Singapore
96196518

Claim Handler

TEO Kitty
6568804602
kitty.teo@axa.com.sg
Additional Instructions
XS - NIL

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

TYPE



SENT

4/22/19 10:29 AM

FROM

TEO Kitty

SUBJECT

WP SURVEY

BODY

Hi Please get audatex.



Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 17 June 2019 4:09 PM
To: 'Simon'
Cc: Rasul (LKKAuto)
Subject: RE: SFH2125Y AXA OD FINALISATION

Dear Simon,

Confirmed final fig \$ 3,324.39 @ 3 days of repairs before excess \$ 0/- & GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Rasul (LKKAuto) [mailto:Rasul@lkkauto.com]
Sent: Tuesday, 11 June 2019 10:45 AM
To: Simon <simon@kkimhin.com.sg>
Cc: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: RE: SFH2125Y AXA OD FINALISATION

Hi Simon,

Kindly forward to me the new headlamp resurvey and after repair photos

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Simon [mailto:simon@kkimhin.com.sg]
Sent: Tuesday, 4 June, 2019 7:08 PM
To: Rasul (LKKAuto)
Cc: SUR
Subject: Fw: SFH2125Y AXA OD FINALISATION
Importance: High

Re send

Regards
Simon
64527018
K. Kim Hin Auto Pte Ltd

From: Simon
Sent: Saturday, May 04, 2019 12:40 PM
To: Rasul LKK
Cc: Veron LKK ; Survey KKH
Subject: SFH2125Y AXA OD FINALISATION

Dear Rasul,

Enclosed for your attention.
P/P \$3324.39
Excess Nil.
Please revert and confirm.

Regards
Simon
KKH

Your message is ready to be sent with the following file or link attachments:
audatex_SF2125Y Adjusted.pdf

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.

KADRI Mateen

From: service <service@kkimhin.com.sg>
Sent: Saturday, April 20, 2019 6:07 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: service@kkimhin.com.sg; Sandra (Gmail); simon@kkimhin.com.sg; survey@kkimhin.com.sg; survey2@kkimhin.com.sg
Subject: SFH 2125 Y (OD- AXA) on 8 April 2019
Attachments: GIAreport 2125.PDF; audatex_SF2125Y.pdf.pdf; COE rebate.pdf; CI.pdf; IC & DL.pdf
Categories: Mateen

Dear Motor Survey Team

Can you kindly assist to register this Own Damage claim as we could not register in smart claim?

Own Damage claim SFH 2125 Y under AXA.

Vehicle is not in yet.

Please kindly appoint surveyor. Thank you.

Best Regards
Sandra
6452 7018
K. Kim Hin Auto Pte Ltd

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9200J
Vehicle Details	
Vehicle No.:	SFH2125Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Apr 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E200 SEDAN (R18)
Primary Colour:	Silver
Manufacturing Year:	2013
Engine No.:	27492030128037
Chassis No.:	WDD2120342A932212
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$45,943.00
Original Registration Date:	06 Mar 2014
First Registration Date:	06 Mar 2014
Transfer Count:	0
Actual ARF Paid:	\$51,321.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Mar 2024
PARF Rebate Amount:	\$35,924.00
Intended COE Rebate Details	
COE Expiry Date:	05 Mar 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$79,000.00
COE Rebate Amount:	\$38,483.00
Total Rebate Amount:	\$74,407.00

The information contained herein is correct as at 14 Apr 2019

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 25 April 2019 4:42 PM
To: 'Sandra Khong'
Cc: 'SUR'
Subject: SFH 2125Y OD (AXA) DOA 08/04/2019

Dear Sandra,

As instructed by our client, please proceed to repair the insured vehicle **SFH 2125Y (Excess \$ 0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Re:RE: Re:FINAL - SFH 2125Y

Type

🔔 Question

Message

Hi Shirley Please authorise if the supplementary is consistent to the accident.

Reply



RE: Re:FINAL - SFH 2125Y

Type

🔔 Question

Message

Hi Kitty, parts invoice submitted. Kindly let us have your authorize approval. Thanks. From : Shirley Hiew

Reply



Re:FINAL - SFH 2125Y

Type

🔗 Question

Message

Hi Shirley There is an increase of \$1006.50, please advice.

Reply



FINAL - SFH 2125Y

Type

🔗 Question

Message

IA submitted. Damages consistent, repair cost economical. We have authorize repair. Thanks. From : Shirley Hiew.

Reply

Model

E200

Service Address

...

Primary Contact/Insured

BONG MOI @ MONG LAI SANG

BLK 170 BISHAN STREET 13, #05-63, 570170, Singapore

96196518

Claim Handler

TEO Kitty

6568804602

kitty.teo@axa.com.sg

Additional Instructions

XS - NIL

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

[New Message](#)

TYPE



SENT

4/25/19 4:18 PM

FROM

TEO Kitty

SUBJECT

Please authorise.

BODY

.



TYPE



SENT

4/25/19 3:34 PM



IA - SFH 2125Y

Type

🔍 Question

Message

IA uploaded. Damages consistent, repair cost economical. we have not authorize repair. Kindly let us have your authorize approval. Thanks. From : Shirley

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 13/06/2019

Survey Details:

Date of loss	8-Apr-19
Date of appointment	22-Apr-19
Date of survey	25-Apr-19
Location of survey	160 SIN MING DRIVE, #02-20 SIN MING AUTOCITY SINGAPORE 575722

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SFH 2125Y
Make and Model	MERCEDES BENZ E200 SEDAN (R18)
Date of registration	6-Mar-14
Excess	NIL
Market Value	\$110,000
Parf Rebate	\$74,407
Nett Loss	\$35,593

Repair details:

Initial Estimate	3,524.39
------------------	----------

Proposed/Revised repair cost:

Parts	\$2,601.50
Check items (estimate)	\$0.00
Labour	\$722.89
Total	\$3,324.39
Lump Sum(if applicable)	\$

Number of days for repair	3 DAYS
---------------------------	---------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

DAMAGES CONSISTENT, REPAIR COST ECONOMICAL.
KINDLY LET US HAVE YOUR AUTHORIZE APPROVAL.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 25/04/2019

Survey Details:

Date of loss	8-Apr-19
Date of appointment	22-Apr-19
Date of survey	25-Apr-19
Location of survey	160 SIN MING DRIVE, #02-20 SIN MING AUTOCITY SINGAPORE 575722

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SFH 2125Y
Make and Model	MERCEDES BENZ E200 SEDAN (R18)
Date of registration	6-Mar-14
Excess	NIL
Market Value	\$110,000
Parf Rebate	\$74,407
Nett Loss	\$35,593

Repair details:

Initial Estimate	2,517.89
------------------	----------

Proposed/Revised repair cost:

Parts	\$1,845.00
Check items (estimate)	\$0.00
Labour	\$472.89
Total	\$2,317.89
Lump Sum(if applicable)	\$

Number of days for repair	3 DAYS
---------------------------	---------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. WE
HAVE NOT AUTHORIZE REPAIR.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	11/04/2019 21:18
Date Of Accident	08/04/2019 18:05
Exact Location Of Accident	BLK 170 BISHAN ST 13
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SFH2125Y
Insured/Policyholder	
Name Of Registered Owner	BONG MOI @ MONG LAI SANG
NRIC No	S2539200J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96196518
Alternative Phone No	OFFICE-96196518
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	E200
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA170412
Cover Note Number	
Driver	
Name of Driver	BONG MOI @ MONG LAI SANG
NRIC No	S2539200J
Date Of Birth	17/07/1948
Occupation	INDOOR
Date Of Driving Pass	22/07/1976
Driving Experience	42 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96196518
Fax Number	
Contact Number	OFFICE-96196518
Email Address	NOEMAIL

Address	BLK 170 BISHAN ST 13 #05-63
Postcode	570170
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BISHAN NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 20 BISHAN STREET 23 , POSTCODE: 579757 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5529999 - FAX NO: 65561905
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN AND POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF1370U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

9/4/19
6pm

Driver's Signature


(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



SKETCH PLAN

Refer to sketch

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 8/4/19 about 6.30pm, I walked to my car to go out. I noticed something on the front left of my car. As I walked closer, I saw my car left Headlamp was cracked and scratches on my front left bumper.

So I quickly pulled out video recordings from my dash cam and noticed vehicle reversed into the parking lot on my left. It happened to be the same model as the one I saw when I approached my vehicle at 6.30pm.

* Late Report because I was not familiar with the process *

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time 8/4/19-6PM

Company Chop (if applicable)

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



1K253P20J
9/4/19
6 PM

13704

525 lot

274-275

DB



**SINGAPORE
POLICE FORCE**



T/20190410/2165

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

1 of 3

Report No. T/20190410/2165

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/04/2019 17:12		Vide Report No.:		Station Diary No.: 99	
Informant's Particulars					
Name of Informant: BONG MOI			Address: APT BLK 170 BISHAN STREET 13 #05-63 SINGAPORE 570170		
ID Type / ID No.: NRIC NO / S2539200J			Contact No.: Home/Office: Mobile: 96196518		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 70	Date of Birth: 17/07/1948	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Company director			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 08/04/2019 18:30	Type of Location: Car Park
Location: Along Road 1 BISHAN STREET 13 Blk 171 Bishan Street 13 Open space car park. Lamp Post Number: 526				
Weather:		Road Surface:		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision:				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBF1370U		NISSAN	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5	Silver		0
SFH2125Y		MERCEDES BENZ	E200 SEDAN (R18)	Silver		0



**SINGAPORE
POLICE FORCE**



T/20190410/2165

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

2 of 3

Report No. T/20190410/2165

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SFH2125Y	AXA INSURANCE SINGAPORE PTE LTD	GA170412	06/03/2019	05/03/2020

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	BONG MOI	ID No.	S2539200J
Related Vehicle	NIL	Contact No.	96196518
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 08/04/2019 at about 1434hrs, I parked my vehicle (SFH2125Y) at Blk 171 Bishan Street 13 open space car park lot 526. At the point of time my vehicle was in order.

On 08/04/2019 at about 1830hrs, I went to retrieve my vehicle (SFH2125Y) and I discovered that the left headlamp of my vehicle was cracked and scratches on my front left bumper.

I then went to playback on the captured footage from the in-built camera that was installed in my vehicle which showed that my vehicle damages were caused by vehicle (GBF1370U).



**SINGAPORE
POLICE FORCE**



T/20190410/2165

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

1 of 3

Report No. T/20190410/2165

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: E / Sgt 2 TAN CHIN SENG, JASON	
Signature Of Interpreter: Not applicable	
Officer In Charge Of Case: TP / HRT / SI ABDUL KAREEM BIN ABDUL HAGUE Contact No.: 65476079	

Authentication Stamp
NP168

Signature Of Informant:	
Date/Time: 10/04/2019 17:12	
Classification Of Case:	SN 061

Officer- In -Charge
Investigation Section
Traffic Police Department
10 Ubi Avenue 3
Singapore 408865

Name: Bong Moi
NRIC No: S2539200J
Add: Apt Blk 170 Bishan St 13
#05-63 Singapore 570170
Hp: 96196518

Dear Sir/Mdm,

Report of a non-injury hit and run at Open Space Carpark of Blk 171 Bishan St 13.

On 10/04/2019 (date) at 1712hrs (time), I lodged a traffic accident report vide:
T/20190410/2165


I wish to amend in the brief details as follows:

1) My vehicle (SFH2125Y) was parked at car park lot number 525, not lot number 526 which was stated in the report.

Yours faithfully,



Signature

If a police officer records this amendment, please complete the following:	
Name / Rank No: SC/Cpl M Muhd Muhsin	Station Diary No. eSD 26 dated on the 11/04/2019
Signature 	SN 061

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:
Assessment number: 002716
Version: 1810
Date calculated: 04/17/2019 02:58 PM

Full Report
Registration: SFH2125Y
Printed: 17/04/2019 3:00 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	SANDRA KHONG	Currency:	SGD
Claim Reference:		Date of Incident:	2019-04-08
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES-BENZ
Model:	E-CLASS (W212)
Sub Model:	E 200
Model Sheet Number:	03 EE 46
Registration:	SFH2125Y
VIN number:	WDD2120342A932212
Odometer:	

Model Specs

FR PRODUCTION START	MOD PACK 13/2	MODIFICAT PACK 13/3	MODEL 2014
FRT COLLISION ALARM	RADIATOR SHROUD	EL DRIVE POS SELECT	PARKTRONIC
LOAD COMPARTMENT BOX	AUDIO 20 CD CHANGER	MULTIMEDIA INTERFACE	GRILLE WITH STAR
SMART LIGHT SYSTEM	LAMINATED GLASS	HEATED WASHER UNIT	LEATHER TRIM
SUNBLIND TWO-PIECE	EQUIPMENT AVANTGARDE	MEMORY PACKAGE	DIPPING MIRROR
S-WDW ROLLER BLIND	WOOD TRIM ASH TREE	REM RELEASE FUEL CAP	KEYLESS GO
PELVIS BAG	RR SCREEN SUN BLIND	ECO START/STOP	STRG COLUMN SHIFT
EMISSION STD EURO 6	7 SPEED AUTOMATIC	DIRECT CONTROL SUSP	TYRES 245/40 YR 18
WHEELS 8.5J X 18 ALU	SPARE WHEEL	FUEL TANK 80 LTR	HD COOLING
COMPRESSOR VARIABLE	PREPARE OFF VEHICLE	CLEAR COAT HARD	TWO COAT PEARL/MICA

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:
 Assessment number: 002716
 Version: 1810
 Date calculated: 04/17/2019 02:58 PM

Full Report
Registration: SFH2125Y
Printed: 17/04/2019 3:00 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
54-1011 01	SHORT TEST INCLUDES: CONNECT + DISCONNECT STAR DIAGNOSIS, PRINT DATA, DELETE ERROR MEMORY		3.0	13.50
88-1140 02	R + R COMPLETE FRONT BUMPER INCLUDES: R + R RADIATOR COWL		7.0	31.50
82-4791 02)	RENEW L/F LAMP UNIT (BUMPER DETACHED)		5.0	22.50
0283	FRONT BUMPER COVER REPAIR		30.0*	135.00
Labour Cost			Hrs	WU
Panel / Mechanical Labour			4.50	45.0
Total of Labour				202.50

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:

Assessment number: 002716

Version: 1810

Date calculated: 04/17/2019 02:58 PM

Full Report

Registration: SFH2125Y

Printed: 17/04/2019 3:00 PM

Code	Description	Price SGD
1000	ONLNE PROGRAM L/HDLP ONLINE PROGRAM	250 450.00*
	Total Extras	450.00

Final Calculation

	SGD	SGD
Parts		
Addition(+10.00%)		
Total Parts		1,595.00
Labour Time Base 10 WU/h		
Total 45.0 WU X 45.00 SGD/h		
Total of Labour		202.50
Total Of Extras		450.00
Paint Work Time Base 10 WU/h		
Labour Cost 47.0 WU X 45.00 SGD/h		
Material Cost		
Total Paint Including Material		270.39
Repair Cost Excludes GST		2,517.89
GST (+7.0%)		176.25
Repair Cost Included GST		2,694.14

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

email: rasul@lkkauto.com

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:
 Assessment number: 002716
 Version: 1810
 Date calculated: 04/17/2019 02:58 PM

Full Report
 Registration: SFH2125Y
 Printed: 17/04/2019 3:00 PM

Paint

Paint Work		Time Basis 10WU/h	
Code	Description - CLEAR COAT HARD	WU	Price SGD
98-1731 01	FRONT BUMPER COVER PAINTING	11.0	49.50
98-2416 01	L/F WING PAINTING STAGE II	5.0	22.50
98-1340 01	PREPARATION WORK FOR TWO COAT PAINTING OF FITTED BODY PARTS	15.0	67.50
98-1356 01	ADD/WORK FOR PLASTIC PARTS	3.0	13.50
98-1620 ZAX	PRIME PLASTIC/METAL PARTS	3.0	13.50
98-1630 ZAX	APPLY SMOOTHG FILLER ON PLAST/MET PARTS	3.0	13.50
98-1625 ZAX	REPAIR/APPLY FILLER ON PLAST/METAL PARTS	2.0	9.00
98-1620 ZAX	APPLY PRIMER FRONT BUMPER (ADD/WORK)	1.0	4.50
98-1630 ZAX	APPLY FILLER FRONT BUMPER (ADD/WORK)	1.0	4.50
98-1625 ZAX	APPLY FILLER PASTE FRONT BUMPER (ADD)	3.0	13.50
Total Paint		Hrs 4.70	WU 47.0
			Price SGD 211.50
Material Cost - Paint			Price SGD
Repair Painting			35.97
Surface-/Blend Paint			9.45
Material-constant Metal			13.47
Total			58.89

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
0561	LEFT HEADLAMP ASSY	212 820 2539	CRA ✓	2365 1,450.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			1,450.00
u: Used parts	Addition(+10.00%)			145.00
	Total			1,595.00

Extras

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
Assessment number: 190196
Version: 1810
Date calculated: 11/06/2019 10:48 AM

Full Report
Registration: SFH2125Y
Printed: 11/06/2019 10:48 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	08/04/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES-BENZ
Model:	E-CLASS (W212)
Sub Model:	E 200
Model Sheet Number:	03 EE 46
Registration:	SFH2125Y
VIN number:	WDD2120342A932212
Odometer:	

Model Specs

FR PRODUCTION START	MOD PACK 13/2	MODIFICAT PACK 13/3	MODEL 2014
FRT COLLISION ALARM	RADIATOR SHROUD	EL DRIVE POS SELECT	PARKTRONIC
LOAD COMPARTMENT BOX	AUDIO 20 CD CHANGER	MULTIMEDIA INTERFACE	GRILLE WITH STAR
SMART LIGHT SYSTEM	LAMINATED GLASS	HEATED WASHER UNIT	LEATHER TRIM
SUNBLIND TWO-PIECE	EQUIPMENT AVANTGARDE	MEMORY PACKAGE	DIPPING MIRROR
S-WDW ROLLER BLIND	WOOD TRIM ASH TREE	REM RELEASE FUEL CAP	KEYLESS GO
PELVIS BAG	RR SCREEN SUN BLIND	ECO START/STOP	STRG COLUMN SHIFT
EMISSION STD EURO 6	7 SPEED AUTOMATIC	DIRECT CONTROL SUSP	TYRES 245/40 YR 18
WHEELS 8.5J X 18 ALU	SPARE WHEEL	FUEL TANK 80 LTR	HD COOLING
COMPRESSOR VARIABLE	PREPARE OFF VEHICLE	CLEAR COAT HARD	TWO COAT PEARL/MICA

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: 190196
 Version: 1810
 Date calculated: 11/06/2019 10:48 AM


Full Report
 Registration: SFH2125Y
 Printed: 11/06/2019 10:48 AM

Vehicle Condition

Vehicle Status
 Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
54-1011 01	SHORT TEST INCLUDES: CONNECT + DISCONNECT STAR DIAGNOSIS, PRINT DATA, DELETE ERROR MEMORY		3.0	13.50
88-1140 02	R + R COMPLETE FRONT BUMPER INCLUDES: R + R RADIATOR COWL		7.0	31.50
82-4791 02)	RENEW L/F LAMP UNIT (BUMPER DETACHED)		5.0	22.50
0283	FRONT BUMPER COVER REPAIR		30.0*	135.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		4.50	45.0	202.50
Total of Labour				202.50

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: 190196
 Version: 1810
 Date calculated: 11/06/2019 10:48 AM

Full Report
 Registration: SFH2125Y
 Printed: 11/06/2019 10:48 AM

Paint

Paint Work		Time Basis 10WU/h	
Code	Description - CLEAR COAT HARD	WU	Price SGD
98-1731 01	FRONT BUMPER COVER PAINTING	11.0	49.50
98-2416 01	L/F WING PAINTING STAGE II	5.0	22.50
98-1340 01	PREPARATION WORK FOR TWO COAT PAINTING OF FITTED BODY PARTS	15.0	67.50
98-1356 01	ADD/WORK FOR PLASTIC PARTS	3.0	13.50
98-1620 ZAX	PRIME PLASTIC/METAL PARTS	3.0	13.50
98-1630 ZAX	APPLY SMOOTHG FILLER ON PLAST/MET PARTS	3.0	13.50
98-1625 ZAX	REPAIR/APPLY FILLER ON PLAST/METAL PARTS	2.0	9.00
98-1620 ZAX	APPLY PRIMER FRONT BUMPER (ADD/WORK)	1.0	4.50
98-1630 ZAX	APPLY FILLER FRONT BUMPER (ADD/WORK)	1.0	4.50
98-1625 ZAX	APPLY FILLER PASTE FRONT BUMPER (ADD)	3.0	13.50

Total Paint	Hrs	WU	Price SGD
	4.70	47.0	211.50

Material Cost - Paint	Price SGD
Repair Painting	35.97
Surface-/Blend Paint	9.45
Material-constant Metal	13.47
Total	58.89

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
0561	LEFT HEADLAMP ASSY	212 820 2539		2,365.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			2,365.00
u: Used parts	Addition(+10.00%)			236.50
	Total			2,601.50

Extras

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: 190196
 Version: 1810
 Date calculated: 11/06/2019 10:48 AM

Full Report
 Registration: SFH2125Y
 Printed: 11/06/2019 10:48 AM

Code	Description	Price SGD
1000	ONLNE PROGRAM L/HDLP ONLINE PROGRAM	250.00*
	Total Extras	250.00

Final Calculation

	SGD	SGD
Parts	2,365.00	
Addition(+10.00%)	236.50	
Total Parts		2,601.50
Labour Time Base 10 WU/h		
Total 45.0 WU X 45.00 SGD/h	202.50	
Total of Labour		202.50
Total Of Extras		250.00
Paint Work Time Base 10 WU/h		
Labour Cost 47.0 WU X 45.00 SGD/h	211.50	
Material Cost	58.89	
Total Paint Including Material		270.39
Repair Cost Excludes GST		3,324.39
GST (+7.0%)		232.71
Repair Cost Included GST		3,557.10

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
TEL NO : 64523938 (6 LINES) FAX NO : 64527936
A/C DEPT : 64590882
Business Reg & GST NO : 201512120M



0228254

TAX INVOICE

REPRINT

K.KIM HIN AUTO PTE LTD
BLK160 SIN MING DRIVE
#02-18/19/20/21 SIN MING AUTOCITY
S'PORE 575708
REMARK : VEH NO.SFH2125Y

DELIVER TO :
ENGINE #02-18/19
BODY PARTS #02-20/21

INV NO : I228254
DATE : 02/05/2019
A/C NO : 304710
TERM : 60
PAGE : 1 OF 1
ISSUE : APS

Printed on 02/05/2019 09:48:18

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT
1	212 820 2539MB	HEAD LAMP UNIT LH <i>CRA</i> ✓	3W2A05	1	PCS	2,365.0	2,365.00

RECEIVED BY

PICKED BY: 8514

SUB-TOTAL : S\$ 2,365.00
ADD 7% GST : S\$ 165.55
TOTAL : S\$ 2,530.55

Goods sold are not returnable except Repairs/Service at authorized workshop.