

VOLKSWAGEN CENTRE SINGAPORE

Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Volkswagen



SKODA



Commercial Vehicles

Quotation

Non binding - Preview

Page 1/1

Company
AXA Insurance Pte Ltd
8 SHENTON WAY
#27-01 AXA TOWER
Singapore 068811

Customer Details:
Ms.
WONG
KIM LAN
582 PASIR RIS STREET 53
#11-17
Singapore 510582

Document no.
Document date 18-04-2019
Customer no. 5211000859
Customer GST-ID 196900406D
Dealer 39999
Job order number 2019000256/ 1
Job order date 18-04-2019
Service Advisor TIOW CHUAN CHEE

License plate	Model code	First registration	VIN	Model	Mileage
SKH8830X	1T32B4	25-01-2013	WVGZZZ1TZDW038605	Touran 1.4 Trend 103 TSID7F	106,681

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	B&P MECH	1	pcs.	200.00	#1	200.00	214.00
	LABOUR <i>Sfo</i>	3	pcs.	580.00	#1 <i>580</i>	1,740.00	1,861.80
	B&P Diagnostic and Programming	1	pcs.	360.00	#1	360.00	385.20
	B&P REVERSE SENSOR	1	pcs.	400.00	#1	400.00	428.00
	SPRAY PAINT <i>Sfo</i>	3	pcs.	500.00	#1 <i>750</i>	1,500.00	1,605.00
1T0807421K GRU	Cover For Bumper Primed <i>DD</i>	1	pcs.	1,242.02	#1	1,242.02	1,328.96
1T0807521H GRU	REAR BUMPER						
	Spoiler Primed <i>X R</i>	1	pcs.	467.43	#1	467.43	500.15
	SPOILER						
1T0807441C GRU	Cover For Towing Eye Prim <i>X R</i>	1	pcs.	51.21	#1	51.21	54.79
	TOW COVER						
1T0807305D	Bumper	1	pcs.	663.28	#1	663.28	709.71
	REINFORCEMENT <i>?</i>						
1T0807863D	Attachment Strip	1	pcs.	61.67	#1	61.67	65.99
	RR CENTRE BRACKET <i>?</i>						
1T0807454	Guide Piece	1	pcs.	36.27	#1	36.27	38.81
	RHR TAILLIGHT BRACKET <i>?</i>						
1T0807394D	Guide Piece	1	pcs.	29.49	#1	29.49	31.55
	RHR SIDE BRACKET <i>?</i>						
1T0945106C	Reflector	1	pcs.	68.93	#1	68.93	73.76
	RH <i>cut</i>						

Quotation valid till 25-04-2019

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
		6,820.30	7%	477.42	6,820.30	7,297.72
		6,820.30		477.42	6,820.30	7,297.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

Service Advisor

Stew (LKK)
8322 8813
stewchen@lkk.sg.com

WHL M/4011 24/4/19, 10.30 am
3 chgs
P/P
Rery bef spray