

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD

8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

Estimate No: ES1991430/WS

Date: 23 Apr 2019

Policy No: MA003590

Veh Reg No: SME2901G

Make/Model: AUDI A1 1.4TFSI S-TRONIC

Chassis No: WAUZZZ8X0CB028082

Engine No: CAX943102

Reg. Date: 19/01/2012

WS Ref: TP-AXA

Claim Type: Third Party

Accident Date: 20/04/2019

TP Veh Reg No: SLN8968P

Not Authair

11 Sep @?

Penny After Paint

4 days

Estimate Repair Cost to Vehicle No :SME2901G

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER	652.11	1 PC	<i>Buo</i> 652.11	<i>✓</i>
2 FRONT BUMPER INNER SPONGE RH	96.57	1 PC	<i>CM</i> 96.57	<i>✓</i>
3 HEADLAMP RH	960.77	1 PC	<i>CM</i> 960.77	<i>✓</i>
4 RH HEADLAMP LOWER BRACKET	96.45	1 PC	<i>CM</i> 96.45	<i>✓</i>
5 WIPER TANK	197.32	1 PC	<i>BU</i> 197.32	<i>✓</i>
6 FRONT RH FENDER	766.86	1 PC	<i>Buc</i> 766.86	<i>✓</i>
7 FRONT RH FENDER INNER SHIELD	164.31	1 PC	<i>CM</i> 164.31	<i>✓</i>
8 FRONT BUMPER FOG LAMP RH	245.15	1 PC	<i>mgcm</i> 245.15	<i>✓</i>
9 FRONT BUMPER RH FOG LAMP GARNISH	179.80	1 PC	<i>mi's</i> 179.80	<i>✓</i>
			3,359.34	
		Less 10%	335.93	3,023.41
Labour				
10 TO PANEL BEATING	800.00	1 LA	800.00	<i>5501</i>
11 TO PUTTY AND RESRPAY PAINTING	800.00	1 LA	800.00	<i>6401</i>
12 TO RE-PROGRAMME ECU SYSTEM	200.00	1 LA	200.00	<i>?</i>
			1,800.00	1,800.00
			Total	S\$ 4,823.41
			Add GST @ 7%	337.64
			Total Amount Payable	S\$ 5,161.05

For Cheng Hoe Motor Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE