



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:YVONNE			Ref: CC4/ASM19007116/Kbs3q2 Date: 17/05/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	PA 928D	Veh. Inspected	SKW 8933D	
Policy No.	P1918643	Coverage (\$)	0.00	
Claim No.	S9M01L3D	Excess (\$)	0.00	
Assign From		Assign Date	23/04/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	NISSAN QASHQAI (A)	c.c	1197	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	SJNFEAJ11U1491683	Colour	METALLIC RED	
Odometer	11686 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	CONTINENTAL	9 mm	
L/H Front Tyre	215/60 R17	CONTINENTAL	9 mm	
R/H Rear Tyre	215/60 R17	CONTINENTAL	9 mm	
L/H Rear Tyre	215/60 R17	CONTINENTAL	9 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	20/04/2019	Inspection Date	23/04/2019	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD BLK C, 3RD FLOOR SINGAPORE 579701.			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>5 Working Days</b>	