

ASS. REC. BY:

REF: CS/MSG19007118/UQD39

Special Instruction:

Survivor: Marcus

ASSIGNMENT (Office)

From (Person): Chia Nque Pui

of MSIG

Date/Time: 22.4.2019 17.22p.m

Estimated Cost:

Bill to:

OD TP WS TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLJ 1564 M

Insured: FT 1245 C

at Workshop m/s Liu's Brother Auto

Tel: 67411730

of BIC 1 Kaki Bukit Ave 6, #01-01

Policy No: MSD/VMT/19-997672-WTT

Claim No: MSC/V/19-000425

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 13.4.2019

CA / REV / REP. / REV 24 HRS

mvp"

H.O.D. Endorsement:

Date/Time: 23.4.2019

Person Contacted: Susan

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate:

SLJ 1564 M - NA / CTI 190066201 h4

D.O.A. - 13/04/2019

FT 1245 C - NA / CTI 190066201 h4

D.O.A. - 13/04/2019

24/4/19 @ 2.24pm referred to Chia Nque Pui via Meamam.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: *SLJ 1564M*at Workshop m/s *11's 20*

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *3* days Res.: Yes or NoLum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *SLJ 1564M* Yr Regn: *11, 16*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *CA*Make: *Chevrolet ORLANDO cc 1362*Colour: *white* A/C: Insured / Std / NI / NASp. Reading: *38767* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *KL1YA7589HK608368*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *245/60R16*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *FALKEN*

Front

Rear

R/Bal. *7* mm R/Bal. *7* mmL/Bal. *7* mm L/Bal. *7* mmD.O.A. *13/4/19* D.O.I. *22/4/19*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

26/4/19 Confirmed 4/5 @ 3750 with Suban.
(Red: 4118, 52%)

[Signature]
26/4/2019

RECEIVED 26 APR 2019.

Date/Time, File Pass to?

☐

Prel. Report

1) *26/4 Tmpst*☒

Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: *3*Resurvey No. of Trip: *2*

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$Report Format: *TP*Lump Sum / I.B.I. (\$) *31507-*

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Apr 2019		22 Apr 2019 17:32 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by Insurer]							
Insured:	BALAKRISHNAN S/O PERIATHAMBY NAGAR, ID: S0242177A, Tel: +6581802204, Email: NOEMAIL								
Main Claimant:	CASTOR & WHEEL (SINGAPORE) PTE LTD, Co. Reg. No.: 198300787H								
Vehicle Reg. No.:	SLJ1564M	Date of Loss:	13/04/2019 13:00 - :59 [28 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/19-000425	Policy/Cover Note No.:	MSD/VMT/19-997672-WTT (Third Party Only) Coverage: 22/02/2019 - 21/02/2020						
Vehicle Reg. No. (Insured):	FT1245C	Policy No. (Claimant):							
		Excess:							
Repairer:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/04/2019]								
Driver/Custodian (Insured):	BALAKRISHNAN S/O PERIATHAMBY NAGAR (68 / Male), NRIC: S0242177A, Tel: +6581802204 Email: NOEMAIL								
Adj Asg. Remarks:	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK. LIABILITY:100% CONTACT: SUSAN LOW 6741 1730								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co,Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 24 Apr 2019

Preliminary Advice

Insured Vehicle No	: FT1245C	Accident Date	: 13/04/2019
TP Vehicle No	: SLJ1564M	Assignment Date	: 22/04/2019
Make	: CHEVROLET ORLANDO	Est. Duration of Repair	: 3.00
Date of Inspection	: 22/04/2019		
Inspection At	: LIU'S BROTHER AUTO ENGINEERING WORKSHOP (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,868.00
Revised Amount	:S\$	4,703.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,703.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0787H
Vehicle Details	
Vehicle No.:	SLJ1564M
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Apr 2019
Vehicle Make:	CHEVROLET
Vehicle Model:	ORLANDO 1.4AT TURBO
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	A14NET162660012
Chassis No.:	KL1YA7589HK608368
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$15,693.00
Original Registration Date:	29 Nov 2016
First Registration Date:	29 Nov 2016
Transfer Count:	1
Actual ARF Paid:	\$15,693.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Nov 2026
PARF Rebate Amount:	\$11,769.00
Intended COE Rebate Details	
COE Expiry Date:	28 Nov 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$56,340.00
COE Rebate Amount:	\$42,802.00
Total Rebate Amount:	\$54,571.00

The information contained herein is correct as at 23 Apr 2019

OK



ANNOUNCING Speedo Motoring as sgCarMart Premium Dealer for the 8th Consecutive Year

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Up To 100% Loan. 1 Owner. Under Agent Warranty.



Very Low Mileage Done. Original
Paintwork. Deluxe Model. Call
Now.
SKL Automobile [StarAd](#)


[Browse by Category](#)
[Sort by Date Posted](#)

6 vehicles

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	Chevrolet Orlando		Any	Any	2016	Any	Any	
	Chevrolet Orlando 1.4A Turbo LS		\$71,888	\$8,300 /yr	29-Dec-2016	1,362 cc	42,700 km	
Flexi-Loan Available. From \$1,030/Month. Genuine Low Mileage, Fully Serviced And Maintained By Agent. Valid Agent Warranty Till 2021 With Family In Mind: Handsome SUV Styling, Great Space, P...								
Cars 88 Pte Ltd								
Posted: 18-Apr-2019 Tags: 2016 Chevrolet Orlando, 2016 chevrolet orlando, Chevrolet Orlando, chevrolet orlando, Chevrolet, Orlando, orlando, Used Chevrolet								
	Chevrolet Orlando 1.4A Turbo LS		\$72,800	\$8,450 /yr	20-Dec-2016	1,362 cc	60,000 km	
One Owner, New Paint, 90% Loan Of Car Price Available. Fully Serviced & Maintained By Agent. Still Under Agent Warranty.Handsome 5 Great Space, Practical & Comfortable With 3rd Row Seats. E...								
Posted: 18-Apr-2019 Tags: 2016 Chevrolet Orlando, 2016 chevrolet orlando, Chevrolet Orlando, chevrolet orlando, Chevrolet, Orlando, orlando, Used Chevrolet								
	Chevrolet Orlando 1.4A Turbo LS		\$66,888	\$8,400 /yr	18-Apr-2016	1,362 cc	78,106 km	
Cheapest In Town! Full Agent Maintain 5 Years Agent Warranty Till April/2021! Full Agent Maintain! In House Loan Or Bank Loan Availat Flexible Loan Approval! Buy With Confidence! Viewing B...								
Posted: 18-Apr-2019 Tags: 2016 Chevrolet Orlando, 2016 chevrolet orlando, Chevrolet Orlando, chevrolet orlando, Chevrolet, Orlando, orlando, Used Chevrolet								
	Chevrolet Orlando 1.4A		\$64,000	\$8,110 /yr	26-Feb-2016	1,362 cc	92,000 km	
One Careful Owner, Full Agent Maintain Records, 5 Years Unlimited Mileage Warranty. Accident Free, 7 Seaters MPV, Call Now To Book Appointment To View This Beauty. Viewing Strictly Appointment Base...								
Posted: 09-Apr-2019 Tags: 2016 Chevrolet Orlando, 2016 chevrolet orlando, Chevrolet Orlando, chevrolet orlando, Chevrolet, Orlando, orlando, Used Chevrolet								
	Exterior Premium Package (Small Vehicle)							
Premium package polishing and coat sealant. Call us to find out more on our different packages.								
Find out more!								
	rolet Orlando 1.4A Turbo		\$70,000	\$8,500 /yr	11-Aug-2016	1,362 cc	32,000 km	

[Compare](#)

rest At 2.28%, Extremely Well Maintained! This Beast Does Not Just Look Beautiful, It's 100% Accident Free. View To Believe!



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-061655
Date of Request: 18/04/2019

Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP
1 Kaki Bukit Ave 6 #01-01
Auto Bay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date: 18/04/2019
Enquiry By: Susan Low Siew Yian
TP Vehicle No: FT1245C
Accident Date: 13/04/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
FT1245C	MSIG Insurance (Singapore) Pte. Ltd.	22/02/2019-21/02/2020	+65 6827 7888

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available if soresed.

ACCIDENT STATEMENT

Date Of Report 15/04/2019 11:50
 Date Of Accident 13/04/2019 13:25
 Exact Location Of Accident BRADDELL RD SLIP RD INTO LOR 6 TOA PAYOH
 Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLJ1564M
 Insured/Policyholder
 Name Of Registered Owner CASTOR & WHEEL (SINGAPORE) PTE LTD
 Co Reg No -
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No OFFICE-67456944
 Vehicle Particulars
 Manufacturer CHEVROLET
 Model ORLANDO-1.4 TURBO (A)
 Exact Purpose for which vehicle was being used at time of accident QTW HOME
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR
 Insurance Company
 Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number DMPCSN3006421900
 Cover Note Number -
 Driver
 Name of Driver ONG MENG KEAT (WANG MINGJIE)
 NRIC No S8316733E
 Date Of Birth 06/05/1983
 Occupation OUTDOOR
 Date Of Driving Pass 12/07/2005
 Driving Experience 13 YEARS AND 9 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-91712250
 Fax Number
 Contact Number
 Email Address NOEMAIL

Approximate Age:

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode


BODY

SLJ1564M

YES

NO

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to statement of

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917531 Tel: 6741-1730 / 731 Fax: 6744-5746 Email: liusbros@gmail.com

Invoice/Ref No: SLJ1564M190413

Estimate

Customer	
No. ms: MSIG Insurance (Singapore) Pte Ltd	Date: 18-04-19
Address Motor Claims Department	Vehicle No: SLJ1564M
4 Shenton Way #21-01	Model/Make: Chevrolet
SGX Centre 2 Singapore 068807	Orlando 1.5AT Turbo

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bumper	\$ 1,340.00	
2	Bumper Lower 540	\$ 560.00	
3	Bumper Centre skirting 300	\$ 430.00	
4	Bumper Top	\$ 310.00	X
5	Bumper Reinforcement	\$ 670.00	
6	Bumper Reverse Sensor 2305.2	\$ 410.00	
7	Tail Lamp Rh 525	\$ 570.00	
8	Reflector Rh	\$ 335.00	X
9	"ORLANDO" Emblem	\$ 195.00	X
10	"TURBO" Emblem	\$ 98.00	X
10	"CHEVROLET" Emblem	\$ 140.00	X
10	Fender Side Garnish Rh 325	\$ 490.00	
10	Fender Cowling Rh 215	\$ 460.00	
	To check all wiring & electrical component for proper function	\$ 80.00	30
	Remove and refix rear bumper reverse sensor	\$ 120.00	50
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 800.00	400
	To putty & spray painting & including touch up paint on accident affected	\$ 800.00	500
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 60.00	10 X

Total Parts & Labour of estimate for damaged vehicle

\$7,868.00

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

6/543750

Not Authorized
LHKK
The photo after repair
3 days
22/4/19

P-3915
107
3523.5
4703.50
3762

LKF Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To do minor damaged parts during resurvey
- Parts replaced subject to confirmation
- That estimate is on a "Without Prejudice" basis
- No other work is to be done
- Supplementary charges must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Apr 2019		22 Apr 2019 17:32 Edit Adj Rpt	\$3,750.00 Edit Estimates	\$3,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	BALAKRISHNAN S/O PERIATHAMBY NAGAR, ID: 50242177A, Tel: +6581802204, Email: NOEMAIL								
Main Claimant:	CASTOR & WHEEL (SINGAPORE) PTE LTD, Co. Reg. No.: 198300787H								
Vehicle Reg. No.:	SLJ1564M	Date of Loss:	13/04/2019 13:00 - :59 [28 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/19-000425	Policy/Cover Note No.:	MSD/VMT/19-997672-WTT (Third Party Only) Coverage: 22/02/2019 - 21/02/2020						
Vehicle Reg. No. (Insured):	FT1245C	Policy No. (Claimant):							
		Excess:							
Repairer:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 22/05/2019]								
Driver/Custodian (Insured):	BALAKRISHNAN S/O PERIATHAMBY NAGAR (68 / Male), NRIC: 50242177A, Tel: +6581802204 Email: NOEMAIL								
Adj Asg. Remarks:	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK. LIABILITY:100% CONTACT: SUSAN LOW 6741 1730								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLJ1564M (MSC/V/19-000425)
[FT1245C]**

TP

CASTOR & WHEEL (SINGAPORE) PTE LTD

Apr 13 2019 1:00PM

[BALAKRISHNAN S/O PERIATHAMBY NAGAR]

Liu's Brother Auto Engineering Workshop

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)								Thumbnail	Print
1	22/04/19 11:53	Accident Statement From: SC - Reg. No: FT1245C, Claimant: BALAKRISHNAN S/O PERIATHAMBY NAGAR								Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	24/04/19 15:23	Adjuster Immediate Advice								Load HTM	
Photos/Images									3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	24/04/19 08:24	Chassis Number								Load JPG	
2	24/04/19 08:24	Odometer Reading								Load JPG	
3	24/04/19 08:25	General View								Load JPG	
4	24/04/19 08:25	General View								Load JPG	
5	24/04/19 08:25	General View								Load JPG	
6	24/04/19 08:25	General View								Load JPG	
7	24/04/19 08:25	General View								Load JPG	
8	24/04/19 08:25	General View								Load JPG	
9	24/04/19 08:25	General View								Load JPG	
10	24/04/19 08:25	General View								Load JPG	
11	24/04/19 08:25	General View								Load JPG	
12	24/04/19 08:25	General View								Load JPG	
13	24/04/19 08:25	General View								Load JPG	
14	24/04/19 08:25	General View								Load JPG	
15	24/04/19 08:25	General View								Load JPG	
16	24/04/19 08:25	General View								Load JPG	
17	24/04/19 08:25	General View								Load JPG	
18	24/04/19 08:25	General View								Load JPG	
19	24/04/19 08:25	General View								Load JPG	
20	24/04/19 08:25	General View								Load JPG	
21	24/04/19 08:25	General View								Load JPG	
22	24/04/19 08:25	General View								Load JPG	
23	24/04/19 08:25	General View								Load JPG	
24	24/04/19 08:25	General View								Load JPG	
25	24/04/19 08:25	General View								Load JPG	
26	24/04/19 08:25	General View								Load JPG	
27	24/04/19 08:25	General View								Load JPG	
28	24/04/19 08:25	General View								Load JPG	
29	24/04/19 08:25	General View								Load JPG	
30	24/04/19 08:25	General View								Load JPG	
31	24/04/19 08:25	General View								Load JPG	
32	24/04/19 08:25	General View								Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				☒
33	24/04/19 08:25	General View	Load JPG	☒
34	24/04/19 08:25	General View	Load JPG	☒
35	24/04/19 08:25	General View	Load JPG	☒
36	24/04/19 08:25	General View	Load JPG	☒
37	24/04/19 08:25	General View	Load JPG	☒
38	24/04/19 08:25	General View	Load JPG	☒
39	24/04/19 08:25	General View	Load JPG	☒
40	24/04/19 08:25	General View	Load JPG	☒
41	24/04/19 08:25	General View	Load JPG	☒
42	24/04/19 08:25	General View	Load JPG	☒
43	24/04/19 08:25	General View	Load JPG	☒
44	24/04/19 08:25	General View	Load JPG	☒
45	24/04/19 08:25	General View	Load JPG	☒
46	24/04/19 08:25	Reinspection Photo	Load JPG	☒
47	24/04/19 08:25	Reinspection Photo	Load JPG	☒
48	24/04/19 08:25	Reinspection Photo	Load JPG	☒
49	24/04/19 08:25	Reinspection Photo	Load JPG	☒
50	24/04/19 08:25	Reinspection Photo	Load JPG	☒
51	24/04/19 08:25	Reinspection Photo	Load JPG	☒
52	24/04/19 08:25	Reinspection Photo	Load JPG	☒
53	24/04/19 08:25	Reinspection Photo	Load JPG	☒
54	24/04/19 08:25	Reinspection Photo	Load JPG	☒
55	24/04/19 08:25	Reinspection Photo	Load JPG	☒
56	24/04/19 08:25	Reinspection Photo	Load JPG	☒
57	24/04/19 08:25	Reinspection Photo	Load JPG	☒
58	24/04/19 08:25	Reinspection Photo	Load JPG	☒
59	24/04/19 08:25	Reinspection Photo	Load JPG	☒
60	24/04/19 08:25	Reinspection Photo	Load JPG	☒
61	24/04/19 08:25	Reinspection Photo	Load JPG	☒
62	24/04/19 08:25	Reinspection Photo	Load JPG	☒
63	24/04/19 08:25	Reinspection Photo	Load JPG	☒
64	24/04/19 08:25	Reinspection Photo	Load JPG	☒
65	24/04/19 08:25	Reinspection Photo	Load JPG	☒
66	24/04/19 08:25	Reinspection Photo	Load JPG	☒
67	24/04/19 08:25	Reinspection Photo	Load JPG	☒
68	24/04/19 08:25	Reinspection Photo	Load JPG	☒
69	24/04/19 08:25	Reinspection Photo	Load JPG	☒
70	26/04/19 10:31	Reinspection Photo	Load JPG	☒
71	26/04/19 10:31	Reinspection Photo	Load JPG	☒
72	26/04/19 10:31	Reinspection Photo	Load JPG	☒
73	26/04/19 10:31	Reinspection Photo	Load JPG	☒
74	26/04/19 10:31	Reinspection Photo	Load JPG	☒
75	26/04/19 10:31	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/04/19 11:53	TP E-file report From: SC - Reg. No: FT1245C, Claimant: BALAKRISHNAN S/O PERIATHAMBY NAGAR	Load PDF	
2	22/04/19 11:53	SLJ1564M GIA Search	Load PDF	
3	22/04/19 13:01	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK	Load PDF	
4	23/04/19 10:32	Valid Driving Licence	Load PDF	

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19007118/UQD3Q2

Date: 06/05/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/19-997672-WTT
Claimant Vehicle No :	SLJ1564M	Insured Vehicle No :	FT1245C
Date of Loss:	13/04/2019	Nature of Claim:	TP
		Claim No:	MSC/V/19-000425

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ1564M	Engine No:	A14NET162660012
Make & Model:	CHEVROLET ORLANDO, 1.4 Turbo (A)	Chassis No:	KL1YA7589HK608368
Reg. Date:	29/11/2016 (Man. Year: 2016)	Odometer:	38767 km
Colour:	White		
Engine Capacity:	1362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Falken 7 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Falken 7 mm	Rear Right Side:	Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,008.00	3,723.50	2,284.50	38.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,860.00	980.00	880.00	47.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,868.00	4,703.50	3,164.50	40.22
Approved Total (Overridden) (S\$)		3,750.00		
Nett Amount (S\$)	7,868.00	3,750.00	4,118.00	52.34

INSPECTION

Date of Assignment:	22/04/2019	
Date Inspected:	22/04/2019 Inspected At:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 May 2019)
Parts:	M1-MPV	CHEVROLET ORLANDO 1.4 Turbo (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ1564M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,340.00 F	*1,340.00 FL
2	1		*REAR BUMPER LOWER	Deformed / Torn	560.00 F	*540.00 FL
3	1		*REAR BUMPER CENTRE SKIRTING	Deformed /Cracked	430.00 F	*300.00 FL
4	1		*REAR BUMPER TOP	Not Necessary	310.00 F	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	670.00 F	*670.00 FL
6	1		*REAR BUMPER REVERSE SENSOR	Shorted	410.00 FS	*200.00 FS
7	1		*REAR TAIL LAMP RH	Scratched	570.00 F	*525.00 FL
8	1		*REAR REFLECTOR RH	Serviceable	335.00 F	*- FL
9	1		*REAR ORLANDO EMBLEM	Not Necessary	195.00 F	*- FL
10	1		*REAR TURBO EMBLEM	Not Necessary	98.00 F	*- FL
11	1		*REAR CHEVROLET EMBLEM	Not Necessary	140.00 F	*- FL
12	1		*REAR FENDER SIDE GARNISH RH	Deformed / Torn	490.00 F	*325.00 FL
13	1		*REAR FENDER COWLING RH	Torn	460.00 F	*215.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,008.00	4,115.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	391.50
Total Parts (\$\$)	6,008.00	3,723.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	80.00	30.00
2	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR	New	120.00	50.00
3	LABOR FOR PANEL BEATING,CUT,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	800.00	400.00
4	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	800.00	500.00
5	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	60.00	0.00
Gross Labour Cost (S\$)			1,860.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >