

22/03/2002

ASS. REC. BY:

REF: CS/Smo1907124/ J4 d30p

Special Instruction:

Surveyor: Hui Jie

ASSIGNMENT (Office)

Minim

From (Person): Huang shiang yi

of Smo

Date/Time: 23.4.2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FX 6561K

Insured: SLD 8568M

at Workshop m/s Lian chin Hung motor

Tel: 67586609

91445487

of BIR 22 woodland link # 01-35

82008888

Policy No: DIA M T R E N T 000119

Claim No: CMID 1900569

Jason.

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 10.01.2019

24.4.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 23.4.2019 3.33pm

Person Contacted: Jason

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

FX 6561K - x

SLD 8568M - x

25/4@16:20pm - sent compose mail to shangyi pending estimate

unconfirm lump sum \$1400/- (Red: 1423, 50%)

Surveyor Huei Jie

REF: Smo

ASSIGNMENT

From: _____ Date: 24.4.2019

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: Px6561K

at Workshop m/s Lian Chin Heng Motor
of BIR 22 Woodlands Link #01-35

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

"wp"

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: Px6561K Yr Regn: 30 Jan 2004

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Piaggio X9 c.c. 198

Colour: Black A/C: Insured / Std / NI / NA

Sp.Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2APM2300004010171

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70 R14

R: 140/70 R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. - mm L/Bal. - mm

D.O.A. 10/1/19

D.O.I. 24/4/19

Survey held at Lian Chin Heng

Des. of Damages: (Frt) / Rear / O/S / (N/S) / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
24/4/19	Waiting for repairer email estimate.

Waiting for workshop to agree with finalized amount

RECEIVED 22 JUL 2019

Date/Time, File Pass to?

1) 22/7 Typist

Date/Time, File Return to?

2) _____

Report Format :

TP

Lump Sum / I.B.I. (\$) 11400

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

☐ S + RS, ☐ SI

Photos

Others

TOTAL

250

11

261

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jan 2019		23 Apr 2019 15:21 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	ETHOZ GROUP LTD, Co. Reg. No.: 198104531H		
Main Claimant:	TAN KIM CHYE THOMAS, ID: S1747736F		
Vehicle Reg. No.:	FX6561K	Date of Loss:	10/01/2019 18:00 - :59
Claim Type:	TP / CMTD1900569	Policy/Cover Note No.:	D19MTRENT000119 (Third Party Only)
Vehicle Reg. No. (Insured):	SLD8568M	Policy No. (Claimant):	
		Excess:	
Repairer:	Lian Chin Heng Motor & Carriage (woodlands) (HQ) BLK 22 WOODLANDS LINK #01-35, 738734 Woodlands - Tel: 67586609		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/05/2019]		
Driver/Custodian (Insured):	JOHN BASHA AKBAR BASHA (), NRIC: S7881342C, Tel: +6590096095 Email:		
Adj Asg. Remarks:	WS: JASON 8200 8888		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***FX6561K (CMTD1900569)**
[SLD8568M]

TP

TAN KIM CHYE THOMAS

Jan 10 2019 6:00PM

[ETHOZ GROUP LTD]

Lian Chin Heng Motor & Carriage (woodlands)

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 25/04/2019 16:25 PM.
To shiangyi.hwang@sompo.com.sg
Subject FX6561K (CMTD1900569) [SLD8568M] TP

Dear Shang Yi,

Please be informed that we have inspected the vehicle SKG 3737X on 15/12/2017
We are pending estimate from repairer.

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/01/2019 17:14
Date Of Accident	10/01/2019 18:20
Exact Location Of Accident	WOODLANDS AVE 5 (OUTSIDE CIVIL CENTRE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FX6561K
Insured/Policyholder	
Name Of Registered Owner	TAN KIM CHYE THOMAS
NRIC No	S1747736F
Email Address	TANTHOMAS@YAHOO.COM
Mobile Phone No	(LOCAL) +65-96876586
Alternative Phone No	OFFICE-67557727

Vehicle Particulars

Manufacturer	PIAGGIO
Model	X9 200-198CC EVO (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5094129277-01
Cover Note Number	

Driver

Name of Driver	TAN KIM CHYE THOMAS
NRIC No	S1747736F
Date Of Birth	21/02/1966
Occupation	INDOOR
Date Of Driving Pass	18/05/1984
Driving Experience	34 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96876586
Fax Number	
Contact Number	OFFICE-67557727
EMail Address	TANTHOMAS@YAHOO.COM

Address	APT BLK 348 WOODLANDS AVENUE 3 #13-81 SINGAPORE
Postcode	730348
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLD8568M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	JOHN BASHA
NRIC/Passport Number	
Contact Number	90096095
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) Involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 11/1/19
14:50hrs


Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 10th Jan 2019, Thursday @ 12hr 20m. I am travelling straight along Woodlands Ave 5, outside Woodland Civic Centre. When a car number Plate SLD 8568M Suddenly come out from the service road into the left most lane. I could not stop in time and bang into the rear right side of the Passenger door. I fell down and my bike pin down on me.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 11/1/19
14 50hrs.

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7736F
Vehicle Details	
Vehicle No.:	FX6561K
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Apr 2019
Vehicle Make:	PIAGGIO
Vehicle Model:	X9 200 EVO A
Primary Colour:	Black
Manufacturing Year:	2003
Engine No.:	M236M11601
Chassis No.:	ZAPM2300004010171
Maximum Power Output:	-
Open Market Value:	\$3,451.00
Original Registration Date:	30 Jan 2004
First Registration Date:	30 Jan 2004
Transfer Count:	5
Actual ARF Paid:	\$518.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jan 2024
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,797.00
COE Rebate Amount:	\$855.00
Total Rebate Amount:	\$855.00

The information contained herein is correct as at 25 Apr 2019

OK



Lian Chin Heng Motor & Carriage

Company Reg No: 38457700L GST Reg No.: M90370716G
Showroom: Blk 731 Yishun Street 72 #01-43 Singapore 760731
Tel: 6754 6922 Fax: 6755 6985
Service Centre: Blk 22 Woodlands Link #01-35 Singapore 738734
Tel: 6758 6609 Email: lchmotor@singnet.com.sg

26.04.2019

Vehicle **FX6561K**

Sompo Insurance Singapore Pte Ltd
Claims Department
50 Raffles Place
#50-01/06
Singapore Land Tower
Singapore 048623

Dear Sir,

RE: Estimate Repair Bill for FX6561K Piaggio X9

Date of Accident: 10th January 2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1 Pc	Centre Shield Inner	CRA ✓	\$ 485.00
1 Pc	Lower Under Cover	CRA ✓	\$ 360.00
1 Pc	Handler Bar	DM ✓	\$ 260.00 130
1 Pc	Mirror	CRA ✓	\$ 280.00 120
1 Pc	Signal FT	SCR ✓	\$ 85.00
	Subtotal of the above		\$ 1,470.00
	Discount 10%		\$ 147.00
	Subtotal 1		\$ 1,323.00
1 Pc	Number Plate	nxx	\$ 50.00
1 Pc	Fork Alignment	rec ✓	\$ 160.00 60
1 Set	Steering Bearing	rec ✓	\$ 145.00 70
	Paint Work		\$ 750.00 300
	Workmanship		\$ 350.00 250
	Towing		\$ 45.00 30

Total Repair Cost: \$ 2,823.00
7% Gst \$ 197.61

Total Repair Cost \$ 4,520.61

Sin Dollar Three Thousand and Seventy Dollars and Cents Sixty-One only.

Manager

Total - \$1400/-

Hwee Jie - LKK
L/S 3days
ay

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jan 2019		23 Apr 2019 15:21 Edit Adj Rpt	S\$1,400.00 Edit Estimates	S\$1,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ETHOZ GROUP LTD, Co. Reg. No.: 198104531H								
Main Claimant:	TAN KIM CHYE THOMAS, ID: S1747736F								
Vehicle Reg. No.:	FX6561K	Date of Loss:	10/01/2019 18:00 - :59 [179 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1900569	Policy/Cover Note No.:	D19MTRENT000119 (Third Party Only)						
Vehicle Reg. No. (Insured):	SLD8568M	Policy No. (Claimant):							
		Excess:							
Repairer:	Lian Chin Heng Motor & Carriage (woodlands) (HQ) BLK 22 WOODLANDS LINK #01-35, 738734 Woodlands - Tel: 67586609								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 03/05/2019]								
Driver/Custodian (Insured):	JOHN BASHA AKBAR BASHA (), NRIC: S7881342C, Tel: +6590096095 Email:								
Adj Asg. Remarks:	WS: JASON 8200 8888								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FX6561K (CMTD1900569)**
[SLD8568M]



















TP

TAN KIM CHYE THOMAS

Jan 10 2019 6:00PM

[ETHOZ GROUP LTD]

Lian Chin Heng Motor & Carriage (woodlands)

Upload Documents		Upload Photos		Compose New Letter		View View in Browser	
Assessment Reports						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail		Print	
1	23/04/19 15:22	Accident Statement From: SC - Reg. No: SLD8568M, Claimant: ETHOZ GROUP LTD		 Load HTM			
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail		Print	
1	25/04/19 09:12	General View		 Load JPG		<input checked="" type="checkbox"/>	
2	25/04/19 09:12	General View		 Load JPG		<input checked="" type="checkbox"/>	
3	25/04/19 09:12	General View		 Load JPG		<input checked="" type="checkbox"/>	
4	25/04/19 09:12	General View		 Load JPG		<input checked="" type="checkbox"/>	
5	25/04/19 09:12	General View		 Load JPG		<input checked="" type="checkbox"/>	
6	25/04/19 09:12	General View		 Load JPG		<input checked="" type="checkbox"/>	
7	25/04/19 09:12	General View		 Load JPG		<input checked="" type="checkbox"/>	
8	25/04/19 09:12	General View		 Load JPG		<input checked="" type="checkbox"/>	
9	25/04/19 09:12	General View		 Load JPG		<input checked="" type="checkbox"/>	
10	25/04/19 09:12	General View		 Load JPG		<input checked="" type="checkbox"/>	
11	25/04/19 09:12	General View		 Load JPG		<input checked="" type="checkbox"/>	
12	25/04/19 09:12	General View		 Load JPG		<input checked="" type="checkbox"/>	
13	25/04/19 09:12	General View		 Load JPG		<input checked="" type="checkbox"/>	
14	25/04/19 09:12	General View		 Load JPG		<input checked="" type="checkbox"/>	
Documentation						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail		Print	
1	17/04/19 15:41	FAX PRI DATED 17.04.19 FROM ARC CLAIMS - FX6561K		 Load PDF			
2	23/04/19 15:16	Pre-Repair Survey - AGREED LKK		 Load PDF			
3	23/04/19 15:18	Third Party E-filed GIA report(M)		 Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19007124/JTD3E2

Date: 23/07/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTRENT000119
Claimant Vehicle No :	FX6561K	Insured Vehicle No :	SLD8568M
Date of Loss:	10/01/2019	Nature of Claim:	TP
		Claim No:	CMTD1900569

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FX6561K	Engine No:	M236M11601
Make & Model:	PIAGGIO X9 200, 198cc EVO (A)	Chassis No:	ZAPM2300004010171
Reg. Date:	30/01/2004 (Man. Year: 2003)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70 R14	Rear Tyre Size:	140/70 R14
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,678.00	1,192.00	486.00	28.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,145.00	580.00	565.00	49.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,823.00	1,772.00	1,051.00	37.23
Approved Total (Overridden) (S\$)		1,400.00		
(S\$)	2,823.00	1,400.00	1,423.00	50.41
+ GST 7.00/7.00% (S\$)	197.61	98.00	99.61	50.41
Nett Amount (S\$)	3,020.61	1,498.00	1,522.61	50.41

INSPECTION

Date of Assignment:	23/04/2019	
Date Inspected:	24/04/2019 Inspected At:	Lian Chin Heng Motor & Carriage (woodlands) (HQ) BLK 22 WOODLANDS LINK #01-35 Singapore 738734
Estimated Period of Repair:	3.0 days	

Adjuster: ONG HWEE JIE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE REPAIRER IS INFORMED ON THE REVISED AMOUNT BUT NOT AGREED WITH OUR RECOMMENDATION.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 23 Jul 2019)	
Parts:	N/A	PIAGGIO X9 200 198cc EVO (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FX6561K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CENTRE SHIELD INNER	Cracked	485.00 FL	*485.00 FL
2	1		*LOWER UNDER COVER	Cracked	360.00 FL	*360.00 FL
3	1		*HANDLER BAR	Damaged	260.00 FL	*130.00 FL
4	1		*MIRROR	Cracked	280.00 FL	*120.00 FL
5	1		*SIGNAL FT	Scratched	85.00 FL	*85.00 FL
6	1		*NUMBER PLATE	Not Necessary	50.00 FS	*- FS
7	1		*FORK ALIGNMENT	Necessary	160.00 FS	*60.00 FS
8	1		*SET STEERING BEARING	Necessary	145.00 FS	*70.00 FS
					Sub Total (\$\$)	1,825.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	147.00
					Total Parts (\$\$)	1,678.00
						1,310.00
						118.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PAINT WORK	New	750.00	300.00
2	WORKMANSHIP	New	350.00	250.00
3	TOWING	New	45.00	30.00
Gross Labour Cost (S\$)			1,145.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >