CC21412014004122/ A202UJ (08/11/13) REF: ASS. REC. BY: MOTEL 253217 Cyr Regn: Date: From: Type(M.Carl M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Estimated Cosi: Truck / Trailer or OD / TP / WS / TP RES / OD RES / EVA / INV / MV 52×39536 Make: To Inspect Vehicle No: Insured / Std / NI / NA Colour at Workshop m/s T/Radio: Insured / Std / NI / NA Sp.Reading Eng/No: Insured: WBASA32000D3333967 C/No: Policy No. Gen. Cond: Good / Fair / Poor / Burnt Claims No. Steering: Inorder / Jammed / Leaked / Burnt or Excess: Sum Insured: Inorder / Jammed / Leaked / Burnt or (Client's Record) NIV I S/Rim L STD A/Rim or Make of Veh: Tyre Size: (Policy Condition) N/S 0/S Remark: The veh had commenced its repair at the time of inspection. TOYO / YOKO of Rear Front Bal. or Market Value: R/Bal R/Bal mm Consistent?: Yes or No IDAC Accident Roort: L/Bal. L/Bal. Consistent?: Yes or No GIA PR Seen D.O.I. D.O.A. 19/ Res.: Yes or No Est. Repairs: days 3 Val.: Yes or No Survey held at Lum Sum: Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or CA / REV / REP. / 24 HRS Vehicle: IN / OUT The U/C / Chassis frame / Body Structure affected due to collision. Person Contacted: Date: Date / Time Action / Instruction RECEIVED 0 7 May 2019 2 Days Of Repair: Preli. Report Survey Fee: Final Report Resurvey No. of Trip: 150 Transportation: 10 Add Fee: : Site Insp (\$ __S+RS,__SI Interview (\$ Photos Tech. Invs (\$ Others Report Format: Lump Sum / I.B.I: (\$ 2,500/_ 45) Weekend (\$ TOTAL 160

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

MSIG Insurance (Singapore) Pte. Ltd. To:

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Irene Tan Gek Ing

Date: 07 May 2019

Preliminary Advice

Insured Vehicle No : SLP7972Y

TP Vehicle No : SLX3953L

Accident Date

: 20/04/2019

Make

: BMW 520I

Assignment Date

: 07/05/2019

Date of Inspection

: 22/04/2019

Est. Duration of Repair

: 2 days

Inspection At

: Fastech Auto Pte Ltd (HQ)

1 Kaki Bukit Ave 6, #01-46/48/50 Autobay

Singapore 417883

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,322.40
Revised Amount	:S\$	3,199.54
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,199.54
Lump Sum Repair	:S\$	2,500.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

٠.	the state of the s			for someth
	1 The venicle i	s economical/not	economical	tor repair.

⁽ X) The above survey was conducted on a 'without prejudice' basis.

Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent:

Wednesday, 24 April 2019 2:45 PM

To:

'Irene Tan'; jinhao_tan@sg.msig-asia.com

Cc:

KKLau; SUR; Accounts (LKKAuto); yiqian_low@sg.msig-asia.com

Subject:

DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA:

19/04/2019, SLX 3953L (TP VEHICLE), SLP 7972Y (OI VEHICLE)

Attachments:

TP GIA REPORT.pdf

Dear Irene/Jin Hao,

Please be informed that we had inspected the vehicle SLX 3953L at M/s: FASTECH AUTO PTE LTD,1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 22/04/2019.

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | \$(408933)

Available

Available

Available

OTHER DESIGNATION.

Available

Luxury

Luxury

SGCARMART.COM Login Sign up Forum Resources New Cars Used Cars Sell My Car Directory Products Insurance Articles **E** AVIVA 18% off now, promo code: CAR18 Get a quote 2016 Mercedes Benz GLA180. Post an Advertisement HIN LUNG AUTO Sell it yourself! Advertise it at just Low Mileage, Immaculate Condition, C&C Unit. \$58 until it's SOLD! One Stop Car Hub Direct Owner Stanko **New and Used Cars** Advertiser Login Ways of Selling Post an Ad ✓ 20 results/page
✓ = Back (12) Next = Sort by Date Posted Browse by Category V 21 vehicles brnw 520 Advanced Search M Submit I Reg Date Eng Cap Model Arty Search Selection 2014 Available bmw 520 \$13,790 /yr Available BMW 5 Series 520i \$97,800 30-Jun-2014 1,997 cc 73,500 km Luxury 1 Owner Unit, Fully And Regularly Maintain By PMI, Free Servicing At PMI, Face-lift Model, Loan And Trade In Welcome, Come And Own This Unit, Postest: 23-Apr-2018 Tage: 2014 BMW 520, 2014 bms 520, BMW 520, bms 520, BMW, 520, Used BMW 1,997 € 86,000 km Available \$102,800 \$14,390 /vr 29-Aug-2014 Euroury BMW 5 Series 520i Highline Well Maintained. Excellent Condition, Well Taken Care Of By Previous Owner. Trade In/Loan Available! Hurry Call Or Visit Us Now For Further Details. Pollet: 31-Apr-2015 Tags: 3014 BMW 520, 2014 brow 520, BMW 520, brow 520, BMW, 530, Used BMW \$14,540 /yr 31-Mar-2014 1.997 cc 66,000 km Luxury Available BMW 5 Series 520i Luxury \$99,800 Promotional 2.28% Interest Rate! High Spec Luxury Model With High ARF \$54871, Facelifted BMW Adaptive LED Headlights With Digital Speedometer Display, Fully Service Record By PML Since Day 1! Posted: 30-Apr-2019 Tags: 2014 BNN 520, 2014 bmw 520, BMW 520, bmw 520, BMW, 520i, Used BMW





Best Deal In The Markett Rare Luxury Edition With Interior Ambient Lighting, Original BMW Front And Risar Recording Cameras, Reverse Camera And Many More Luxury Specs! In House/Bank Loan Available!

26-Sep-2014

30-May-2014

10-5ep-2014

1.997 cc

1,997 cc

1,997 cm

77,000 km

93,922 km

96,893 km

\$14,360 /vr

Posted: 20 Apr-2019 Tago: 2014 BMW 520, 2014 brow 520, 8HW 520, 6mw 520, 8MW, 520, Used BMW

\$103,800



Toyota Camry takes on Volkswagen's Passat

BMW 5 Series 520i Luxury

BMW 5 Series 520i Luxury

BMW 5 Series 520i

The Toyota Carnry offers more legroom for rear passengers, is sportier around corners and has more safety systems but the Volkswagen Passat is more affordable and feels more premium overall

\$14,780 /vr

Find out more!



(BMW Adaptive LED Headlights With Digital Speedometer Display). Easy And Flexible In-House Loan And Balloon Scheme Available, No Gimmickst Full PML Service Record, 1 Owner, GPS/Bluetooth, Keyless Entr...

Posted: 25-Apr-2019 Tags: 2014 BMW 530r, 2014 bmw 520r, 89W 520r, bmw 520r, 8MW, 520r, Used BMW



\$98,800

\$101,800

Graded B by 319 Low Interest Rate, 1 Year Warranty, Balloon Scheme, In-house Financing Available, Buy With A Peace Of Mind, 100% Genuine Mileage, No. Chassis/Structural Damage. Immaculate Condition. All Trade In Welco...

\$13,770 /yr

Posted: 20-Apr-2019 Tags: 2014 IMW 520; 2014 brow 520; BMW 520; brow 520; BMW, 520; Used BMW

Compare 57,900 km BMW 5 Series 520i Luxury \$105,800 \$14,860 /vr 30-Sep-2014 1,997 cc Luxury

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

/ehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	8250J
Vehicle Details	
Vehicle No.:	SLX3953L
Vehicle to be Exported:	No
ntended Deregistration Date:	02 Aug 2019
Vehicle Make:	B.M.W.
Vehicle Model:	520I AT D/AB 2WD 4DR LED NAV
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	B0660588N20B20B
Chassis No.:	WBA5A32000D333967
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$47,692.00
Original Registration Date:	27 Jan 2014
First Registration Date:	27 Jan 2014
Transfer Count:	1
Actual ARF Paid: Intended PARF Rebate Details	\$53,769.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jan 2024
PARF Rebate Amount:	\$37,638.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jan 2024
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$79,000.00
COE Rebate Amount:	\$35,401.00
Total Rebate Amount:	\$73,039.00

The information contained herein is correct as at 22 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Mobile Number Fax Number Contact Number EMail Address

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver,
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- Any false reporting may be referred to the Police for investigation.
 This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	22/04/2019 14:04
Date Of Accident	19/04/2019 00:10
Exact Location Of Accident	AT TECK LING ROAD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLX3953L
Insured/Policyholder	
Name Of Registered Owner	POH HUAT CAR SERVICES
Co Reg No	53318250J
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-88200034
Vehicle Particulars	
Manufacturer	BMW
Model	520I AT D/AB 2WD 4DR LED NAV
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	THE RESIDENCE OF THE PARTY OF T
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5100772419
Cover Note Number	
Driver	the second second second second second second
Name of Driver	GOH KAI LOON
NRIC No	S8739207D
Date Of Birth	19/11/1987
Occupation	OUTDOOR
Date Of Driving Pass	06/01/2009
Driving Experience	10 YEARS AND 3 MONTHS
Gender	MALE
	PACE AND THE PACE

(LOCAL) +65-88200034

NOEMAIL

Address

BLK 333D YISHUN STREET 31 #07-145

Postcode

764333

Was driver an employee of the Insured's Company NO

OTHER - SOLE-PROPIETOR

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLANI

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

WITH DRIVER

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLP7972Y

Vehicle Make/Model/Colour

TOYOTA VIOS 1.5E CVT

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withhelding of muterial facts may allow insurance companies to reputliste policy liability.
- The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesald.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, admowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Porsonal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpare(s)
 - processing, handling and/or dualing with my claims including the sottlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enguirles by me,
 - (iv) administering my dains (including the mailing of correspondence, statements, involves, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use; disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile daims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed;
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

2 2 APR 2019

Policyholder's Signature Date & Time: BI

Driver's Signature (If driver is not the policyholder) Dute & Time: 1DAC KAKI BUKIT(VAC) 23 KAKI BUKITAVE 4

Reporting Centra Personnel Str. 91.933 Name: Tel: 67416697 NRIC/FIN No.: Fax: 67492305

Fax: 67492305 Email: vackb@singnet.com.sg

SKETCH PLAN SLX3153L DESCRIBE CIRCUMSTANCES OF THE ACCIDENT the Stated date Suddenly veh: cle B neversed portion DECLARATION 2 2 APR 2019 I/We decla g particulars are true in every respect. IDAC KAKI BUKIT(VAC) 23 KAKI BUKIT AVE 4 Reporting Centre Petrol 1 (1593)
Name: Policyhalder's Signature Driver's Signature Date & Time: (If driver is not the policyholder)

Date & Time:

value the Carlos of

Name: Fux: 67492305 NHIC/FIN No.: Fux: 67492305 Email: vackb@singnet.com.sg

Date of Accident	: 19/4/19 Accident Time: 12.09am(24-HR-Format)
Accident Place	: At Teck Ling Road
Vehicle. No. (Car Plate No.)	:SLX 3953 L Make/Model: BMW COOT
Insurace Company	:_ N TUC Policy No:_ 5160772419
Owner or Company Name /IC No.	: Poh Hunt cor services / 533182501
Owner or Company Contact No.	7
DRIVER'S Name / IC No.	Goh Kai Lun / 58739207 D
DRIVER'S Date Of Birth	191 1.927
Relationship of Owner & Driver	: Sponse Parente Children City
DRIVER'S Address	: Sponse Parents Children Sibling Employee Others: : B K 333D
DRIVER'S Contact No./ Alt No.	382,00034
DRIVER'S Occupation	2) > 764335
Email Address	: INDOOR \ OUTDOOR (e.g. working inside or outside office)
Weather & Road Surface	CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
Reporting Type :	Reporting Only \ Claim Other Party \ Claim Own Insurance
Number of Passengers (Including Driv	er): 1 Driver
Was there any video Captured by car of Exact purpose for which vehicle was be Any Injury (If YES, Pis state):/	amera: YES \ NO eing used at the time of accident: Private use \ Work purpose
Other Par	ty Driver's Particular (if any)
Vehicle, No: SLP79709	(Ms(n) Vehicle, No:
Vehicle Make\Model:	Vehicle Make\Model:
Name Driver:	
C No. Driver/Contact:	
NIPEV II.	The Comment

^{*} NEW - Passenger's name & gender:

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature Date & Time: BI

Driver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

		N	of Authorisel
FASTECHA	UTO PTE LTD		Walk (
BLK1 KAKI E	BUKIT AVE 6		1 2 (7) 2/
#01-46,48,50	AUTOBAY		1/3 \$ 2500
SINGAPORE			F 22/4/19 2 d
VEHICLE NO:	SLX 3953L		10,0402 40
QTY	PARTICULAR		
1 PCS	REAR BUMPER /165.32		70/DE \$1,655.00
1 PCS	REAR BUMPER PDC SENSOR		AA \$313.00 X
1 PCS	REAR BUMPER SIDE HOLDER O/S		11 \$145.50 X
1 PCS	REAR BUMPER REINFORCEMENT JHE-LT		34 \$711.00
1 PCS	REAR BUMPER TOP RETAINER		44 \$315.00 X
1 PCS	REAR BUMPER LOWER COVER CENTRE 1/1.30	1	cru \$166.20
1 PCS	REAR BUMPER LOWER O/S COVER /64 . 20	161	C/m \$188.50
1 PCS	REAR END PANEL	136	\$1,018.20
			\$4,512.40
	LABOUR CHARGES:		- 4
	TO CHECK WIRING		\$80.00
	TO DISMANTLE & REFIX PDC SENSOR		\$80.00
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY		√ 1\$120.00 ×
	TO SPRAY RUST PROOFING		-1-1 \$50.00 X
	LABOUR FOR PANEL BEATING & REPLACING PARTS		\$680.00 300
	TO PUTTY & SPRAY PAINTING		\$800.00 40
			TOTAL \$6,322.40

9-2517.42 52 2429:54

As in Commetting Promote molify

The second party acting activity

The second party acting promote back

The second party must be promoted and

The second party active promote Company

Administration by Proporties

Engrance:

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25. Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/MSG19007135/USD3N2

Date:

08/05/2019

REFERENCE

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

29114756

Claimant Vehicle No:

SLX3953L

Insured Vehicle No:

SLP7972Y

Date of Loss:

20/04/2019

Nature of Claim:

TP

Claim No: 591214

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLX3953L

BMW 520I, 2.0 L AT D/AB 2WD 4DR GAS/D NAV

Engine No:

B0660588N20B20B

Reg. Date: Colour:

27/01/2014 (Man. Year: 2013) Black

Chassis No: Odometer:

WBA5A32000D333967 167861 km

Engine Capacity:

1997 cc

Market Value/New Car

Make & Model:

N/A

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No. Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: Front Left Side: Front Right Side: 245/40 ZR19 Dunlop 6 mm Dunlop 6 mm Rear Tyre Size: Rear Left Side: Rear Right Side:

6,764.97

275/35 ZR19 Dunlop 6 mm Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,512.40	2,429.55	2,082.85	46.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,810.00	770.00	1,040.00	57.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S	\$) 6,322.40	3,199.55	3,122.85	49.39
Approved Total (Overridden) (S	(\$)	2,500.00		
(S	(\$) 6,322.40	2,500.00	3,822.40	60.46
+ GST 7.00/7.00% (S	(\$) 442.57	175.00	267.57	60.46

INSPECTION

Date of Assignment:

07/05/2019

Date Inspected:

22/04/2019 Inspected At:

Nett Amount (S\$)

Fastech Auto Pte Ltd (HQ)

1 Kaki Bukit Ave 6, #01-46/48/50

4,089.97

60.46

Autobay

2,675.00

Singapore 417883

Estimated Period of Repair:

2.0 days

Adjuster: MARCUS CHUA Manager: Hiew May Fung Adjuster Report Page 2 of 4

NOTE. This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Referen	ce	
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 May 2019)
Parts:	143	BMW 520I 2.0 L AT D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted	, no print-code for SLX3953L)
Validity:		ites are valid only if they contain the print code (above) on all estimate pages, running page the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values	not in reference catalogue are prefixed with an asterisk *.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented/Deformed	1,655.00 F	*1,565.32 FL
2	1		*REAR BUMPER PDC SENSOR	Not Necessary	313.00 F	*-FL
3	1		*REAR BUMPER SIDE HOLDER O/S	Not Necessary	145.50 F	*-FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	711.00 F	*711.00 FL
5	1		*REAR BUMPER TOP RETAINER	Not Necessary	315.00 F	*-FL
6	1		*REAR BUMPER LOWER COVER CENTRE	Cracked	166.20 F	*115.30 FL
7	1		*REAR BUMPER LOWER O/S COVER	Cracked	188.50 F	*165.80 FL
8	1		*REAR END PANEL	Repair	1,018.20 F	*-FL
F∍F⊓	anchise	part. L=ListIti	emDisc.	A Level Const	0,000	200000000
				Sub Total (S\$)	4,512.40	2,557.42
			- List Item Discount on L	Items 0.00/5.00% (S\$)	0.00	127.87
				Total Parts (S\$)	4,512.40	2,429.55

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING	New	80.00	20.00
2	TO DISMANTLE & REFIX PDC SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY	New	120.00	0.00
4	TO SPRAY RUST PROOFING	New	50.00	0.00
5	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	680.00	300.00
6	TO PUTTY & SPRAY PAINTING	New	800.00	400.00
	Gross Labor	ur Cost (S\$)	1,810.00	770.00
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >