

2/20/2001

ASS. REC. BY:

REF:

CS3/AIG19007151/GCD312

Special Instruction:

Surveyor/Estimator

GA

ASSIGNMENT (Office)

From (Person):

for Yinnal

of

AIG

Date/Time:

23/4/19 @ 2:48pm

Estimated Cost:

Bill to:

OD/UTP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

Fx 9598K

Insured:

SJS 639P

at Workshop m/s

Ambra Enterprise

Tel:

64537594

of

Blk 5034 Amk Ind. Park 2 # 01-327

Policy No:

Claim No:

589036871659

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

31/03/2019

CA / REV / REP. / REV 24 HRS

24/4/19

H.O.D. Endorsement:

Date/Time:

5:06pm @ 23/4/19

Person Contacted:

Mr. Rom

Vehicle:

IN/OUT

Date/Time

Action/Instruction (X) Estimate

pass frunk.

Fx 9598K - X

SJS 639P - CS/REG-17013408 / Arbn 2

DOA: 9/7/17

622

REF: A19

PRS

ASSIGNMENT

From: _____ Date: 24.4.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: Fx 9598K

at Workshop m/s Ambra Enterprises

of BIK 503p #01-327 AMC Ind. Pk 2

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: FX9598K Yr Regn: Apr / 04

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Piaggio runner 200 c.c. 198

Colour: Black A/C: Insured / Std / NI / NA

Sp.Reading: 231618 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZAPM2400002007296


Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 120/70-12 R: " "



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS "WP"

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front	Rear
R/Bal. 4 mm	R/Bal. 4 mm
L/Bal. mm	L/Bal. mm
D.O.A. _____	D.O.I. 24-04-19

Survey held at w/s _____ 5pm

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or _____

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Tuo Qiang,
	PLS check repair margin.
16/5	Simon said vehicle still economical repair, proceed to submit DAR.

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

2) _____

Days Of Repair: 6

Resurvey No. of Trip: -

Survey Fee: 180

Transportation: _____

Photos _____

Others: 10

TOTAL: 190

Report Format: DAR.

Lump Sum / I.B.I.: (\$ _____)

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Apr 2019 Edit Reg		23 Apr 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:			
Main Claimant:	-		
Vehicle Reg. No.:	FX9598K	Date of Loss:	31/03/2019 00:00 - :59
Claim Type:	TP / 5890368716SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SJS639P	Policy No. (Claimant):	
		Excess:	
Repairer:	Ambra Enterprises Transport & Courier Services (HQ) Blk 5034, #01-327, Ang Mo Kio Industrial Park 2, 569537 Ang Mo Kio - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 03/05/2019]		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS	View All	Search Tasks	Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION REQUEST – FX9598K vs SJS639P (OI) on D.O.A.: 31/03/2019

From: Hor, Yinrul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur
Sent: 23/4/2019 2:48:17 PM
Attachments:  tmpAAC9.tif  tmpAAC9.tif

Hi,

Please refer to the enclosed request from A H Sultan & Associates.

Claim no : 5890368716SG003
Case Owner : MING YAO LEE

If you have any queries/concerns, please let us know.
Kindly assist to assign Mohamad Taufikh as Single Joint Expert as requested.

Thanks & Regards,

Yin Rul, Hor (Viviane)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Yinrul.Hor@aig.com | www.aig.sg

From: A H Sultan & Associates [mailto:ahsa@ahsultan.com]
Sent: Tuesday, April 23, 2019 1:41 PM
To: Hor, Yinrul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur
Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJS639P AND FX9598K ON 31/03/2019


This message is from an external sender; be cautious with links and attachments.

Dear Sirs

We refer to your email of 23 April 2019.

We appoint Mr Mohamad Taufikh from LKK Auto Consultants Pte Ltd to conduct a pre-repair inspection on our client's motorcycle.

Best Regards
Abdul Hamid Sultan
Advocates & Solicitors
Commissioner For Oaths/Notary Public
A H Sultan & Associates
101 Upper Cross Street
#05-08 People's Park Centre
Singapore 058357
Tel: 63239122/Fax:62262870
email: ahsa@ahsultan.com



IMPORTANT NOTICE:
The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinrul.Hor@aig.com
To: ahsa@ahsultan.com
Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, Baljit.Kaur@aig.com, NoorMariesa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJS639P AND FX9598K ON 31/03/2019
Date: Tue, 23 Apr 2019 02:37:04 +0000
Without Prejudice

Your Reference : AHS/1107/2019/L
Our Reference : 5890368716SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd

Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Yin Rui, Hor (Viviane)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Yinnui.Hor@aig.com | www.aig.sg

AHSA A H SULTAN & ASSOCIATES
 ADVOCATES & SOLICITORS
 COMMISSIONER FOR OATHS
 NOTARY PUBLIC

Your Ref:
 Our Ref: AHS/1107/2019/L

Date: 18 April 2019

101 UPPER CROSS STREET
 #05-09 PEOPLE'S PARK CENTRE
 SINGAPORE 058387
 Tel: (65) 6323 9122
 Fax: (65) 6226 2870
 E-mail: ahsa@ahsultan.com
 UEN No. 53130924W

AIG Asia Pacific Insurance Pte Ltd
 AIG Building
 78 Shenton Way #09-16
 Singapore 079120

By Fax (68357416) & Post

Attn: Claims Department

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL ACCIDENT INVOLVING MOTORCYCLE NO. FX9598K AND VEHICLE NO. SJS639P ON 31/03/2019 AT 12.35 P.M. AT STEVENS ROAD JUNCTION OF BALMORAL ROAD

We act for the owner who has appointed the undermentioned workshop to repair their motorcycle no. FX9598K.

Please be informed that the said vehicle can be inspected at:

Name of Workshop : Ambra Enterprises Transport & Courier Services
 Address : Block 5034 #01-327 Ang Mo Kio Industrial Park 2
 Singapore 5695537
 Contact Person : Mr Ram
 Telephone No : 6453 7594
 Fax No : 6482 0016

We hereby give you two (2) clear days notice to conduct a pre-repair inspection of the said vehicle at the abovementioned workshop during office hours.

Yours faithfully

(Abdul Hamid Sultan)

Fax and email not intended for service of Court documents

CONFIDENTIALITY NOTICE: This facsimile transmission is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you are not the intended recipient, you should not disclose, disseminate, distribute, copy or use any of the information contained in this transmission. If you have received this transmission in error, please notify us immediately by telephone and mail the original transmission to us at the address stated above.

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2429C
Vehicle Details	
Vehicle No.:	FX9598K
Vehicle to be Exported:	No
Intended Deregistration Date:	16 May 2019
Vehicle Make:	PIAGGIO
Vehicle Model:	RUNNER 200
Primary Colour:	Black
Manufacturing Year:	2003
Engine No.:	M243M8857
Chassis No.:	ZAPM2400002007296
Maximum Power Output:	-
Open Market Value:	\$2,428.00
Original Registration Date:	16 Apr 2004
First Registration Date:	16 Apr 2004
Transfer Count:	3
Actual ARF Paid:	\$365.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2024
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$2,474.00
COE Rebate Amount:	\$1,205.00
Total Rebate Amount:	\$1,205.00

The information contained herein is correct as at 16 May 2019

OK

MENU



HIGHLIGHTS DESCRIPTION Get the app Sign up FREE

SELLER INFO (https://www.singaporebikes.com/bikemart/sg/)

Gilera Runner ST 200

Price S\$5500.00



unknown



20000km



FBK-****-A



Class 2B



CHAT

(MESSAGES/U/48546)

Description

6.5 YEARS LEFT!

Low Mileage & Lowest Depreciation @ \$80 / Month



Specifications

MENU



Bike Model Runner ST 200

Bike Class Class 2B

Bike Type Scooters

Transmission Automatic

Engine Capacity 198 cc

Under Hire Purchase No

Additional

First Owner No

Effective Date Ownership 02-01-2018

Original Reg. Date 02-06-2015

Bike Color



Additional**MENU**

Road Tax
Expiry Date

01-06-2019

Mileage

20000km

Instalment
Details

N/A

Accessories

Leo Vince LTA Approved Exhaust System Recent servicing in 2018 -
Include Replace new original Carb, Pollini Drive Belt, Pollini Oil Filter,
Pollini Rollers, NGK Spark Plug, Pollini Clutch Speed Bell, Variator
Pollini Maxi Hi-Speed, Replace Engine Mounting, New Tyres RECEIPT
available as proof of replaced parts.

Seller Information

MENU

HIGHLIGHTS DESCRIPTION SPECS
 Get the app Login Sign up FREE
 SELLER INFO

Gilera Runner ST 200


Price S\$3333.00



2010




30000km



FBE-****-Z



Class 2B



CHAT

(MESSAGES/U/47893)

Singapore
BIKES.



Description

(<https://www.singaporebikes.com/bikemart/sg/>)

Gilera ST 200

MILEAGE 30000 KM ONLY


COE 2020

INSPECTION PASSED

HASSLE FREE FULLY DONE UP NAKED SETUP

CUSTOM BAR & STEM (Not typical DABOMB like other
naked users, more high end)

Open to nego. If reasonable



Malossi Air Filter

Pollini Speed Control

Pollini C - Clip

Malossi Clutch Bell

Malossi Racing CDI

Truativ Hussefelt Stem Snow White Edition 31.8mm

Deity CZ38 Special Handlebar Black/Purple

Stage 6 Parts Fast Throttle kit

Stage 6 Parts Signal / Headlight Indicator

Stage 6 Parts Speedometer White Line (ONLY ONE IN
SGP)

F1 mirror

Hell Brake Hose Candy Purple Front & Rear (CUSTOM)

Maintenance :

Singapore



Top Overhaul + Replace Carb Slider in October 2017

Full servicing + Malossi Belt + Pollini clip + Original
Rectifier + Original Pinion Starter Gear + Magnetic Coil
(<https://www.singaporebikes.com/bikemart/sg/>)

done in December 2017 (AGIP ENI)

Pirelli Diablo Scooter changed in July 2017 Front & Rear


Outlook :

Inner Panel Gloss Black by Scoot Veloci Jan 2017

Full cover set Mustard Yellow by Scoot Veloci Jan 2017

Horn Cover + Engine Undertray + Side Cap custom
design decal by Cuztom Studio Feb 2017

Candy Purple Rim Spray by 7Angolz April 2017



Not dekitting. Either full cash or I have my own shop available to do reloan if needed.

I GUARANTEE that the engine is fully done up. Bring along helmet upon viewing and I'll PERSONALLY show you why it's much more powerful. Furthermore, the design done up on bike is custom.




Specifications

General Info.

Bike Make	Gilera
Bike Model	Runner ST 200
Bike Class	Class 2B
Bike Type	Scooters
Transmission	Automatic

General Info.

MENU

**Additional**

First Owner	No
Effective Date Ownership	01-07-2022
Original Reg. Date	N/A
Bike Color	
COE Expiry Date	01-07-2022
Quota Premium (QP)	0.00
Road Tax Expiry Date	N/A
Mileage	30000km
Instalment Details	N/A

MSUB19048711-01 / Su Brothers Motor Workshop - AMK
 ENTRY DATE & TIME 15/04/2019 13:41
 SUBMITTED BY: Koh Siew Ling

Your NCD will be affected due to late reporting
 Actual e-Filing Submission Date & Time: 15/04/2019 14:13

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/04/2019 13:41
Date Of Accident	31/03/2019 12:35
Exact Location Of Accident	STEVENS RD JUNCTION OF BALMORAL RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FX9598K
Insured/Policyholder	
Name Of Registered Owner	MUHD AIMRAN QUEK B AB
NRIC No	S1712429C
Email Address	RONEYQ@YAHOO.COM
Mobile Phone No	(LOCAL) +65-97437465
Alternative Phone No	OTHERS-07437465
Vehicle Particulars	
Manufacturer	GILERA
Model	RUNNER VXR200-198CC
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5026737249-10
Cover Note Number	
Driver	
Name of Driver	MUESA BIN MUHAMMAD AIMRAN QUEK
NRIC No	S9712651H
Date Of Birth	22/04/1997
Occupation	INDOOR
Date Of Driving Pass	03/03/2016
Driving Experience	3 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	+65-93219147
Fax Number	
Contact Number	
Email Address	MUESA.CUEK@GMAIL.COM

Address	BLK 508 SERANGOON NORTH AVE 4 #10-394
Postcode	550508
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORTNO. T/20190405/2118.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJS638P
Vehicle Make/Model/Colour	HYUNDAI I30
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	MUESA BIN MUHAMMAD AIMRAN QUEK
------	--------------------------------

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FX9598K

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode


Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time


Reporting Centre Personnel's Signature
Name
NRIC/FIN No.:

Condition (CON)

- (01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
 (07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

ACTION (AC)

1. Replace (✓) 2. Repair (X) 3. Check (?)
 4. Not Consistent (NC)

May 2005

FOR MOTORCYCLE

Vehicle No: **FX 9598K**

Motorcycle

NAC	INC	Item	CON	AC	Qty
1001	991886	Front Number Plate	CRA	/	
3001	995065	Front Tyre			
3002	995095	Front Rim			
3003	994872	Front Tyre Rim Spoke			
3004	991771	Front Fender Wheel Guard	Cut	-	
3005	991283	Front Brake Disc	BT	-	
3006	991281	Front Brake Caliper			
3007	991785	Front Fork Assy	BT	-	
3008	991787	Front Fork Inner Tube			
3009	991789	Front Fork Outer Tube			
3010	991167	Front Fork Bracket	BT	-	
3011	991182	Front Fork Oil Seal	nc	-	
3012	991174	Front Fork Garnish oil	nc	-	
3013	992376	Front Headlamp Rim			
3014	992328	Front Headlamp		?	
3015	992337	Front Headlamp Bracket		?	
3016	992345	Front Headlamp Fairing	CRA	-	
3017	992130	Front Windshield	CRA	-	
3018	992134	Front Wing Mirror	CRA	-	2
3019	995245	Front LH Signal Lamp	Sch	-	
3020	995246	Front RH Signal Lamp	CRA	-	
3021	992556	Meter Casing	re	-	
3022	992553	Meter Assy		?	
1118	991019	ERP Bracket			
1119	991020	ERP Unit	Cut	-	
3023	992446	Ignition Switch			
3024	992442	Ignition Key Assy			
3025	990706	Cowling Stay			
3026	994470	Steering Stem	BT	-	
3027	994427	Steering Cone and bearing	nc	-	
3028	992299	Handle Bar	BT	-	
3029	992312	Handle Bar Switch			
3030	992310	Handle Bar Grip			
3031	995184	Handle Bar Balancer LH			
3032	992300	Handle Bar Balancer RH			
1252	992179	Fuel Tank			
3033	990438	Brake Reservoir			
3034	990621	Clutch Lever			
3035	992293	Hand Brake Lever			
3036	991119	Side Fairing	Cut	CRA	2
3037	994220	Side Fairing Top Garnish		?	
3038	994219	Side Fairing Inner Garnish	re	-	
3039	991118	Fairing Shield			
3040	992047	Front Top Fairing Inner Garnish			
3041	991123	Fairing Top Garnish			
3042	990538	Center Fairing Rear	mis	-	
3043	993378	Rear Fairing	CRA	-	
3044	991121	Fairing Stopper			
3045	991117	Fairing Lower	Cut	-	2

NAC	INC	Item	CON	AC	Qty
1052	995074	Radiator			
1053	992738	Radiator Cowling			
3046	994146	Seat Assy		re	-
3047	990915	Engine Crash Bar			
3048	990928	Engine Guard			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
3049	991144	Foot Brake			
3050	991154	Front Foot Rest			
3051	991779	Front Foot Rest Bracket			
3052	994269	Side Stand			
3053	992549	Main Stand			
3054	990615	Clutch Engine Cover			
3055	992478	Kick Starter Rubber			
3056	992477	Kick Starter Lever			
3057	991145	Foot Gear Shifter			
3058	993500	Rear Foot Rest			
3059	993501	Rear Foot Rest Bracket			
3060	992581	Exhaust Muffler Heat Shield			
3061	991058	Exhaust Muffler Assy			
1405	993719	Rear LH Shock Absorber			
1445	993720	Rear RH Shock Absorber			
3062	995065	Rear Tyre			
3063	991200	Rear Rim			
3064	994872	Rear Tyre Rim Spoke			
3065	993474	Rear Fender Wheel Guard			
3066	993443	Rear Fender Mudflap			
3067	992940	Rear Brake Disc			
3068	992936	Rear Brake Caliper			
3069	995236	Rear Spocket			
3070	990585	Chain			
3071	990580	Chain Guard			
3072	994530	Swing Arm			
1420	993819	Rear Sub frame		Repair	
3073	995245	Rear LH Signal Lamp		CRA	-
3074	995246	Rear RH Signal Lamp		CRA	-
3075	995251	Rear Taillamp		CRA	-
1137	993626	Rear Number Plate		BT	-
3076	994192	Side Box			
3077	992927	Rear Box			
3078	992928	Rear Box Bracket			
3079	991328	Emblem			
1136	990247	Sticker			
		Body Frame		Repair	

[Signature]
 6 Days
 25/4/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Apr 2019 Edit Reg		23 Apr 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	BIZLINK RENT - A- CAR PTE LTD , Co. Reg. No.: 200402911Z								
Main Claimant:	NA								
Vehicle Reg. No.:	FX9598K	Date of Loss:	31/03/2019 00:00 - :59 [179 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5890368716SG	Policy/Cover Note No.:	0999994542 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJS639P	Policy No. (Claimant):							
		Excess:							
Repairer:	Ambra Enterprises Transport & Courier Services (HQ) Blk 5034, #01-327, Ang Mo Kio Industrial Park 2, 569537 Ang Mo Kio - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 03/05/2019]								
Claimant's Solicitor:	A H SULTAN & ASSOCIATES - Tel: 6323 9122								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FX9598K (5890368716SG)

[SJS639P]

TP

NA

Mar 31 2019 12:00AM

[BIZLINK RENT - A- CAR PTE LTD]

Ambra Enterprises Transport & Courier Services

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	View in Browser	
Photos/Images											3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
2	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
3	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
4	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
5	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
6	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
7	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
8	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
9	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
10	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
11	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
12	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
13	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
14	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
15	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
16	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
17	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
18	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
19	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
20	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
21	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
22	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
23	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
24	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
25	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
26	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
27	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
28	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
29	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
30	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
31	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
32	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
33	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
34	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
35	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
36	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		
37	02/05/19 12:38	General View							Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	02/05/19 12:38	General View	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG19007151/GCD3E2**Date:** 27/05/2019REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994542
Claimant Vehicle No :	FX9598K	Insured Vehicle No :	SJS639P
Date of Loss:	31/03/2019	Nature of Claim:	TP
		Claim No:	5890368716SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FX9598K	Engine No:	M243M8857
Make & Model:	GILERA RUNNER VXR200, 198cc	Chassis No:	ZAPM2400002007296
Reg. Date:	16/04/2004 (Man. Year: 2003)	Odometer:	231618 km
Colour:	Black		
Engine Capacity:	198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70-12	Rear Tyre Size:	120/70-12
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	23/04/2019	
Date Inspected:	24/04/2019	Inspected At:
		Ambra Enterprises Transport & Courier Services (HQ) Blk 5034, #01-327, Ang Mo Kio Industrial Park 2 Singapore 569537

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT NUMBER PLATE	Cracked	0.00 F	*- F	
2	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F	
3	1		*FRONT BRAKE DISC	Bent	0.00 F	*- F	
4	1		*FRONT FORK ASSY	Bent	0.00 F	*- F	
5	1		*FRONT FORK BRACKET	Bent	0.00 F	*- F	
6	1		*FRONT FORK OIL SEAL	Necessary	0.00 F	*- F	
7	1		*FRONT FORK OIL	Necessary	0.00 F	*- F	
8	1		*FRONT HEADLAMP	* Check	0.00 F	*- F	
9	1		*FRONT HEADLAMP BRACKET	* Check	0.00 F	*- F	
10	1		*FRONT HEADLAMP FAIRING	Cracked	0.00 F	*- F	
11	1		*FRONT WINDSHIELD	Cracked	0.00 F	*- F	
12	2		*FRONT WING MIRROR	Cut	0.00 F	*- F	
13	1		*FRONT LH SIGNAL LAMP	Scratched	0.00 F	*- F	
14	1		*FRONT RH SIGNAL LAMP	Cracked	0.00 F	*- F	
15	1		*METER CASING	Deformed	0.00 F	*- F	
16	1		*METER ASSY	* Check	0.00 F	*- F	
17	1		*ERP UNIT	Cut	0.00 F	*- F	
18	1		*STEERING STEM	Bent	0.00 F	*- F	
19	1		*STEERING CONE AND BEARING	Necessary	0.00 F	*- F	
20	1		*HANDLE BAR	Bent	0.00 F	*- F	
21	2		*SIDE FAIRING	Cut	0.00 F	*- F	
22	1		*SIDE FAIRING TOP GARNISH	* Check	0.00 F	*- F	
23	1		*SIDE FAIRING INNER GARNISH	Deformed	0.00 F	*- F	
24	1		*CENTER FAIRING REAR	Missing	0.00 F	*- F	
25	1		*REAR FAIRING	Cracked	0.00 F	*- F	
26	2		*FAIRING LOWER	Cut	0.00 F	*- F	
27	1		*SEAT ASSY	Deformed	0.00 F	*- F	
28	1		*REAR SUB FRAME	Repair	0.00 F	*- F	
29	1		*REAR LH SIGNAL LAMP	Cracked	0.00 F	*- F	
30	1		*REAR RH SIGNAL LAMP	Cracked	0.00 F	*- F	
31	1		*REAR TAILLAMP	Cracked	0.00 F	*- F	
32	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F	
33	1		*BODY FRAME	Repair	0.00 F	*- F	
					Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >