

ASAC: HRC: HRC

REP

CS/FCI 1900 71SS/E/d302

Special Instruction

Surveyor
CWS

Steve

ASSIGNMENT (Office)

From (Person)

Joanne Yong

of

FCI

Date/Time

5:41pm @ 22/4/19

Estimated Cost

Bill to

OD TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No.

SLE 6731R

Insured

SHA 7207A

at Workshop m/z

Mova

Tel

62723892

of

Blie 1008 Blf menh June 3 #01-04

Policy No.

Claim No

019002484MF84

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A

9/4/2019

CA / REV / REP / REV 24 HRS

(DS)

H.O.D. Endorsement

Date/Time

5:47pm @ 22/4/19

Person Contacted

Nithan

Vehicle

IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLE 6731R - NA / HP 1900 6370 / 24

DVA: 9/4/19

SHA 7207A - NA / HP 1900 6370 / 24

DVA: 9/4/19

25/4 @ 3:43pm - Revised preli advise via email

STERN

REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
QD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s: _____
of: _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____
(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

N/S	O/S

Veh No: SLE 6731R Yr Regn: 16/12/09
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Volkswagen Polo CC: 1390
Colour: Red A/C Insured / Std / NI / NA
Sp. Reading: 84213 T/Ratio: Insured / Std / NI / NA
Eng/No: _____
C/No: WVW2ZZ6R2A4006340
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 185/60R15
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Ling Long
Front Rear
R/Bal. 7 mm R/Bal. 7 mm
L/Bal. 7 mm L/Bal. 7 mm
D.O.A. 9/14/15 D.O.I. 23/4/19
Survey held at Mora, Bukit Merah
Des. of Damages: Fr / Rea / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time : Action / Instruction
MV - 13,000 Workshop agreed \$4,800 repair
PV - 8619
NV - 4381
market value - 13,000
LTA - 8619
NHT - 4381

24/7/19 Finalize \$4800, 8-days cred: 7963.88 (62%~)

RECEIVED 26 JUL 2019

Date/Time, File Pass to: ☐ Prel. Report
25/7/19 Typist ☒ Final Report
Date/Time, File Return to?

Days Of Repair: 8
Resurvey No. of Trip: _____

Report Format: TP
Lump Sum / I.B.L: 48001-

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Invs (\$)
☐ Weekend (\$)

Survey Fee:
Transportation
S + R: 30
Photos
Labor
2x14=30
170+30
50
50
50
390

MOTOR SURVEY ASSIGNMENT

Date	11-04-2019	Our Ref No. D19002484MFSH
Accident Date	09-04-2019	Claim Type. Third Party
Insured Vehicle	SHA7207A	Third Party Vehicle. SLE6731R
Survey Location	BLOCK 1008 BUKIT MERAH LANE 3 #01-04/06/08	
Contact Person.	NITHA	
Contact No.	62723892/ 0	Fax No. 62708314
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MOVA AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0821A
Vehicle Details	
Vehicle No.:	SLE6731R
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Apr 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	POLO 1.4 AT 6R13E7
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	CGG224971
Chassis No.:	WVWZZZ6RZAU006340
Maximum Power Output:	63.0 kW (84 bhp)
Open Market Value:	\$14,860.00
Original Registration Date:	16 Dec 2009
First Registration Date:	16 Dec 2009
Transfer Count:	3
Actual ARF Paid:	\$14,860.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Dec 2019
PARF Rebate Amount:	\$7,430.00
Intended COE Rebate Details	
COE Expiry Date:	15 Dec 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$8,855.00
COE Rebate Amount:	\$1,189.00
Total Rebate Amount:	\$8,619.00

The information contained herein is correct as at 23 Apr 2019

OK



AVIVA

Post an Advertisement
Sell It Yourself! Advertise It at Just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 10 Years Coe Renewal Toyota Wish 1.8A



3.05% P.A. Low Interest @ GV
Finance 2 Years
Warranty Monthly From \$788.
GV Credit Pte Ltd [StarAd](#)



Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

7 vehicles

volkswagen polo

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	volkswagen polo		Any	Any	2010	Any	Any	Any	Available

**Volkswagen Polo 1.4A****\$13,800****\$8,330 /yr****29-Jan-2010****1,390 cc****116,000 km****Hatchback****Available**

Well Maintained. View To Appreciate, Car Drive Smooth And Silent. Loan/Trade In Available. Please SMS For Viewing Appointment.

Posted: 06-Apr-2019

Tags: 2010 Volkswagen Polo, 2010 volkswagen polo, Volkswagen Polo, volkswagen polo, Volkswagen, Polo, polo, Used Volkswagen

DEALER OWNED

**Volkswagen Polo 1.4A (New 5-yr COE)****\$29,800****\$5,950 /yr****01-Mar-2010****1,390 cc****78,200 km****Hatchback****Available**

Cheapest In Market. Single Owner. Fully Agent Serviced, Maintained And Original Paint From Day 1. Servicing Records Available Upon Request. Low Mileage. 100% No Repairs Needed. 100% Accident Free. Und...

Posted: 13-Apr-2019

Tags: 2010 Volkswagen Polo, 2010 volkswagen polo, Volkswagen Polo, volkswagen polo, Volkswagen, Polo, polo, Used Volkswagen

PREMIUM AD

**Volkswagen Polo 1.4A****\$16,900****\$8,880 /yr****13-May-2010****1,390 cc****107,320 km****Hatchback****Available**

Drive With Assurance! 1 Year Warranty! Genuine And Transparent Deal! New 5yrs COE \$32.9k, New 10yrs COE \$47.9k. Bank/In House 100% Loan At Monthly Installment \$636, Easy Approval! Our Quality Pre-Owned...

CarQuotz Singapore

Posted: 20-Apr-2019

Tags: 2010 Volkswagen Polo, 2010 volkswagen polo, Volkswagen Polo, volkswagen polo, Volkswagen, Polo, polo, Used Volkswagen

**Volkswagen Polo 1.4A****\$16,800****\$8,400 /yr****31-May-2010****1,390 cc****70,000 km****Hatchback****Available**

Super Low Mileage Of Only 70k Km Done! Carefully Taken Care Of By Previous Expat Owner! Totally Under Utilised! 100% Accident Free! STA Evaluation Welcome! View To Believe! High And Flexible Loan Avail...

ST Carz Pte Ltd

Posted: 17-Apr-2019

Tags: 2010 Volkswagen Polo, 2010 volkswagen polo, Volkswagen Polo, volkswagen polo, Volkswagen, Polo, polo, Used Volkswagen



GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.

**Volkswagen Polo 1.4A****\$17,800****\$9,100 /yr****09-Jun-2010****1,390 cc****-****Hatchback****Available**

Possible To Renew 5 Year COE At \$30800 To Get Better Instalment Plan. Very Well Maintain By Previous Owner, Smooth Engine, Easy To Maintained Unit. Buy With A Peace Of Mind, Sell At It Conditions! Bu...

Car (5) Pte Ltd

Posted: 18-Apr-2019

Tags: 2010 Volkswagen Polo, 2010 volkswagen polo, Volkswagen Polo, volkswagen polo, Volkswagen, Polo, polo, Used Volkswagen

PREMIUM AD

**Volkswagen Polo 1.4A****\$17,500****\$7,790 /yr****03-Aug-2010****1,390 cc****138,500 km****Hatchback****Available**

Well Maintain And Regular Service. Recently Repair To New Engine Mounting, New Brake Pad And Rotor, 4 New Tyres. View And Test Drive To Offer At Sin Ming Workshop With A Peace Of Mind.

Posted: 10-Apr-2019

Tags: 2010 Volkswagen Polo, 2010 volkswagen polo, Volkswagen Polo, volkswagen polo, Volkswagen, Polo, polo, Used Volkswagen

**Volkswagen Polo 1.4A****\$19,800****\$8,340 /yr****12-Oct-2010****1,390 cc****80,200 km****Hatchback****Available**

Genuine Low Mileage Of 9000km Yearly With Receipts(VW Singapore) To Prove! Serviced And Maintained By Agent. Just Spend \$1,300 On Preventive Maintenance (18/1/2019) With Oil Leak Replacement, Speed Se...

Posted: 20-Apr-2019

Tags: 2010 Volkswagen Polo, 2010 volkswagen polo, Volkswagen Polo, volkswagen polo, Volkswagen, Polo, polo, Used Volkswagen

PREMIUM AD

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

[Compare](#)
[Home](#)
[New Cars](#)
[Used Cars](#)
[Sell My Car](#)
[Directory](#)
[Products](#)
[Insurance](#)
[Article](#)
[Forum](#)
[Resources](#)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: D19002484MFSH

Date: 25/4/2019

Our Ref: CS/FCI19007155/Etd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLE 6731R

Please be informed that we had conducted the inspection of the abovementioned vehicle
25/4/2019 at the premises of M/s Mova have the following to report: -

Workshop Estimate Amount	: S\$ 12,703.88
Revised Estimate Amount	: S\$ 10,234.85
"Check" Items Amount	: S\$ 326.30
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the
Front and rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Rasul

Automotive Assessor

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 25 April 2019 3:43 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D19002484MFSH/1
Attachments: PRELI ADVISED SLE 6731R.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLE 6731R**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 23 April 2019 11:18 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <JoanneYong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002484MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 22 April 2019 5:40 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <JoanneYong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002484MFSH/1

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	10/04/2019 15:34
Date Of Accident	09/04/2019 16:55
Exact Location Of Accident	PIE (TUAS) AFTER STEVEN RD EXIT
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLE6731R
Insured/Policyholder	
Name Of Registered Owner	TAN YU PING JASMINE
NRIC No	S8530821A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98567402
Alternative Phone No	OFFICE-98567402
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	POLO 1.4 AT 6R13E7
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SI18V07385/VPE/R01
Cover Note Number	
Driver	
Name of Driver	TAN YU PING, JASMINE (CHEN YUPING)
NRIC No	S8530821A
Date Of Birth	19/09/1985
Occupation	OUTDOOR
Date Of Driving Pass	18/07/2013
Driving Experience	5 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98567402
Fax Number	
Contact Number	OFFICE-98567402
EMail Address	NOEMAIL

Address	BLK 327 TAH CHING ROAD #05-16
Postcode	610327
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	5
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA7207A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLE1658C
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SKR6270Y

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number

SJS849A

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

TAN YU PING, JASMINE (CHEN YUPING)

Approximate Age

Injuries Sustain

BODY

Injured person in which vehicle?

SLE6731R

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

E. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Person's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along PHE Taxis Turn after Sticks Exit. The vehicle in my group, I then group suddenly, I felt a huge impact from the rear. The impact was so huge that it caused my vehicle to move forward & hit over the vehicle in front. I got down & realized 5 cars were involved.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NIC/FIN No.:

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

18/04/2019

MS FIRST CAPITAL INSURANCE LIMITED

36 Robinson Road

#16-01 City House

Singapore 068877.

Attention :- XA026

Page # :- 1

Veh # :- SLE6731R

Veh Model :- VOLKSWAGEN POLO

Estimate# :- CK419027

Claim # :-

ACC. Date :- 09/04/19

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :

1.	FRONT BONNET / DD	1	PC	1,050.20	1,050.20
2.	BONNET HINGE X R	2	PC	115.00	230.00 X
3.	FRONT FENDER RH / DD	1	PC	498.75	498.75
4.	COWLING RH X / MM	1	PC	181.35	181.35 X
5.	COWLING CLIPS X / MM	10	PC	3.80	38.00 X
6.	COWLING LH X R	1	PC	181.35	181.35 X
7.	COWLING CLIPS X / MM	10	PC	3.80	38.00 X
8.	FRONT HEADLAMP L+R / BR	2	PC	590.90	1,181.80 972
9.	FRONT HEADLAMP LOWER BRACKET L+R ? X MM	2	PC	163.15	326.30 X
10.	FRONT HEADLAMP TOP PANEL L+R / DD	2	PC	94.35	188.70
11.	FRONT SUPPORT PANEL / BR	1	PC	842.25	842.25
12.	FRONT BONNET LOCK / BT	1	PC	369.95	369.95
13.	FRONT GRILLE INNER / BR	1	PC	385.85	385.85
14.	FRONT EMBLEM / MIS	1	PC	162.95	162.95
15.	FRONT BUMPER / DD	1	PC	1,003.45	1,003.45 810
16.	FRONT BUMPER RETAINER L+R / BR	2	PC	135.00	270.00 174
17.	BUMPER CLIPS / MM	10	PC	3.80	38.00 30
18.	FRONT BUMPER TOW COVER X R	1	PC	48.95	48.95 X
19.	FRONT LOWER GRILLE / CH	1	PC	298.25	298.25
20.	FRONT FOG LAMP GARNISH L+R RH-MIS L4-X MM	12	PC	108.60	217.20 108-60
21.	FRONT REINFORCEMENT / DD	1	PC	673.80	673.80 5478
22.	FRONT RADIATOR / DD	1	PC	1,021.75	1,021.75
23.	RADIATOR COWLING / BR	1	PC	187.85	187.85
24.	FAN MOTOR X / MM	1	PC	697.65	697.65
25.	CONDENSER / DD	1	PC	698.35	698.35
26.	REAR BUMPER - REPAIR X R	1	PC		
27.	FRONT DOOR RH - REPAIR X R	1	PC		
28.	FRONT FENDER LH - REPAIR X R	1	PC		
29.	REAR BUMPER BRACKET CENTRE - CHECK ? X MM	1	PC		
30.	REAR REINFORCEMENT - CHECK X MM	1	PC		
31.	REAR PARKING SENSOR - CHECK ? X MM	1	PC		

LIST TOTAL S\$

10% DISCOUNT S\$

7983.05
- 10%
7184.74

10,830.70

-1,083.07

9,747.63

SPECIAL NET ITEMS :

1.	NUMBER PLATE / NEL	1	PC	45.00	45.00
2.	COOLANT / NEL	1	PC	37.40	37.40
3.	AIRCON GAS / NEL	1	PC	80.00	80.00
4.	AUTO OIL / NEL	1	PC	53.85	53.85

SPECIAL NET TOTAL S\$

182.40 216.25

LABOUR :

TO REPAIR FRONT WHEELHOUSE L+R, FRONT DOOR RH
FRONT FENDER LH. TO STRAIGHTEN & REALIGN ON
ACCIDENT DAMAGED PARTS. TO REMOVE & REPLACE
ALL ACCIDENT DAMAGED PARTS

800 1,250.00

Estimate

18/04/2019

MS FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road
#16-01 City House
Singapore 068877.

Attention :- **XA026**

Page # :- 1 134681

Veh # :- SLE6731R

Veh Model :- VOLKSWAGEN POLO

Estimate# :- CK419027

Claim # :-

ACC. Date :- 09/04/19

Terms :- C.O.D Days

Remarks :-

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel : **(65) 6476 3333**
 Fax : (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel : **(65) 6272 3892**
 Fax : (65) 6270 8314

Co. Reg. 198904033G
 GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
	TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS		900	950.00
	TO INSPECT ON FRONT HEADLAMP WATER LEAKAGE TEST		X	40.00
	TO REMOVE FRONT AIRCON CONDENSER & TOP UP GAS		100	150.00
	TO APPLY SEAL ON WELDING JOINT & NEW PARTS		30	80.00
	TO SETTING FRONT HEADLAMP ADAPTIVE		80	150.00
	TO RUST PROOF ON ACCIDENT DAMAGED PARTS		30	40.00
	TO REMOVE & REFIX REAR PARKING SENSOR & CHECK WIRING		30	80.00
	LABOUR TOTAL S\$	1970		2,740.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 12,703.88

GST @ 7 % 889.27

AMOUNT DUE S\$ 13,593.15

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Printed Name:

P- 7184.74
 M- 182.40
 L- 1970
 9337.14
 L/S - 7469.71
 = 7450

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 100B,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Performa Invoice

21/05/2019

MS FIRST CAPITAL INSURANCE LIMITED

36 Robinson Road

#16-01 City House

Singapore 068877.

Attention :- XA026

Page # :- 1 134681

Veh # :- SLE6731R

Veh Model :- VOLKSWAGEN POLO

Performa# :- CK508230

JOB # :- T510419

ACC. Date :- 09/04/19

Terms :- C.O.D

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	Lump Sum Amount			4,800.00

E. & O.E

AMOUNT S\$ 4,800.00

GST @ 7 % 336.00

AMOUNT DUE S\$ 5,136.00

Customer's Signature/Co. Stamp

MOVA AUTOMOTIVE PTE LTD

Please issue the payment of **S\$ 6,553.89** in favor of **MOVA AUTOMOTIVE PTE LTD.**

If you have any enquires, please call or email **Suann Chiu – suann@moval.com.sg**

Thank you.
Yours faithfully,
For Claims Manager
Claims Department

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: **(65) 6476 3333**
Fax: (65) 6271 5891
www.moval.com.sg

Workshop Dept:
Block 100B,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

NOTE: # Please note that the Loss of Use/Rental will be paid based on negotiation and on the NIMA Protocol (Court Guideline).
As of 01.06.08 all claims scenario will be based on the BOLA, Barometer Of Liability set by GIA, General Insurance Association of Singapore.

Tel: **(65) 6272 3892**
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19007155/Etd3e2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 29-07-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7207A	Veh. Inspected	SLE 6731R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002484MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	22/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN POLO	c.c	1390	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	WWWZZZ6RZAU006340	Colour	RED	
Odometer	84213	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	LING LONG	7 mm	
L/H Front Tyre	185/60 R15	LING LONG	7 mm	
R/H Rear Tyre	185/60 R15	LING LONG	7 mm	
L/H Rear Tyre	185/60 R15	LING LONG	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/04/2019	Inspection Date	23/04/2019	
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 6731R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET	DENTED	1,050.20	1,050.20
2	BONNET HINGE @\$115.00	TO REPAIR SEE LABOUR	230.00	-
1	FRONT FENDER RH	DENTED	498.75	498.75
1	COWLING RH	NOT NECESSARY	181.35	-
10	COWLING CLIPS @\$3.80	NOT NECESSARY	38.00	-
1	COWLING LH	TO REPAIR SEE LABOUR	181.35	-
10	COWLING CLIPS @\$3.80	NOT NECESSARY	38.00	-
2	FRONT HEADLAMP L+R @\$590.90	BROKEN	1,181.80	972.00
2	FRONT HEADLAMP LOWER BRACKET L+R @\$163.15	NOT NECESSARY	326.30	-
2	FRONT HEADLAMP TOP PANEL L+R @\$94.35	DENTED	188.70	188.70
1	FRONT SUPPORT PANEL	BROKEN	842.25	842.25
1	FRONT BONNET LOCK	BENT	369.95	369.95
1	FRONT GRILLE INNER	BROKEN	385.85	385.85
1	FRONT EMBLEM	MISSING	162.95	162.95
1	FRONT BUMPER	DENTED	1,003.45	810.00
2	FRONT BUMPER RETAINER L+R @\$135.00	BROKEN	270.00	174.00
10	BUMPER CLIPS @\$3.80	NECESSARY	38.00	30.00
1	FRONT BUMPER TOW COVER	TO REPAIR SEE LABOUR	48.95	-
1	FRONT LOWER GRILLE	CUT	298.25	298.25
2	FRONT FOG LAMP GARNISH L+R @\$108.60	O/S MISSING / N/S NOT NECESSARY	217.20	108.60
1	FRONT REINFORCEMENT	DENTED	673.80	547.80
1	FRONT RADIATOR	DENTED	1,021.75	1,021.75
1	RADIATOR COWLING	BROKEN	187.85	187.85
1	FAN MOTOR	NOT NECESSARY	697.65	-
1	CONDENSER	DENTED	698.35	698.35
1	REAR BUMPER (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT DOOR RH (NPA)	TO REPAIR SEE LABOUR	-	-

Report Ref No. CS/FCI19007155/Etd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT FENDER LH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER BRACKET CENTRE (NPA)	NOT NECESSARY	-	-
1	REAR REINFORCEMENT (NPA)	NOT NECESSARY	-	-
1	REAR PARKING SENSOR (NPA)	NOT NECESSARY	-	-
	LESS 10% DISCOUNT		-1,083.07	-834.73
			9,747.63	7,512.52
	<u>SPECIAL NETT ITEMS</u>			
1	NUMBER PLATE (SN)	NECESSARY	45.00	35.00
1	COOLANT (SN)	NECESSARY	37.40	37.40
1	AIRCON GAS (SN)	NECESSARY	80.00	80.00
1	AUTO OIL (SN)	NECESSARY	53.85	30.00
			216.25	182.40
	<u>LABOUR</u>			
	TO REPAIR FRONT WHEELHOUSE L+R, FRONT DOOR RH, FRONT FENDER LH, TO STRAIGHTEN & REALIGN ON ACCIDENT DAMAGED PARTS. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF BONNET HINGE, COWLING LH, FRONT BUMPER TOW COVER, REAR BUMPER, FRONT DOOR RH AND FRONT FENDER LH.		1,250.00	800.00
	TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS.		950.00	900.00
	TO INSPECT ON FRONT HEADLAMP WATER LEAKAGE TEST.	NOT NECESSARY	40.00	-
	TO REMOVE FRONT AIRCON CONDENSER & TOP UP GAS.		150.00	100.00
	TO APPLY SEAL ON WELDING JOINT & NEW PARTS.		80.00	30.00
	TO SETTING FRONT HEADLAMP ADAPTIVE.		150.00	80.00
	TO RUST PROOF ON ACCIDENT DAMAGED PARTS.		40.00	30.00
	TO REMOVE & REFIX REAR PARKING SENSOR & CHECK WIRING.		80.00	30.00
			2,740.00	1,970.00
	GRAND TOTAL		12,703.88	9,664.92
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,800.00

Report Ref No. CS/FCI19007155/Etd3e2



Report Ref No. CS/FCI19007155/Etd3e2

MARKET VALUE: \$13,000.00(EST)-LTA REIMBURSEMENT VALUE: \$8,619.00=NETT VALUE: \$4,381.00

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.