

INSURANCE

KSC

DOI:

ASSIGNMENT

24/4/19

Date / Time:

23/4/19

Registered in Merimen:

21/4/19

Freight / CCU / FTE



Insured Vehicle No.:

SKK 6795 L

Name of Insured:

RAMIAH RAMIAH OBU

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

11/04/2019

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLP 7194B



INSRS:

WSP:

Tel:

Liability:

RMKS:

Chen hoon



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call CI:

After call ltr to CI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to CI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: KSC

Repair Cost: PIP S\$1,134.80

(7 days) Reduction:

28 %

Email ☒ Call ☐

FINAL SETTLEMENT Date/Time: 03.03.20

Confirm with: KSC

Email ☒ Call ☐

Final Liability: % 100

(Agreed / Assessed) BOLA S/N No.: 24

If NO or B 28, Ass. Lia:

Repair Cost: WILCO S\$1,634.24

REMOVE OUT OF P. LOT 5 (WILCO) (M1 7P)

Loss of Rental (LOR): WILCO S\$1,171.00

(11 days) x 100

Loss of Use (LOU): S\$ - (3 x days)

Loss of Income (LOI): S\$ - (3 x days)

LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search: S\$31.00

Medical: S\$ -

Disbursement: S\$ -

Legal Cost: S\$ -

(e.g. Tow/Independent)

Total: S\$8,810.24

Global Sum S\$:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TT

3) Survey fee: 4320

FINAL PAYMENT Date/Time: 02.03.20

Confirm with: KSC

Email ☒ Call ☐

Payee 1: S\$8,810.24

Name 1: (M1) GOON MOTO

Payee 2: (Strike if N/A) S\$ -

Name 2:

Payee 3: (Strike if N/A) S\$ -

Name 3:

COPY SENT
9/3/2020

ASSIGNMENT

From: _____ Date: 24/4/19

Estimated Cost: _____

OD ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLP 7194B

at Workshop m/s Chew Guan Motor

of Bike 10, Amk Ind. park 2A # 01-15

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No


Est. Repairs: 07 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date: _____ Person Contacted: _____

Vehicle: IN / OUT



Veh No: SLP 7194B Yr Regn: 06, 17

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Grey Hybrid 1496 C.C.

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 129325 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: Cam 41 - 109591

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____ R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front: _____ Rear: _____

R/Bal. 9 mm R/Bal. 9 mm

L/Bal. 9 mm L/Bal. 9 mm

D.O.A. 11/4/19 D.O.I. 24/4/19

Survey held at ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	P/P: 7.134.30 (RBD: +2,832 28/1)

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee: _____

Transportation: _____

S + RS, SR _____

Photos _____

Others _____

TOTAL: _____

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

8713480

Policy No

Third Party

Date 23.04.2019

Accident Date : 11.04.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	金额 Amount \$ cts.
Estimate Cost Of Repair To "Honda Grace" Reg. No. SLP7194B Claiming Against Your Insured Reg. No. SKK6795L			
1pc	Front Fender RH		295.00 ✓
1pc	Front Fender Shield		84.00 ✓
10pcs	Front Fender Shield Clips	3.50	35.00 ✓
1pc	Front Fender Badge Hybrid		33.50 ✓
1pc	Front Door RH		722.00 ✓
1pc	Front Door Sticker		20.00 ✓
1pc	Front Door Lower Hinge		65.00 X
1pc	Front Door Weatherstrip		162.00 ✓
1pc	Front Door Wing Mirror		645.00 X
1pc	Front Door Wing Mirror Cover		64.00 X
1pc	Front Door Glass Regulator		269.00 ✓
1pc	Front Door Glass Motor		269.00 ✓
1pc	Front Door Lower Rubber Seal		49.00 ✓
10pcs	Front Door Trim Board Clips	3.50	35.00 X
1pc	Front Wheel Cap		175.00 X
1pc	Front Wheel Bearing		285.00 X
1pc	Rocker Panel RH 970.00		1,120.00 ✓
1pc	Rear Door RH		832.00 ✓
1pc	Rear Door Sticker		16.50 ✓
1pc	Rear Door Weatherstrip		149.00 ✓
1pc	Rear Door Glass Regulator		211.00 ✓
10pcs	Rear Door Trim Board Clips	3.50	35.00 X
1pc	Rear Door Lower Hinge		64.00 ✓
1pc	Rear Wheel Cap		192.00 ✓
1pc	Rear Wheel Bearing		310.00 ✓
1pc	Rear Shock Absorber		167.00 ✓
1pc	Rear Bumper 696.00		955.00 ✓
10pcs	Rear Bumper Clips	3.50	35.00 ✓
1pc	Rear Bumper Reflector		52.00 X
Less 20%			7,346.00
			1,469.20
			5,876.80
C/F			5,876.80

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AD

Policy No: _____ Third Party _____

Date 23.04.2019

Accident Date : 11.04.2019

承接汽车烧焊喷漆及
代理各种车辆赔偿

Specialised in Car Painting, Welding
Panel-Beating and Insurance Claim.

ESTIMATE

ESTIMATE			
数量 Quantity	货名 DESCRIPTION	单价 Unit Price	金额 Amount \$ cts.
	Estimate Cost Of Repair To "Honda Grace" Reg. No. SLP7194B Claiming Against Your Insured Reg. No. SKK6795L		
		B/F	5,876.80
	To Conduct Front Electrical Check, Locking System, Etc		40.00 201
	To Dismantle / Transfer Door Fittings / Ancillary Accessories * 2		300.00 1201
	To Dismantle / Replace Front Wheel Bearing and Perform Press	nn	120.00 X
	To Dismantle / Replace Rear Wheel Bearing Perform Press & Absorber		180.00 801
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		200.00 1201
	To Conduct Computerize Wheel Alignment Test		80.00 601
	To Conduct High Speed Balancing	nn	80.00 X
	To Supply Panel Joint Sealant - Rocker Panel		60.00 301
	To Reseal Rocker Panel Chip Resistant Primo		100.00 801
	To Dismantle / Refit Rear Seats, Floor Carpet.		150.00 801
	To Diagnose / Erase / Reprogram Air Bag SRS Error Code	nn	180.00 X
	Labour Charge - Panel Beating, Repairing Of Front Fender Inner Panel Floor Panel, Door 'B' Pillar Rear Fender Etc Cnt, Weld Rocker Panel and Parts Replacement		1,200.00 9001
	To Respray Affected Areas		1,400.00 12001
		Total :	9,966.80

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Not Authored
1.2/1
Returning B/L point

Today

Policy No: Third Party

Date: 23.04.2019

Accident Date : 11.04.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Honda Grace" Reg. No. SLP7194B Claiming Against Your Insured Reg. No. SKK6795L			
1pc	Front Fender RH		R 295.00 ✓
1pc	Front Fender Shield		R 84.00 ✓
10pcs	Front Fender Shield Clips	3.50	R 35.00 ✓
1pc	Front Fender Badge Hybrid		R 33.50 ✓
1pc	Front Door RH		R 722.00 ✓
1pc	Front Door Sticker		R 20.00 ✓
1pc	Front Door Lower Hinge		R 65.00 X
1pc	Front Door Weatherstrip		R 162.00 ✓
1pc	Front Door Wing Mirror		R 645.00 X
1pc	Front Door Wing Mirror Cover		R 64.00 X
1pc	Front Door Glass Regulator		R 269.00 ?
1pc	Front Door Glass Motor		R 269.00 ?
1pc	Front Door Lower Rubber Seal		R 49.00 ✓
10pcs	Front Door Trim Board Clips	3.50	R 35.00 X
1pc	Front Wheel Cap		R 175.00 X
1pc	Front Wheel Bearing		R 285.00 X
1pc	Rocker Panel RH		R 1,120.00 ✓
1pc	Rear Door RH		R 832.00 ✓
1pc	Rear Door Sticker		R 16.50 ✓
1pc	Rear Door Weatherstrip		R 149.00 ✓
1pc	Rear Door Glass Regulator		R 211.00 ?
10pcs	Rear Door Trim Board Clips	3.50	R 35.00 X
1pc	Rear Door Lower Hinge		R 64.00 ?
1pc	Rear Wheel Cap		R 192.00 ✓
1pc	Rear Wheel Bearing		R 310.00 ?
1pc	Rear Shock Absorber		R 167.00 ?
1pc	Rear Bumper		R 955.00 ✓
10pcs	Rear Bumper Clips	3.50	R 35.00 ✓
1pc	Rear Bumper Reflector		R 52.00 X
			7,346.00
	Less 20%		1,469.20
			5,876.80
		C/F	5,876.80

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 23.04.2019

Accident Date : 11.04.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Honda Grace" Reg. No. SLP7194B Claiming Against Your Insured Reg. No. SKK6795L		
		B/F	5,876.80
	To Conduct Front Electrical Check, Locking System, Etc		40.00 201
	To Dismantle / Transfer Door Fittings / Ancillary Accessories * 2		300.00 1201
	To Dismantle / Replace Front Wheel Bearing and Perform Press	nn	120.00 X
	To Dismantle / Replace Rear Wheel Bearing Perform Press & Absorber		180.00 7
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		200.00 1201
	To Conduct Computerize Wheel Alignment Test		80.00 601
	To Conduct High Speed Balancing	nn	80.00 X
	To Supply Panel Joint Sealant - Rocker Panel		60.00 301
	To Reseal Rocker Panel Chip Resistant Primo		100.00 801
	To Dismantle / Refit Rear Seats, Floor Carpet		150.00 801
	To Diagnose / Erase /Reprogram Air Bag SRS Error Code		180.00 7
	Labour Charge - Panel Beating, Repairing Of Front Fender Inner Panel Floor Panel, Door 'B' Pillar,Rear Fender Etc.Cnt, Weld Rocker Panel and Parts Replacement		1,200.00 9001
	To Respray Affected Areas		1,400.00 12001
		Total :	9,966.80

LKK Auto Consultants hereby notify
the Receiver of the following:

- To survey vehicle damage
- To supply consumable parts during recovery
- Repaired area must be inspected
- Third party survey is on a "Without Prejudice" basis
- No legal hold/interest is placed
- Supplementary items must be reserved and
is subject to final approval from Insurance Company

Acknowledged by Receiver

Signature:

Date:

PRE-REPAIR INSPECTION REQUEST – SLP7194B vs SKK6795L (OI) on D.O.A.: 11/04/2019

From: Hor, Yinnal
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim; Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur
Sent: 23/4/2019 9:30:27 AM

Hi,

Please refer to the enclosed request from **Chew Goon Motor**.

Claim no : 1134271036SG003
Case Owner : NORSIAH BTE MD NOOR

If you have any queries/concerns, please let us know.

Thanks & Regards,

Yin Rui, Hor (Viviane)
AIG
Claim Adjuster II, Singapore FNCI, Claims Operations – Auto
Yinnal.Hor@aig.com | www.aig.sg

4:52pm @ 23/4/19
person @ Yan
vehicle in
average on 24/4/19

From: Chew Goon Motor(ad3) [mailto:ad3@chewgoonmotor.com.sg]
Sent: Monday, April 22, 2019 4:49 PM
To: Chan, Yoke Shi
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim; Noor Mariesa; Md Ishak; Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshana; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina; chewgoon@singnet.com.sg; Eric
Subject: [EXTERNAL] SLP7194B Claiming Against Your Insured Vehicle No. SKK6795L Acc Date: 11.04.2019

This message is from an external sender; be cautious with links and attachments.

Dear Sir/ Mdm,

Vehicle SLP7194B is lying at our workshop.

According to your list, we will prefer **LKK Auto Consultants Pte Ltd** to survey the vehicle.
Kindly arrange for survey.

Thanks & Regards,
Kelly

Chew Goon Motor
Blk 10, Ang Mo Kio Ind Park 2A,
Ave 5 #01-15, 16 & 17,
Ang Mo Kio Autopoint
Singapore 568047
Tel: 6484 1626
Fax: 6484 0465

Sent from Mail for Windows 10

IMPORTANT NOTICE:
The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**TO WHOM IT MAY CONCERN
LETTER OF AUTHORITY**

ACCIDENT ON 11.04.2019 AT KING GEORGE'S AVENUE
INVOLVING SLP7194B & SKK6795L

I, TGEE WHEELS NRIC No. 53361381K

OF _____

Owner of motor vehicle registration No. SLP7194B

insured by NTUC INCOME

under policy no. 5091924396-01 do hereby authorise **M/S CHEW GOON MOTOR** of
Blk 10 Ang Mo Kio Ind. Park 2A, Ave 5, #01-15, 16 & 17 AMK Autopoint Singapore
568047 as my authorised representative to write, negotiate & settle claim on my behalf in my
claim against the owner and/or driver of motor vehicle registration no. SKK6795L
in respect of the above mentioned accident.

I also hereby authorise that the agreed settlement sum be made in favour of my
representative **M/S CHEW GOON MOTOR** and that the said payment be forwarded to them
as full and final discharge of my claim. I hereby exonerate the
AIG INSURANCE and/or their insured and/or driver of vehicle
no. SKK6795L from any liability after payment of any claim to my authorised
representative **M/S CHEW GOON MOTOR**.

Signature : 
(Company's stamp if necessary)



Dated : _____

WITHOUT PREJUDICE to:

- (a) Insurers' Subrogated Claim and/or
 - (b) Any Personal Injury Claims
- [Note: This Notice supersedes any inconsistencies found in this Discharge Voucher]

C/O BLK 10 ANG MO KIO IND. PARK 2A
AVE 5, #01-15, 16 & 17 AMK AUTOPOINT
SINGAPORE 568047

DATE :

THE MOTOR CLAIMS DEPARTMENT
AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

DEAR SIRs,

ACCIDENT ON : 11.04.2019
ALONG/AT : KING GEORGE'S AVENUE
INVOLVING : SLP7194B & SKK6795L

I/ We /am /are the registered owner of vehicle no. SLP7194B which was involved
in the above mentioned accident with your insured vehicle no. SKK6795L.

As the accident was caused due to the gross negligence on the part of your insured driver of
vehicle no. SKK6795L . I/we have no alternative but to look to you for
compensation for the losses sustained as a result of the above accident.

Presently, my/ our vehicle is lying at **M/S CHEW GOON MOTOR** of Blk 10, Ang Mo Kio
Industrial Park 2A, Ave 5, #01-15, 16 & 17 AMK Autopoint, Singapore 568047. Telephone
6484 1626. Kindly arrange to have it surveyed by your assessor, failing which I / we shall
authorised my/ our repairer to proceed on with the repairs and the final bills will be
forwarded to you for settlement.

Thank you.

Yours faithfully

THIRD PARTY'S DISCHARGE AGREEMENT

Claim ref. : _____

To M/s : AIG INSURANCE

In consideration of your paying at my request to M/S CHEW GOON MOTOR of Blk 10
Ang Mo Kio Ind. Park 2A, #01-15, 16 & 17, Ave 5, Singapore 568047 the sum of Dollars

: TEN THOUSAND ONE HUNDRED FOUR AND CENTS EIGHTY FOUR ONLY

(\$ 10,104.84) being cost of repair carried out to my/our motor vehicle no :

SLP7194B All actions, claims and damages arising out of and, in
consequence of an accident occurring on 11.04.2019

at KING GEORGE'S AVENUE

between SLP7194B & SKK6795L

I/We furthermore agree that the foregoing sum is voluntarily accepted as full and final
compromise and settlement of all claims, that the payment of the said amount shall never
be construed as an admission of liability by the parties hereby reached.

Signature :  _____



Witness : _____

Name : TGEE WHEELS

Name : _____

NRIC No. : 53361381K

Date : _____

Address : _____

Date : _____

WITHOUT PREJUDICE to:

- (a) Insurers' Subrogated Claim and/or
- (b) Any Personal Injury Claims

[Note: This Notice supersedes any inconsistencies
found in this Discharge Voucher]

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	1381K
Vehicle Details	
Vehicle No.:	SLP7194B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	12 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	GRACE 1.5LX HYBRID A
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	LEB5259612
Chassis No.:	GM41109591
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$21,900.00
Original Registration Date:	15 Jun 2017
First Registration Date:	15 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jun 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jun 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,001.00
COE Rebate Amount:	\$42,400.00
Total Rebate Amount:	\$46,150.00

The information contained herein is correct as at 12 Apr 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)
Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Apr 2019 Edit Reg		23 Apr 2019 00:00 Edit Adj Rpt	\$57,134.80 Edit Estimates	\$57,134.80 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS			[Created by adjuster]
Insured:	RAMIAH KAMALA DEVI, ID: S1151843E, Tel: +6597556489		
Main Claimant:	TGEE WHEELS, Co. Reg. No.: 53361381K		
Vehicle Reg. No.:	SLP7194B	Date of Loss:	11/04/2019 00:00 - :59 [21 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1134271036SG	Policy/Cover Note No.:	2100348736 (Comprehensive)
Vehicle Reg. No. (Insured):	SKK6795L	Policy No. (Claimant):	5091924396-01
		Excess:	
Repairer:	Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64841626		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 03/05/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (21/02/2020): Alert - Adj Mandate Approved (\$58842.24) - SLP7194B - Claim Handler: MdNoor, Nor...
- AIG_SG (02/05/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLP7194B (1134271036SG)
[SKK6795L]
TP
TGEE WHEELS
Apr 11 2019 12:00AM
[RAMIAH KAMALA DEVI]
Chew Goon Motor

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	[Draft]	Third Party Express Settlement - Payment Breakdown		Edit

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/02/20 16:44	General View	Load JPG	☒
2	17/02/20 16:44	General View	Load JPG	☒
3	17/02/20 16:44	General View	Load JPG	☒
4	17/02/20 16:44	General View	Load JPG	☒
5	17/02/20 16:44	General View	Load JPG	☒
6	17/02/20 16:44	General View	Load JPG	☒
7	17/02/20 16:44	General View	Load JPG	☒
8	17/02/20 16:44	General View	Load JPG	☒
9	17/02/20 16:44	General View	Load JPG	☒
10	17/02/20 16:44	General View	Load JPG	☒
11	17/02/20 16:44	General View	Load JPG	☒
12	17/02/20 16:44	General View	Load JPG	☒
13	17/02/20 16:44	General View	Load JPG	☒
14	17/02/20 16:44	General View	Load JPG	☒
15	17/02/20 16:44	General View	Load JPG	☒
16	17/02/20 16:44	General View	Load JPG	☒
17	17/02/20 16:44	General View	Load JPG	☒
18	17/02/20 16:44	General View	Load JPG	☒
19	17/02/20 16:44	General View	Load JPG	☒
20	17/02/20 16:44	Odometer Reading	Load JPG	☒
21	17/02/20 16:44	General View	Load JPG	☒
22	17/02/20 16:44	Chassis Number	Load JPG	☒
23	17/02/20 16:44	General View	Load JPG	☒
24	17/02/20 16:44	General View	Load JPG	☒
25	17/02/20 16:44	General View	Load JPG	☒
26	17/02/20 16:44	General View	Load JPG	☒
27	17/02/20 16:44	General View	Load JPG	☒
28	17/02/20 16:44	Reinspection Photo	Load JPG	☒
29	17/02/20 16:44	Reinspection Photo	Load JPG	☒

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/04/19 19:15	ACKNOWLEDGEMENT EMAIL TO AIG DD 23.04.2019	Load PDF	
2	23/04/19 19:15	EMAIL FROM AIG DD 23.04.2019	Load PDF	
3	02/05/19 13:25	TP ESTIMATE - MARKED	Load PDF	
4	02/05/19 13:25	TP GIA REPORT	Load PDF	
5	22/05/19 17:38	LETTER TO OI	Load PDF	
6	05/02/20 15:47	RENTAL RECEIPT	Load PDF	
7	05/02/20 15:47	GIA SEARCH	Load PDF	
8	05/02/20 15:47	LOD	Load PDF	
9	16/03/20 10:21	WORKSHOP INVOICE	Load PDF	
10	16/03/20 10:21	AUTHORISATION TO ACT FORM	Load PDF	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
11	16/03/20 10:21	Release Voucher		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	02/05/19 10:48	01 GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

v

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)

Vehicle No:	SKK6795L (Insd veh)	Model:	HONDA GRACE HYBRID 1.5
	SLP7194B (TP veh)		(A)
Date of Accident:	11/04/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	10,664.48
Final Repair Cost	:	\$	7,634.24
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	1,177.00 11 days
LTA / GIA Search Fee	:	\$	31.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	8,842.24
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100____(%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____(%)		Assessed Liability (*): _____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Chew Goon Motor	:	\$ 8,842.24
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

16 Mar
2020

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19007166/KEA3Q2

Date: 16/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100348736
 Claimant Vehicle No: SLP7194B Insured Vehicle No: SKK6795L
 Date of Loss: 11/04/2019 Nature of Claim: TP Claim No: 1134271036SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP7194B
 Make & Model: HONDA GRACE HYBRID, 1.5 (A) Engine No: LEB5259612
 Reg. Date: 15/06/2017 (Man. Year: 2017) Chassis No: GM41109591
 Colour: Metallic Black Odometer: 129325 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 9 mm
 Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,876.80	4,464.80	1,412.00	24.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,090.00	2,670.00	1,420.00	34.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,966.80	7,134.80	2,832.00	28.41
+ GST 7.00/7.00% (S\$)	697.68	499.44	198.24	28.41
Nett Amount (S\$)	10,664.48	7,634.24	3,030.24	28.41
+ Car Rental (11.0 x S\$100.00/day + 7.00% GST) (S\$)		1,177.00		
+ Doc/Search Fee (S\$)		31.00		
Nett Liability (S\$)		8,842.24		

INSPECTION

Date of Assignment: 23/04/2019
 Date Inspected: 24/04/2019 Inspected At: Chew Goon Motor (AMK)
 Blk 10 Ang Mo Kio Industrial Park 2A,
 #01-15/16 & 17, AMK Autopoint
 Singapore 568047
 Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Bent	295.00 FL	*295.00 FL
2	1		*FRONT FENDER SHIELD	Distorted	84.00 FL	*84.00 FL
3	10		*FRONT FENDER SHIELD CLIPS	Necessary	35.00 FL	*35.00 FL
4	1		*FRONT FENDER BADGE HYBRID	Necessary	33.50 FL	*33.50 FL
5	1		*FRONT DOOR RH	Bent	722.00 FL	*722.00 FL
6	1		*FRONT DOOR STICKER	Necessary	20.00 FL	*20.00 FL
7	1		*FRONT DOOR LOWER HINGE	Repair	65.00 FL	*- FL
8	1		*FRONT DOOR WEATHERSTRIP	Cut	162.00 FL	*162.00 FL
9	1		*FRONT DOOR WING MIRROR	Serviceable	645.00 FL	*- FL
10	1		*FRONT DOOR WING MIRROR COVER	Serviceable	64.00 FL	*- FL
11	1		*FRONT DOOR GLASS REGULATOR	Distorted	269.00 FL	*269.00 FL
12	1		*FRONT DOOR GLASS MOTOR	Jammed	269.00 FL	*269.00 FL
13	1		*FRONT DOOR LOWER RUBBER SEAL	Cut	49.00 FL	*49.00 FL
14	10		*FRONT DOOR TRIM BOARD CLIPS	Not Necessary	35.00 FL	*- FL
15	1		*FRONT WHEEL CAP	Serviceable	175.00 FL	*- FL
16	1		*FRONT WHEEL BEARING	Not Necessary	285.00 FL	*- FL
17	1		*ROCKER PANEL RH	Bent	1,120.00 FL	*970.00 FL
18	1		*REAR DOOR RH	Bent	832.00 FL	*832.00 FL
19	1		*REAR DOOR STICKER	Necessary	16.50 FL	*16.50 FL
20	1		*REAR DOOR WEATHERSTRIP	Cut	149.00 FL	*149.00 FL
21	1		*REAR DOOR GLASS REGULATOR	Distorted	211.00 FL	*211.00 FL
22	10		*REAR DOOR TRIM BOARD CLIPS	Not Necessary	35.00 FL	*- FL
23	1		*REAR DOOR LOWER HINGE	Distorted	64.00 FL	*64.00 FL
24	1		*REAR WHEEL CAP	Dented	192.00 FL	*192.00 FL
25	1		*REAR WHEEL BEARING	Jammed	310.00 FL	*310.00 FL
26	1		*REAR SHOCK ABSORBER	Bent	167.00 FL	*167.00 FL
27	1		*REAR BUMPER	Mtg Cracked	955.00 FL	*696.00 FL
28	10		*REAR BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
29	1		*REAR BUMPER REFLECTOR	Serviceable	52.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	7,346.00	5,581.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,469.20	1,116.20
Total Parts (\$\$)	5,876.80	4,464.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT FRONT ELECTRICAL CHECK, LOCKING SYSTEM, ETC.	New	40.00	20.00
2	TO DISMANTLE / TRANSFER DOOR FITTINGS / ANCILLARY ACCESSORIES	New	300.00	120.00
3	TO DISMANTLE / REPLACE FRONT WHEEL BEARING AND PERFORM PRESS.	New	120.00	0.00
4	TO DISMANTLE / REPLACE REAR WHEEL BEARING AND PERFORM PRESS & ABSORBER.	New	180.00	80.00
5	TO APPLY RUST PROOFING / RESEAL TUFF COATING TREATMENT TO RESPRAY / REPLACED / REPAIR PANEL.	New	200.00	120.00
6	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST.	New	80.00	60.00
7	TO CONDUCT HIGH SPEED BALANCING.	New	80.00	0.00
8	TO SUPPLY PANEL JOINT SEALANT - ROCKER PANEL.	New	60.00	30.00
9	TO RESEAL ROCKER PANEL CHIP RESISTANT PRIMO.	New	100.00	60.00
10	TO DISMANTLE / REFIT REAR SEATS, FLOOR CARPET.	New	150.00	80.00
11	TO DIAGNOSE / ERASE / REPROGRAM AIR BAG SRS ERROR CODE.	New	180.00	0.00
12	LABOUR CHARGE - PANEL BEATING, REPAIRING OF FRONT FENDER INNER PANEL , FLOOR PANEL, DOOR B PILLAR, REAR FENDER ETC. CNT, WELD ROCKER PANEL AND PARTS REPLACEMENT.	New	1,200.00	900.00
13	TO RESPRAY AFFECTED AREAS.	New	1,400.00	1,200.00
Gross Labour Cost (S\$)			4,090.00	2,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >