

ASSIGNMENT (Office)

Surveyor

REG CS3/ASM 19007(74) Rkd302

Agent's Instruction

From (Person)

Rahul
Motorsunny

of

ASM(CAXA)

Date/Time

23/4/19 @ 11:15am

Estimated Cost

Bill to

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

JQN 1638

Insured

SKN 3512R

at Workshop n/a

Teamwork

Tel

68442475

of

53 ubi Ave 1 # 01-25

Policy No

Claim No

S9M01L3G

Sum Insured

Excess

Make of Veh

D.O.A

22/04/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time

1:49pm @ 23/4/19

Person Contacted

Darren

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (X) Estimate

JQN 1638 - X

SKN 3512R - C04 / ASM # 018466 / Cpa342

D.O.A: 21/4/17

Dismantle: 30/4/2019

Surveyor *Form*


REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: JQN 1638 Yr Regn: Dec / 14
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____

Make: Yamaha 135LC C.C. 135
 Colour: MULTI A/C: Insured / Std / NI / NA
 Sp. Reading: 5663 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: _____
 Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 70/90-17
 R: 80/90-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or MAXXIS

Front Rear
 R/Bal. 3 mm R/Bal. 3 mm
 L/Bal. mm L/Bal. mm
 D.O.A. 22/04/19 D.O.I. 23/04/19 0342pm

Survey held at Term work
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair Range - (2k-25k) / 3 day
	JQN 1638 - X
	SKN 3512R - X
	<i>21/5/2019</i>

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format : PR

Lump Sum / I.B.I. (\$) _____

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

100
100



Service Request Details

Claim

S9M01L3G

Reference

CC4/ASM19007174/ea3 

Loss Date

April 22, 2019

Report Date

Apr 23, 2019 8:53:39 AM

Request Date

April 23, 2019

Due Date

April 23, 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Complete Work

More ▼

Vehicle Information

Incident Vehicle Registration #

JQN1638

Model

MOTORCYCLE

Service Address

...

Primary Contact/Insured

LEE KOH SONG

13 UPPER BOON KENG ROAD, 380013, Singapore

96224143

OATAN@SINGNET.COM.SG

Claim Handler

NG Stacey

6568804351

stacey.ng@axa.com.sg

Additional Instructions

INSURED NOT REPORTED

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

TYPE



SENT

4/24/19 9:42 AM

FROM

NG Stacey

SUBJECT

Non reporting

BODY

Please assist to follow up.



Nivitha (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Tuesday, 23 April 2019 11:15 AM
To: assignments
Subject: FW: OUR REF : 1904-54 // YOUR REF : SKN3512R ACCIDENT INVOLVING SKN3512R AND JQN1638
Attachments: 2019_04_22_17_47_58.pdf

Hi

TP smart. Kindly assist. Plz confirm PRI / DS.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: TEAMWORK <claims@teamworkgarage.com>
Sent: Monday, 22 April, 2019 5:49 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Cc: TEAMWORK <claims@teamworkgarage.com>
Subject: OUR REF : 1904-54 // YOUR REF : SKN3512R ACCIDENT INVOLVING SKN3512R AND JQN1638

WITHOUT PREJUDICE

OUR REF : 1904-54
YOUR REF : SKN3512R

Dear Sir / Madam,
PRE-REPAIR INSPECTION FOR JQN1638
ACCIDENT INVOLVING SKN3512R AND JQN1638 ON 22.04.2019.

We refer to the above matter and enclosed herewith our client's GIA report and notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction-Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention.

Regards,

Shu Shan

Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1
#01-24
Paya Ubi Industrial Park
Singapore 408934
Tel: 6844 2475
Fax: 6844 2474

JABATAN PENGANGKUTAN JALAN MALAYSIA

PERAKUAN PENDAFTARAN KENDERAAN

MSR 8952452
YEARWORTH

NO PENDAFTARAN JON1638

781005015063
[MAL]

1.000
36/

TERI PUH HOCK

NO 23 JLN HILIRALANG 8 TIRU TUN ABINAH
81200 JOHOR BAHRU JOHOR

8000000000
011
Berat Kurb
8.1 M
6.01
8.00
8.00
8.00
8.00
8.00
8.00
8.00
8.00
8.00
8.00
8.00

MSR-205621
PRT-204100240621
YABHA
YABHA 135LG
135 LG
PRT-111
0011
M3100HCL
M3100HCL
0014
00712/2014
PERUBAHAN

12 bulan
RM7.00

Nama Pemohon
Syarikat

Alamat

No. Enjin
No. Chasis
Binaan
Merek Model
Kapasiti Enjin
Sistem Pajam
Warna
Kelas Angkutan
Jenis Bahan
Tahun Dibina
Tarikh Pendaftaran
Status Pemilik
Masa Tg. Uji
Denda
Kerusi Kanan
Kerusi Kiri

8 bulan
RM2.00

JABATAN PENGANGKUTAN JALAN MALAYSIA

PERAKUAN PENDAFTARAN KENDERAAN

NO. PENDAFTARAN

JON1638

8852452
YEARONIN

Nama Pemilik
Kenderaan

YER PUN KUN

78100015962
(MAL)

Alamat

NO 22 JLN HILIRBALAH 8 TAN LUN ANTHAN
81000 JOHOR BAHRU JOHOR

No. Enjin

01996-248621

00000000

No. Chasis

PM10004100250021

00000000

Buatan

YAROKA

00000000

Nama Model

YAROKA 1350.0

00000000

Kapasiti Enjin

120 A.P

00000000

Bahan Bakar

PETROL

00000000

Warna

ORAN

00000000

Kelas Kenderaan

MOTOSIKAL

00000000

Tahun Bina

2014

00000000

Tahun Pendaftaran

08/12/2014

00000000

Status Pemohon

PERSEORANGAN

00000000

Starter Tempet

00000000

00000000

Denda

1

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

Kadar Lesen

00000000

00000000

UNTUK KEDUAH PEJABAT

Kedua-dua pejabat

NO 22 JLN HILIRBALAH 8 TAN LUN ANTHAN 81000 JOHOR BAHRU JOHOR

NOTA PENTING

1. Dokumen ini adalah dokumen rasmi. Ia adalah dokumen rasmi yang dikeluarkan oleh Jabatan Pengangkutan Jalan Malaysia (JPJ) dan ia adalah dokumen rasmi yang dikeluarkan oleh JPJ.
2. Dokumen ini adalah dokumen rasmi yang dikeluarkan oleh JPJ dan ia adalah dokumen rasmi yang dikeluarkan oleh JPJ.
3. Dokumen ini adalah dokumen rasmi yang dikeluarkan oleh JPJ dan ia adalah dokumen rasmi yang dikeluarkan oleh JPJ.
4. Dokumen ini adalah dokumen rasmi yang dikeluarkan oleh JPJ dan ia adalah dokumen rasmi yang dikeluarkan oleh JPJ.
5. Dokumen ini adalah dokumen rasmi yang dikeluarkan oleh JPJ dan ia adalah dokumen rasmi yang dikeluarkan oleh JPJ.
6. Dokumen ini adalah dokumen rasmi yang dikeluarkan oleh JPJ dan ia adalah dokumen rasmi yang dikeluarkan oleh JPJ.
7. Dokumen ini adalah dokumen rasmi yang dikeluarkan oleh JPJ dan ia adalah dokumen rasmi yang dikeluarkan oleh JPJ.
8. Dokumen ini adalah dokumen rasmi yang dikeluarkan oleh JPJ dan ia adalah dokumen rasmi yang dikeluarkan oleh JPJ.
9. Dokumen ini adalah dokumen rasmi yang dikeluarkan oleh JPJ dan ia adalah dokumen rasmi yang dikeluarkan oleh JPJ.
10. Dokumen ini adalah dokumen rasmi yang dikeluarkan oleh JPJ dan ia adalah dokumen rasmi yang dikeluarkan oleh JPJ.
11. Dokumen ini adalah dokumen rasmi yang dikeluarkan oleh JPJ dan ia adalah dokumen rasmi yang dikeluarkan oleh JPJ.
12. Dokumen ini adalah dokumen rasmi yang dikeluarkan oleh JPJ dan ia adalah dokumen rasmi yang dikeluarkan oleh JPJ.



SINGAPORE POLICE FORCE



T/20190422/2108

1 of 3

Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

Report No. T/20190422/2108

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/04/2019 16:28		Vide Report No.: G/20190422/0084		Station Diary No.: 13	
Informant's Particulars					
Name of Informant: TER POH HOCK			Address:		
ID Type / ID No.: FIN NO / F8072690L			Contact No.: Home/Office: Mobile: 91403233		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 40	Date of Birth: 05/10/1978	Type of Informant: Rider		
Race: Chinese			Language:		Institution / School Name:
Occupation: Working proprietor (construction)			Driving Licence Information: Class: 2B,3C Date of Expiry: 13/03/2024		

General Information of the Accident

Type of Accident:	Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 22/04/2019 13:20	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 BEDOK NORTH ROAD BEDOK RESERVOIR ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JQN1638	Motorcycle				Slightly Damaged	0
SKN3512R	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190422/2108

2 of 3

Police Station Of Origin:
Kampong Ubi NPP
9 Eunus Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

Report No. T/20190422/2108

CONTINUATION OF REPORT

Rider			
Name	TER POH HOCK	ID No.	F8072690L
Related Vehicle	JQN1638 (Motorcycle)	Contact No.	91403233
Hospital/Clinic	Intemedical 24hrs clinic	Class of Driving Licence & Expiry Date	Class: 2B,3C Date of Expiry: 13/03/2024
Date Treatment	22/04/2019	Date Discharge	22/04/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On 22/04/2019 at around 1320hrs, I riding my motorbike and I made a stop on the most left lane at the traffic junction of Bedok North Road and Bedok Reservoir Road as the traffic light was red in colour. While waiting for the traffic light to turn green, suddenly a vehicle hit the rear side of my motorbike. The driver was still sleeping inside the vehicle.



**SINGAPORE
POLICE FORCE**



T/20190422/2108

3 of 3

Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

Report No. T/20190422/2108

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 LING JUNXIAN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

22/04/2019 16:28

Officer In Charge Of Case:

TP / AEIT /

SI ANG YI TING, STEPHANIE

Contact No.: 65476414

Classification Of Case:

Authentication Stamp

NP168



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD		Ref: CS3/ASM19007174/R1cd3e2		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date: 20-06-2019		
ATTN: STACEY NG		Code: ASM		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SKN 3512R	Veh. Inspected	JQN 1638	
Policy No.		Coverage (\$)	0.00	
Claim No.	S9M01L3G	Excess (\$)	0.00	
Assign From	STACEY NG	Assign Date	23/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA 135LC	c.c	135	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.		Colour	MULTI COLOUR	
Odometer	50663 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	70/90-17	MAXXIS	3 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	80/90-17	MAXXIS	3 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	22/04/2019	Inspect Date / Time	23/04/2019 (03:42 PM)	
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$2,500				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

Report Ref No. CS3/ASM19007174/R1cd3e2

Inspected By



MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.