

Surveyor

Steve

REF: AIG

7180 / EP

ASSIGNMENT

From:

Date:

14/5/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLG 4384L

at Workshop m/s

Performance

of

303 Alexandra Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Before 7pm
Inthian

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLG 4384L

Yr Regn:

30/9/16

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 218i Coupe

C.C.

1499

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading

26041

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA 2F / 2969V 75F323

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

275/45R17

R:

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

20/4/19

D.O.A.

14/5/19

Survey held at

Performance

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-149K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + R\$, \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / L.B.I. (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7545Z
Vehicle Details	
Vehicle No.:	SLG4384L
Vehicle to be Exported:	No
Intended Deregistration Date:	14 May 2019
Vehicle Make:	B.M.W.
Vehicle Model:	218I COUPE AT HID ABS NAV SR
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	F1611442B38B15A
Chassis No.:	WBA2F12060V758323
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$26,822.00
Original Registration Date:	30 Sep 2016
First Registration Date:	30 Sep 2016
Transfer Count:	1
Actual ARF Paid:	\$24,551.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2026
PARF Rebate Amount:	\$18,413.00
Intended COE Rebate Details	
COE Expiry Date:	29 Sep 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$56,956.00
COE Rebate Amount:	\$41,668.00
Total Rebate Amount:	\$60,081.00

The information contained herein is correct as at 14 May 2019

OK