

ASS. REC. BY:

REF: CS/SMO190071951 7/td3ⁿ²

Special Instruction:

Surveyor: Thelma Choo

ASSIGNMENT (Office)

Minimun

From (Person): Thelma Choo of SMO Date/Time: 6.5.19 1.28pm

Estimated Cost: _____ Bill to: _____

GD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLN 8991X Insured: SGV 1888A

at Workshop m/s Eurokars Group Tel: 63310682

of JFA Tanjung Penjun

Policy No: DIA MTPV01003756 Claim No: CMTD190275 / THE

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 3.5.2019
(Client's Record) 7/5/19 @ 3:30pm

CA / REV / REP. / REV 24 HRS r.w.p H.O.D. Endorsement: _____

Date/Time: 6.5.19 Person Contacted: Jobi Vehicle IN/OUT

Date/Time	Action/Instruction
	Ishtimati (✓)
	SLN 8991X - X
	SGV 1888A - X
8/5 -	Revised preli advise via marimen.

Surveillance *Taufiq*

REF: SMO

ASSIGNMENT

From: _____ Date: **7.5.2019**

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SLN 8991X**

at Workshop n/s **TRANS Eurokars**

of **27 A Tanjung Penjuru**

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: **3.00pm - 3.30pm (concurrent)**

Veh No: **SLN 8991X** Yr Regn: **2017 / May**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: **Mercedes** c.c. **1496**

Colour: **Blue** A/C: **Insured / Std / NI / NA**

Sp. Reading: **18852** T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: **JM6BN 22A8H 014S301**

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: **Inorder** / Jammed / Leaked / Burnt or

Brake: **Inorder** / Jammed / Leaked / Burnt or

Modi: **Nil** / S/Rim / STD A/Rim or

Tyre Size: F: **205/60R16**
R: **205/60R16**

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: **967k.**

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS **"rap"**

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front	6		Rear	6	
R/Bal.		mm	R/Bal.		mm
L/Bal.	6	mm	L/Bal.	6	mm

D.O.A. _____ D.O.I. **4/5/1983**

Survey held at _____

Des. of Damages: Frt / Rear / **O/S** / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
30/7	Email Airframe CR \$10,206,62, 10 days (Red: 2380.51; 18%)
	Rebate \$51,846

RECEIVED 26 AUG 2019

[Signature]
21/8/2019

Date/Time, File Pass to? : Preli. Report
 : Final Report

1) **2/8/2019 Typist**

Date/Time, File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$ **10,216.62**)

Days Of Repair: **10**

Resurvey No. of Trip: **1**

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee:	
Transportation:	
S + RS, SI	350
Photos	11
Others	
TOTAL	361

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Thelma Choo

Date: 08 May 2019

Preliminary Advice

Insured Vehicle No	: SGV1888A	Accident Date	: 03/05/2019
TP Vehicle No	: SLN8991X	Assignment Date	: 06/05/2019
Make	: MAZDA 3	Est. Duration of Repair	: 10.00
Date of Inspection	: 07/05/2019		
Inspection At	: TRANS EUROKARS PTE LTD - TANJONG PENJURU (HQ) 27A TANJONG PENJURU SINGAPORE 609025		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages O/S portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,147.13
Revised Amount	:S\$	9,766.62
Check Items (Estimated)	:S\$	93.69
Total	:S\$	9,860.31

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Survey on "wp"

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 May 2019		06 May 2019 13:30 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	TAN CHOR YONG, ID: S1371532G								
Main Claimant:	VINOD NAIR, ID: S8242913A								
Vehicle Reg. No.:	SLN8991X	Date of Loss:	03/05/2019 12:00 - :59						
Claim Type:	TP / CMTD1902175	Policy/Cover Note No.:	D19MTPV01003756 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGV1888A	Policy No. (Claimant):							
		Excess:							
Repairer:	Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ) 27A Tanjong Penjuru, 609025 West Coast - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/05/2019]								
Driver/Custodian (Insured):	TAN SHU QI NICOLE (), NRIC: S9637308B, Tel: +6596253465 Email:								
Adj Asg. Remarks:	WS: JOBI 6331 0682 PLS ARR SUR TMR 07/05/19								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
<input type="checkbox"/> ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Monday, 6 May, 2019 1:28 PM
To: jobithomas@eurokars.com.sg; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'
Cc: eva.kok@eurokars.com.sg; vion.lim@eurokars.com.sg; samuel.ng@eurokars.com.sg;
Choo, Thelma; Ye, Yong Kang Melvin; Henry, Irene James
Subject: CMTD1902175/THE - LKK(LIA)/ SGV1888A & SLN8991X ACC ON 03.05.19 - PLS ARR
SUV TMR 07/05/19

Without Prejudice

Our Reference: CMTD1902175/THE

Your Reference: SLN8991X

Hi Jobi,

We acknowledged receipt of your claim documents.

Please be informed that **Ms. Thelma Choo** is the handler of this case.

Please be informed, we have appointed **LKK AUTO** to survey the above vehicle.

Aside to **LKK AUTO**,

Please make arrangement to conduct the survey for SLN8991X on a without Prejudice and any admission of liability basis.

Please submit with your report via Merimen upon completion of survey.

Aside to Thelma,

Please refer to the liability request from Eurokars Group.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: jobithomas@eurokars.com.sg [mailto:jobithomas@eurokars.com.sg]
Sent: Monday, May 06, 2019 11:17 AM
To: Claims - Motor Survey
Cc: eva.kok@eurokars.com.sg; vion.lim@eurokars.com.sg; samuel.ng@eurokars.com.sg
Subject: YOUR REF: SGV1888A / OUR REF: SLN8991X THIRD PARTY CLAIM

YOUR REF: SGV1888A / OUR REF: SLN8991X THIRD PARTY CLAIM

Dear Sir/Mdm,

Kindly arrange the survey of our client's car SLN8991X on 07/06/2019 @ 1500 - 1700 hrs at 27A Tanjong Penjuru.

Attached is the ESTIMATE & ACCIDENT REPORT for your perusal.

We would appreciate it if you can kindly let us know the liability/status of this case.

Best Regards.



Jobi Thomas
Senior Insurance Claims Executive
27A Tanjong Penjuru, Singapore 609042
T: (65) 6331 0680 D: (65) 6331 0682 F: (65) 6331 0690
E: jobithomas@eurokars.com.sg W: www.eurokarsgroup.com

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	913A
Vehicle Details	
Vehicle No.:	SLN8991X
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Jul 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	P520437848
Chassis No.:	JM6BN22A8H0148301
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$19,359.00
Original Registration Date:	22 May 2017
First Registration Date:	22 May 2017
Transfer Count:	0
Actual ARF Paid:	\$14,359.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 May 2027
PARF Rebate Amount:	\$10,769.00
Intended COE Rebate Details	
COE Expiry Date:	21 May 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,106.00
COE Rebate Amount:	\$39,895.00
Total Rebate Amount:	\$50,664.00

The information contained herein is correct as at 30 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/05/2019 16:33
Date Of Accident	03/05/2019 12:55
Exact Location Of Accident	STADIUM DRIVE ROUNDABOUT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN8991X
Insured/Policyholder	
Name Of Registered Owner	VINOD NAIR
NRIC No	S8242913A
Email Address	MAMBO69@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92722692
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MAZDA
Model	3-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV-2018-00005135
Cover Note Number	

Driver

Name of Driver	VINOD NAIR
NRIC No	S8242913A
Date Of Birth	22/12/1982
Occupation	INDOOR
Date Of Driving Pass	28/05/2002
Driving Experience	16 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92722692
Fax Number	
Contact Number	OFFICE-NOPHONE
EMail Address	MAMBO69@GMAIL.COM

Address	BLK 312C CLEMENTI AVE #24-193
Postcode	123312
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - ROUNDABOUT
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGV1888A
Vehicle Make/Model/Colour	WHITE NISSAN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN SHU QI NICOLE
NRIC/Passport Number	S9637308B
Contact Number	90616808
Address	
Postcode	
Insurance Company Name	SOMPO INSURANCE SINGAPORE PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

VEHICLE NO: SLN 8991X
ACCIDENT DATE: 3/5/19

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer [collectively the "Personal Information"] and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


NOTE: DO NOT THAT YOU MAY HAVE A 14-DAYS TIMEFRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE REFER TO YOUR POLICY FOR MORE INFORMATION.

[Signature]
Policyholder's Signature
Date & Time:

[Signature]
Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]
CHARN'S CUSTOMER CENTRE
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving at the stadium drive roundabout on the outermost lane. I was driving straight, the other car from the inner lane that was behind mine suddenly turned towards my car trying to exit and collided into the side of my car. As she hit the driver's side I had to move the car to the side of the road of the exit. When she came out she apologized and we exchanged contacts and took pictures.

OWN DAMAGE () 3RD PARTY CLAIM (/) REPORTING ONLY () OWN WORKSHOP (/)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

(X) 
 Policyholder's Signature
 Date & Time:

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 CHARN'S CUSTOMCRAFT
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN NO.:



CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.
All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2018-00005135 (Comprehensive - Classic Plan)

Car plate number: SLN8991X

Your name (As the policyholder): Vinod Nair

Coverage start date: 22/05/2018

Coverage end date: 21/05/2019

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

(a) You; and

(b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

Finance company: OCBC Bank Limited

We confirm that this Policy complies with the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189).

Issued on: 15/04/2018

Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please immediately inform us at +65-6322-2072
or email us at contact@fwd.com.sg if any details
in this Certificate of Insurance need to be changed.

03/05/2019 17:07

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8242913A



Name
VINOD NAIR



Race
INDIAN
Date of birth
22-12-1982
Country/Place of birth
SINGAPORE

Sex
M

S8242913A



S247542




NRIC No. S8242913A



Date of issue
13-12-2013

APT BLK 312C CLEMENTI AVENUE 4 #24-103
SINGAPORE 123312
NRIC No: S8242913A Date: 19/02/2017





TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

Sompo Insurance Pte. Ltd. 50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWER SINGAPORE 048623 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Vinod Nair ADDRESS : Blk 312C Clementi Avenue 4 #24-193 Singapore 123312 TEL : 92722692Vinod	WIP : 31259 EXCESS : DATE : 6-May-19
VEH NO :	SLN8991X	DATE IN :	CONTACT PERSON : Jobi 63310682
CHASSIS NO :	JM6BN22A8H0148301	MILEAGE :	TYPE OF CLAIM : THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.: 22-May-17	POLICY NO. :

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	2	MGHP9-50-0Z5	X	\$ 5.80
2	2	MB45A-56-146A	X	\$ 6.00
3	12	MC274-50-133	X	\$ 44.40
4	4	MTK21-50-355	X	\$ 36.80
5	4	M551S-51-833	X	\$ 16.00
6	8	MGD7A-50-EA1	X	\$ 25.60
7	1	MB45A-52-111B	Ry	\$ 350.60
8	15	MB45A-56-146A	✓ nee	\$ 45.00
9	1	MB63B-69-1N12P	nm X	\$ 128.40
10	1	MB63B-69-122A	nm X	\$ 85.80
11	1	MB63B-69-121A	✓ cut	\$ 396.90
12	1	MBHY0-58-02XF	✓ bt	\$ 1,200.40
13	1	MGHP9-58-762A	✓ nee	\$ 3.20
14	1	MBF67-51-261	✓ nee	\$ 2.40
15	1	MBF67-51-261	✓ nee	\$ 2.40
16	1	MGS1D-58-315A	✓ nee	\$ 2.40
17	1	MGD7A-50-EA1	✓ nee	\$ 3.20
18	8	MGJ6A-58-975	✓ nee	\$ 24.00
19	1	M9991-00-503	✓ nee	\$ 3.80
20	1	MBHS2-58-97XB	nm X ?	\$ 104.10
21	8	MKD53-50-M38	✓ nee	\$ 98.40
22	1	MBHP2-50-640C	nm X	\$ 80.40
23	7	MGJ6A-58-975	✓ nee	\$ 21.00
24	1	MB6YS-70-271	✓ bt	\$ 924.00
25	1	MBHS2-50-4P2	✓ nee	\$ 18.20
26	1	MBHR1-69-014A	✓ nee	\$ 6.50
TOTAL PARTS				\$ 3,635.70
LESS 10%				\$ 363.57
TOTAL PARTS COST				\$ 3,272.13

Labour Description				
1		TO REPLACE FRONT FENDER RH, FRONT DOOR RH, DOOR MIRROR RH AND ROCKER PANEL RH. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	660 2470 ✓	\$ 3,300.00
2	MZ-SP-SFRT01	TO RESPRAY FRONT FENDER RH, COVER DOOR MIRROR RH, FRONT DOOR RH AND ROCKER PANEL RH. (TO BLEND REAR FENDER RH AND FRONT PILLAR OUTER RH)	630 2520 ✓	\$ 2,835.00
3		TO SUPPLY CHASSIS STICKER.	✓	NETT \$ 120.00
4	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.	✓	\$ 330.00
5	MZ-BR-TRIMS1	TO REMOVE & REFIT CARPET & TRIMS ON THE FRONT SECTION TO GIVE WAY TO THE REPAIR ON THE FRONT SECTION.	660 ✓	\$ 990.00
6	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	180 ✓	\$ 350.00
7	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	150 ✓	\$ 250.00
8	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150 ✓	\$ 250.00
9	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180 ✓	\$ 350.00
10	MZ-BR-SUNDRI	SUNDRIES.	30 ✓ NETT	\$ 100.00

Approved
 Taufik 97995789
 'w'
 7/5/19 @ 330
 Reamy before print
 10 days
 Svelthaus.com

TOTAL LABOUR	\$ -	\$ 8,875.00
TOTAL PARTS	\$ -	\$ 3,272.13
TOTAL	\$ -	\$ 12,147.13
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ -
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

12597.13

TRANS EUROKARS PTE LTD

REMARKS:
 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



TRANS EUROKARS PTE LTD



FINALISED COST OF REPAIRS

Sompo Insurance Pte. Ltd. 50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWER SINGAPORE 048623 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Vinod Nair ADDRESS : Blk 312C Clementi Avenue 4 #24-193 Singapore 123312 TEL : 92722692Vinod	WIP : 31259 EXCESS : DATE: 6-May-19
VEH NO :	SLN8991X	DATE IN :	CONTACT PERSON : Jobi 63310682
CHASSIS NO :	JM6BN22A8H0148301	MILEAGE :	TYPE OF CLAIM : THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	POLICY NO. :

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	2	MGHP9-50-0Z5		\$ 5.80
2	2	MB45A-56-146A		\$ 6.00
3	12	MC274-50-133		\$ 44.40
4	4	MTK21-50-355		\$ 36.80
5	4	M551S-51-833		\$ 16.00
6	8	MGD7A-50-EA1		\$ 25.60
7	1	MB45A-52-111B		\$ 350.60
8	15	MB45A-56-146A	\$ 45.00	\$ 45.00
9	1	MB63B-69-1N12P		\$ 128.40
10	1	MB63B-69-122A		\$ 85.80
11	1	MB63B-69-121A	\$ 396.90	\$ 396.90
12	1	MBHY0-58-02XF	\$ 1,200.40	\$ 1,200.40
13	1	MGHP9-58-762A	\$ 3.20	\$ 3.20
14	1	MBF67-51-261	\$ 2.40	\$ 2.40
15	1	MBF67-51-261	\$ 2.40	\$ 2.40
16	1	MGS1D-58-315A	\$ 2.40	\$ 2.40
17	1	MGD7A-50-EA1	\$ 3.20	\$ 3.20
18	8	MJG6A-58-975	\$ 24.00	\$ 24.00
19	1	M9991-00-503	\$ 3.80	\$ 3.80
20	1	MBHS2-58-97XB		\$ 104.10
21	8	MKD53-50-M38	\$ 98.40	\$ 98.40
22	1	MBHP2-50-640C		\$ 80.40
23	7	MJG6A-58-975	\$ 21.00	\$ 21.00
24	1	MB6YS-70-271	\$ 924.00	\$ 924.00
25	1	MBHS2-50-4P2	\$ 18.20	\$ 18.20
26	1	MBHR1-69-014A	\$ 6.50	\$ 6.50
TOTAL PARTS			\$ 2,751.80	\$ 3,635.70
LESS 10%			\$ 275.18	\$ 363.57
TOTAL PARTS COST			\$ 2,476.62	\$ 3,272.13

Labour Description					
1		TO REPLACE FRONT DOOR RH, DOOR MIRROR RH AND ROCKER PANEL RH. REPAIR FRONT FENDER RH AND AREAS AFFECTED BY THE ACCIDENT.	\$ 2,970.00	\$ 3,300.00	
2	MZ-SP-5FRT01	TO RESPRAY FRONT FENDER RH, COVER DOOR MIRROR RH, FRONT DOOR RH AND ROCKER PANEL RH. (TO BLEND REAR FENDER RH AND FRONT PILLAR OUTER RH)	\$ 2,520.00	\$ 2,835.00	
3		TO SUPPLY BODY COATING (INVOICES ATTACHED) ✓	\$ 450.00	TBA (A)	
4		TO SUPPLY CHASSIS STICKER.	\$ 120.00	\$ 120.00	
5	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.	\$ 330.00	\$ 330.00	
6	MZ-BR-TRIMS1	TO REMOVE & REFIT CARPET & TRIMS ON THE FRONT SECTION TO GIVE WAY TO THE REPAIR ON THE FRONT SECTION.	\$ 660.00	\$ 990.00	
7	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	\$ 180.00	\$ 350.00	
8	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 150.00	\$ 250.00	
9	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00	
10	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00	
11	MZ-BR-SUNDRI	SUNDRIES.	\$ 30.00	\$ 100.00	
			TOTAL LABOUR	\$ 7,740.00	\$ 8,875.00
			TOTAL PARTS	\$ 2,476.62	\$ 3,272.13
			TOTAL	\$ 10,216.62	\$ 12,147.13
			LESS EXCESS	\$ -	\$ -
			TOTAL AFTER EXCESS	\$ 10,216.62	
			GST 7%	\$ 715.16	\$ -
			GRAND TOTAL	\$ 10,931.78	\$ -

12597.13

REMARKS:

10 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)



C.R.N: 201536586N

INVOICE

Bill To:
Name : Mr. Vinod Nair
Contact Number : 9272 2692
Address :

DATE:
4-Jun-19

INVOICE #
5D 19330

Vehicle Make/Model/Colour : Mazda 3 Blue
Vehicle Registration Number : SLN 8991 X

TERM: Nets / Cash / Credit

DESCRIPTION	AMOUNT
Recoat : Front Right Fender + 2 Door + Rear Fender + Door Edge	\$ 450.00
Remarks (if any):	
Car Maintenance Tips: 1. Wash your car regularly with mild car soap (Recommended once a week) 2. Avoid doing any further polishing and using wax as it will void your warranty * we provide car wash services which will include application of Kube Bond Diamond Plus Coating Enhancer * For hard to remove stains, please do not hesitate to come back to use for stain removal	
	\$ 450.00

* old invoice



C.R.N: 201536586N

INVOICE

Bill To:
Name : Mr. Vinod Nair
Contact Number : 9272 2692
Address :

DATE:
22-Jun-17

INVOICE #
5D 17580

Vehicle Make/Model/Colour : Mazda 3 Blue
Vehicle Registration Number : SLN 8991 X

TERM: Nets / Cash / Credit

DESCRIPTION	AMOUNT
KB Advance + Interior Seats Protection	\$ 980.00
Door Edge Protector	\$ 100.00
Remarks (if any):	
Car Maintenance Tips: 1. Wash your car regularly with mild car soap (Recommended once a week) 2. Avoid doing any further polishing and using wax as it will void your warranty * we provide car wash services which will include application of Kube Bond Diamond Plus Coating Enhancer * For hard to remove stains, please do not hesitate to come back to use for stain removal	
	\$ 1,080.00

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19007195/T1TD3N2

Date: 27/08/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPV01003756
Claimant Vehicle No :	SLN8991X	Insured Vehicle No :	SGV1888A
Date of Loss:	03/05/2019	Nature of Claim:	TP
		Claim No:	CMTD1902175

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN8991X	Engine No:	P520437848
Make & Model:	MAZDA 3, 1.5 (A)	Chassis No:	JM6BN22A8H0148301
Reg. Date:	22/05/2017 (Man. Year: 2017)	Odometer:	18852 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,372.13	2,506.62	865.51	25.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,225.00	7,710.00	1,515.00	16.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	12,597.13	10,216.62	2,380.51	18.90
+ GST 7.00/7.00% (\$\$)	881.80	715.16	166.64	18.90
Nett Amount (\$\$)	13,478.93	10,931.78	2,547.15	18.90

INSPECTION

Date of Assignment:	06/05/2019	
Date Inspected:	07/05/2019	Inspected At: Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ) 27A Tanjong Penjuru Singapore 609025
Estimated Period of Repair:	10.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Aug 2019)
Parts: 144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLN8991X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*GROMMET,FRONT BUMPER	Not Necessary	5.80 FL	*- FL
2	2		*FASTENER,FRONT BUMPER	Not Necessary	6.00 FL	*- FL
3	12		*CLIP,FRONT BUMPER	Not Necessary	44.40 FL	*- FL
4	4		*RIVET,FRONT BUMPER	Not Necessary	36.80 FL	*- FL
5	4		*RIVET,FRONT BUMPER	Not Necessary	16.00 FL	*- FL
6	8		*FASTENER,FRONT BUMPER	Not Necessary	25.60 FL	*- FL
7	1		*FRONT FENDER RHS	Repair	350.60 FL	*- FL
8	15		*FASTENER,MUDGUARD	Necessary	45.00 FL	*45.00 FL
9	1		*COVER RHS,DOOR MIRROR	Not Necessary	128.40 FL	*- FL
10	1		*LAMP RHS,DOOR MIRROR	Not Necessary	85.80 FL	*- FL
11	1		*DOOR MIRROR RHS	Cut	396.90 FL	*396.90 FL
12	1		*FRONT DOOR RHS	Bent	1,200.40 FL	*1,200.40 FL
13	1		*FASTENER,FRONT DOOR	Necessary	3.20 FL	*3.20 FL
14	1		*GROMMET,FRONT DOOR	Necessary	2.40 FL	*2.40 FL
15	1		*GROMMET,FRONT DOOR	Necessary	2.40 FL	*2.40 FL
16	1		*CLIP,FRONT DOOR	Necessary	2.40 FL	*2.40 FL
17	1		*FASTENER,FRONT DOOR	Necessary	3.20 FL	*3.20 FL
18	8		*GROMMET,FRONT DOOR	Necessary	24.00 FL	*24.00 FL
19	1		*GROMMET,FRONT DOOR	Necessary	3.80 FL	*3.80 FL
20	1		*CARRIER RHS,FRONT DOOR	Not Necessary	104.10 FL	*- FL
21	8		*CLIP,DOOR GARNISH	Necessary	98.40 FL	*98.40 FL
22	1		*WEATHERSTRIP OUTER RHS,FRONT DOOR	Not Necessary	80.40 FL	*- FL
23	7		*GROMMET,SPEAKER	Necessary	21.00 FL	*21.00 FL
24	1		*ROCKER PANEL RHS	Bent	924.00 FL	*924.00 FL
25	1		*GUARD STONE RHS	Necessary	18.20 FL	*18.20 FL
26	1		*LABEL,TIRE	Necessary	6.50 FL	*6.50 FL
27	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,735.70	2,781.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	363.57	275.18
Total Parts (\$\$)	3,372.13	2,506.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT FENDER RH,FRONT DOOR RH,DOOR MIRROR RH AND ROCKER PANEL RH.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	3,300.00	2,970.00
2	TO RESPRAY FRONT FENDER RH,COVER DOOR MIRROR RH,FRONT DOOR RH AND ROCKER PANEL RH. (TO BLEND REAR FENDER RH AND FRONT PILLAR OUTER RH)	New	2,835.00	2,520.00
3	TO SUPPLY CHASSIS STICKER	New	120.00	120.00
4	TO TRANSFER THE DOOR MECHANISM	New	330.00	330.00
5	TO REMOVE & REFIT CARPET & TRIMS ON THE FRONT SECTION TO GIVE WAY TO THE REPAIR ON THE FRONT SECTION	New	990.00	660.00
6	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	New	350.00	180.00
7	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	150.00
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
10	TO SUPPLY BODY COATING (INVOICES ATTACHED)	New	450.00	450.00
Gross Labour Cost (S\$)			9,225.00	7,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >