

ASS. REC. BY:

REF: CS/CMO19007216 / G9d3

Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

mupin

From (Person): Thelma Chooof SMDDate/Time: 24.4.19 401p.m

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMK 49729Insured: GBF 5294 Eat Workshop m/s CAS GarageTel: 87827171of 1. Kaki Bukit Ave 6 # 02-22Policy No: D18MTHCUE003196Claim No: CMTD1902024

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 23.4.2019

CA / REV / REP. / REV 24 HRS

"W"

H.O.D. Endorsement:

Date/Time: 24.4.19 226p.mPerson Contacted: AllanVehicle IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
	SMK 49729 - X	
	GBF 5294 E - X	
7/4/19 @	2.59pm	revised to Thelma Choo via Messenger.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Apr 2019		24 Apr 2019 14:01 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	DIESEL INJECTRONIC PTE LTD, Co. Reg. No.: 200206731N	[Created by insurer]
Main Claimant:	HAFIDAH BINTE SAIDOLLAH, ID: S8312206D	
Vehicle Reg. No.:	SMK4972G	Date of Loss: 23/04/2019 00:00 - :59
Claim Type:	TP / CMTD1902024	Policy/Cover Note No.: D18MTHCVE003196 (Comprehensive)
Vehicle Reg. No. (Insured):	GBF5294E	Policy No. (Claimant):
Repairer:	Cas Garage Pte Ltd (HQ) No.1, Kaki Bukit Ave 6, #02-22 Autobay, 417883 Kaki Bukit - Tel: 4681	Excess:
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/05/2019]	
Adj Asg. Remarks:	WS: ALLAN GOH 8782 7171 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT	

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompso Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Thelma Choo

Date: 25 Apr 2019

Preliminary Advice

Insured Vehicle No	: GBF5294E	Accident Date	: 23/04/2019
TP Vehicle No	: SMK4972G	Assignment Date	: 24/04/2019
Make	: HYUNDAI ACCENT	Est. Duration of Repair	: 12.00
Date of Inspection	: 24/04/2019		
Inspection At	: CAS GARAGE PTE LTD (HQ) NO.1, KAKI BUKIT AVE 6, #02-22 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,268.56
Revised Amount	:S\$	10,726.40
Check Items (Estimated)	:S\$	4,342.72
Total	:S\$	15,069.12

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2206D
Vehicle Details	
Vehicle No.:	SMK4972G
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Apr 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ACCENT (RB) 1.4 CVT
Primary Colour:	Red
Manufacturing Year:	2019
Engine No.:	G4LCKU145787
Chassis No.:	KMHCU41BTKU465076
Maximum Power Output:	73.6 kW (98 bhp)
Open Market Value:	\$8,949.00
Original Registration Date:	12 Apr 2019
First Registration Date:	12 Apr 2019
Transfer Count:	0
Actual ARF Paid:	\$8,949.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Apr 2029
PARF Rebate Amount:	\$6,711.00
Intended COE Rebate Details	
COE Expiry Date:	11 Apr 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$29,159.00
COE Rebate Amount:	\$29,052.00
Total Rebate Amount:	\$35,763.00

The information contained herein is correct as at 25 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/04/2019 10:25
Date Of Accident	23/04/2019 23:15
Exact Location Of Accident	ALONG BUKIT BATOK ROAD TOWARDS PIE (TUAS/CHANGI)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMK4972G
Insured/Policyholder	
Name Of Registered Owner	HAFIDAH BINTE SAIDOLLAH
NRIC No	S8312206D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96746660
Alternative Phone No	OFFICE-96746660
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	ACCENT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN041442
Cover Note Number	CN041442
Driver	
Name of Driver	SITI AISYAH BINTE IRWAN
NRIC No	S8909949H
Date Of Birth	23/03/1989
Occupation	INDOOR
Date Of Driving Pass	30/10/2010
Driving Experience	8 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-85886160
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address- 548B SEGAR ROAD
#14-672
Postcode 672548
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured RELATIVE
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 3
Passenger 1 NAME: : HAFIDAH BINTE SAIDOLLAH
GENDER: : FEMALE
Passenger 2 NAME: : MARDIAH BT KHOZALI MUSA
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: FILE TOO LARGE
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBF5294E
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

SITI AISYAH BINTE IRWAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

HAFIDAH BINTE SAIDOLLAH

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 3

Name

MARDIAH BT KHOZALI MUSA

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders;

X 
 Policyholder's Signature
 Date & Time:

X 
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attached

DECLARATION

I/We declare the foregoing particulars are true in every respect:

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

On 23.04.19 at about 2315 hours at the T-Junction of Bukit Batok Road and Bukit Batok West Ave 6 (77F). I was on Bukit Batok Road heading towards PIE (TUAS/ Changi Airport) traveling at Lane 2.

I saw the traffic light changed to amber and I slowed down and stopped my vehicle (A). Vehicle (B) came from the back and hit directly at rear portion of my vehicle causing severe damages to my vehicle.

There were 2 more passengers in my vehicle.

Vehicle (A) : SMK4972G

Vehicle (B) : GBF5294E

aysha

**CAS GARAGE PTE LTD**

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATEInsurance Company: SOMPO INSURANCE SINGAPORE PTE LTD
(MOTOR CLAIMS DEPARTMENT)Address: NO 50, RAFFLES PLACE, #05-01/06
SINGAPORE LAND TOWER, S(048623)

Telephone: 64616555 Fax: 62257947

Email: motorsurvey@sompo.com.sg

Make/ Model : HYUNDAI ACCENT

Chassis No : KMHCU41BTKU465076

Date/Time of Accide 23.04.2019/2315

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed

Date: 24.04.2019
is subject to final approval from Insurance Company

Vehicle No: SMK4972G
Signature: _____
Date: _____

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	SPARE TYRE FLOOR PANEL ?	1	\$ 896.90		\$ 896.90
2	SPARE TYRE TOP MAT ?	1	\$ 258.20		\$ 258.20
3	REAR END PANEL / BT	1	\$ 608.70		\$ 608.70
4	REAR END PANEL TOP GARNISH / de	1	\$ 192.50		\$ 192.50
5	BOOTLID / Bue	1	\$ 1,198.60		\$ 1,198.60
6	BOOTLID INNER TRIM / TN	1	\$ 285.10		\$ 285.10
7	BOOTLID HINGE / BT	2	\$ 145.80		\$ 291.60
8	BOOTLID INNER TRIM ?	1	\$ 105.60		\$ 105.60
9	BOOTLID NUMBER PLATE LAMP ?	2	\$ 80.90		\$ 161.80
10	BOOTLID LOGO / de	1	\$ 85.60		\$ 85.60
11	BOOTLID "ACCENT" EMBLEM / de	1	\$ 79.50		\$ 79.50
12	BOOTLID WEATHERSTRIP / Twi	1	\$ 192.60		\$ 192.60
13	BOOTLID INNER LOCK / BT	1	\$ 185.90		\$ 185.90
14	BOOTLID OUTER GARNISH / de	1	\$ 236.70		\$ 236.70
15	BOOTLID NUMBER PLATE LAMP x repair	2	\$ 80.90		\$ 161.80
16	REAR BUMPER / de	1	\$ 679.80		\$ 679.80
17	REAR BUMPER REFLECTORS / de	2	\$ 127.50		\$ 255.00
18	REAR BUMPER SIDE RETAINERS / de	2	\$ 75.90		\$ 151.80
19	REAR BUMPER REINFORCEMENT ?	1	\$ 759.60		\$ 759.60
20	REAR REINFORCEMENT BRACKETS ?	2	\$ 69.70		\$ 139.40
21	REAR FENDER / Bue	2	\$ 1,845.60		\$ 3,691.20
22	REAR FENDER INNER TRIM ?	2	\$ 389.50		\$ 779.00
23	REAR FENDER INNER COWLING ?	2	\$ 195.60		\$ 391.20
24	REAR SILENCER BOX ?	1	\$ 745.80		\$ 745.80
25	REAR SILENCER BOX MOUNTING ?	2	\$ 45.60		\$ 91.20
26	REAR SILENCER BOX HEAT SHIELD ?	1	\$ 187.20		\$ 187.20
27	REAR WINDSCREEN MOULDING / de	1	\$ 185.90		\$ 185.90
Total List Price Cost					\$ 12,998.20
PARTS DISCOUNT 20%					\$ 10,398.56

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	REAR BUMPER CLIPS / <i>acc</i>	1 SET	\$ 30.00	\$ 30.00
2	REAR NUMBER PLATE WITH CASING / <i>acc</i>	1 SET	\$ 50.00	\$ 40 50.00
3	REAR FENDER COWLING <i>clips / acc</i>	2 SET	\$ 60.00	\$ 60.00
4	REAR FENDER INNER TRIM <i>clips / acc</i>	2 SET	\$ 60.00	\$ 60.00
5	BOOTLID INNER TRIM <i>clips - acc</i>	1 SET	\$ 30.00	\$ 30.00
6	END PANEL TOP GARNISH CLIPS / <i>acc</i>	1 SET	\$ 30.00	\$ 30.00
7	REVERSE SENSORS / <i>acc</i>	1 SET	\$ 250.00	\$ 250.00
8	REVERSE SENSORS HARDNESS ?	1	\$ 280.00	\$ 280.00
9	END PANEL TOP GARNISH CLIPS / <i>acc</i>	1 SET	\$ 30.00	\$ 30.00
10	EMERGENCY SIGN KIT ?	1	\$ 200.00	\$ 200.00
11	END PANEL SEALANTS / <i>acc</i>	2	\$ 80.00	\$ 80.00
12	WINDSCREEN SEALANTS / <i>acc</i>	2	\$ 80.00	\$ 80.00
13	SPARE TYRE FLOOR INSULATOR ?	1	\$ 250.00	\$ 250.00
Total Special Nett Items				\$ 1,430.00

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS	\$ 3,000.00
	<i>1400 - 1700</i>
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 2,800.00
	<i>1200</i>
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 80 200.00
TO REMOVE/ REFIT INTERIOR UPHOLSTERY	\$ 60 150.00
TO REMOVE /REFIT REAR WINDSCREEN TO FACILITATE FENDER REPLACEMENT	\$ 100 180.00
TO APPLY SEALANT TO THE AFFECTED AREAS	\$ X 180.00
TO REMOVE/ REFIT WIRING CHECKS	\$ 30 120.00
TO REMOVE/ REFIT FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ 60 250.00
TO REMOVE/ REFIT / REPLACE REAR SILENCER BOX	\$ 60 180.00
TO REMOVE/ REPLACE REVERSE SENSORS	\$ 40 180.00
TO REMOVE AND REPLACE/REFIT BOOTLID MECHANISM	\$ 50 200.00
Total Others Cost	\$ 1,640.00
GRAND TOTAL	
	\$ 19,268.56

CAS GARAGE PTE LTD
 UEN 201828067M
 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
 SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan
 Direct Contact: +65 8782 7171
 Email: allangoh.cas@gmail.com
 Fax: +65 6509 9501.

10-12 Days .
Cumsum Repair.
After repair photos
Gmo Repair.
24/4/19.

Consultants hence notify the Repairer of the following:

- Resurvey before/after spray painting
- Display damaged part(s) during resurvey
- All works are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

REQUEST FOR SUPPLEMENTS PARTS

Accident Case Number		Date of Collection	/ /
Vehicle No	SMK4972G	Date of Request	25.04.2019
Vehicle Model	HYUNDAI ACCENT	Number of Days to Extend (If any)	

S/N	Part Number	Part Description	Quantity	Unit Price
1		REAR FENDER AIR DUCT RH / el	1	\$95.60
2		REAR BOOT SMART RELEASE ANTENNA(OUTER) / 5PM	1	\$285.70
3		REAR BOOT SMART KEY ANTENNA(INNER) / 5PM	1	\$285.70
4		REAR REINFORCEMENT METAL BRACKET RH / mis	1	\$185.60
5		REAR BOOT TOP PANEL RH / blue	1	\$325.80

<<< Please submit photographs for damaged parts >>>

6mo Rep.
25/4/19.

CAS GARAGE PTE LTD
UEN 201828067M
1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
SINGAPORE 417883

**CAS GARAGE PTE LTD**

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATEInsurance Company: SOMPO INSURANCE SINGAPORE PTE LTD
(MOTOR CLAIMS DEPARTMENT)Address: NO 50, RAFFLES PLACE, #05-01/06
SINGAPORE LAND TOWER, S(048623)

Telephone: 64616555 Fax: 62257947

Make/ Model : HYUNDAI ACCENT

Chassis No : KMHCU41BTKU465076

Date/Time of Accide 23.04.2019/2315

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed, and is subject to final approval from Insurance Company

Date: 24.04.2019

Vehicle No. SMK4972G

Signature: _____

Date: _____

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	SPARE TYRE FLOOR PANEL ✓	1	\$ 896.90		\$ 896.90
2	SPARE TYRE TOP MAT ✓	1	\$ 258.20		\$ 258.20
3	REAR END PANEL / BT	1	\$ 608.70		\$ 608.70
4	REAR END PANEL TOP GARNISH / Re	1	\$ 192.50		\$ 192.50
5	BOOTLID / Bue	1	\$ 1,198.60		\$ 1,198.60
6	BOOTLID INNER TRIM / TN	1	\$ 285.10		\$ 285.10
7	BOOTLID HINGE / BT	2	\$ 145.80		\$ 291.60
8	BOOTLID INNER TRIM X	1	\$ 105.60		\$ 105.60
9	BOOTLID NUMBER PLATE LAMP X	2	\$ 80.90		\$ 161.80
10	BOOTLID LOGO / Re	1	\$ 85.60		\$ 85.60
11	BOOTLID "ACCENT" EMBLEM / Re	1	\$ 79.50		\$ 79.50
12	BOOTLID WEATHERSTRIP / Twi	1	\$ 192.60		\$ 192.60
13	BOOTLID INNER LOCK / BT	1	\$ 185.90		\$ 185.90
14	BOOTLID OUTER GARNISH / Re	1	\$ 236.70		\$ 236.70
15	BOOTLID NUMBER PLATE LAMP X Report	2	\$ 80.90		\$ 161.80
16	REAR BUMPER / Re	1	\$ 679.80		\$ 679.80
17	REAR BUMPER REFLECTORS / Scr.	2	\$ 127.50		\$ 255.00
18	REAR BUMPER SIDE RETAINERS / Re	2	\$ 75.90		\$ 151.80
19	REAR BUMPER REINFORCEMENT ✓	1	\$ 759.60		\$ 759.60
20	REAR REINFORCEMENT BRACKETS ✓	2	\$ 69.70		\$ 139.40
21	REAR FENDER / Bue	2	\$ 1,845.60		\$ 3,691.20
22	REAR FENDER INNER TRIM ✓	2	\$ 389.50		\$ 779.00
23	REAR FENDER INNER COWLING PH ✓	2	\$ 195.60		\$ 391.20
24	REAR SILENCER BOX ✓	1	\$ 745.80		\$ 745.80
25	REAR SILENCER BOX MOUNTING X	2	\$ 45.60		\$ 91.20
26	REAR SILENCER BOX HEAT SHIELD X	1	\$ 187.20		\$ 187.20
27	REAR WINDSCREEN MOULDING / Re	1	\$ 185.90		\$ 185.90
Total List Price Cost					\$ 12,998.20
				PARTS DISCOUNT 20%	\$ 10,398.56

Floor Panel spray & / 258.2

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1*	REAR BUMPER CLIPS / <i>etc</i>	1 SET	\$ 30.00	\$ 30.00
2	REAR NUMBER PLATE WITH CASING / <i>etc</i>	1 SET	\$ 50.00	\$ <i>40</i> 50.00
3	REAR FENDER COWLING <i>clips - etc</i>	2 SET	\$ 60.00	\$ 60.00
4	REAR FENDER INNER TRIM <i>clips - etc</i>	2 SET	\$ 60.00	\$ 60.00
5	BOOTLID INNER TRIM <i>clips - etc</i>	1 SET	\$ 30.00	\$ 30.00
6	END PANEL TOP GARNISH CLIPS / <i>etc</i>	1 SET	\$ 30.00	\$ 30.00
7	REVERSE SENSORS / <i>etc</i>	1 SET	\$ 250.00	\$ 250.00
8	REVERSE SENSORS HARDNESS ✓	1	\$ 280.00	\$ 280.00
9	END PANEL TOP GARNISH CLIPS - <i>etc</i>	1 SET	\$ 30.00	\$ 30.00
10	EMERGENCY SIGN KIT X	1	\$ 200.00	\$ 200.00
11	END PANEL SEALANTS / <i>etc</i>	2	\$ 80.00	\$ 80.00
12	WINDSCREEN SEALANTS / <i>etc</i>	2	\$ 80.00	\$ 80.00
13	SPARE TYRE FLOOR INSULATOR ✓	1	\$ 250.00	\$ 250.00
Total Special Nett Items				\$ 1,430.00

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS	\$ 3,000.00
<i>1400 - 1700</i>	
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 2,800.00
<i>1200</i>	
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ <i>80</i> 200.00
TO REMOVE/ REFIT INTERIOR UPHOLSTERY	\$ <i>60</i> 150.00
TO REMOVE /REFIT REAR WINDSCREEN TO FACILITATE FENDER REPLACEMENT	\$ <i>100</i> 180.00
TO APPLY SEALANT TO THE AFFECTED AREAS	\$ X 180.00
TO REMOVE/ REFIT WIRING CHECKS	\$ <i>30</i> 120.00
TO REMOVE/ REFIT FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ <i>60</i> 250.00
TO REMOVE/ REFIT / REPLACE REAR SILENCER BOX	\$ <i>60</i> 180.00
TO REMOVE/ REPLACE REVERSE SENSORS	\$ <i>40</i> 180.00
TO REMOVE AND REPLACE/REFIT BOOTLID MECHANISM	\$ <i>50</i> 200.00
Total Others Cost	\$ 1,640.00
GRAND TOTAL	
	\$ 19,268.56

CAS GARAGE PTE LTD
 UEN 201828067M
 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
 SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan
 Direct Contact: +65 8782 7171
 Email: allangoh.cas@gmail.com
 Fax: +65 6509 9501

*10-12 Days .
 Lumpsum Repair .
 After repair photos
 Gmo Qiang .
 24/4/19 .*

<p>Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • Resurvey before/after spray painting • Display damaged part(s) during resurvey • Estimates are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary term(s) must be resurveyed and is subject to final approval from Insurance Company <p>Accepted by Repairer Signature: Date:</p>
