Surveyor RASHL | REF: | 2006N

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBF 9753X

at Workshop m/s AS PHOON

of 36, TOH GUAN RD EAST #01-35

Insured: ASM (AXA)

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition) after 4.30pm

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 3.5K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBF 9753X Yr Regn: 2012 / REG B

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: YAMAHA YBR125M c.c : 124

Colour BLACK A/C: Insured / Std / NI / NA

Sp.Reading 01134 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: LBPKE1781C0001856

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 2.75-18

R: 3.00-18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or METZELER

Front		Rear	
R/Bal.	3 mm	R/Bal.	3 mm
L/Bal.	mm	L/Bal.	mm

D.O.A. 12/04/19 D.O.I. 16/05/19

Survey held at A.S PHOON

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee:

Transportation: __S + RS, __SI

Photos

Others

TOTAL