

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile    |   |  |                               |            |  |
|--|---|--|-------------------------------|------------|--|
| AXA INSURANCE PTE LTD  |   |  | Ref : CC4/ASM19007240/R1ga3s2 |            |  |
| 8 SHENTON WAY #24-01<br>AXA TOWERSINGAPORE 068811<br>ATTN: SAW THENG |   | Date: 01-10-2020<br>Code: ASM                        |                               |            |  |
| 1. Policy Particulars :- THIRD PARTY CLAIM                           |   |  |                               |            |  |
|  | Insured Veh.  | GBC 7223M  | Veh. Inspected                | FBF 9753X  |  |
|  | Policy No.  | P1822811   | Coverage (\$)                 | 0.00       |  |
|  | Claim No.   | S9M01K5Z   | Excess (\$)                   | 0.00       |  |
|  | Assign From   | SAW THENG  | Assign Date                   | 24/04/2019 |  |
| 2. Vehicle Particulars & Condition                                   |   |  |                               |            |  |
|  | Make & Model  | YAMAHA YBR 125 M                                     | c.c                           | 124        |  |
|  | Engine No.  | HIDDEN   | Year of Reg.                  | 2012       |  |
|  | Chassis No.   | LBPKE1781C0001856                                    | Colour                        | BLACK      |  |
|  | Odometer  | 01134  | Steering                      | IN ORDER   |  |
|  | Brakes  | IN ORDER   | Modification                  | SPORTS RIM |  |
|  | General   | FAIR   |                               |            |  |
| 3. Conditions of Tyres   |   |  |                               |            |  |
|  |   | Size   | Make                          | Balance    |  |
|  | R/H Front Tyre  | 2.75-18  | METZELER                      | 3 mm       |  |
|  | L/H Front Tyre  |  |                               | mm         |  |
|  | R/H Rear Tyre   | 3.00-18  | METZELER                      | 3 mm       |  |
|  | L/H Rear Tyre   |  |                               | mm         |  |
| 4. Description of Damages  |   |  |                               |            |  |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND O/S BODY.   |  |                               |            |  |
|  | DAMAGES SEE DETAILS.  |  |                               |            |  |
| 5.   | General Information   |  |                               |            |  |
|  | Accident Date   | 12/04/2019   | Inspection Date               | 16/05/2019 |  |
|  | Survey held at  | A.S. PHOON PTE LTD                                   |                               |            |  |
|  |   | BLK 36 TOH GUAN ROAD EAST<br>#01-35 SINGAPORE 608580 |                               |            |  |
| 5a.  |   |  |                               |            |  |
|  | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                               |            |  |
| 5b.  | `   |  |                               |            |  |
|  | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days  |  |                               |            |  |