

SERVICE REQUESTS

MESSAGES

CLAIMS

Claim	S9M01KNH
Reference	CS3/ASM19007274/Ua3s2 
Loss Date	April 17, 2019
Report Date	Apr 24, 2019 8:51:00 AM
Request Date	May 30, 2019
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident Vehicle Registration #	SMA4016U
Make	TPVD HONDA
Model	STREAM-1.8 RN6 (A)

Service Address

, , ,

Primary Contact/Insured

ESRIC
333B ANCHORVALE LINK, #13-332, 542333, Singapore
96686285
SHARONJ@AVALLIS.COM

Claim Handler

KHONG Lynn
68804892
lynn.khong@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1[1].pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	July 4, 2019
 LKKPreRepairInspection[1].pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 4, 2019
 LKKPhoto(3).pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	July 4, 2019
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	July 4, 2019
 IA - AMENDED.pdf	Forms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	April 29, 2019
 IA.pdf	Forms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	April 29, 2019
 LKK SURVEY PHOTO.pdf	Forms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	April 29, 2019

English (default) ▾		LKK AUTO CONSULTANTS PTE LTD (TP) ▾		SUB-TYPE	AUTHOR	DATE UPLOADED
	SERVICE REQUESTS	MESSAGES	CLAIMS	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	April 29, 2019
	 GBB148Z INSD GIA REPORT.PDF	Reports & Statement		GIA Report	DHAKAL Raghav	April 24, 2019
	 TP PRI FROM WORKSHOP.msg	Letters and Correspondence		Workshop	DHAKAL Raghav	April 24, 2019
	 SMA4016U TP GIA REPORT.PDF	Reports & Statement		GIA Report	DHAKAL Raghav	April 24, 2019