

ASS. REC. BY:

REF: CS3/CT1190072931 Ecd302 Special Instruction:

Surveyor: STAVEASSIGNMENT (Office)

MURIMAN

From (Person): Claine Chiongof CT1Date/Time: 25.4.2019 11.55 a.m

Estimated Cost: _____

Bill to: _____

OD ~~(TP)~~ WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: BHH 3428Insured: SLR 5348Cat Workshop m/s ACE AutoLubonTel: 6844184of 13 Kaki Bukit Road 4, #03-29Policy No: DMPCSN1829121800Claim No: SNM19D201698C02

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A. 13.4.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement: _____

Date/Time: 25.4.19 1.00 p.mPerson Contacted: AnnaVehicle IN (OUT)

Date/Time	Action/Instruction (X) Estimate
	BHH 3428 - X
	SLR 5348C - CS/CT119006999/Kvd3 D.O.A - 13/4/19

108/11/19
Surveyor

Steve

REF: C71

ASSIGNMENT

From: _____ Date: 26/4/19
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: BHH 3428
at Workshop m/s Ace Auto Solution
of 13 Kaki Bkt Rd 4 #01-20
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: 4pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: BHH 3428 Yr Regn: No record
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Nissan Vanette C.C. 1488
Colour: White A/C: Insured / Std / NI / NA
Sp. Reading: 347463 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: VPC 22- A3318F
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim
Tyre Size: F: 175/70 R13
R: 11"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Falken

Front		Rear	
R/Bal. <u>5</u>	mm	R/Bal. <u>5</u>	mm
L/Bal. <u>5</u>	mm	L/Bal. <u>5</u>	mm
D.O.A. <u>13/4/19</u>		D.O.I. <u>26/4/19</u>	

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* Registration Card, Insurance Policy

4K-5K, 6 days

14/5/2019

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Report Format : PRS

Lump Sum / I.B.I. (\$) _____

Survey Fee: 160

Transportation: _____

\$ + RS, \$ _____

Photos _____

Others _____

TOTAL

160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Apr 2019		25 Apr 2019 11:55 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:									
Main Claimant:		LAW CHOON HUAT							
Vehicle Reg. No.:		BHH3248	Date of Loss:	13/04/2019 11:00 - :59					
Claim Type:		TP / SNM19D201698C02	Policy/Cover Note No.:	DMPCSN1829121800					
Vehicle Reg. No. (Insured):		SLR5348C	Policy No. (Claimant):						
		Excess:	S\$1,000.00						
Repairer:		Ace Autolution (HQ) 13 KAKI BUKIT ROAD 4, #03-29 Bartley Biz Centre, 417807 Kaki Bukit - Tel:							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/05/2019]							
ASSOCIATED MAIL RECEIVED			View All Compose Case Mail						
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



**SINGAPORE
POLICE FORCE**



T/20190413/2098

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

1 of 3

Report No. T/20190413/2098

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/04/2019 15:20	Vide Report No.:	Station Diary No.: 26
--	------------------	--------------------------

Informant's Particulars

Name of Informant: LAW CHOON HUAT			Address: 106B DEPOT ROAD #04-571 SINGAPORE 102106	
ID Type / ID No.: FIN NO / F7926022M			Contact No.: Home/Office: Mobile: 87785445	
Nationality: MALAYSIAN			Email:	
Sex: Male	Age: 46	Date of Birth: 12/02/1973	Type of Informant: Driver	
Race: Chinese			Language: Mandarin	Institution / School Name:
Occupation: CONSTRUCTION WORKER			Driving Licence Information: Class: Date of Expiry:	

General Information of the Accident

Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 13/04/2019 12:00	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY TOWARDS CHANGI, BEFORE LORNIE RD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
BHH3428	Van	NISSAN	C22	White	Slightly Damaged	1
SLR5348C	Car	FORD		Silver	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No		
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA	



**SINGAPORE
POLICE FORCE**



T/20190413/2098

2 of 3

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

Report No. T/20190413/2098

CONTINUATION OF REPORT

Passenger			
Name	LAW CHOON GUAN		ID No. G7103939R
Related Vehicle	BHH3428 (Van)		Contact No. 87785445
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LAW CHOON HUAT		ID No. F7926022M
Related Vehicle	BHH3428 (Van)		Contact No. 87785445
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	Lee Chiang Kuen		ID No. S8486877I
Related Vehicle	SLR5348C (Car)		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the above mentioned date, time and location. I was driving a white Nissan van along second lane. The silver ford from first lane suddenly swerved to the left, into my lane in order to avoid an accident. As such, the silver ford collided onto the right body of my van causing multiple superficial damage.

Both parties were not injured and we exchanged particulars and left.



**SINGAPORE
POLICE FORCE**



T/20190413/2098

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

3 of 3

Report No. T/20190413/2098

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 1 TAN LI JIE

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:


TP / AEIT /

Sgt 2 SHARIFAH NOR FARIZAN BINTE SYED
MOHD SAID

Contact No.: 65476172

Authentication Stamp

NP168



Signature Of Informant:

Date/Time:

13/04/2019 15:20

Classification Of Case:

...CLAIM SUBFOLDER...(Pending for Survey Report)

































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Apr 2019		25 Apr 2019 11:55 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	LAW CHOON HUAT								
Vehicle Reg. No.:	BHH3428	Date of Loss:	13/04/2019 11:00 - :59						
Claim Type:	TP / SNM19D201698C02	Policy/Cover Note No.:	DMPCSN1829121800						
Vehicle Reg. No. (Insured):	SLR5348C	Policy No. (Claimant):							
		Excess:	S\$1,000.00						
Repairer:	Ace Autolution (HQ) 13 KAKI BUKIT ROAD 4, #03-29 Bartley Biz Centre, 417807 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 07/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***BHH3428 (SNM19D201698C02)**
[SLR5348C]

TP
LAW CHOON HUAT
Apr 13 2019 11:00AM
[-]
Ace Autolution

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Photos/Images									3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
2	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
3	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
4	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
5	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
6	26/04/19 16:41	Odometer Reading								Load JPG	<input checked="" type="checkbox"/>			
7	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
8	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
9	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
10	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
11	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
12	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
13	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
14	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
15	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
16	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
17	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
18	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
19	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
20	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
21	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
22	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
23	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
24	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
25	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
26	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
27	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
28	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
29	26/04/19 16:41	General View								Load JPG	<input checked="" type="checkbox"/>			
30	26/04/19 16:41	Chassis Number								Load JPG	<input checked="" type="checkbox"/>			
31	26/04/19 16:41	Chassis Number								Load JPG	<input checked="" type="checkbox"/>			
Documentation									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)								Thumbnail	Print			
1	25/04/19 11:56	PRS - BHH3428								Load PDF				

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19007293/ECD3E2

Date: 24/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN1829121800

Claimant Vehicle
No : BHH3428Insured Vehicle
No : SLR5348C

Date of Loss: 13/04/2019

Nature of Claim: TP

Claim
No: SNM19D201698C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: BHH3428

Make & Model: NISSAN VANETTE, 1.5 VPC22EFU (M)

Engine No: HIDDEN

Reg. Date: (Man. Year:)

Chassis No: VPC22A33188

Colour: White

Odometer: 347463 km

Engine Capacity: 1488 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R13

Rear Tyre Size: 175/70 R13

Front Left Side: Falken 5 mm

Rear Left Side: Falken 5 mm

Front Right Side: Falken 5 mm

Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 25/04/2019

Date Inspected: 26/04/2019 Inspected At:

Ace Autolution (HQ)
13 KAKI BUKIT ROAD 4, #03-29 Bartley
Biz Centre
Singapore 417807

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 24 May 2019)	
Parts:	N/A	NISSAN VANETTE 1.5 VPC22EFU (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for BHH3428)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >