ASS. REC. BY: Adrian | REF: 7603/Hg

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SGM5660K Yr Regn: 2018 / May

Type: (M.Car) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Audi A6 c.c 1798.

Colour Bronze. A/C: Insured / Std / NI / NA

Sp.Reading 29342. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WAUZZZ4G9JN027725

Gen. Cond: (Good) / Fair / Poor / Burnt

Steering: (Inorder) / Jammed / Leaked / Burnt or

Brake: (Inorder) / Jammed / Leaked / Burnt or

Modi : Nil / (S/Rim) / STD A/Rim or

Tyre Size: F: 245/45R18.

R: 245/45R18.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.		D.O.I.	30/04/19.

Survey held at Premium.

Des. of Damages : Frt / Rear / O/S / (N/S) / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP 111
	MV :
	PV :
	Nett :

Date/Time, File Pass to?	Date/Time, File Return to?
1)	2)
3)	4)
5)	6)
Preli. Report:	
Final Report:	

Part Prices Check:

IN	OUT

Survey Fee: Date:

Basic & Add.

__ S + RS, __ SI

Photos

Others

TOTAL