

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBG1349C

Yr Regn:

2017JuneType: M.Car / M.Cycle / Bus / Van / ~~Motor~~ / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Dyna

C.C

2982

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp.Reading

62971

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTFAT35YXOK207583.

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

Inorder / Jammed / Leaked / Burnt or

Brake:

Inorder / Jammed / Leaked / Burnt or

Modi:

Nil / STD A/Rim or

Tyre Size:

F:

195R15CLexotik

R:

155R12CCondor

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

02/05/19.

Survey held at

Succes UnitedDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TPAXA.MV: 63K (plus Refrigerator)PV: 20.8K.Nett: 422K.

Date/Time, File Pass to?

Date/Time, File Return to?

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Prel. Report:

Final Report: