



## SMRT Accident Vehicle Repair Estimates


<b>SMRT Automotive Services Pte Ltd</b>	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 23/04/2019

User ID : GohKK2

Section A - Accident Details	
Registration Number	SG1180U
Case Reference Number	BUS/04/19/1048
Registration Date	14/11/2016
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	CITARO O530
Name of Driver	Chai Kim Ket
Type of Accident	Side Swipe
Accident Date and Time	19/4/2019 11:32 AM
Accident Reported Date and Time	23/4/2019 10:45 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG1180U - RIGHT FRONT PORTION SHA4804X (TP) - COMFORT TAXI. INSURED WITH III.
Prepared Date and Time	23/4/2019 5:16 PM
Chassis Number	WEB62808323130015
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$0.00
Total Spray Cost	\$528.00	\$0.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
<b>TOTAL COST</b>	<b>\$1,323.00</b>	<b>\$0.00</b>
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	23/04/2019 5:22 PM	
Signature		<input type="checkbox"/>
Remarks		



Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 23/04/2019

User ID : GohKK2

### Section D - Details of Repair Estimates

Part 1 - Labour Works									
Job Scope		Quotation from AR				Adjusted by Surveyor, if applicable			
TO REPAIR RH PORTION		\$795.00 <span style="margin-left: 20px;">530</span>							
<b>Total Labour</b>		<b>\$795.00</b>							
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$528.00 <span style="margin-left: 20px;">446</span>							
<b>Total Spray Painting &amp; Panel Beating</b>		<b>\$528.00</b>							
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
Total									
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**  
 Signature:  
 Date:

Hwa Jie-Lkk  
 24/4/19  
 P/P 2days.