

ASS. REC. BY:

REF:

A/G

73371140

62

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GT 18744

Yr Regn:

08, 00

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Pick Up

Make:

NIS

c.c

2664

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

41806

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN1 C14GD 22800 42379

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: M1 / S/Rim / STD A/Rim or

Tyre Size:

F:

185R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Corda

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

17/4/11

D.O.I.

8/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

01514

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fixings

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

**Enquire Vehicle & Owner Information ( Vehicle No. SCG9181D As At 17 Apr 2019 / 14:00:00 )****Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: CHM-GT1874

**Current Owner Details**

Owner ID Type: Singapore NRIC

Owner ID: S1202581E

Owner Name: HO CHEW SENG

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.:13

Registered Street Name: COUNTRYSIDE WALK

Registered Unit No.: -

Registered Building Name: -

Registered Postal Code: 789692

**Current Vehicle Details**

Vehicle No.: SCG9181D

Make Description/Model: MERCEDES BENZ / E200 SEDAN (R18)

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

&gt; Back to OneMotoring

**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	6613Z
<b>Vehicle Details</b>	
Vehicle No.:	GT1874A
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Apr 2019
Vehicle Make:	NISSAN
Vehicle Model:	P/UP D/CAB
Primary Colour:	Silver
Manufacturing Year:	2000
Engine No.:	TD27659093
Chassis No.:	JN1CHGD22Z0042379
Maximum Power Output:	-
Open Market Value:	\$21,865.00
Original Registration Date:	04 Aug 2000
First Registration Date:	04 Aug 2000
Transfer Count:	1
Actual ARF Paid:	\$30,611.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	03 Aug 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$30,960.00
COE Rebate Amount:	\$4,003.00
<b>Total Rebate Amount:</b>	<b>\$4,003.00</b>

The information contained herein is correct as at 18 Apr 2019

OK

CHENG HOE MOTOR PTE LTD  
 Blk 1019, Yishun Ind. Park A  
 #01-374, Singapore 768761  
 Tel: 6755 6142 Fax: 6755 7719  
 Email: chmotor@singnet.com.sg