

ASS. REC. BY:

REF: CS/CT1/9007364/ GCD3<sup>SY</sup>

Special Instruction:

Surveyor: GR

## ASSIGNMENT (Office)

MUMUN

From (Person): Elaine Cheong

of CT1

Date/Time: 25.4.19 17.25p.m.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJT 7659E

Insured:

SJT 9039E

at Workshop m/s Teck Siang Motor

Tel:

90060235

of Block 5034 Ane Industrial Park 2 # 01-331

Policy No: DMPESN3033971806

Claim No:

SRM190201778602

Sum Insured:

Excess:

Make of Veh:

D.O.A. 21.4.2019

(Client's Record)

29.4.19 11.30a.m

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time: 26.4.19 9.27a.m

Person Contacted:

Jordan

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SJT 7659E - X
	SJT 9039E - X
	Dismantle: 30/4/2019
	After repair: 2/5/2019

PRS  
602

REF: C11

3142H

# ASSIGNMENT

From: \_\_\_\_\_ Date: **29.4.2019**

Estimated Cost: \_\_\_\_\_

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SJT 7659E**

at Workshop m/s **Tack Siang Motor**

of **Block 5034 Amk Industrial Park #01-33**

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: **11.30 am (waiting)**

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: **\$18K**

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: **5** days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **wp**

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: **SJT7659E** Yr Regn: **29 Oct 2009**

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: **Toyota Altis** c.c. **1598**

Colour: **silver** A/C: **Insured / Std / NI / NA**

Sp. Reading: **83088** T/Radio: **Insured / Std / NI / NA**

Eng/No: \_\_\_\_\_

G/No: **MR0538EE 1061570 46**

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: **Nil / S/Rim / STD / A/Rim or**

Tyre Size: F: **195/65 R15** R: **1**

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. **5** mm L/Bal. **5** mm D.O.A. \_\_\_\_\_

Rear R/Bal. **5** mm L/Bal. **5** mm D.O.I. **29-04-19**

Survey held at **w/s 11:30**

Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop or**

The ☒ Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<b>\$4000 - \$5000</b>
	<b>30/4/2019</b>

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Days Of Repair: **5**

Resurvey No. of Trip: **2**

Date/Time, File Return to?

2) \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : **PRS**

Lump Sum / I.B.I. (\$) \_\_\_\_\_

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Apr 2019		25 Apr 2019 17:25 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:									
Main Claimant: <b>NG YAP HUA</b> , ID: S2513142H									
Vehicle Reg. No.:		<b>SJT7659E</b>	Date of Loss:	21/04/2019 13:00 - :59					
Claim Type:		<b>TP / SNM19D201778C02</b>	Policy/Cover Note No.:	DMPCSN3033971806					
Vehicle Reg. No. (Insured):		<b>SJF9039E</b>	Policy No. (Claimant):	5089451575-01					
		Excess:	S\$750.00						
Repairer: <b>Teck Siang Motor Service (HQ)</b> Block 5034 Ang Mo Kio Industrial Park 2 #01-331, 569537 Ang Mo Kio - Tel: 6483 3445									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Claimant's Insurer: <b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Final Rpt due 07/05/2019]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<input type="checkbox"/> <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Nivitha (LKK Auto)**

---

**From:** Elaine Cheong <elaine.cheong@sg.cntaiping.com>  
**Sent:** Thursday, 25 April 2019 5:19 PM  
**To:** Doreen; assignments  
**Subject:** RE: PRE-REPAIR SURVEY NOTICE (CLAIM REF: SNM19D201778C02/9)  
**Attachments:** FW: PRE-REPAIR SURVEY NOTICE (504 KB)

WITHOUT PREJUDICE

Dear Doreen,

We refer to your email of 25.04.19.

Please be advised that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards,

**Elaine Cheong**  
Executive (Motor Claims)  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389 6530  
Fax: 6224 7478 / 6224 7175  
Email: [elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

---

**From:** Doreen [mailto:doreen@crlpractice.com]  
**Sent:** Thursday, 25 April, 2019 4:07 PM  
**To:** Elaine Cheong <elaine.cheong@sg.cntaiping.com>  
**Subject:** FW: PRE-REPAIR SURVEY NOTICE (CLAIM REF: SNM19D201778C02/9)

Dear Elaine

Further to my email to you earlier, please inform your surveyor who's conducting the PRS to contact Jordan Goh at 9006 0235 directly.

Thank you

Doreen

---

**From:** Doreen [<mailto:doreen@crlpractice.com>]  
**Sent:** Thursday, April 25, 2019 4:05 PM  
**To:** 'Elaine Cheong' <[elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)>  
**Subject:** RE: PRE-REPAIR SURVEY NOTICE (CLAIM REF: SNM19D201778C02/9)

Without Prejudice

Dear Madam

Thank you for your reply.

Our client is not agreeable to your list of surveyors and would like to propose the following surveyors listed below. Considering the fact that our client's repairer is a modest workshop, they are only able to nominate 4 surveyors.

List of surveyors:

1. Errol Tan
2. Andrew How
3. Dave Chang
4. Lee Kok Weng

We look forward to your agreement to any one of the said 4 surveyors to be the mutual surveyor (single joint expert).

Please be informed that our client's vehicle can be inspected at M/s TECK SIANG MOTOR SERVICE located at Block 5034 Ang Mo Kio Industrial Park 2, #01-331 S'pore 569537.

Please contact Mr Jordan Goh at telephone nos. 6483 3445 / 9006 0235 to confirm the date and time of your pre-repair survey.

We will submit our client's claim once all the relevant supporting documents are in order.

Best regards

Doreen Tan

---

**From:** Elaine Cheong [<mailto:elaine.cheong@sg.cntaiping.com>]  
**Sent:** Thursday, April 25, 2019 3:25 PM  
**To:** [doreen@crlpractice.com](mailto:doreen@crlpractice.com)  
**Cc:** [tecksiangmotor@gmail.com](mailto:tecksiangmotor@gmail.com)  
**Subject:** FW: PRE-REPAIR SURVEY NOTICE (CLAIM REF: SNM19D201778C02/9)

**WITHOUT PREJUDICE**

Dear Doreen,

We refer to your email of 24.04.19.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

**Elaine Cheong**

Executive (Motor Claims)  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389 6530  
Fax: 6224 7478 / 6224 7175  
Email: [elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

---

**From:** Claims Dept of CTI

**Sent:** Wednesday, 24 April, 2019 11:19 AM

**To:** Elaine Cheong <[elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)>

**Cc:** Angie Foo <[angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)>

**Subject:** FW: PRE-REPAIR SURVEY NOTICE

Dear Elaine,

Please conduct PRS – TP: SJT7659E soonest possible.

The file is with you.

---

**From:** Doreen [<mailto:doreen@crlpractice.com>]

**Sent:** Wednesday, 24 April 2019 11:16 AM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Cc:** 'Teck Siang Motor Service' <[tecksiangmotor@gmail.com](mailto:tecksiangmotor@gmail.com)>

**Subject:** PRE-REPAIR SURVEY NOTICE

Dear Sir/Madam

Please refer to our PRS notice attached and let us have your reply soonest (we have faxed the same to your office earlier).

Regards

Doreen Tan

C RAMESH LAW PRACTICE  
TEL: 62914086

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



Virus-free. [www.avg.com](http://www.avg.com)

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/04/2019 14:15
Date Of Accident	21/04/2019 13:45
Exact Location Of Accident	MIDDLE ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT7659E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NG YAP HUA
NRIC No	S2513142H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97591702
Alternative Phone No	OTHERS-97591702

### Vehicle Particulars

Manufacturer	TOYOTA
Model	ALTIS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5089451575-01
Cover Note Number	

### Driver

Name of Driver	LER WATT KIAU
NRIC No	S2513143F
Date Of Birth	22/11/1947
Occupation	INDOOR
Date Of Driving Pass	16/05/1978
Driving Experience	40 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97896012
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 160 HOUGANG ST 11 #04-45
Postcode	530160
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ONG GUET CHOON GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN - CIRCUMSTANCES OF THE ACCIDENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJF9039E
Vehicle Make/Model/Colour	HONDA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	DONNA LOR
NRIC/Passport Number	S8023498H
Contact Number	96233620
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name  
 NRIC/FIN No:

## SKETCH PLAN

refer to the attachment


## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


ON 21 04 2019 I WAS driving along BEACH Rd AND turn  
 to NICOL Highway. When I was turning into NICOL Highway  
 vehicle No STF 903 9E came from my right hand side and banged  
 onto my right side front portion AS a result my vehicle front right  
 side was very damage.


I want to say that that vehicle at my right side he is  
 only can going straight but cannot turn left.  
 That is all.


## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No:



> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	3142H
Vehicle No.:	SJT7659E
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	3ZZ4938275
Chassis No.:	MR053ZEE106157046
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,853.00
Original Registration Date:	29 Oct 2009
First Registration Date:	29 Oct 2009
Transfer Count:	1
Actual ARF Paid:	\$17,853.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Oct 2019
PARF Rebate Amount:	\$8,926.00
COE Expiry Date:	28 Oct 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$6,282.00
COE Rebate Amount:	\$934.00
<b>Total Rebate Amount:</b>	<b>\$9,860.00</b>

The information contained herein is correct as at 29 Apr 2019

OK

**▶ Altis Used Vehicle List (19 vehicles)**

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
<b>Toyota Corolla Altis 1.6A (New 5-yr COE)</b>	<b>\$28,800</b>	<b>\$5,750 /yr</b>	<b>24-Jun-2009</b>	<b>1,598 cc</b>	<b>-</b>	<b>GV Credit Pte Ltd</b>	<b>Available</b>
Office No. - 63443344 Alvin - 93607619  2.98%P.A.\$488 Monthly.\$0 Admin Fees For All GV Purchase. Extra Add On Items: New 2 Years Warrantny For Engine And Gearbox.New 2k Metallic Paint.New Pure Leather.New Rims 16" Tyres. New Pioneer DVD An...							
<b>Toyota Corolla Altis 1.6A</b>	<b>\$18,800</b>	<b>-</b>	<b>19-Aug-2009</b>	<b>1,598 cc</b>	<b>-</b>	<b>GV Credit Pte Ltd</b>	<b>Available</b>
Most Of The Wear And Tear Has Been Done Up. Drive Without Hassle. Low Repair Cost With Super Low Fuel Consumption. Please Call Our Sales Consultant Stated Below For More Enquiries Now! Office No. - 63443344 Kelvin Lim - 87770700   Sam - 90095051							
<b>Toyota Corolla Altis 1.6A (New 5-yr COE)</b>	<b>\$26,800</b>	<b>\$5,350 /yr</b>	<b>21-Apr-2009</b>	<b>1,598 cc</b>	<b>110,000 km</b>	<b>SmartCars Boutique Pte Ltd</b>	<b>Available</b>
Monthly \$481 (Bank Loan). Own This Known For Reliable And Fuel Saver Sedan. Car Done Up With New Paint And Interior. All Done Up To Showroom Condition. Any Trade In Car Welcome With Highest Offered. S... Office No. - 67410182 Wyne - 82980773   Johnny - 90047217							
<b>Toyota Corolla Altis 1.6A (New 5-yr COE)</b>	<b>\$26,800</b>	<b>\$5,350 /yr</b>	<b>18-Feb-2009</b>	<b>1,598 cc</b>	<b>-</b>	<b>Sing Thai Hin Car</b>	<b>Available</b>
Single Owner. Internal Family Transfer For Number Plate Redemption Purpose, With Proof From LTA. In Minimal Condition With No Repairs Needed. Low Mileage Clocked, Due To Family Second Car. Popular Cho... Office No. - 67490238 Mr Tee - 83052624   Ng - 93666036							
<b>Toyota Corolla Altis 1.6A (New 5-yr COE)</b>	<b>\$26,888</b>	<b>\$5,370 /yr</b>	<b>29-Apr-2009</b>	<b>1,598 cc</b>	<b>-</b>	<b>SG Auto Pte Ltd</b>	<b>Available</b>
Best Sedan Of Its Class! Well Maintained By A Meticulous Owner! High Loan And Trade In Avail! Lowest Interest Rates In Town 2.98% Only! No Unnecessary Or Misc Charges! Hurry Down For A No Obligation T... Office No. - 68484844 Koh - 92475893   Jamme - 98179689							
<b>Toyota Corolla Altis 1.6A (COE till 04/2024)</b>	<b>\$27,800</b>	<b>\$5,580 /yr</b>	<b>23-Apr-2009</b>	<b>1,598 cc</b>	<b>-</b>	<b>GV Credit Pte Ltd</b>	<b>Available</b>
2.98%P.A.\$488 Monthly.\$0 Admin Fees For All GV Purchase. Extra Add On Items: New 2 Years Warrantny For Engine And Gearbox.New 2k Metallic Paint.New Pure Leather.New Rims 16" Tyres. New Pioneer DVD An... Office No. - 63443344 Wan - 82805406							
<b>Toyota Corolla Altis 1.6A (New 5-yr COE)</b>	<b>\$27,800</b>	<b>\$5,550 /yr</b>	<b>27-May-2009</b>	<b>1,598 cc</b>	<b>-</b>	<b>GV Credit Pte Ltd</b>	<b>Available</b>
2.98%P.A.\$488 Monthly.\$0 Admin Fees For All GV Purchase. Extra Add On Items: New 2 Years Warranty For Engine And Gearbox.New 2k Metallic Paint.New Pure Leather.New Rims 16" Tyres. New Pioneer DVD And... Office No. - 63443344 Mave - 90099586							
<b>Toyota Corolla Altis 1.6A (New 5-yr COE)</b>	<b>\$27,800</b>	<b>\$5,550 /yr</b>	<b>01-Apr-2009</b>	<b>1,598 cc</b>	<b>-</b>	<b>GV Credit Pte Ltd</b>	<b>Available</b>
2.98%P.A.\$488 Monthly.\$0 Admin Fees For All GV Purchase. Extra Add On Items: New 2 Years Warrantny For Engine And Gearbox.New 2k Metallic Paint.New Pure Leather.New Rims 16" Tyres. New Pioneer DVD An... Office No. - 63443344 Wan - 82805406							
<b>Toyota Corolla Altis 1.6A (COE till 02/2024)</b>	<b>\$27,800</b>	<b>\$5,820 /yr</b>	<b>05-Feb-2009</b>	<b>1,598 cc</b>	<b>-</b>	<b>GV Credit Pte Ltd</b>	<b>Available</b>
2.98%P.A.\$488 Monthly.\$0 Admin Fees For All GV Purchase. Extra Add On Items: New 2 Years Warrantny For Engine And Gearbox.New 2k Metallic Paint.New Pure Leather.New Rims 16" Tyres. New Pioneer DVD An...							

Office No. - 63443344  
Mave - 90099586

**Toyota Corolla Altis 1.6A**    **\$27,800**    **\$5,740 /yr**    **02-Mar-2009**    **1,598 cc**    **-**    **GV Credit Pte Ltd**    **Available**  
(COE till 03/2024)

2.98%P.A.\$488 Monthly.\$0 Admin Fees For All GV Purchase. Extra Add On Items: New 2 Years Warrantry For Engine And Gearbox.New 2k Metallic Paint.New Pure Leather.New Rims 16" Tyres. New Pioneer DVD An...

Office No. - 63443344  
Alvin - 93607619

**Toyota Corolla Altis 1.6A**    **\$27,800**    **\$5,560 /yr**    **28-Apr-2009**    **1,598 cc**    **-**    **GV Credit Pte Ltd**    **Available**  
(COE till 04/2024)

2.98%P.A. \$488 Monthly. \$0 Admin Fees For All GV Purchase. Extra Add On Items: New 2 Years Warrantry For Engine And Gearbox. New 2k Metallic Paint. New Pure Leather.New Rims 16" Tyres. New Pioneer DV...

Office No. - 63443344  
Mave - 90099586

**Toyota Corolla Altis 1.6A**    **\$27,800**    **\$5,630 /yr**    **06-Apr-2009**    **1,598 cc**    **-**    **GV Credit Pte Ltd**    **Available**  
(COE till 04/2024)

2.98%P.A.\$488 Monthly.\$0 Admin Fees For All GV Purchase. Extra Add On Items: New 2 Years Warrantry For Engine And Gearbox.New 2k Metallic Paint.New Pure Leather.New Rims 16" Tyres. New Pioneer DVD An...

Office No. - 63443344  
Mave - 90099586

**Toyota Corolla Altis 1.6A**    **\$27,800**    **\$5,700 /yr**    **13-Mar-2009**    **1,598 cc**    **-**    **Precise Auto Trading Pte Ltd**    **Available**  
(COE till 03/2024)

Full Loan Available At \$640 Monthly, Interest From 3.18%. Bank Loan And In House Loan Available. Vehicle Checked By In House Workshop. Trade In Welcome.

Office No. - -  
Wei Quan - 97713559 | Marcus Ong - 94897930

**Toyota Corolla Altis 1.6A**    **\$28,500**    **\$5,910 /yr**    **23-Feb-2009**    **1,598 cc**    **90,000 km**    **Absolute Wheels Leasing Pte Ltd**    **Available**  
(COE till 02/2024)

Loan Available. No Repair Needed, Well Maintained And Service Regularly. Bank/In House Loan And Competitive Insurance Available. Comes With 1 Year In House Warranty For Engine And Gear Box. Contact Ou...

Office No. - 92269616  
Augustine - 97540677 | Mike - 83872323 | Jayden - 84847926

**Toyota Corolla Altis 1.6A**    **\$28,788**    **\$5,750 /yr**    **27-May-2009**    **1,598 cc**    **110,290 km**    **ABS Auto Capital Pte Ltd**    **Available**  
(New 5-yr COE)

We Are The COE Specialist. No Gimmicks, Honest Dealing, Car In Good Condition, Full Loan Available. 100% Approval. Trade In Welcome, Bank Loan Available. Call Us For An Appointment At Our Showroom Tod...

Office No. - 64753423  
Ken - 91196006 | Kenny - 98259995 | Roy - 83158315 | Alex - 82298229

**Toyota Corolla Altis 1.6A**    **\$28,800**    **\$5,750 /yr**    **08-Jun-2009**    **1,598 cc**    **-**    **Car World Automobile**    **Available**  
(New 5-yr COE)

(Interest Rate From 3.18% Monthly Of \$486)I Owner Car,Price Include New Paint/New Leather Seats, Rims, Comes With 6 Months Engine And Gearbox Warranty, All Our Quality Pre-owned Car Are Selling At Low...

Office No. - 64712822  
Thomas Hii - 88383233 | Vincent Lim - 96338877 | Alfred Koh - 94567818 | Ambrose Koh - 97912121

**Toyota Corolla Altis 1.6A**    **\$28,800**    **\$5,910 /yr**    **12-Mar-2009**    **1,598 cc**    **-**    **88 Motor Trading**    **Available**  
(COE till 03/2024)

Full Loan Mthly \$700 Plus, We Are SgcarMart Premium Dealer! Buy With No Worries! No Hidden Cost! Car In Original Condition! Low Mileage! Accident Free! In House Loan Or Bank Loan Available! No Need Gu...

Office No. - 62911187  
Jeremy - 97625070 | Ben - 90913551 | Lek - 87555787 | Nic - 81001945

**Toyota Corolla Altis 1.6A**    **\$28,800**    **\$5,850 /yr**    **31-Mar-2009**    **1,598 cc**    **131,222 km**    **Ka-Hup Vehicles Trading**    **Available**  
(COE till 03/2024)

Well Maintained By Previous Owner. New Paintwork And Clean Interior. Smooth Engine And Responsive Gearbox. Bank And In House Loans Are Available. Trade In Is Welcome. Contact Us For Viewing Appointmen...

Office No. - 67419997  
Kelvin - 91017559 | Johnson - 90722292

**Toyota Corolla Altis 1.6A**    **\$28,800**    **\$5,750 /yr**    **05-May-2009**    **1,598 cc**    **-**    **88 Motor Trading**    **Available**

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Apr 2019		25 Apr 2019 17:25 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	NG YAP HUA, ID: S2513142H		
Vehicle Reg. No.:	SJT7659E	Date of Loss:	21/04/2019 13:00 - :59 [113 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D201778C02	Policy/Cover Note No.:	DMPCSN3033971806
Vehicle Reg. No. (Insured):	SJF9039E	Policy No. (Claimant):	5089451575-01
		Excess:	S\$750.00
Repairer:	Teck Siang Motor Service (HQ) Block 5034 Ang Mo Kio Industrial Park 2 #01-331, 569537 Ang Mo Kio - Tel: 6483 3445		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 07/05/2019]		

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*SJT7659E (SNM19D201778C02)

[SJF9039E]































TP













































NG YAP HUA




















Apr 21 2019 1:00PM

[-]











Teck Siang Motor Service

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Su Brothers' Motor Workshop (AMK)	Thumbnail	Print
1	22/04/19 14:25	<b>Accident Statement</b>	 Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Su Brothers' Motor Workshop (AMK)	Thumbnail	Print
1	22/04/19 14:21	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	22/04/19 14:21	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	22/04/19 14:21	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	22/04/19 14:21	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	22/04/19 14:21	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	22/04/19 14:21	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/05/19 09:27	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
2	02/05/19 09:27	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
3	02/05/19 09:27	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	02/05/19 09:27	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	02/05/19 09:27	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	02/05/19 09:27	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	02/05/19 09:27	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	02/05/19 09:27	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	02/05/19 09:27	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	02/05/19 09:27	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	02/05/19 09:27	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	02/05/19 09:27	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	02/05/19 09:27	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	02/05/19 09:27	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	02/05/19 09:27	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	02/05/19 09:27	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	02/05/19 09:27	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
18	02/05/19 09:27	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
19	02/05/19 09:27	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
20	02/05/19 09:27	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
21	02/05/19 09:27	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
22	02/05/19 09:27	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
23	02/05/19 09:27	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Su Brothers' Motor Workshop (AMK)	Thumbnail	Print
24	02/05/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
25	02/05/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
26	02/05/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
27	02/05/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
28	02/05/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
29	02/05/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
30	02/05/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
31	02/05/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
32	02/05/19 09:28	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
33	02/05/19 09:28	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
34	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
35	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
36	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
38	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	02/05/19 09:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	10/05/19 11:38	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
70	10/05/19 11:38	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
71	10/05/19 11:38	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Su Brothers' Motor Workshop (AMK)	Thumbnail	Print
72	10/05/19 11:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	10/05/19 11:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	10/05/19 11:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	10/05/19 11:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	10/05/19 11:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	10/05/19 11:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	10/05/19 11:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	10/05/19 11:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	10/05/19 11:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	10/05/19 11:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	10/05/19 11:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	10/05/19 11:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
84	10/05/19 11:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
85	10/05/19 11:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/04/19 17:27	PRS - SJT7659E	 Load PDF	
2	25/04/19 17:29	PRS - SJT7659E	 Load PDF	
No	Finalized On	Su Brothers' Motor Workshop (AMK)	Thumbnail	Print
1	22/04/19 14:20	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	22/04/19 14:20	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	
3	22/04/19 14:20	ATTACHMENT [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

## Linked Accident Report Documents

			View	View in Browser
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Su Brothers' Motor Workshop (AMK)	Thumbnail	Print
1	22/04/19 14:25	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Su Brothers' Motor Workshop (AMK)	Thumbnail	Print
1	22/04/19 14:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	22/04/19 14:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	22/04/19 14:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	22/04/19 14:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	22/04/19 14:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	22/04/19 14:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Su Brothers' Motor Workshop (AMK)	Thumbnail	Print
1	22/04/19 14:20	Sketch Plan	 Load TIF	
2	22/04/19 14:20	Sketch Plan #2	 Load TIF	
3	22/04/19 14:20	ATTACHMENT	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19007364/GCD3S2

Date: 07/06/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3033971806
Claimant Vehicle No :	SJT7659E	Insured Vehicle No :	SJF9039E
Date of Loss:	21/04/2019	Nature of Claim:	TP
		Claim No:	SNM19D201778C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SJT7659E	Engine No:	3ZZ4938275
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106157046
Reg. Date:	29/10/2009 (Man. Year: 2009)	Odometer:	83088 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment:	25/04/2019	
Date Inspected:	29/04/2019	Inspected At: Teck Siang Motor Service (HQ) Block 5034 Ang Mo Kio Industrial Park 2 #01-331 Singapore 569537
Estimated Period of Repair:	5.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 05 Jun 2019)

**Parts:** 143      TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SJT7659E)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >