

2/29/2002

ASS. REC. BY

REC'D / SPF 19007378 / G4 d3 02

Special Instructions:

SMVey/n

QA

ASSIGNMENT (Office)

From (Person):

Frankie Thay

of

SPF

Date/Time:

26/4/19 @ 11:23am

Estimated Cost:

Bill to:

OD / IT / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

PA 1777R

Insured:

QX 1204U

at Workshop n/a

Yee Auto

Tel:

9687 4031

of

160 Sin Ming Drive #02-17

Policy No:

Claim No:

AEMD/105/009 / 2019/045

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

30.4.2019 (After 230p.m)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:20pm @ 26/4/19

Person Contacted:

Mr Chen

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

PA 1777R - X

10/1/14

Surveyor

GIL

REF: SPF

3075A

ASSIGNMENT

(-2022)

From:

Date: 30.4.2019

Veh No:

PA1777R

Yr Regn:

01 Aug 2020

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: PA1777R

Make:

Toyota Hiace

c.c

2986

at Workshop m/s

Yee Auto

Colour:

white

A/C: Insured / Std / NI / NA

of 160 sin ming Drive #02-17

Sp. Reading

490937

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

441740003906

Policy No.

C/No:

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

After 2.30 p.m

Modi: Nil / S/Rim / STD A/Rim or

Mr. Chan 9687 4031

Tyre Size:


F: 185 R14

R:

11

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

6 mm

R/Bal.

6 mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

6 mm

L/Bal.

6 mm

Est. Repairs:

5

days

Res.: Yes or No

D.O.A.

D.O.I.

30-04-19

Lum Sum:

20

%

3 Val.: Yes or No

Survey held at

w/s

2:30pm

CA / REV / REP. / 24 HRS

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Vehicle: IN / OUT

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Total \$1600 submit. CRed:

upper range \$1500 - \$2000

working day 5
Week end - 2 days.

RECEIVED 06 MAY 2019

Do Not Finalise

Date/Time, File Pass to?



: Preli. Report

1) 615 Typist



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

Report Format :

TP

Lump Sum / I.B.I. (\$

1600

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

220

Transportation:

S + RS, SI

Photos

Others

TOTAL

220

Nivitha (LKK Auto)

From: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>
Sent: Friday, 26 April 2019 11:23 AM
To: Veron Chen (LKKAuto); assignments
Cc: Abdul Rahman MOHAMAD SALIM (SPF); Hafizul Farhan RAHMAT (SPF)
Subject: RE : Pre-Repair Inspection for vehicle PA 1777 R

Your reference: PA 1777 R
Our reference: AEEMD/105/009/2019/045

Veron,
Please conduct a Pre-Repair Inspection for Vehicle PA 1777 R at the address listed below:

Yee Auto Service
160 Sin Ming Drive #02-17
Sin Ming Autocity,
Singapore 575722
Kindly contact the person in charge Mr Chan at 9687 4031 for appointment.

Thanks.

Frankie Thay (Mr)
Safe Driving Manager
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4841 | FAX: (65) 6478 4848



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	26/04/2019 16:00
Date Of Accident	25/04/2019 07:10
Exact Location Of Accident	ALONG PUNGGOL FIELD TOWARDS PUNGGOL WALK
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	PA1777R
Insured/Policyholder	
Name Of Registered Owner	TAN TAI YONG
NRIC No	S1263075A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96682195
Alternative Phone No	OFFICE-96682195
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	GA273284/1
Cover Note Number	
Driver	
Name of Driver	TAN TAI YONG
NRIC No	S1263075A
Date Of Birth	04/01/1957
Occupation	INDOOR
Date Of Driving Pass	01/11/1976
Driving Experience	42 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96682195
Fax Number	
Contact Number	OFFICE-96682195
EMail Address	NOEMAIL

Address	-
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : PASSENGER GENDER: : FEMALE
Passenger 2	NAME: : PASSENGER GENDER: : FEMALE
Passenger 3	NAME: : PASSENGER GENDER: : MALE
Passenger 4	NAME: : PASSENGER GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TECK GHEE NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 321 ANG MO KIO STREET 31 , POSTCODE: 560321 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4599999 - FAX NO: 64574478
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

refer attached police report.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	QX1204U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:



 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN

(A) PA1777R

(B) QX12044

Punggol Field



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

Police Report No. T/20190425/2173

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190425/2173

1 of 4

Police Station Of Origin:
Teck Ghee NPP
321 Ang Mo Kio Street 31 SINGAPORE
560321

Tel No: 1800-4599999

Report No. T/20190425/2173

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/04/2019 20:33		Vide Report No.: F/20190425/0055		Station Diary No.: 28	
Informant's Particulars					
Name of Informant: TAN TAI YONG			Address: APT BLK 326 ANG MO KIO AVENUE 3 #04-1996 SINGAPORE 560326		
ID Type / ID No.: NRIC NO / S1263075A			Contact No.: Home/Office: Mobile: 96682195		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 62	Date of Birth: 04/01/1957	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: School Bus Driver			Driving Licence Information: Class: 3,4,5		Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Police Vehicle	Drink Drive: No	Date/Time of Accident: 25/04/2019 07:10	Type of Location: X-Junction
Location: Along Road 1 PUNGGOL FIELD PUNGGOL WALK NEAR THE JUNCTION OF PUNGGOL FIELD AND PUNGGOL WALK				
Weather: Clear	Road Surface: Dry	Road Speed Limit: 60 Km/h		
Traffic Flow: One Way	Traffic Control: Traffic Light - Working	Traffic Volume: Moderate		
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
PA1777R	Bus/Coach/Mi nibus	TOYOTA	HIACE COMM D	White	Slightly Damaged	4
QX1204U	Car	CHEVROLET	CRUZE NB 1.6D 6AT (P)	White	Slightly Damaged	2

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
PA1777R	AXA INSURANCE SINGAPORE PTE LTD	GA273284	01/10/2018	30/09/2019



**SINGAPORE
POLICE FORCE**



T/20190425/2173

2 of 4

Police Station Of Origin:
Teck Ghee NPP
321 Ang Mo Kio Street 31 SINGAPORE
560321
Tel No: 1800-4599999

Report No. T/20190425/2173

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TAN TAI YONG	ID No.	S1263075A
Related Vehicle	PA1777R (Bus/Coach/Minibus)	Contact No.	96682195
Hospital/Clinic	338 FAMILY CLINIC PTE LTD	Class of Driving Licence & Expiry Date	Class: 3,4,5 Date of Expiry: NIL
Date Treatment	25/04/2019	Date Discharge	NIL
No. of Days granted Medical Leave	02	Degree of Injury	Slight
Driver			
Name	Noorhidayat Binte Mohamad Noor	ID No.	S9112683D
Related Vehicle	QX1204U (Car)	Contact No.	91806576
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2,3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 25/04/2019 at about 0710hrs, I was driving my mini school bus bearing registration plate PA1777R along Punggol Field towards Punggol way near the Punggol Walk junction. There are 3 lanes and I was in the middle lane. The traffic was red hence I stopped my vehicle. There is 3 vehicles ahead of mine. And shortly after I stopped my vehicle, I felt a collision from the rear. As such I got out from my vehicle and discovered that a police car bearing registration plate QX1204U had collided onto my vehicle's rear. After which I exchanged particulars with the driver and was issued reference number F/20190425/0055.

There are 4 passengers in my vehicle at the point of time and no one is injured. However, after the accident I felt pain on my back and slight giddy hence I went to 338 Family Clinic Pte Ltd for treatment and received 2 days' medical leave from 26/04/2019 to 27/04/2019. There is no in-car camera in my vehicle.

Details of the driver of QX1204U are as follows:

Name: Noorhidayat Binte Mohamad Noor
HP: 91806576
NRIC: S9112683D



**SINGAPORE
POLICE FORCE**



T/20190425/2173

Police Station Of Origin:
Teck Ghee NPP
321 Ang Mo Kio Street 31 SINGAPORE
560321
Tel No: 1800-4599999

3 of 4

Report No. T/20190425/2173

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20190425/2173

Police Station Of Origin:
Teck Ghee NPP
321 Ang Mo Kio Street 31 SINGAPORE
560321
Tel No: 1800-4599999

4 of 4

Report No. T/20190425/2173

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F/
Sgt 2 TAY YU ZHI

Signature Of Informant:

Signature Of Interpreter:
Not applicableDate/Time:
25/04/2019 20:33

Officer In Charge Of Case:

TP / DDGVT /
Sgt 3 MUHAMMAD FIRDAUS BIN SULEIMAN
Contact No.: 65476223

Classification Of Case:

SN 085

Authentication Stamp
NP168

Signature:

Singapore Police Force

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3075A
Vehicle Details	
Vehicle No.:	PA1777R
Vehicle to be Exported:	No
Intended Deregistration Date:	02 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE COMM D
Primary Colour:	White
Manufacturing Year:	2000
Engine No.:	5L4926940
Chassis No.:	LH1740003906
Maximum Power Output:	-
Open Market Value:	\$31,866.00
Original Registration Date:	01 Aug 2000
First Registration Date:	01 Aug 2000
Transfer Count:	0
Actual ARF Paid:	\$1,594.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$24,394.00
COE Rebate Amount:	\$14,203.00
Total Rebate Amount:	\$14,203.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 02 May 2019

OK



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S: LKK AUTO CONSULTANTS PTE LTD

51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL
SINGAPORE 408933

Estimate No: ES1800157

Date: 27 Apr 2019

Policy No:

Veh Reg No: PA1777R

Make/Model: TOYOTA HIACE COMM
D

Chassis No: LH1740003906

Engine No: 5L4926940

Reg. Date: 01/08/2000

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 25/04/2019

TP Veh Reg No: QX1204U

Estimate Repair Cost to Vehicle No :PA1777R

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
Net Price				
1 REAR TAILGATE 'TOYOTA' STICKER	25.00	1 PC	25.00	/
2 SPEED LIMIT STICKER '60KM/H'	20.00	1 PC	20.00	10
3 REAR TAILGATE 'EMERGENCY EXIT' STICKER	40.00	1 PC	40.00	20
			85.00	55 85.00
Spare Parts				
4 REAR WINDSCREEN RUBBER	298.70	1 PC	298.70	X
5 REAR TAILGATE	1,459.10	1 PC	1,459.10	X
6 REAR TAILGATE WEATHERSTRIP	219.20	1 PC	219.20	/
7 REAR TAILGATE LOCK	185.10	1 PC	185.10	X
8 REAR END PANEL	479.20	1 PC	479.20	/
9 REAR END INNER PANEL	469.50	1 PC	469.50	X
10 REAR END PANEL TOP PLATE	158.20	1 PC	158.20	/
11 TAIL LAMP LH	284.40	1 PC	284.40	X
12 TAIL LAMP RH	284.40	1 PC	284.40	X
13 REAR BUMPER	534.50	1 PC	534.50	374.45
14 REAR BUMPER REINFORCEMENT	232.00	1 PC	232.00	/
15 REAR BUMPER BRACKET - LH	54.00	1 PC	54.00	X
16 REAR BUMPER BRACKET - RH	54.00	1 PC	54.00	X
17 REAR BUMPER SIDE CLIP	80.00	1 SET	80.00	/
18 SPARE WHEEL BRACKET	240.20	1 PC	240.20	X
19 REAR EXHAUST MUFFLER	585.00	1 PC	585.00	X
20 REAR TAILGATE 'LOGO'	98.50	1 PC	98.50	61
21 REAR TAILGATE 'HIACE' STICKER	35.90	1 PC	35.90	/
			5,751.90	5,751.90
Labour				
22 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,200.00	1 JOB	1,200.00	400
23 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,200.00	1 JOB	1,200.00	300 400
24 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	120.00	1 JOB	120.00	X
25 TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS.	150.00	1 JOB	150.00	X
26 TO REMOVE/TRANSFER TAILGATE COMPONENTS.	100.00	1 PC	100.00	X
27 TO REMOVE/RENEW EXHAUST MUFFLER.	100.00	1 JOB	100.00	X



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S: LKK AUTO CONSULTANTS PTE LTD

51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL
SINGAPORE 408933

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 25/04/2019

TP Veh Reg No: QX1204U

Estimate No: ES1800157

Date: 27 Apr 2019

Policy No:

Veh Reg No: PA1777R

Make/Model: TOYOTA HIACE COMM
D

Chassis No: LH1740003906

Engine No: 5L4926940

Reg. Date: 01/08/2000

Estimate Repair Cost to Vehicle No :PA1777R

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			2,870.00	2,870.00
			Total	S\$ 8,706.90
			Add GST @ 7%	609.48
			Total Amount Payable	S\$ 9,316.38

TOTAL: SINGAPORE DOLLAR NINE THOUSAND THREE HUNDRED SIXTEEN AND CENTS THIRTY EIGHT ONLY

5 Days. (5)

Unpainted repair.

After repair photos.

Guo Qian - 8288 0282

30/4/19.

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

2016.31

20/4/1600

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION			Ref : CS/SPF19007378/Gtd3e2	
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333			Date : 21-05-2019 Code : SPF	
ATTN : FRANKIE THAY				
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	QX 1204U	Veh. Inspected	PA 1777R	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/105/009/2019/045	Excess (\$)	0.00	
Assign From	FRANKIE THAY	Assign Date	26/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2986	
Engine No.	HIDDEN	Year of Reg.	2000	
Chassis No.	LH1740003906	Colour	WHITE	
Odometer	490937	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185 R14	FALKEN	6 mm	
L/H Front Tyre	185 R14	FALKEN	6 mm	
R/H Rear Tyre	185 R14	FALKEN	6 mm	
L/H Rear Tyre	185 R14	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/04/2019	Inspection Date	30/04/2019	
Survey held at	160 SIN MING DRIVE #02-17			
Repairer	YEE AUTO SERVICE			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 1777R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR WINDSCREEN RUBBER	NOT NECESSARY	298.70	-
1	REAR TAILGATE	TO REPAIR SEE LABOUR	1,459.10	-
1	REAR TAILGATE WEATHERSTRIP	TWISTED	219.20	219.20
1	REAR TAILGATE LOCK	NOT NECESSARY	185.10	-
1	REAR END PANEL	BUCKLED	479.20	479.20
1	REAR END INNER PANEL	TO REPAIR SEE LABOUR	469.50	-
1	REAR END PANEL TOP PLATE	NOT NECESSARY	158.20	-
1	TAIL LAMP LH	NOT NECESSARY	284.40	-
1	TAIL LAMP RH	NOT NECESSARY	284.40	-
1	REAR BUMPER	DEFORMED	534.50	374.45
1	REAR BUMPER REINFORCEMENT	BENT	232.00	232.00
1	REAR BUMPER BRACKET - LH	NOT NECESSARY	54.00	-
1	REAR BUMPER BRACKET - RH	NOT NECESSARY	54.00	-
1	SPARE WHEEL BRACKET	NOT NECESSARY	240.20	-
1	REAR EXHAUST MUFFLER	NOT NECESSARY	585.00	-
1	REAR TAILGATE 'LOGO'	NECESSARY	98.50	61.00
1	REAR TAILGATE 'HIACE' STICKER	NECESSARY	35.90	35.90
	LESS 25% DISCOUNT		-	-350.44
			5,671.90	1,051.31
<u>SPECIAL NETT ITEMS</u>				
1	REAR TAILGATE 'TOYOTA' STICKER (SN)	NECESSARY	25.00	25.00
1	SPEED LIMIT STICKER '60KM/H' (SN)	NECESSARY	20.00	10.00
1	REAR TAILGATE 'EMERGENCY EXIT' STICKER (SN)	NECESSARY	40.00	20.00
1	SET REAR BUMPER SIDE CLIP (SN)	NECESSARY	80.00	30.00
			165.00	85.00
<u>LABOUR</u>				
	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY. INCLUSIVE OF THE REPAIR OF REAR TAILGATE AND REAR END INNER PANEL.		1,200.00	500.00
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.		1,200.00	400.00
	TO APPLY RUST-PROOFING ON REPAIRED, REPLACED PANEL.	NOT NECESSARY	120.00	-

Report Ref No. CS/SPF19007378/Gtd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE / REFIT REAR WINDSCREEN TO FACILITATE REPAIRS.	NOT NECESSARY	150.00	-
	TO REMOVE / TRANSFER TAILGATE COMPONENTS.	NOT NECESSARY	100.00	-
	TO REMOVE / RENEW EXHAUST MUFFLER.	NOT NECESSARY	100.00	-
			2,870.00	900.00
GRAND TOTAL			8,706.90	2,036.31

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,600.00
---	--	--	--	----------

Report Ref No. CS/SPF19007378/Gtd3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,000

RECOMMENDED REPAIR DAYS : 5

WEEKEND : 2

TOTAL DAYS : 7

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.