

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Steve (83228813)
(LKK)

with P/P 4 days
Ray bok spg
30/4/19 3-45pm

Quotation
Non binding - Preview

Page 1/2
Document no.
Document date 30-04-2019
Customer no. 5211000859
Customer GST-ID 196900406D
Dealer 39999
Job order number 2019000360/ 1
Job order date 25-04-2019
Service Advisor TIOW CHUAN CHEE

Company
AXA Insurance Pte Ltd
8 SHENTON WAY
#27-01 AXA TOWER
Singapore 068811

Customer Details:
Mr
ALVIN
LIEW KHOONG KIN
253 PASIR RIS STREET 21
#05-227
Singapore 510253

License plate SLS9684A	Model code 3G24JZ	First registration 12-10-2017	VIN VWVZZZ3CZHE054224	Model PASSAT Sed. HLBMT 132 D7F	Mileage 28,953
---------------------------	----------------------	----------------------------------	--------------------------	------------------------------------	-------------------

Part No.	Description	Quantity	Unit	Unit Price excl. GST	Unit Price incl. GST	Total amount excl. GST	Total amount incl. GST
	B&P MECH	1	pcs.	200.00	#1	200.00	214.00
	LABOUR	1.5	pcs.	580.00	#1	2,320.00	2,482.40
	SPRAY PAINT	1.2	pcs.	500.00	#1	2,000.00	2,140.00
	B&P DIAG	1	pcs.	360.00	#1	360.00	385.20
	WHEEL ALIGNMENT	1	pcs.	360.00	#1	360.00	385.20
	Rim & Balance	1	pcs.	50.00	#1	50.00	53.50
3G5807417	GRU Cover Primed	1	pcs.	1,530.46	#1	1,530.46	1,637.59
	REAR BUMPER	1	pcs.				
3G0807521B	GRU Spoiler Primed	1	pcs.	217.41	#1	217.41	232.63
	SPOILER	1	pcs.				
3G0998491	1 Set Sensor Brackets	1	pcs.	39.84	#1	39.84	42.63
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	74.29	#1	74.29	79.49
D 822150A1	Bonding Agent For Plastic	1	pcs.	56.90	#1	56.90	60.88
000863890A	Insulation	1	pcs.	36.22	#1	36.22	38.76
3G0853841	ZZZ Decorative Moulding Brigh LH CHROME MOLDING	1	pcs.	150.53	#1	150.53	161.07
3G0853842	ZZZ Decorative Moulding Brigh RH CHROME MOLDING	1	pcs.	150.53	#1	150.53	161.07
3G0853835	ZZZ Decorative Moulding Brigh CTR CHROME MOLDING	1	pcs.	195.49	#1	195.49	209.17
3G0945105A	Reflector LH OUTER	1	pcs.	63.86	#1	63.86	68.33
3G0945103A	Reflector LH INNER	1	pcs.	63.86	#1	63.86	68.33
3G5807375	Guide Piece LHR SIDE BRACKET	1	pcs.	34.66	#1	34.66	37.09
3G5807483A	Guide LHR TAILLIGHT BRACKET	1	pcs.	20.09	#1	20.09	21.50
WHT005263	Rivet	5	pcs.	1.09	#1	5.45	5.83
3G0601025G	ZD8 Alloy Wheel Anthracite/Al	1	pcs.	1,254.11	#1	1,254.11	1,341.90
311601361	Rubber Valve	1	pcs.	3.22	#1	3.22	3.45
3G5945207E	Led Tail Light RR TAILLIGHT OUTER	1	pcs.	604.94	#1	604.94	647.29

Quotation valid till 02-05-2019

Tax Code	Description	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	• To resurvey both... • To display... 9,791.86	7%	685.43	9,791.86	10,477.29
Total	9,791.86		685.43	9,791.86	10,477.29

• Third party survey...
• No illegal...
• Supplier... surveyed and is subject... insurance Company

Acknowledged by Repairer
Signature:
Date:

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Volkswagen



SKODA



Commercial Vehicles

Quotation

Non binding - Preview

Page 2/2

Company
AXA Insurance Pte Ltd
8 SHENTON WAY
#27-01 AXA TOWER
Singapore 068811

Customer Details:
Mr
ALVIN
LIEW KHOONG KIN
253 PASIR RIS STREET 21
#05-227
Singapore 510253

Document no.
Document date 30-04-2019
Customer no. 5211000859
Customer GST-ID 196900406D
Dealer 39999
Job order number 2019000360/ 1
Job order date 25-04-2019
Service Advisor TIOW CHUAN CHEE

License plate SLS9684A	Model code 3G24JZ	First registration 12-10-2017	VIN WWWZZZ3CZHE054224	Model PASSAT Sed. HLBMT 132 D7F	Mileage 28,953
---------------------------	----------------------	----------------------------------	--------------------------	------------------------------------	-------------------

Customer

Service Advisor

---VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).---

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: