

22/03/2019

ASS. REC. BY:

REF: CS/Smo19007399/Kvd3

n2

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Gnoh Pau Loong of Smo Date/Time: 24.19 14.31p.m

Estimated Cost: _____ Bill to: _____

OD ~~(TP)~~ WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJA 9939A Insured: GBG 995Tat Workshop m/s Tropical Success Auto Tel: 64817773of Blk 5032 Amt nr 3 #101-303Policy No: D18MTPCVE00/632 Claim No: MTD1902046

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 25.4.2019
(Client's Record)CA / REV / REP. / REV 24 HRS rup H.O.D. Endorsement: _____Date/Time: 26.4.19 3.32p.m Person Contacted: calvin Vehicle (IN) OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SJA 9939A - X</u>
	<u>GBG 995T - CC4/ASIN 19007393/063</u> <u>D.O.A - 26/04/2019</u>
<u>29/4/19</u>	<u>Send preli revised via merimen</u>
<u>15/6/19</u>	<u>112, 81300 email confirmed by email (Ref 5676.50, 8190)</u>

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Monday, 22 April, 2019 2:39 PM

To: Chee So Chow <sochow.chee@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; info@yewteegroup.com

Cc: Wang Jia Wei <jiawei.wang@sg.cntaiping.com>

Subject: OUR REF: SNM19D201726 - GBE5476C - Accident involving GBE6861S (LONPAC) claiming against GBE5476C (China Taiping)

ASS. REC. BY:

REF: J1401

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 7/12 Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJQ 993PA Yr Regn: 07, 07

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Civic c.c. 1595

Colour: M. Gold AG: Insured / Std / NI / NA

Sp. Reading: 196787 TRadio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMFD 4820 7S20099

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 25/4/19

Survey held at

Des. of Damages: Frit / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

RECEIVED 17 JUN 2019

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$

merimen

1300/-

250

11

261

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 29 Apr 2019

Preliminary Advice

Insured Vehicle No	: GBG995T	Accident Date	: 25/04/2019
TP Vehicle No	: SJQ9939A	Assignment Date	: 26/04/2019
Make	: HONDA CIVIC	Est. Duration of Repair	: 4
Date of Inspection	: 26/4/2019		
Inspection At	: TROPICAL TECH AUTOMOBILE SERVICES		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,976.50
Revised Amount	:S\$	1,834.75
Check Items (Estimated)	:S\$	549.00
Total	:S\$	2,383.75

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The above survey was conducted on a 'Without Prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Apr 2019		26 Apr 2019 14:31 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	RAY-ON GLASS PTE LTD, Co. Reg. No.: 200600776R								
Main Claimant:	SOON SIN CONTRACTS PTE. LTD., Co. Reg. No.: 200502981M								
Vehicle Reg. No.:	SJQ9939A	Date of Loss:	25/04/2019 08:00 - :59						
Claim Type:	TP / CMTD1902046	Policy/Cover Note No.:	D18MTPCVE001632 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBG995T	Policy No. (Claimant):							
		Excess:							
Repairer:	Tropical Success Auto Care (HQ) BLK 5032 Ang Mo Kio Avenue 3, #01-303 Industrial Park 2, 569535 Ang Mo Kio - Tel: 6461 7773								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/05/2019]								
Driver/Custodian (Insured):	GOH LAI MENG (), NRIC: F4509358K, Tel: +6591850119 Email:								
Adj Asg. Remarks:	WS: CALVIN 64817773								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: William Tan <tanlihao74@gmail.com>
Sent: Saturday, 15 June 2019 6:43 AM
To: Kenneth Kong (LKKAUTO); Veron Chen (LKKAUTO); William Tan
Subject: Re: SJQ9939A

Dear Sir / Madam,

I accept your lump sum cost of repair @ \$1,300 and accept 4 working repair day.

From : William Tan

On Fri, 14 Jun 2019 at 9:38 AM, Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com> wrote:

Attach finalised for SJQ 9939A.

From: William Tan [mailto:tanlihao74@gmail.com]
Sent: Friday, 14 June, 2019 4:46 AM
To: Kenneth Kong (LKKAUTO); Veron Chen (LKKAUTO); William Tan
Subject: Fwd: SJQ9939A

Your message is ready to be sent with the following file or link attachments:

IMG_9521
IMG_9511
IMG_9512
IMG_9513
IMG_9514
IMG_9516
IMG_9517
IMG_9518
IMG_9519
IMG_9520

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.

SH 8159G

Qty	Parts Description/Labour	Type	Unit Price	Amount
	Labour Charge			\$ 1,600.00
	Panel Beating			\$ 1,400.00
	Spray Painting Charge			\$ 50.00
	Wiring Charge			\$ 100.00
	Tuff Coat			\$ 50.00
	Towing Charge			\$ 50.00
	Transfer of Door			\$ 120.00
	Remove/Refix Undercarriage (FRT)			\$ 200.00
	FRT Wheel Alignment			\$ 120.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
	Remove/Refix Dashboard			\$ 450.00
	Remove/Refix Front Windscreen Glass			\$ 120.00
	Remove/Refix Cushion & Upholstery Front			\$ 90.00
	Re-set Fit ABS System			\$ 200.00
	Re-set Fit Power Window System			\$ 200.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
	TOTAL LABOUR			\$ 5,330.00
	ESTIMATE TOTAL			\$ 25,921.88
				\$ 27,032.28
				\$ 180.00
				\$ 17205.40
				\$ 1110.40
				\$ 18315.80
				\$ 45146581

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/04/2019 17:37
Date Of Accident	25/04/2019 07:50
Exact Location Of Accident	ALONG WOODLANDS AVE 2 EXIT 9
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJQ9939A
Insured/Policyholder	
Name Of Registered Owner	SOON SIN CONTRACTS PTE. LTD.
Co Reg No	200502981M
Email Address	MICHELLE@SINENG.COM.SG
Mobile Phone No	(LOCAL) +65-87848595
Alternative Phone No	OFFICE-87848595

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-1.6 L (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	18-MU007969
Cover Note Number	06/07/2018 - 03/07/2019

Driver

Name of Driver	NICOLE ANN GIAN JIA EN
NRIC No	S9516108A
Date Of Birth	02/05/1995
Occupation	INDOOR
Date Of Driving Pass	28/11/2016
Driving Experience	2 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-87848595
Fax Number	
Contact Number	OTHERS-87848595
Email Address	MICHELLE@SINENG.COM.SG

Address	298 CHQA CHU KANG AVE 3 #05-408
Postcode	680283
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SERANGOON GARDENS NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: 51 SERANGOON GARDEN WAY , POSTCODE: 555947 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2879999 - FAX NO: 62815969
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE POLICE REPORT & SKETCH PLAN BY DRIVER

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PASS TO OWN WORKSHOP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG995T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	GOH CAI MENG
NRIC/Passport Number	4509358K
Contact Number	91850119
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

GZ9692Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

ANTHONY ARULSAMY ARUL AROCKIYADASS

NRIC/Passport Number

G8401492W

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Describe Circumstances of the Accident

Please Refer Attached Police Repo 4

- ☐ Claim OD/TP at Ah Lim Motos ☒ Claim OD/TP at other workshop
☐ Reporting Only

Remarks : Please forward a copy of my efile accident report to :

My workshop : Tropical Tech
 email address : tsac303@singnet.com.sg
 & myself
 email address : michelle@singnet.com.sg

Note : Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

Declaration

We declare the foregoing particulars are true in every respect



Driver's Signature (If driver is not the policyholder) (Name & Title)



E-mail: tsac303@sinenet.com.sg

Page 1 of 2

1144

Tropical Tech Automobile Services

BLK 5030 ANG MO KIO AVENUE 3 #01-201 INDUSTRIAL PARK 3 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484

E-mail : tsac303@singnet.com.sg

M / s : **Sompo Insurance Singapore Pte Ltd**
50, Raffles Place, #05-01 / 06,
Singapore Land Tower,
Singapore 048623

Attn : Motor Claims Department
Tel : 6221 2211, 6461 6555
Fax : 6221 3147

Estimate bill : TT 25 / 19 / TP / WT

Registration No : SJQ9939A

Make / model : Honda Civic

Mileage : Date : 26 / 04 / 2019

TRAFFIC CHAIN ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : GZ9692A, GBG995T AND SJQ9939A ALONG WOODLANDS AVENUE 2 EXIT 9 ON 25 APRIL 2019 AT ABOUT 0750 HRS.

Remove and transfer rear boot necessary attachment spare part items.

Remove and transfer rear bumper necessary attachment spare part items.

Remove and refit rear boot, rear boot reflector, rear boot upper lock, rear boot rubber, rear boot hinge, rear tail lamp, rear end panel, rear end panel top garnish, rear bumper, rear bumper PDC sensor, rear bumper side bracket, rear bumper reinforcement.

Heat / weld / beating / pull / straighten / align rear chassis frame by Chassis Alignment Jack.

To check rear tail lamp wiring.

Diagnostic & reset bumper PDC sensor by HHT.

Tuff koff rear damaged portion.

Putty / primer application, spray painting rear boot, rear boot spoiler, rear end panel, rear bumper, rear bumper PDC sensor.

Balance amount brought from Page 1 :

Grand amount :

\$ 1,200.00

\$ 80.00

\$ 100.00

\$ 150.00 X

\$ 1,500.00

\$ 3,946.50

\$ 6,976.50

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19007399/KVD3N2

Date: 18/06/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPCVE001632
Claimant Vehicle No :	SJQ9939A	Insured Vehicle No :	GBG995T
Date of Loss:	25/04/2019	Nature of Claim:	TP
		Claim No:	CMTD1902046

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ9939A	Engine No:	R16A12001880
Make & Model:	HONDA CIVIC, 1.6 L (A)	Chassis No:	JHMFD46207S200991
Reg. Date:	04/07/2007 (Man. Year: 2007)	Odometer:	196787 km
Colour:	Metallic Gold		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,946.50	606.00	3,340.50	84.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,030.00	1,015.00	2,015.00	66.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,976.50	1,621.00	5,355.50	76.76
Approved Total (Overridden) (S\$)		1,300.00		
Nett Amount (S\$)	6,976.50	1,300.00	5,676.50	81.37

INSPECTION

Date of Assignment:	26/04/2019	
Date Inspected:	26/04/2019 Inspected At:	Tropical Success Auto Care (HQ) BLK 5032 Ang Mo Kio Avenue 3, #01-303 Industrial Park 2 Singapore 569535
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jun 2019)
Parts:	143	HONDA CIVIC 1.6 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJQ9939A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Repair	780.00 FL	*- FL
2	2		*REAR BOOT REFLECTOR	Serviceable	330.00 FL	*- FL
3	1		*REAR BOOT UPPER LOCK	Repair	300.00 FL	*- FL
4	1		*REAR BOOT RUBBER	Serviceable	203.00 FL	*- FL
5	2		*REAR BOOT HINGE	Repair	348.00 FL	*- FL
6	2		*REAR TAIL LAMP	Serviceable	570.00 FL	*- FL
7	1		*REAR END PANEL	Repair	840.00 FL	*- FL
8	1		*REAR END PANEL TOP GARNISH	Serviceable	167.00 FL	*- FL
9	1		*REAR BUMPER	Buckled	600.00 FL	*600.00 FL
10	1		*REAR BUMPER PDC SENSOR SET	Serviceable	280.00 FL	*- FL
11	1		*REAR BUMPER SIDE BRACKET	O/s Distorted	72.00 FL	*36.00 FL
12	1		*REAR BUMPER REINFORCEMENT	No such part	600.00 FL	*- FL
13	1		*REAR BOOT H EMBLEM	Necessary	45.00 FS	*45.00 FS
14	1		*REAR BOOT CIVIC DESIGNATION	Necessary	84.00 FS	*84.00 FS
					Sub Total (\$\$)	5,219.00 765.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,272.50 159.00
					Total Parts (\$\$)	3,946.50 606.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIT REAR BOOT,REAR BOOT REFLECTOR,REAR BOOT UPPER LOCK,REAR BOOT RUBBER,REAR BOOT HINGE,REAR TAIL LAMP,REAR END PANEL,REAR END PANEL TOP GARNISH,REAR BUMPER,REAR BUMPER PDC SENSOR,REAR BUMPER SIDE BRACKET,REAR BUMPER REINFORCEMENT.HEAT/WELD/BEATING/PULL/STRAIGHTEN/ALIGN REAR CHASSIS FRAME BY CHASSIS ALIGNMENT JACK }	New	1,200.00	400.00
2	REMOVE AND TRANSFER REAR BOOT NECESSARY ATTACHMENT SPARE PART ITEMS }	New	0.00	0.00
3	REMOVE AND TRANSFER REAR BUMPER NECESSARY ATTACHMENT SPARE PART ITEMS }	New	0.00	0.00
4	TO CHECK REAR TAIL LAMP WIRING	New	80.00	15.00
5	DIAGNOSTIC & RESET BUMPER PDC SENSOR BY HHT	New	100.00	50.00
6	TUFF KOFF REAR DAMAGED PORTION	New	150.00	0.00
7	PUTTY/PRIMER APPLICATION,SPRAY PAINTING REAR BOOT,REAR BOOT SPOILER,REAR END PANEL,REAR BUMPER,REAR BUMPER PDC SENSOR	New	1,500.00	550.00
Gross Labour Cost (\$\$)			3,030.00	1,015.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

