

ASS. REC. BY:

REF:

7421AJ + Omp Sur

Adrian

ASSIGNMENT

Front:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

TP AXA.

mv: OK

PV:

Nett:

Veh No: SLW7672B

Yr Regn:

2018, May

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

c.c 1597

Colour:

silver

A/C:

Insured / Std / NI / NA

Sp. Reading

11564

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MRHFC5650JTO00414

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

215/55R16

R:

215/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Hankook

Front

Rear

R/Bal.

ob

mm

R/Bal.

ob

mm

L/Bal.

ob

mm

L/Bal.

ob

mm

D.O.A.

D.O.I.

30/04/19

Survey held at

Kah Motors

Des. of Damages: Frt / Rear / O/S / (N/S) / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL