

INSURANCE

ISS. CASE OWNER:

CC 6 /AIG1900 7416, 4/13/19

LKK:

IDAC:

Surveyor:

Marius

DOI:

ASSIGNMENT

20/4/19

Date / Time:

20/4/19

Registered in Merimen:

20/4/19

Pre-assign / CCU / FTE:

SMG 83934

271591381656



Insured Vehicle No.:

700 KAT SI

Claim No.:

1901008950

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

97,671073

Make / Model:

MATDA

Excess Sec II :SS

D.O.A.:

20/4/19

Place of Accident:

SEMIKANT W RD THERMAL

Is driver the owner?

(YES / NO)

Nature of Accident:

INTO VET RD

If NO. Driver Name / Age:

Driver Tel No.:

(V/L- YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

CLD 66917



INSRS:
WSP:
Tel:
Liability:
RMKS:

Tan
Lim



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

CLD 66917 - X

SMG 83934 - X

| STAGE | DATE / PIC |
|-----------------------------------|----------------|
| Non-Reporting Itr (1st): | |
| Non-Reporting Itr (2nd): | |
| Non-Reporting Itr (Final): | |
| Notification Itr (if non-pickup): | |
| Call Of: | |
| After call Itr to OI: | JOY 13-5-19 |
| Documentation Check List: | Handler Typist |
| Notification Itr (if non-pickup) | |
| After call Itr to OI: | EMAIL |
| Authorisation To Act: | |
| Release Voucher: | |
| Final Repair Bill: | |
| Car Rental Invoice: | |
| Towing Invoice: | |
| LTA / GIA: | |
| Medical Bill: | |
| PIR: | |
| Mandate/Reject Instruction: | |
| LOD: | |
| Payment Breakdown Form: | |
| Post-Repair Photos: | |
| Others: | |

13-5-19 @ 1106 AM W/OI SHE
WILL FORWARD THE
VIDEO.

13-5-19 RECEIVED VIDEO FROM OI.
BY EMAIL.

14/06/19 VIDEO SHOULD- NO ARROW.
- SHOLD NOT OPPE TO TP
- TP ACCEPTED OFFER. ALL WORK IN ORDER.

| | | | | | | |
|---------------------------|--------------------------|------------|-------------------------------------|-----------------------|--------------------------|-----------------|
| PRELIMINARY ADVICE | | Date/Time: | Sent By: | Confirm with: | | Confirm by: |
| FINALIZATION | | Date/Time: | Repair Cost: | SS | days) Reduction: | |
| FINAL SETTLEMENT | | Date/Time: | Confirm with: | Email | Call | |
| Final Liability: | % | 100 | (Assessed / Assessed) BOLA S/N No.: | 5 | If NO or B 28, Ass. Lia | |
| Repair Cost: | SS | 2,354.00 | (OI WORKING TURN) | | | |
| Loss of Rental (LOR): | SS | 240.00 | days) | | | |
| Loss of Use (LOU): | SS | 240.00 | days) | | | |
| Loss of Income (LOI): | SS | X | days) | | | |
| LOR only | <input type="checkbox"/> | LOU only | <input checked="" type="checkbox"/> | LOR + LOU | <input type="checkbox"/> | [Tick only one] |
| GIA/LTA Search | SS | 2-X | | | | |
| Medical: | SS | X | | | | |
| Disbursement: | SS | X | (e.g. Tow/ Independent) | | | |
| Legal Cost: | SS | X | | | | |
| Total: | SS | 2,596.00 | Global Sum SS: | --- | | |
| FINAL PAYMENT | | Date/Time: | Confirm with: | Email | Call | |
| Payee 1: | SS | 2,596.00 | Name 1: | TAN LIM MOTOR PTB LTD | | |
| Payee 2: (Strike if N.A.) | SS | --- | Name 2: | --- | | |
| Payee 3: (Strike if N.A.) | SS | --- | Name 3: | --- | | |

ASSIGNMENT

From: Estimated Cost:

Date:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

G/A / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

17A4639

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLD657Yr Regn: 6.16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Fit

c.c

1317

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

49698

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GK31119573

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/50R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

25/4/19

D.O.I.

26/4/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/4/19 confirmed H/S #2200 with MR Tan.

(CRD: \$2,228.32/50%)

Date/Time, File Pass to?

☐

Prel. Report

☐

Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) \$ + R5.00

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

) TOTAL

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

36/4 - custom with Marcus

1/5 2200



TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SMG8393Y

Date of Accident : 25 April 2019

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

not Aishah nla

The photo before party.

3 dy

26/4/19

Mr Tan Ji-Sien, Jonathan

Date : 25 April 2019

Estimate To Repair SLD6651T - Honda FIT 1.3G F PACKAGE CVT ABS D/A

Chassis No : GK31119573

Uk - Marcus

| S/No | Quantity | Description | Amount |
|-----------------------------------|----------|---|---------------|
| LIST ITEMS | | | |
| 01 | 1 pc | front bumper | \$ 515 532.70 |
| 02 | 1 pc | front bumper side retainer left | \$ 11 29.50 |
| 03 | 8 ps | front bumper clips @ \$4.50 | \$ 36 36.00 |
| 04 | 1 pc | front bumper fog lamp left | \$ 51 281.80 |
| 05 | 1 pc | front bumper fog lamp holder left | \$ 11 25.80 |
| 06 | 1 pc | front bumper fog lamp garnish left | \$ 91 65.80 |
| 07 | 1 pc | front bumper reinforcement | \$ 11 203.30 |
| 08 | 1 pc | left headlamp | \$ 51 649.50 |
| 09 | 1 pc | left headlamp lower bracket | \$ 11 21.90 |
| 10 | 1 pc | front fender left | \$ 1 455.10 |
| 11 | 1 pc | front fender inner cowling left | \$ 11 71.50 |
| Less 20 % | | | \$ 2,372.90 |
| | | | \$ 474.58 |
| | | | \$ 1,898.32 |
| SPECIAL NETT ITEMS | | | |
| 12 | 1 pc | front bumper lower spoiler - accessory (1) | \$ 1,200.00 |
| | | | \$ 1,200.00 |
| LABOUR & MISC. CHARGES | | | |
| 01 | | To check electrical lighting concerned. | \$ 50.00 |
| 02 | | To rust-proofing of the affected areas. | \$ 11 80.00 |
| 03 | | Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same. | \$ 600.00 |
| 04 | | Putty and spray painting of the affected portion. | \$ 600.00 |
| | | | \$ 1,330.00 |
| Total | | | \$ 4,428.32 |

I hereby certify that the above is a true and correct estimate of the repair work required for the vehicle described above.
 Signature of the Repairer:
 Date:

P-1565.80
 202
 1252.64
 2772.64

—
 X
 —
 —
 X
 —
 X
 —
 X
 —
 X

800

20
 X
 300
 400

[-> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 2533G

Vehicle Details

Vehicle No.: SLD6651T
Vehicle to be Exported: No
Intended Deregistration Date: 25 Apr 2019
Vehicle Make: HONDA
Vehicle Model: FIT 1.3G F PACKAGE CVT ABS D/AIRBAG 2WD
Primary Colour: White
Manufacturing Year: 2015
Engine No.: L13B1219561
Chassis No.: GK31119573
Maximum Power Output: 73.0 kW (97 bhp)
Open Market Value: \$14,025.00
Original Registration Date: 24 Jun 2016
First Registration Date: 24 Jun 2016
Transfer Count: 0
Actual ARF Paid: \$9,025.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 23 Jun 2026
PARF Rebate Amount: \$6,768.00

Intended COE Rebate Details

COE Expiry Date: 23 Jun 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$55,200.00
COE Rebate Amount: \$39,541.00
Total Rebate Amount: \$46,309.00

The information contained herein is correct as at 25 Apr 2019

OK



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Address: 1 Defu Lane 6 Singapore 539365

Tel: 6858 5151 Fax: 6858 0877

Our Ref - TP031042019

Date 09.05.2019

Your Ref - SM68393Y

WITHOUT PREJUDICE

Claims Department - Executive in charge

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Dear Sir/Madam,

ACCIDENT INVOLVING SLD6651T / SM68393Y ON 25.04.2019

Refer to the above accident and please acknowledge receipt of this letter within 14 days.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

☐ Original Tax-invoice number - TP0519/001

☐ Merimen Search

☐ Authorization to act

*Survey under insurance instruction - LKK.

| | | |
|--------------|---|-------------------|
| a) | Cost of repair (inclusive GST) | \$2,354.00 |
| b) | Vehicle Search fees | \$2.00 |
| c) | Loss of use | \$240.00 |
| d) | Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe) | \$100.00 |
| Total | | \$2,696.00 |

* Driver's injury and other losses exclude in this claim.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Tan Lim Motor Pte Ltd" within 28 days.

Yours faithfully,

Patricia Tan / Sam Low / Johnson Chua

Email: pt@tlimotor.com.sg / sam@tlimotor.com.sg / johnson.chua@tlimotor.com.sg

Joy Irene (LKKAUTO)

From: Joy Irene (LKKAUTO)
Sent: Friday, 14 June 2019 10:55 AM
To: Kai Si Teo
Cc: Admin A; Vic (LKKAUTO)
Subject: RE: ACCIDENT INVOLVING SMG 8393Y AND SLD 6651T ON 25/04/19

Dear Kai Si,

Thank you for the video.

We have reviewed the matter and based on the scenario at the junction and the traffic light condition, there is no green arrow for us to proceed with our turning. Hence, liability is down against us.

We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Kai Si Teo [mailto:bluesky_1806@hotmail.com]
Sent: Monday, 13 May 2019 11:33 AM
To: Joy Irene (LKKAUTO) <JoyIrene@lkkauto.com>
Subject: Re: ACCIDENT INVOLVING SMG 8393Y AND SLD 6651T ON 25/04/19

Hi joy,

Pls refer to the attached.

Thanks.

Sent from my Samsung Galaxy smartphone.

----- Original message -----

From: "Joy Irene (LKKAUTO)" <JoyIrene@lkkauto.com>

Date: 13/05/2019 11:11 am (GMT+08:00)

To: bluesky_1806@hotmail.com

Cc: Admin A <admin-a@lkkauto.com>

Subject: ACCIDENT INVOLVING SMG 8393Y AND SLD 6651T ON 25/04/19



Our Ref: CC6/AIG19007416/Ujb3

TEO KAI SI

Policy Hoder

Dear Madam,

ACCIDENT INVOLVING SMG 8393Y AND SLD 6651T ON 25/04/19

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you under the Auto Insurance policy taken up with them.

As spoken, kindly send us a copy of your video for our liability assessment.

Thank you.

Please call us if you have further queries.



AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Tan Ji-Sien Jonathan ("the third party claimant")
of Block 451 A Sengkang West way #16-771 Singapore 791451 (address),
owner of SLD 66517 (vehicle no.) hereby authorize
Tan Lim Motor Pte Ltd

("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SLD 66517 that was
damaged pursuant to the accident which occurred on 25/04/2019 (date) along
Junction of Seletar Road and Tio Chu Kang Road (location)
involving vehicle no/s SM G 8393X ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 25 day of April (month) 2019 (year)

"The contents of this document apply to vehicle
damages only. All personal injuries and
damages arising therefrom are excluded from
the ambit and application of this document."

Signed by "the third party claimant"

Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **TAN LIM MOTOR PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$2,354.00** (Repair Cost), **S\$240.00** (Loss of Rental/Use), **S\$ 2.00** (Disbursement), for vehicle no. **SLD 6651T** that was damaged pursuant to the accident which occurred on **25/04/2019** (date) along **SENGKANG WEST ROAD** (location) involving vehicle no/s **SMG 8393Y**. This is pursuant to the inspection conducted on **26/04/2019** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **TAN JI-SIEN JONATHAN** ("the third party claimant") of vehicle no. **SLD 6651T** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SLD 6651T** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 14th (day) of JUNE (month) **2019** (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



TAX-INVOICE
NUMBER: TP0519/001

(Please quote our reference number TP031042019 for payment)

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Tan Ji-Sien, Jonathan

Date: 02/05/2019

Vehicle No: SLD6651T
Model: HONDA FIT 1.3 G

| Description | Amount |
|--|------------|
| To lump sum repair as recommended by surveyor. | \$2,200.00 |
| Reimbursement of LTA search fees. | \$1.87 |

| | |
|--------------|-------------------|
| Sub Total | \$2,201.87 |
| Add 7% GST | \$154.13 |
| Total | \$2,356.00 |


Tan Lim Motor Pte Ltd

No. 1 Defu Lane 6 Singapore 539365
~~No. 51 Defu Lane 10 Singapore 530216~~
Tel : 6858 5151 (24 hours) Fax : 6858 0877
email@tlimotor.com.sg www.tlimotor.com.sg
Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-065062

Date of Request: 25/04/2019

Your Ref No:

Online Purchase

Tan Lim Motor Pte Ltd
1 Defu Lane 6
Singapore 539365

Dear Sir/Madam,

Enquiry Date: 25/04/2019
Enquiry By: Lam Wei Shong
TP Vehicle No: SMG8393Y
Account Date: 25/04/2019

| DESCRIPTION | AMOUNT (S\$) |
|----------------------------------|--------------|
| TP Insurer Enquiry | 1.87 |
| GST Amount | 0.13 |
| Total Amount Due (GST Inclusive) | 2.00 |

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-065062
Date of Request: 25/04/2019

Your Ref No: Online Purchase

Tan Lim Motor Pte Ltd
1 Defu Lane 6
Singapore 539365

Dear Sir/Madam,

Enquiry Date: 25/04/2019
Enquiry By: Lam Wei Shong
TP Vehicle No: SMG8393Y
Account Date: 25/04/2019

Enquiry Result

| TP Vehicle No. | Insurer | Period of Insurance | Insurer Tel. No. |
|----------------|--------------------------------------|-----------------------|------------------|
| SMG8393Y | AIG Asia Pacific Insurance Pte. Ltd. | 31/12/2018-30/12/2020 | 65-6419-3000 |

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane















| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---------------|---|--|--|------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 26 Apr 2019 Edit Reg | | 26 Apr 2019 00:00 Edit Adj Rpt | S\$2,200.00 Edit Estimates | S\$2,200.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|--|------------------------|---|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: | TEO KAI SI, ID: S8117819D | | | | | | | | |
| Main Claimant: | TAN JI-SIEN JONATHAN | | | | | | | | |
| Vehicle Reg. No.: | SLD6651T | Date of Loss: | 25/04/2019 00:00 - :59 [34 Months and 1 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / 2315913816SG | Policy/Cover Note No.: | (Comprehensive) | | | | | | |
| Vehicle Reg. No. (Insured): | SMG8393Y | Policy No. (Claimant): | 5081133276-02 | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6, 539365 Defu Lane - Tel: 6858 5151 | | | | | | | | |
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com | | | | | | | | |
| Claimant's Insurer: | NTUC Income Insurance Co-operative Ltd (HQ) - Tel: | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 08/05/2019] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| <ul style="list-style-type: none"> AIG_SG (29/04/2019): Request To Upload TP GIA Report | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SLD6651T (2315913816SG)
[SMG8393Y]
TP
TAN JI-SIEN JONATHAN
Apr 25 2019 12:00AM
[TEO KAI SI]
Tan Lim Motor Pte Ltd

| | | | | | | | | | | | | | | | | | | |
|-------------------------|-----------------|--|--|--|--|--------------------|--|--|--------------|--|--|--------------|-----------|--|--|--|-------------------------------------|--|
| Upload Documents | | | Upload Photos | | | Compose New Letter | | | Upload Video | | | Upload Audio | | | View | | View in Browser | |
| Video | | | | | | | | | | | | | | | 1 per page | | <input checked="" type="checkbox"/> | |
| No | Finalized On | | LKK Auto Consultants Pte Ltd (HQ) | | | | | | | | | | Thumbnail | | Print | | | |
| 1 | 14/06/19 10:56 | | FROM INSURED - NO GREEN ARROW | | | | | | | | | | | | Load MP4 | | | |
| | | | | | | | | | | | | | | | | | | |
| Letters/Correspondences | | | | | | | | | | | | | | | 1 per page | | <input checked="" type="checkbox"/> | |
| No | Finalized On | | LKK Auto Consultants Pte Ltd (HQ) | | | | | | | | | | Thumbnail | | Print | | | |
| 1 | (Draft) | | Third Party Express Settlement – Payment Breakdown | | | | | | | | | | | | Edit | | | |
| | | | | | | | | | | | | | | | | | | |
| Photos/Images | | | | | | | | | | | | | | | 3 per page | | <input checked="" type="checkbox"/> | |
| No | Relabel/Reorder | | LKK Auto Consultants Pte Ltd (HQ) | | | | | | | | | | Thumbnail | | Print | | | |
| 1 | 26/04/19 18:10 | | Chassis Number | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 2 | 26/04/19 18:10 | | Odometer Reading | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 3 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 4 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 5 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 6 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 7 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 8 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 9 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 10 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 11 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 12 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 13 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 14 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 15 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 16 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 17 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 18 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 19 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 20 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 21 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 22 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 23 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 24 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 25 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 26 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 27 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 28 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 29 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |
| 30 | 26/04/19 18:11 | | General View | | | | | | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | |

| Video | | | 1 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|---|--|-------------------------------------|
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 31 | 26/04/19 18:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 32 | 26/04/19 18:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 33 | 26/04/19 18:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 34 | 26/04/19 18:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 35 | 26/04/19 18:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 26/04/19 18:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 26/04/19 18:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 26/04/19 18:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 26/04/19 18:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 26/04/19 18:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 29/04/19 19:04 | TP ESTIMATE- MARKED |  Load PDF | |
| 2 | 02/05/19 10:58 | TP GIA REPORT |  Load PDF | |
| 3 | 14/06/19 10:57 | LETTER TO INSURED- |  Load PDF | |
| 4 | 27/06/19 10:21 | WORKSHOP INVOICE |  Load PDF | |
| 5 | 27/06/19 10:21 | AUTHORISATION TO ACT FORM |  Load PDF | |
| 6 | 27/06/19 10:21 | Release Voucher |  Load PDF | |
| 7 | 27/06/19 10:21 | GIA SEARCH |  Load PDF | |
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail | Print |
| 1 | 29/04/19 10:44 | OI GIA REPORT |  Load PDF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

| | | | |
|-------------------|---------------------|--------|-----------------|
| Vehicle No: | SMG8393Y (Insd veh) | Model: | HONDA FIT 1.3 G |
| | SLD6651T (TP veh) | | F-PACKAGE (A) |
| Date of Accident: | 25/04/2019 | | |

| | | | | |
|-----------------------|---|------------------------------|--|------------------------------|
| Global Sum Settlement | : | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No | |
| Repair Estimate | : | \$ | 4,738.30 | |
| Final Repair Cost | : | \$ | 2,354.00 | |
| Loss of Use | : | \$ | 240.00 | 4.00 days at \$60.00 per day |
| Rental (if any) | : | \$ | 0.00 | days |
| LTA / GIA Search Fee | : | \$ | 2.00 | |
| Others: | : | \$ | 0.00 | |
| | : | \$ | | |
| Final Settlement Sum | : | \$ | 2,596.00 | |

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

| Payment Instruction: Payee's Breakdown | | | |
|--|-----------------------|---|-------------|
| 1) | Tan Lim Motor Pte Ltd | : | \$ 2,596.00 |
| 2) | | : | \$ |
| 3) | | : | \$ |

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

27 Jun
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19007416/UHB3Q2

Date: 27/06/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLD6651T

Insured Vehicle No : SMG8393Y

Date of Loss: 25/04/2019

Nature of Claim: TP

Claim No: 2315913816SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLD6651T

Make & Model: HONDA FIT, 1.3 G F-Package (A)

Engine No: L13B1219561

Reg. Date: 24/06/2016 (Man. Year: 2015)

Chassis No: GK31119573

Colour: White

Odometer: 49698 km

Engine Capacity: 1317 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R16

Rear Tyre Size: 205/50 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-----------------|-----------------|-----------------|--------------|
| Parts | 3,098.32 | 2,052.64 | 1,045.68 | 33.75 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,330.00 | 720.00 | 610.00 | 45.86 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 4,428.32 | 2,772.64 | 1,655.68 | 37.39 |
| Approved Total (Overridden) (S\$) | | 2,200.00 | | |
| (S\$) | 4,428.32 | 2,200.00 | 2,228.32 | 50.32 |
| + GST 7.00/7.00% (S\$) | 309.98 | 154.00 | 155.98 | 50.32 |
| Nett Amount (S\$) | 4,738.30 | 2,354.00 | 2,384.30 | 50.32 |
| + Loss of Use (4.0 x S\$60.00/day) (S\$) | | 240.00 | | |
| + Doc/Search Fee (S\$) | | 2.00 | | |
| Nett Liability (S\$) | | 2,596.00 | | |

INSPECTION

Date of Assignment: 26/04/2019

Date Inspected: 26/04/2019 Inspected At:

Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------|-------------|------------|
| 1 | 1 | | *FRONT BUMPER | Distorted | 532.70 FL | *532.70 FL |
| 2 | 1 | | *FRONT BUMPER SIDE RETAINER LEFT | Not Necessary | 29.50 FL | *- FL |
| 3 | 8 | | *FRONT BUMPER CLIPS | Necessary | 36.00 FL | *36.00 FL |
| 4 | 1 | | *FRONT BUMPER LAMP LEFT | Scratched | 281.80 FL | *281.80 FL |
| 5 | 1 | | *FRONT BUMPER FOG LAMP HOLDER LEFT | Not Necessary | 25.80 FL | *- FL |
| 6 | 1 | | *FRONT BUMPER FOG LAMP GARNISH LEFT | Grazed | 65.80 FL | *65.80 FL |
| 7 | 1 | | *FRONT BUMPER REINFORCEMENT | Not Necessary | 203.30 FL | *- FL |
| 8 | 1 | | *LEFT HEADLAMP | Scratched | 649.50 FL | *649.50 FL |
| 9 | 1 | | *LEFT HEADLAMP LOWER BRACKET | Not Necessary | 21.90 FL | *- FL |
| 10 | 1 | | *FRONT FENDER LEFT | Repair | 455.10 FL | *- FL |
| 11 | 1 | | *FRONT FENDER INNER COWLING LEFT | Not Necessary | 71.50 FL | *- FL |
| 12 | 1 | | *FRONT BUMPER LOWER SPOILER -ACCESSORY | Cut | 1,200.00 FS | *800.00 FS |

F=Franchise part, S=SpcNett, L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (S\$) | 3,572.90 | 2,365.80 |
| - List Item Discount on L Items 20.00/20.00% (S\$) | 474.58 | 313.16 |
| Total Parts (S\$) | 3,098.32 | 2,052.64 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | TO CHECK ELECTRICAL LIGHTING CONCERNED | New | 50.00 | 20.00 |
| 2 | TO RUST-PROOFING OF THE AFFECTED AREAS | New | 80.00 | 0.00 |
| 3 | PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME | New | 600.00 | 300.00 |
| 4 | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION | New | 600.00 | 400.00 |
| Gross Labour Cost (\$\$) | | | 1,330.00 | 720.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >