


ASS. REC. BY: _____ REF: CS3/FWD18009570/Gvd31²⁷
 Subject: QD ASSIGNMENT (Office)
 From (Person): Josey Toh at FWD Date/Time: 24/04/2019
 Estimated Cost: _____ Bill to: _____
 OD TP WS TP RES OD RES EVA INV MV CS
 To Inspect Vehicle No: SLP 3379L Insured: SJH 1289S
 at Workshop no: Cadre Automobile Tel: 6747 7618
 of No. 1, Kaki Bukit Ave 6 #02-49
 Policy No: _____ Claim No: 1201800006319
 Sum Insured: _____ Excess: _____
 Make of Veh: _____ D.O.A. 20/05/2018
 (Client's Record)
 CA / REV / REP. / REV 24 HRS (wp)
 Date/Time: 25/5/18 5:08pm Person Contacted: Mr. Chen H.O.D. Endorsement: _____
 Vehicle: INV/DUT

Date/Time	Action/Instruction (X) Estimate
	SLP 3379L - X
	SJH 1289S - X
30/5/18	SI manifested
11/6/19	\$4800, 6 Days. (Red 13,200, 73%) Submit LS

RECEIVED 1 JUN 2019


 11/6/2019

PKS
Xml.

REF: FWD

52954

ASSIGNMENT

2009

From: _____ Date: 28/5/18

Estimated Cost: _____

OO WS / TP RES / OO RES / EVA / INV / MV

To inspect Vehicle No: SLP 3379L

at Workshop no: Cadre Automobile

at 1 Kaki Bukit Ave 6 # 02-19 Autobay

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SLP3379L Vt Regn: 07 Aug 2009

Type: M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Audi A5 2.0 cc 1984

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 92369 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZ8T3AA000965

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Mod: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 245/40R18
R: 11

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front		Rear	
R/Bal	6 mm	R/Bal	6 mm
L/Bal	6 mm	L/Bal	6 mm
D.O.A		D.O.I	28-05-18

Survey held at: w/s 3:15pm

Des. of Damages: Frt / Rear / O/S / N/S UIC / Rooftop or _____

The Chassis frame / Body Structure affected due to collision.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? Yes or No

GIA / PR Seen: _____ Consistent? Yes or No

Est. Repairs: _____ days Res: Yes or No

Lump Sum: _____ % 3 Val. Yes or No

CA / REV / REP. / 24 HRS (up)

Date: _____ Person Contacted: _____ Vehicle IN / OUT

Date / Time Action / Instruction

* Repair Estimate: S\$ 12,500 - 13,500

* 4 days

31/5/18 submit PKS Report.

RECEIVED 1 JUN 2018

Copy/Time File Pass to: Prel. Report Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Add Fee: Site Insp: \$ Inton: \$ Tech: \$ Other: \$

Report Format: _____

Lump Sum / I.B.: \$ _____

Nivitha (LKK Auto)

From: josey.loh@fwd.com
Sent: Wednesday, 24 April 2019 3:32 PM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Cc: motorclaims.sg@fwd.com
Subject: [Paper Survey] Accident Involving SJH1289S & SLP3379L On 22.05.2018 (FWD Ref: 1201800006319)
Attachments: 20190424152155828.pdf

Hi LKK team,

Please conduct a paper resurvey on an urgent basis.

Kindly let us have the paper resurvey report soonest possible via email.

Thank you.

Kind Regards
Josey Loh
Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872
E josey.loh@fwd.com
W fwd.com.sg

FWD
insurance



ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

MC-COY

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Report Reference : TP / 18043-05/MY / 2018
Date of Report : 14 Mar 2019

Lim Kian Heng
c/o No.1 Kaki Bukit Ave 6
#02-49 AutoBay @ Kaki Bukit
Singapore 417883

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 22 May 2018

Workshop Address : Cadre Automobile
No.1 Kaki Bukit Ave 6
#02-49 AutoBay @ Kaki Bukit
Singapore 417883

As per your instruction dated **28 May 2018** with regard to the above matter. We have carried out a physical inspection on the said vehicle **SLP 3379 L**. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No	: SLP 3379 L	Engine No	: CDN049005
Model	: Audi A5	Mileage	: 92369
Year / Capacity	: 2009/1984	Colour	: Black
Chassis No	: WAUZZZ8T3AA000969		

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT O/S	: 245/40 R18	Continental	6.00	mm	Sport
REAR O/S	: 245/40 R18	Continental	6.00	mm	Sport
FRONT N/S	: 245/40 R18	Continental	6.00	mm	Sport
REAR N/S	: 245/40 R18	Continental	6.00	mm	Sport

MC-COY

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417983
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear n/s and undercarriage portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 8 working days to complete.

5. Enclosed number of photograph : 98 copies.

6. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a "**Without Prejudice**" basis. We hope that this report will be of assistance to you in dealing with the matter.

7. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SLP 3379 L
 Report No: TP/ 18043-05/MY / 2018

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Front door	Repair	\$ 1408.00	\$
1	Front door lock	Intact	\$ 446.00	\$
1	Front door rubber	Intact	\$ 189.00	\$
1	Rear windscreen seal	Damage	\$ 160.00	\$ X 160.00 NA
1	Rear taillamp	Intact	\$ 894.00	\$
1	Rear bumper	Damage	\$ 120.00	\$ 120.00 ✓
1	Rear bumper lower skirting	Intact	\$ 587.00	\$
1	Rear bumper side retainer	Damage	\$ 148.00	\$ 148.00 ✓
1	Rear fender	Damage	\$ 1474.00	\$ X 1474.00 Repair
1	Rear fender inner garnish	Intact	\$ 753.30	\$
1	Rear fender inner shield	Damage	\$ 182.00	\$ 182.00 ✓
1	Rear wheel hub with bearing	Damage	\$ 326.00	\$ 326.00 ✓
1	Rear shock absorber	Damage	\$ 1224.31	\$ 1224.31 ✓
1	Rear knuckle arm	Damage	\$ 1011.11	\$ 1011.11 ✓
1	Rear lower arm	Damage	\$ 776.10	\$ 776.10 ✓
1	Rear trailing arm	Damage	\$ 508.48	\$ X 508.48 ✓
1	Rear sub crossmember	Damage	\$ 4014.29	\$ X 4014.29 ✓
1	Rear stabilizer bar	Damage	\$ 354.06	\$ 354.06 ✓
1	Rear n/s drive shaft	Intact	\$ 1687.64	\$
1	Rear differential unit	Damage	\$ 12501.73	\$ X 12501.73 NA
			\$ 28765.02	\$ 22800.08
	Discount	5.0%	\$ 1438.25	\$ 1140.00
			\$ 27326.77	\$ 21660.08
<u>Special Nett Items</u>				
1	Rear windscreen sealant	Necessary	\$ 80.00	\$ NA X 60.00
1	Rear bumper reverse sensor	Intact	\$ 286.00	\$
1	Rear fender quarter glass sealant	Necessary	\$ 60.00	\$ NA X 40.00
1	Rear tyre (Depreciation)	Damage	\$ 650.00	\$ 325.00 150
1	Rear sport rim	Damage	\$ 800.00	\$ 600.00 ✓
			\$ 1876.00	\$ 1025.00 750
Spare Parts Total			\$ 29202.77	\$ 22685.08

Vehicle No: SLP 3379 L
 Report No: TP/ 18043-05/MY / 2018

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 29202.77	\$ 22685.08
1	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 60.00	\$ 40.00 30
2	To remove and refit rear cushion seats, radio speaker board, interior upholstery to facilitate the repairs.	\$ 250.00	\$ 180.00 60
3	To remove and refit rear bumper sensor.	\$ 180.00	\$ 140.00 40
4	To remove and refit rear undercarriage.	\$ 800.00	\$ 550.00 250
5	To check and re-adjust (Computerized) all wheel alignment.	\$ 160.00	\$ 120.00 60
6	To remove and refit rear windscreen glass.	\$ 210.00	\$ 160.00 X NN
7	To remove and refit quarter glass to facilitate the repairs.	\$ 100.00	\$ 60.00 X NN
8	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 900.00	\$ 750.00 500
9	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1000.00	\$ 800.00 400
			1340
	Total	\$ 32862.77	\$ 25485.08

6024.5
 20% = 4800

Vehicle No: SLP 3379 L
Report No: TP/ 18043-05/MY / 2018

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
Total c/f		\$ 32862.77	\$ 25485.08

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of: \$ 18000.00

SDLS: EIGHTEEN THOUSAND ONLY



Qualified Appraiser



redefining insurance

ALLIANCE
123456789
123456789
123456789
123456789
123456789

Certificate of Insurance

123456789
123456789

THIS CERTIFICATE OF INSURANCE IS A SUMMARY OF THE POLICY TERMS AND CONDITIONS. FOR THE COMPLETE POLICY TERMS AND CONDITIONS, PLEASE REFER TO THE POLICY CONTRACT.

Policy details

Policyholder Name	123456789	Company Name	123456789
Address	123456789	City/State	123456789
Effective Date	12/31/2023	Expiration Date	12/31/2024
Policy Number	123456789	Class Code	123456789

Persons or classes of persons entitled to drive*

1. 123456789
 2. 123456789
 3. 123456789

Limitations on use*

1. 123456789
 2. 123456789
 3. 123456789
 4. 123456789

CLASS	123456789	123456789
-------	-----------	-----------

- 1. 123456789
- 2. 123456789
- 3. 123456789
- 4. 123456789

Additional classes & endorsements to your policy

1. 123456789
 2. 123456789

123456789

123456789

Important note

1. 123456789
 2. 123456789
 3. 123456789

123456789
 123456789
 123456789

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 5295H

Vehicle Details

Vehicle No.:	SLP3379L
Vehicle to be Exported:	Yes
Intended Deregistration Date:	10 Apr 2019
Vehicle Make:	AUDI
Vehicle Model:	A5 2.0L TFSI QUATTRO
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	CDND49005
Chassis No.:	WAUZZZ8T3AA000969
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$48,698.00
Original Registration Date:	07 Aug 2009
First Registration Date:	07 Aug 2009
Transfer Count:	1
Actual ARF Paid:	\$48,698.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Aug 2019
PARF Rebate Amount:	\$24,349.00
Intended COE Rebate Details	
COE Expiry Date:	06 Aug 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$16,801.00
COE Rebate Amount:	\$541.00
Total Rebate Amount:	\$24,890.00

The information contained herein is correct as at 10 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/05/2018 14:24
Date Of Accident	22/05/2018 19:40
Exact Location Of Accident	GUILLEMARD ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJH1289S
Insured/Policyholder	
Name Of Registered Owner	HAN SIEW FONG
NRIC No	S2737190F
Email Address	CHICANE58@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97611848
Alternative Phone No	OFFICE-97611848

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS-1.5 E (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2017-00004770
Cover Note Number	

Driver

Name of Driver	HAN SIEW FONG
NRIC No	S2737190F
Date Of Birth	06/12/1967
Occupation	INDOOR
Date Of Driving Pass	25/07/2007
Driving Experience	10 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97611848
Fax Number	
Contact Number	OFFICE-97611848
EEmail Address	CHICANE58@GMAIL.COM

Address	80 DAKOTA CRESCENT #13-19
Postcode	399946
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : CONNIE GENDER: : FEMALE
Passenger 2	NAME: : CARA SIM GENDER: : FEMALE
Passenger 3	NAME: : CARISSA SIM GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

STATEMENT RECORDED BY SOO - PROGRESSIVE AUTOMOTIVE PTE LTD (6741 5336)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP3379L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Rewards Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claim, including the settlement of the claim, and any necessary investigation relating to the claim;
 - (ii) investigating the accident and/or my claim;
 - (iii) my work and/or dealing with my insurance or responding to any enquiries by me;
 - (iv) administering my claim (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me, to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or;
 - (v) complying with applicable law or administering, processing, handling and/or dealing with my claim collectively the "Purposes".
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may can be disclosed by any of the insurers and/or GIA to their third party service providers or agents including their lawyers/law firms, which may be used outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected (under (b) above) may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud;
 - (ii) regulators, law enforcement and government agencies as reasonably required for the purposes stated; and
 - (iii) for complying with requirements under any regulatory laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

After check oncoming vehicle was cleared so i proceeded to move out. Out of sudden, a vch B from numbers side swipe onto my front left portion while i'm almost finish my proceed way.

DECLARATION

I/We declare the foregoing particulars are true in every respect. Please be advised that your insurer may have a 14 day clause whereby the claim against own policy must be made within the stipulated timeframe from the date of occurrence. Kindly check your policy for more details.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No:



CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2017-00004770 (Comprehensive - Classic Plan)

Car plate number: SJH12895

Your name (As the policyholder): Han Siew Fong

Coverage start date: 12/06/2017

Coverage end date: 27/07/2018

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

- (a) You, and
- (b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 07/06/2017



Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please immediately inform us at +65-6322-2072
or email us at connect.sg@fwd.com if any details
in this Certificate of Insurance need to be changed.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S2737190F



Name

HAN SIEW FONG

李秀芳

Race

CHINESE

Date of birth

08-12-1967

Sex

F

S2737190F



Country/Place of birth

MALAYSIA

REPUBLIC OF SINGAPORE DRIVING LICENCE



S2737190F

HAN SIEW FONG

Exp. Date 06 Dec 1967

Issue Date 13 Aug 2007



001635809G

5320344



NRIC No S2737190F



Date of issue

23-06-2014

Address

80 DAKOTA CRESCENT
#13-12
SINGAPORE 399946

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 2B	Motorcycles <= 200 cc	25 Jul 2007
Class 3	Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg	25 Jul 2007



License No: S2737190F

NP 426A

Accident Photo



Accident Photo



Accident Photo



TOYOTA MOTOR CORPORATION
MODEL NCP93R-BEPRKT
ENGINE 1NZ-FE 1497 mL
FRAME No. MR053HY9305072839
COLOR TRIM PLANT GVM(kg)
1D4 FE10 Z35 -
TMA/BUILT U340E -02A JUL 08
MFD.BY: TOYOTA MOTOR THAILAND CO.,LTD. MADE IN THAILAND

Accident Photo





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FWD SINGAPORE PTE LTD		Ref : CS3/FWD18009570/Gvd3e2-1	
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4SINGAPORE 038986		Date : 17-06-2019	
		Code : FWD	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJH 1289S	Veh. Inspected	SLP 3379L
Policy No.		Coverage (\$)	0.00
Claim No.	1201800006319	Excess (\$)	0.00
Assign From	JOSEY LOH	Assign Date	24/04/2019
2. Vehicle Particulars & Condition			
Make & Model	AUDI A5 2.0	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	WAUZZZ8T3AA000969	Colour	BLACK
Odometer	92369	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/40 R18	CONTINENTAL	6 mm
L/H Front Tyre	245/40 R18	CONTINENTAL	6 mm
R/H Rear Tyre	245/40 R18	CONTINENTAL	6 mm
L/H Rear Tyre	245/40 R18	CONTINENTAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	22/05/2019	Inspection Date	28/05/2018
Survey held at	CADRE AUTOMOBILE 1 KAKI BUKIT AVE 6 #02-49 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 3379L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR	TO REPAIR SEE LABOUR	1,408.00	-
1	FRONT DOOR LOCK	INTACT	446.00	-
1	FRONT DOOR RUBBER	INTACT	189.00	-
1	REAR WINDSCREEN SEAL	NOT NECESSARY	160.00	-
1	REAR TAILLAMP	INTACT	894.00	-
1	REAR BUMPER	DAMAGED	120.00	120.00
1	REAR BUMPER LOWER SKIRTING	INTACT	587.00	-
1	REAR BUMPER SIDE RETAINER	DAMAGED	148.00	148.00
1	REAR FENDER	TO REPAIR SEE LABOUR	1,474.00	-
1	REAR FENDER INNER GARNISH	INTACT	753.30	-
1	REAR FENDER INNER SHIELD	DAMAGED	182.00	182.00
1	REAR WHEEL HUB WITH BEARING	DAMAGED	326.00	326.00
1	REAR SHOCK ABSORBER	DAMAGED	1,224.31	1,224.31
1	REAR KNUCKLE ARM	DAMAGED	1,011.11	1,011.11
1	REAR LOWER ARM	DAMAGED	776.10	776.10
1	REAR TRAILING ARM	NOT NECESSARY	508.48	-
1	REAR SUB CROSSMEMBER	NOT NECESSARY	4,014.29	-
1	REAR STABILIZER BAR	DAMAGED	354.06	354.06
1	REAR N/S DRIVE SHAFT	INTACT	1,687.64	-
1	REAR DIFFERENTIAL UNIT	NOT NECESSARY	12,501.73	-
	LESS 5% DISCOUNT		-1,438.25	-207.08
			27,326.77	3,934.50
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR BUMPER REVERSE SENSOR (SN)	INTACT	286.00	-
1	REAR FENDER QUARTER GLASS SEALANT (SN)	NOT NECESSARY	60.00	-
1	REAR TYRE (SN)	DAMAGED	650.00	150.00
1	REAR SPORT RIM (SN)	DAMAGED	800.00	600.00
			1,876.00	750.00

Report Ref No. CS3/FWD18009570/Gvd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607196-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE AND REFIT REAR ELECTRICAL WIRING, REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING.		60.00	30.00
	TO REMOVE AND REFIT REAR CUSHION SEATS, RADIO SPEAKER BOARD, INTERIOR UPHOLSTERY TO FACILITATE THE REPAIRS.		250.00	60.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		180.00	40.00
	TO REMOVE AND REFIT REAR UNDERCARRIAGE.		800.00	250.00
	TO CHECK AND RE-ADJUST (COMPUTERIZED) ALL WHEEL ALIGNMENT.		160.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	210.00	-
	TO REMOVE AND REFIT QUARTER GLASS TO FACILITATE THE REPAIRS.	NOT NECESSARY	100.00	-
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF FRONT DOOR AND REAR FENDER.		900.00	500.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		1,000.00	400.00
			3,660.00	1,340.00
	GRAND TOTAL		32,862.77	6,024.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,800.00

Report Ref No. CS3/FWD18009570/Gvd3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.