

ASS. REC. BY:

REF: CS/CT1 19007423/ Jg dz ^{e2}

Special Instruction:

MWH/NN

Survivor: Hwee He **ASSIGNMENT (Office)**From (Person): Elaine Cheong of CT1 Date/Time: 25.4.19 17:58 p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: GBD 52029 Insured: _____at Workshop m/s Graffiti Garage Tel: 96664445of 39 Woodland close #04-01/02Policy No: DMC VSN3069651800 Claim No: SNM19D201700Sum Insured: _____ Excess: \$450.00Make of Veh: _____ D.O.A. 13.4.2019(Client's Record) 29.4.19 (After lunch)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: _____

Date/Time: 26.4.19 5.08 p.m Person Contacted: _____ Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	GBD 52029 - NSI INC 16015234 / H/V bn 2 P.O.A - 14/03/2016
02/5/19 @ 2.44pm	revert to Elaine Cheong via messenger.
03/5/19 @ 11.10am	Elaine Cheong informed C/A via messenger.
03/5/19 @ 11.36am	Informed Daniel C/A DEX: \$450 by email.
29/5/19 @ 2.49pm	Confirmed with Daniel Ruel fig 84543, 5 days. (CRD 65127, 53%)

Surveyor: Hume Jk

REF: CTI

ASSIGNMENT

From: _____ Date: 30/4/19

Estimated Cost: _____

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBD 5202G
at Workshop m/s Graffiti Garage
of 39 woodlands close # 04-01 / 02

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: \$450.00

(Client's Record)

Make of Veh: Daniel @ 9666 4445

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBD 5202 G Yr Regn: 28 Apr 2008

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Land Rover C.C. Motor

Colour: Black A/C: Insured / Std / NI / NA

Sp.Reading: 181362 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SALLDVAS78A758468

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/70R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 13/4/19 D.O.I. 30/4/19

Survey held at

Graffiti

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Pending log card.</u>
	<u>63,000</u>
	<u>MV - \$6000</u>
	<u>PV - \$14966</u>
	<u>NV - \$52034</u>
	<u>4834</u>
	<u>Waiting to take after repair before to proceed finalize</u>

RECEIVED 30 JUL 2019

Date/Time, File Pass to? ☐ : Preli. Report

11/7/19 ☐ : Final Report

Date/Time, File Return to? _____

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee: 220

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

220

Report Format: NER-OD

Lump Sum / I.B.I: (\$ 4543)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Apr 2019		25 Apr 2019 17:58 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS				
Insured:		SNIPE, Co. Reg. No.: 53123990W		[Created by insurer]
Vehicle Reg. No.:		GBD5202G	Date of Loss:	13/04/2019 22:00 - :59
Claim Type:		OD / SNM19D201700	Policy/Cover Note No.:	DMCVSN3069651800 (Comprehensive) Coverage: 29/10/2018 - 28/10/2019
		Excess:	S\$450.00	
Repairer:		Graffiti Garage Sg Pte Ltd (HQ) 39 WOODLANDS CLOSE, MEGA @WOODLANDS, #04-01/02, 737856 Woodlands - Tel:		
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/05/2019]		
Adj Asg. Remarks:		Please survey Insured vehicle & let us have your findings Excess \$450.00 applicable (NO waiver)		
ASSOCIATED MAIL RECEIVED				
				View All
Compose Case Mail				
There are no mail for this case.				
<input type="checkbox"/>				
ALL ASSOCIATED TASKS				
		View All	Search Tasks	Create New Task
Due Date	Priority	Type	Task Group	Subject
			Handler	Assigned By
			Completed On	Created On
				Done?
No results.				

Nivitha (LKK Auto)

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent: Thursday, 25 April 2019 3:35 PM
To: danielwee444@gmail.com; assignments@lkkauto.com; SUR; Billy Magendran
Cc: Elaine Cheong; Alfred Toh; Chee So Chow; Angie Foo; 'Charlie Koh'; Eddie Sim
Subject: Quotation for repairing of GBD5202G - SNM19D201700
Attachments: Land Rover.pdf

M/s LKK Auto Consultants Pte Ltd

We refer to the above matter.

Please assist to conduct survey on Insured vehicle (OD claim) at M/s Graffiti Garage SG Pte Ltd and let us have your findings for our next course of action.

Merimen folder shall be created shortly.

Best Regards

Alfred Toh
Senior Executive
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID : (65) 6389 6183
FAX: (65) 6224 7478

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: daniel wee [mailto:danielwee444@gmail.com]
Sent: Wednesday, 24 April 2019 2:51 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: billy@snipemedia.com.sg
Subject: Quotation for repairing of GBD5202G

Dear all,

Attachment is the quotation for the repairing of Land Rover GBD5202G.

Feel free to contact me if there is any query.

Thank you and have a nice day ahead.

Daniel Wee
Graffiti Garage SG Pte Ltd
HP: +65 9666 4445

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 3 May 2019 11:36 AM
To: danielwee444@gmail.com
Cc: SUR
Subject: OD VEHICLE GBD 5202G (DOA: 13/04/2019)

Dear Daniel,

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle **GBD 5202G (Excess \$450/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	25 Apr 2019 17:27	Clim Veh Model Changed	(205340) LAND ROVER DEFENDER 90 2.4 D L (M).		[I] Alfred Toh
2	25 Apr 2019 17:27	Clim Created	Reg No: GBD5202G, Policy No: DMCVSN3069651800, Acct Date: 2019/04/13, Claim Type: OD, Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ), Workshop: Graffiti Garage Sg Pte Ltd (HQ), Ins.Status => Incoming Claim		[I] Alfred Toh
3	25 Apr 2019 17:58	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please survey Insured vehicle & let us have your findings Excess \$450.00 applicable (NO waiver)		[I] Alfred Toh
4	25 Apr 2019 17:58	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/05/07		[I] Alfred Toh
5	25 Apr 2019 17:58	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.		[I] Alfred Toh
6	26 Apr 2019 08:47	Assignment 1st Accessed			[A] LEE SUTHING
7	26 Apr 2019 17:46	Adj Adjuster Assigned	[None] -> XING GUO QIANG		[A] Nivitha Govindasamy
8	02 May 2019 09:27	Adj Adjuster Assigned	XING GUO QIANG -> ONG HWEE JIE		[A] Nivitha Govindasamy
9	02 May 2019 13:49	Adj Rpt Initiated			[A] SHIAU CHAN
10	02 May 2019 13:49	Clim Dtl Modified	Circumstances of Loss: -> 17.		[A] SHIAU CHAN
11	02 May 2019 13:49	Clim Dtl Modified	JPJ Reg. Date: -> 2008/04/28.		[A] SHIAU CHAN
12	02 May 2019 13:49	Clim Details Notified			[A] SHIAU CHAN
13	02 May 2019 14:43	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/05/07		[A] SHIAU CHAN
14	02 May 2019 14:44	Adj Mandate Request	Cur.Req:4543.00:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. ACCORDING TO THE REPAIRER, THE VEHICLE REPAIR ON PART BY PART BASIS DUE TO NO 2ND HAND PARTS AVAILABLE. WE HAVE NOT AUTHORISE REPAIR.		[A] SHIAU CHAN
15	03 May 2019 11:10	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/05/07		[I] Elaine Cheong
16	03 May 2019 11:10	Adj Mandate Set	Approved:4543.00.		[I] Elaine Cheong

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2133682	02/05/2019 13:49	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBD5202G		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Cheong

Date: 02 May 2019

Preliminary Advice

Vehicle No	: GBD5202G	Accident Date	: 13/04/2019
Make	: LAND ROVER DEFENDER 90	Policy No.	: DMCVSN3069651800
Assignment Date	: 25/04/2019	Excess	: S\$450.00
Date of Inspection	: 30/04/2019	Est. Duration of Repair	: 5.00
Inspection At	: GRAFFITI GARAGE SG PTE LTD (HQ) 39 WOODLANDS CLOSE, MEGA @WOODLANDS, #04-01/02 SINGAPORE 737856		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,670.00
Revised Amount	:S\$	4,543.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,543.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	63,000.00
COE / PARF Rebate	:S\$	14,966.00
Salvage Value	:S\$	
Margin for Repair	:S\$	48,034.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : ACCORDING TO THE REPAIRER, THE VEHICLE REPAIR ON PART BY PART BASIS DUE TO NO 2ND HAND PARTS AVAILABLE.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	9126L
Vehicle Details	
Vehicle No.:	GBD5202G
Vehicle to be Exported:	No
Intended Deregistration Date:	02 May 2019
Vehicle Make:	LAND ROVER
Vehicle Model:	DEFENDER 90 2.4L PUMA
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	080219180924244DT
Chassis No.:	SALLDVAS78A758468
Maximum Power Output:	-
Open Market Value:	\$40,750.00
Original Registration Date:	28 Apr 2008
First Registration Date:	28 Apr 2008
Transfer Count:	3
Actual ARF Paid:	\$2,038.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Apr 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$18,773.00
COE Rebate Amount:	\$14,966.00
Total Rebate Amount:	\$14,966.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 02 May 2019

OK

Lyft beats Uber in race to

Land Rover Defender

Price Range ▼

Depreciation ▼

> 10 year(▼

Vehicle Type ▼

Advanced
Search

Home » Used Cars » Bavarian Marques Pte Ltd » Land Rover Defender 90 (COE till 04/2023)

Land Rover Defender 90 (COE till 04/2023)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

PREMIUM AD



Price	\$70,000	Lifespan	27-Apr-2028
Depreciation ⓘ	\$17,550 /yr	Reg Date	28-Apr-2008 (3yrs 11mths 25days COE left)
Mileage	N.A.	Manufactured ⓘ	2008
Road Tax ⓘ	N.A.	Transmission	Manual
Dereg Value ⓘ	\$14,977 as of today (change)	OMV ⓘ	\$40,750
COE ⓘ	\$18,773	ARF ⓘ	\$2,038
Engine Cap	2,402 cc	No. of Owners ⓘ	4
Curb Weight ⓘ	1,740 kg		
Type of Vehicle	Truck		



Location Map

Shortlist

Compare

Add note

Report Error

More Actions

Features

2.4L 4 Cylinder PUMA Engine From The Acclaimed Ford Duratorq Line Designed For Improved Lubrication On Wet/Dusty Condition At Extreme Angles. View specs of the Land Rover Defender

Accessories

Iron Man Suspension, Loads Of Safari Equip Parts, Original 2 DIN Centre Console, Strut Bars, Upgraded Intercooler, Snorkel And Much More To List.

Description

Rare And Only Defender PUMA In The Market. Exceptional Upkeep, Maintained Very Timely With Only Original And Upgraded Imported Parts. This Monster Boasts A 122Bhp Turbocharged Engine With 300Nm Of Torque On A 6 Speed Gearbox. This Is The Last TD5 Engine To Be Built In-House At Solihull. Owned By A True Enthusiast, Selling To Make Way For Another Ride. View It Once And You Will Buy It. Call Us Now!

Category

COE Car, Premium Ad Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Seller Information

Company	Bavarian Marques Pte Ltd » dealer's pricelist » 27 vehs sold 77 vehs available	
Address	39 Woodlands Close #03-01/22 Search cars nearby this location	
Location	Mega@Woodlands	
Website	www.bavarianmarques.com.sg	
Office No	67178811	
Contact Person(s)	Jeremiah Shawn Eugene Qai	98807671 88188544 81333924 88148478

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/04/2019 12:48
Date Of Accident	13/04/2019 22:15
Exact Location Of Accident	BUKIT INDAH FROM WOODLANDS CAUSEWAY
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD5202G
Insured/Policyholder	
Name Of Registered Owner	SNIP FOCUS AV
Co Reg No	5312300W 53379270C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-92788319

Vehicle Particulars

Manufacturer	LAND ROVER
Model	DEFENDER 90 2.4L PUMA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3069651800
Cover Note Number	29/10/18-27/10/19

Driver

Name of Driver	MAGENDRAN S/O GNANSEGARAN
NRIC No	S8527917C
Date Of Birth	12/09/1985
Occupation	INDOOR
Date Of Driving Pass	25/01/2006
Driving Experience	13 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92788319
Fax Number	
Contact Number	
Email Address	BILLY@SNIPEDIA.COM.SG

Address	BLK 236 BT PANJANG RING RD #04-39
Postcode	670236
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	JTF1964 (COMMERCIAL VEHICLE)
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : DRIVER'S BROTHER GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JOHOR BAHRU
Police Station Address	ROAD: JOHOR , POSTCODE: NA , COUNTRY: MALAYSIA
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING TO BUKIT INDAH FROM WOODLANDS CAUSEWAY. A CAR BRAKED INFRONT OF ME AND I BRAKED. THE CAR BEHIND ME FAILED TO BRAKE BUT INSTEAD CHOOSE TO HIGH BEAM ME. AFTER WHICH HE HIT ME ON THE REAR RIGHT CAUSING DAMAGE TO MY REAR DOOR, RIGHT REAR LAMP AREA, RIM AND POSSIBLY AXEL. I WENT TO THE POLICE STATION IN JB FOR STATEMENT. I HAVE NOT RECEIVED THE STATEMENT YET. I WILL BE GIVEN IN A WEEK TIME, I ALSO HAVE VIDEO EVIDENCE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	JTF1964
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN


VEHICLE NO.: GBD52026
INSURER: China
DATE & TIME: 13.4.2019
10:14pm

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: YS
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS driving to bukit indah from woodlands Causeway. A CAR Breached in front of me and I braked. the car behind me failed to brake but instead choose to high beam me. After which he hit he me on the Rear Right causing damage to my rear door, right rear lamp, Rim and possibly Axel. I went to the police station in JB for statement. I have not received the statement yet. It will be given in a week time. I also video evidence

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:
15/4/19

GLA/MC Sketch Plan Form V3 () Claim Own Policy () Claim Third Party () Reporting Only
() Claim OD/TP at other workshop ()



Singapore 737856

QUOTATION

Vehicle Carplate : SBD5202G GBD5202G

Total: \$4543/-

Daniel Wee _____

Date:

Excess: \$450/-

Not Authorise

Resurvey Photo before paint.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Apr 2019		25 Apr 2019 17:58 Edit Adj Rpt	S\$4,543.00 Edit Estimates	S\$4,543.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

Vehicle Reg. No.:

Claim Type:

Repairer:

Handling Insurer:

Adjuster:

Adj Asg. Remarks:

SNIFE, Co. Reg. No.: 53123990W
GBD5202G
OD / SNM19D201700C01
Graffiti Garage Sg Pte Ltd (HQ) 39 WOODLANDS CLOSE, MEGA @WOODLANDS, #04-01/02, 737856 Woodlands - Tel:
China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by **Elaine Cheong**]
LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by **ONG HWEE JIE**] ... **[Final Rpt due 07/05/2019]**
 Please survey Insured vehicle & let us have your findings Excess \$450.00 applicable (NO waiver)

[Created by insurer]

Date of Loss: 13/04/2019 22:00 - :59
[131 Months and 16 Days From LTA Reg Date (Man Yr)]
 Policy/Cover Note No.: DMCVSN3069651800 (Comprehensive)
 Coverage: 29/10/2018 - 28/10/2019
 Excess: S\$450.00

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- CHINA_TAIPIING (03/05/2019): Alert - Adj Mandate Approved (S\$4543.00) - GBD5202G - Claim Handler: Elaine Cheo...

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents





































*GBD5202G (SNM19D201700C01)

OD

Apr 13 2019 10:00PM

[SNIPE]

Graffiti Garage Sg Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	02/05/19 14:43	Adjuster Immediate Advice				 Load HTM			
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	02/05/19 09:00	General View				 Load JPG		<input checked="" type="checkbox"/>	
2	02/05/19 09:00	General View				 Load JPG		<input checked="" type="checkbox"/>	
3	02/05/19 09:00	General View				 Load JPG		<input checked="" type="checkbox"/>	
4	02/05/19 09:00	General View				 Load JPG		<input checked="" type="checkbox"/>	
5	02/05/19 09:00	General View				 Load JPG		<input checked="" type="checkbox"/>	
6	02/05/19 09:00	General View				 Load JPG		<input checked="" type="checkbox"/>	
7	02/05/19 09:00	General View				 Load JPG		<input checked="" type="checkbox"/>	
8	02/05/19 09:00	General View				 Load JPG		<input checked="" type="checkbox"/>	
9	02/05/19 09:00	General View				 Load JPG		<input checked="" type="checkbox"/>	
10	02/05/19 09:00	General View				 Load JPG		<input checked="" type="checkbox"/>	
11	02/05/19 09:00	General View				 Load JPG		<input checked="" type="checkbox"/>	
12	02/05/19 09:00	General View				 Load JPG		<input checked="" type="checkbox"/>	
13	02/05/19 09:00	General View				 Load JPG		<input checked="" type="checkbox"/>	
14	02/05/19 09:00	General View				 Load JPG		<input checked="" type="checkbox"/>	
15	02/05/19 09:00	General View				 Load JPG		<input checked="" type="checkbox"/>	
16	02/05/19 09:00	General View				 Load JPG		<input checked="" type="checkbox"/>	
17	02/05/19 09:00	General View				 Load JPG		<input checked="" type="checkbox"/>	
18	02/05/19 09:00	General View				 Load JPG		<input checked="" type="checkbox"/>	
19	29/07/19 15:41	Reinspection Photo				 Load JPG		<input checked="" type="checkbox"/>	
20	29/07/19 15:41	Reinspection Photo				 Load JPG		<input checked="" type="checkbox"/>	
21	29/07/19 15:41	Reinspection Photo				 Load JPG		<input checked="" type="checkbox"/>	
22	29/07/19 15:41	Reinspection Photo				 Load JPG		<input checked="" type="checkbox"/>	
23	29/07/19 15:41	Reinspection Photo				 Load JPG		<input checked="" type="checkbox"/>	
24	29/07/19 15:41	Reinspection Photo				 Load JPG		<input checked="" type="checkbox"/>	
25	29/07/19 15:41	Reinspection Photo				 Load JPG		<input checked="" type="checkbox"/>	
26	29/07/19 15:41	Reinspection Photo				 Load JPG		<input checked="" type="checkbox"/>	
27	29/07/19 15:41	Reinspection Photo				 Load JPG		<input checked="" type="checkbox"/>	
28	29/07/19 15:41	Reinspection Photo				 Load JPG		<input checked="" type="checkbox"/>	
29	29/07/19 15:41	Reinspection Photo				 Load JPG		<input checked="" type="checkbox"/>	
30	29/07/19 15:41	Reinspection Photo				 Load JPG		<input checked="" type="checkbox"/>	
31	29/07/19 15:41	Reinspection Photo				 Load JPG		<input checked="" type="checkbox"/>	
32	29/07/19 15:41	Reinspection Photo				 Load JPG		<input checked="" type="checkbox"/>	
33	29/07/19 15:41	Reinspection Photo				 Load JPG		<input checked="" type="checkbox"/>	
34	29/07/19 15:41	Reinspection Photo				 Load JPG		<input checked="" type="checkbox"/>	
35	29/07/19 15:41	Reinspection Photo				 Load JPG		<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
36	29/07/19 15:41	LKK Auto Consultants Pte Ltd (HQ) Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	29/07/19 15:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	29/07/19 15:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	29/07/19 15:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	29/07/19 15:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	29/07/19 15:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	29/07/19 15:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	29/07/19 15:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	29/07/19 15:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	29/07/19 15:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	29/07/19 15:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	29/07/19 15:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	29/07/19 15:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	29/07/19 15:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	29/07/19 15:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	25/04/19 17:28	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) Singapore Accident Statement	Load PDF	
2	25/04/19 17:30	ESTIMATES	Load PDF	
3	25/04/19 17:59	EMAIL NOTIFICATION	Load PDF	
No	Relabel/Reorder		Thumbnail	Print
1	02/05/19 13:43	LKK Auto Consultants Pte Ltd (HQ) ESTIMATE	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19007423/JQD3E2

Date: 31/07/2019

REFERENCE

Insured/Claimant: SNIPE Policy No: DMCVSN3069651800
Date of Loss: 13/04/2019 Nature of Claim: OD Claim No: SNM19D201700C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD5202G**
Make & Model: LAND ROVER DEFENDER 90, 2.4 D L (M) Engine No: 080219180924244DT
Reg. Date: 28/04/2008 (Man. Year: 2008) Chassis No: SALLDVAS78A758468
Colour: Black Odometer: 181362 km
Engine Capacity: 2402 cc
Market Value/New Car Price: S\$63,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 275/70 R16 Rear Tyre Size: 275/70 R16
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,470.00	2,943.00	3,527.00	54.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	1,600.00	1,600.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,670.00	4,543.00	5,127.00	53.02
- Excess (S\$)	450.00	450.00	0.00	0.00
Nett Amount (S\$)	9,220.00	4,093.00	5,127.00	55.61

INSPECTION

Date of Assignment: 25/04/2019
Date Inspected: 30/04/2019 Inspected At: Graffiti Garage Sg Pte Ltd (HQ)
39 WOODLANDS CLOSE, MEGA
@WOODLANDS, #04-01/02
Singapore 737856

Estimated Period of Repair: 5.0 days

Adjuster: ONG HWEE JIE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 29 Jul 2019)
Parts: 192	LAND ROVER DEFENDER 90 2.4 D L (M) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD5202G)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAND ROVER DEFENSER PUMA RIM CAP LOGO	Missing	60.00 F	*60.00 FL
2	1		*DEFENSER 90 LIGHT PROTECTION GRILL	Bent	380.00 F	*380.00 FL
3	1		*DEFENSER 90 REAR LIGHT - RIGHT UK	Cracked	150.00 F	*150.00 FL
4	1		*DEFENSER 90 REAR MUD GUARD LR	Cut	180.00 F	*180.00 FL
5	1		*DEFENSER 90 REAR PROTECTION BAR - UK	Repair	1,500.00 F	*- FL
6	1		*DEFENSER 90 REAR END PANEL LR	Buckled	800.00 F	*800.00 FL
7	1		*DEFENSER 90 REAR LH SIDE PANEL LR	Buckled	2,200.00 F	*1,700.00 FL
8	1		*FRONT RUNNER SPARE WHEEL CARRIER	Not Necessary	1,200.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	6,470.00	3,270.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	327.00

Total Parts (S\$)	6,470.00	2,943.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR INSTALLATION OF PARTS & LABOUR FOR PANEL BEATING & SPRAY PAINT.	New	3,200.00	1,600.00
Gross Labour Cost (\$\$)			3,200.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >