

ASS. REC. BY:

REF: CS/SMO/9007492/J+d3

Special Instruction:

Sunayr: HUIER JIR

ASSIGNMENT (Office)

Memorin

From (Person): Agnes Chan Shu Hui of SMO Date/Time: 24.1.19 8.45 a.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMG 2511M Insured: SDM 990B

at Workshop m/s Kah Motor Tel: 82886302
of 6A mandai Estate

Policy No: D19MTRENT00050 Claim No: CMTD1901562

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 16.3.19
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP" H.O.D. Endorsement: _____

Date/Time: 24.1.19 1.27p.m Person Contacted: Anikka Vehicle ID / OUT

Date/Time	Action/Instruction	Eohmott (✓)
	SMG 2511M - X	
	SDM 990B - X	
<u>2019-</u>	<u>Revised via Memorin</u>	

REF: SOMPO


UNIQUE Hwee Jie

ASSIGNMENT

From _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop n/s: _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SM62511W Yr Regn: 12 Dec/2018
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda Civic cc 1498
 Colour: Red A/C: Insured / Std / NI / NA
 Sp. Reading: 9264 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MRHFC1660JT000291
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: Nil / S/R / STD A/Rim or _____
 Tyre Size: F: 215/50 R17
 R: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date _____ Person Contacted: _____ Vehicle: IN / OUT



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. <u>16/3/19</u>	D.O.I. <u>29/4/19</u>

 Survey held at Kah water
 Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooflap or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$1603.94 confirm part by part (Red: 375.85; 70%)
	RECEIVED 07 MAY 2019

: Preli. Report
 : Final Report
 Days Of Repair: 3
 Resurvey No. of Trip: -
 Survey Fee: _____
 Transportation: _____
 Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)
 Report Format: TP
 Lump Sum / I.E. (\$) 1603.94
 TOTAL _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Mar 2019		29 Apr 2019 08:45 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS				[Created by insurer]																				
Insured:	ETHOZ GROUP LTD, Co. Reg. No.: 198104531H																							
Main Claimant:	CHUA WEE ENG, ID: S1704643H																							
Vehicle Reg. No.:	SMG2511M	Date of Loss:	16/03/2019 07:00 - :59																					
Claim Type:	TP / CMTD1901562	Policy/Cover Note No.:	D19MTRENT000050 (Third Party Only)																					
Vehicle Reg. No. (Insured):	SDM990B	Policy No. (Claimant):																						
		Excess:																						
Repairer:	Kah Motor Co Sdn Bhd (HQ) 6A MANDAI ESTATE, SINGAPORE 729903, 729903 Mandai - Tel:																							
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/05/2019]																							
Adj Asg. Remarks:	WS: Anikka 8288 6302 /6514 5248 VEH CMG IN TODAY																							
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail																			
There are no mail for this case.																								
<div style="border: 1px solid black; padding: 5px;"> <p>ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table> </div>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 7 May 2019 9:49 AM
To: Anikka Lai; Hwee Jie (LKK Auto)
Subject: RE: SMG2511M - FINALIZATION

Dear Anikka,

Confirm final figure at \$1,603.94 with 3days

Please submit your documents to sompo insurance

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Anikka Lai <anikkalai@honda.com.sg>
Sent: Friday, 3 May 2019 1:49 PM
To: Hwee Jie (LKK Auto) <hweejie@lkkauto.com>
Subject: SMG2511M - FINALIZATION

Dear Hwee Jie,

We enclosed the total final repair costs for,

Vehicle No.	SMG2511M
Final Repair Costs (exclude GST)	\$1603.94
Repair Period* (Days)	3 days

***Note: Repair period does include Sunday and Public Holiday.**

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

In addition, I have attached photos of before paint, '?' items and supplementary parts (if any) for your records.

Thank you

Warmest Regards

Anikka Lai
Kah Motor Co. Sdn Bhd
6A Mandai Estate
Singapore 729903
DID : 6514 5248 HP : 8288 6302

Denise Tay (LKKAuto)

From: Anikka Lai <anikkalai@honda.com.sg>
Sent: Friday, 3 May 2019 1:49 PM
To: Hwee Jie (LKK Auto)
Subject: SMG2511M - FINALIZATION
Attachments: 0157_001.pdf; Resurvey B4 Paint _ SMG 2511 M

Dear Hwee Jie,

We enclosed the total final repair costs for,

Vehicle No.	SMG2511M
Final Repair Costs (exclude GST)	\$1603.94
Repair Period* (Days)	3 days

**Note: Repair period does include Sunday and Public Holiday.*

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

In addition, I have attached photos of before paint, '?' items and supplementary parts (if any) for your records.

Thank you

Warmest Regards

Anikka Lai
Kah Motor Co. Sdn Bhd
6A Mandai Estate
Singapore 729903
DID : 6514 5248 HP : 8288 6302
Email: anikkalai@honda.com.sg

From: Printer Service <printservice@honda.com.sg>
Sent: Friday, 3 May, 2019 10:51 AM
To: Anikka Lai <anikkalai@honda.com.sg>
Subject: Attached Image



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sampo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 30 Apr 2019

Preliminary Advice

Insured Vehicle No	: SDM990B	Accident Date	: 16/03/2019
TP Vehicle No	: SMG2511M	Assignment Date	: 29/04/2019
Make	: HONDA CIVIC	Est. Duration of Repair	: 3.00
Date of Inspection	: 29/04/2019		
Inspection At	: KAH MOTOR CO SDN BHD (HQ) 6A MANDAI ESTATE, SINGAPORE 729903 SINGAPORE 729903		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,359.79
Revised Amount	:S\$	1,603.94
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,603.94
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Survey on WP

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/03/2019 15:34
Date Of Accident	16/03/2019 07:30
Exact Location Of Accident	2ND LINK > MALAYSIA NEAR JB CHECKPOINT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMG2511M
Insured/Policyholder	
Name Of Registered Owner	CHUA WEE ENG
NRIC No	S1704643H
Email Address	ZONGYIN.TAN@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97931910
Alternative Phone No	OFFICE-62566381

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-1.5 TURBO VTI-S SR (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	TAN ZONG YIN SHAWN
NRIC No	S8840687G
Date Of Birth	19/10/1988
Occupation	INDOOR
Date Of Driving Pass	09/03/2011
Driving Experience	8 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97931910
Fax Number	
Contact Number	
E-Mail Address	ZONGYIN.TAN@HOTMAIL.COM

Address -
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured CHILDREN
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 3
Passenger 1 NAME: : ROY KOH
GENDER: : MALE
Passenger 2 NAME: : JOCELYN LIM
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

AS ANNEX D&E

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SDM990B
Vehicle Make/Model/Colour BMW / BLUE
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver SIM HOON CHAN
NRIC/Passport Number
Contact Number 98867677 / 97267343
Address
Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

Vehicle Number: SMG 2511M

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4643H
Vehicle Details	
Vehicle No.:	SMG2511M
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.5 TURBO VTIS SR
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	L15B73625183
Chassis No.:	MRHFC1660JT000291
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$26,710.00
Original Registration Date:	12 Dec 2018
First Registration Date:	12 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$29,394.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Dec 2028
PARF Rebate Amount:	\$22,045.00
Intended COE Rebate Details	
COE Expiry Date:	11 Dec 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,302.00
COE Rebate Amount:	\$31,051.00
Total Rebate Amount:	\$53,096.00

The information contained herein is correct as at 30 Apr 2019

OK



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION
: M200050223
Comp : S60FC1380G

Customer : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE #05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

Registration No : SMG2511M

Chassis No : MRHFC1660JT000291

Model : CIVIC 1.5 TURBO VTIS YM2018

Owner's Name : CHUA WEE ENG

Ins Policy No. :

Date of Accident : 16/3/2019

Document No. : SQT19001421 **Page** 1

Date : 28. Mar 2019

Customer No. : WZH023

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : L15B73625183

Date | Time : 28. Mar 2019 7:15:20 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST	
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CHUA WEE ENG OWNER INSURER: TOKIO MARINE ACC DATE: 16/03/2019 SURVEYED BY: DATE: REF NO: TP INSURER: SOMPO TP VEH: SDM990B							
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER DEF ✓	1	617.20 ✓	25	462.90	32.40	495.30	
71593-TEA-T01	SPACERR.RR.BUMPER SIDE nec ✓	1	11.50 ✓	25	8.62	0.60	9.22	
71598-TEA-T01	SPACERL.RR.BUMPER SIDE nec ✓	1	11.50 ✓	25	8.62	0.60	9.22	
91505-TM8-003	CLIP,BUMPER nec ✓	8	2.30 ✓	25	13.80	0.97	14.77	
71503-TEA-T00	GARNISHR.RR.BUMPER SIDE n n x	1	7.80 ✓	25	5.85	0.41	6.26	
68500-TEA-N00ZZ	LID COMP TRUNK n n x	1	486.20 ✓	25	364.65	25.53	390.18	
75722-TBA-A00	EMBLEM SETRR. n n x	1	11.80 ✓	25	8.85	0.62	9.47	
75724-TBA-A00	EMBLEM n n x	1	24.20 ✓	25	18.15	1.27	19.42	
75701-TBA-A10	EMBLEM,H-MARK n n x	1	12.20 ✓	25	9.15	0.64	9.79	
90301-ST0-003	NUTPUSH 3MM n n x	2	2.10 ✓	25	3.15	0.22	3.37	
33500-TEA-T01	TAILLIGHT ASSYR. n n x	1	261.40 ✓	25	196.05	13.72	209.77	
					Sum Item	1099.79	76.98	1,176.77
BOSUN	SUNDRIES nec	1	100.00 ✓		20 100.00	7.00	107.00	
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00 ✓		80.00 X	5.60	85.60	
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	100.00 ✓		80 100.00	7.00	107.00	
BOMISC1	RESET & CALLIBRATE SMART ENTRY SYSTEM (N)	1	200.00 ✓		200.00 X	14.00	214.00	
BOMISC1	REMOVE & INSTALL REAR VIEW CAMERA (N)	1	280.00 ✓		280.00 X	19.60	299.60	
BKBU02R	REMOVE & RENEW RR BUMPER.	1	2000.00 ✓		560 2000.00	140.00	2140.00	

Printed on 28/3/2019 7:28:42 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE #05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623
Registration No : SMG2511M
Chassis No : MRHFC1660JT000291
Model : CIVIC 1.5 TURBO VTIS YM2018
Owner's Name : CHUA WEE ENG
Ins Policy No. :
Date of Accident : 16/3/2019

Document No. : SQT19001421 **Page** 2
Date : 28. Mar 2019
Customer No. : WZH023
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : L15B73625183
Date | Time : 28. Mar 2019 7:15:20 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	1500.00	45%	1500.00	105.00	1605.00
Sum Labor					4260.00	298.20	4,558.20

Survey By: Hui Jie - LKK
Date & Time: 29/4/19
Excess: -
Status: PIP 3days
Signature: [Signature]

[Handwritten Signature]
30/4/19

Total Amount 5,359.79 375.18 5,734.97
Total (Inclusive of GST) 5,734.97

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before other spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 28/3/2019 7:28:42 PM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZH023 / SOMPO INSURANCE
 Chassis No: MRHFC1660JT000291
 License No: SMG2511M
 Mileage: 9274
 Engine No: L15B73625183

Document No: SVO19027011
 Printed By: ANIKKALAI
 Order Date: 29. April 2019
 Order Time: 7:04:50 PM
 Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CHUA WEE ENG OWNER INSURER: TOKIO MARINE ACC DATE: 16/03/2019 SURVEYED BY: HWEE JIE / LKK DATE: 29/04/2019 REF NO: TP INSURER: SOMPO TP VEH: SDM990B						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER	8	2.30	25	13.80	0.97	14.77
	SUM PARTS:				493.94	34.57	528.51
BOSUN		1	20.00		20.00	1.40	21.40
	SUNDRIES						
BA02R		1	80.00		80.00	5.60	85.60
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BKBU02R		1	560.00		560.00	39.20	599.20
	REMOVE & RENEW RR BUMPER.						
BP03R		1	450.00		450.00	31.50	481.50
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P)						
	SUM LABOUR:				1,110.00	77.70	1,187.70
	TOTAL SGD				1,603.94	112.27	1,716.21
	Total Payable (SGD)						1,716.21

GST Amount is calculated from individual line(s)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Mar 2019		29 Apr 2019 08:45 Edit Adj Rpt	S\$1,603.94 Edit Estimates	S\$1,603.94 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ETHOZ GROUP LTD , Co. Reg. No.: 198104531H								
Main Claimant:	CHUA WEE ENG , ID: S1704643H								
Vehicle Reg. No.:	SMG2511M	Date of Loss:	16/03/2019 07:00 - :59 [3 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1901562	Policy/Cover Note No.:	D19MTRENT000050 (Third Party Only)						
Vehicle Reg. No. (Insured):	SDM9908	Policy No. (Claimant):							
		Excess:							
Repairer:	Kah Motor Co Sdn Bhd (HQ) 6A MANDAI ESTATE, SINGAPORE 729903, 729903 Mandai - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 09/05/2019]								
Adj Asg. Remarks:	WS: Anikka 8288 6302 /6514 5248 VEH CMG IN TODAY								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMG2511M (CMTD1901562)
[SDM990B]
TP
CHUA WEE ENG
Mar 16 2019 7:00AM
[ETHOZ GROUP LTD]
Kah Motor Co Sdn Bhd

Upload Documents		Upload Photos		Compose New Letter		View View in Browser	
Assessment Reports						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail	Print		
1	29/04/19 08:41	Accident Statement <small>From: SC - Reg. No: SDM990B, Claimant: ETHOZ GROUP LTD</small>			Load HTML		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	30/04/19 15:14	Adjuster Immediate Advice			Load HTML		
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	30/04/19 09:40	General View			Load JPG	<input checked="" type="checkbox"/>	
2	30/04/19 09:40	General View			Load JPG	<input checked="" type="checkbox"/>	
3	30/04/19 09:40	General View			Load JPG	<input checked="" type="checkbox"/>	
4	30/04/19 09:40	General View			Load JPG	<input checked="" type="checkbox"/>	
5	30/04/19 09:40	General View			Load JPG	<input checked="" type="checkbox"/>	
6	30/04/19 09:40	General View			Load JPG	<input checked="" type="checkbox"/>	
7	30/04/19 09:40	General View			Load JPG	<input checked="" type="checkbox"/>	
8	30/04/19 09:40	General View			Load JPG	<input checked="" type="checkbox"/>	
9	30/04/19 09:40	General View			Load JPG	<input checked="" type="checkbox"/>	
10	13/05/19 08:50	Replacement Part Photo			Load JPG	<input checked="" type="checkbox"/>	
11	13/05/19 08:50	Replacement Part Photo			Load JPG	<input checked="" type="checkbox"/>	
12	13/05/19 08:50	Replacement Part Photo			Load JPG	<input checked="" type="checkbox"/>	
13	13/05/19 08:50	Replacement Part Photo			Load JPG	<input checked="" type="checkbox"/>	
Documentation						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail	Print		
1	29/03/19 10:39	Repair Estimates			Load PDF		
2	29/03/19 10:39	Third Party E-filed GIA report			Load PDF		
3	29/04/19 08:45	TP - ASSIGN LKK			Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19007482/JTD3Q2

Date: 14/05/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTRENT000050
Claimant Vehicle No :	SMG2511M	Insured Vehicle No :	SDM990B
Date of Loss:	16/03/2019	Nature of Claim:	TP
		Claim No:	CMTD1901562

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG2511M	Engine No:	L15B73625183
Make & Model:	HONDA CIVIC, 1.5 TURBO VTI-S SR (A)	Chassis No:	MRHFC1660JT000291
Reg. Date:	12/12/2018 (Man. Year: 2018)	Odometer:	9264 km
Colour:	Red		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,199.79	513.94	685.85	57.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,160.00	1,090.00	3,070.00	73.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,359.79	1,603.94	3,755.85	70.07
+ GST 7.00/7.00% (S\$)	375.19	112.28	262.91	70.07
Nett Amount (S\$)	5,734.98	1,716.22	4,018.76	70.07

INSPECTION

Date of Assignment:	29/04/2019	
Date Inspected:	29/04/2019 Inspected At:	Kah Motor Co Sdn Bhd (HQ) 6A MANDAI ESTATE, SINGAPORE 729903 Singapore 729903
Estimated Period of Repair:	3.0 days	

Adjuster: ONG HWEE JIE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 May 2019)
Parts: 143	HONDA CIVIC 1.5 TURBO VTI-S SR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG2511M)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE ASSY .RR.BUMPER	Deformed	462.90 FS	*462.90 FS
2	1		*SPACERR.RR.BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
3	1		*SPACERL.RR.BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
4	1		*CLIP,BUMPER (8 PCS)	Necessary	13.80 FS	*13.80 FS
5	1		*GARNISHR.RR.BUMPER SIDE	Not Necessary	5.85 FS	*. FS
6	1		*LID COMP TRUNK	Not Necessary	364.65 FS	*. FS
7	1		*EMBLEM SETRR	Not Necessary	8.85 FS	*. FS
8	1		*EMBLEM	Not Necessary	18.15 FS	*. FS
9	1		*EMBLEM ,H-MARK	Not Necessary	9.15 FS	*. FS
10	2		*NUTPUSH 3MM	Not Necessary	3.15 FS	*. FS
11	1		*TAILLIGHT ASSYR	Not Necessary	196.05 FS	*. FS
12	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	1,199.79	513.94
---------------------------	-----------------	---------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT RR LIGHTING MECHANISMS .PERFORM WATER	New	80.00	0.00
2	REMOVE & RENEW REVERSE SENSORS	New	100.00	80.00
3	RESET & CALLIBRATE SMART ENTRY SYSTEM	New	200.00	0.00
4	REMOVE & INSTALL REAR VIEW CAMERA	New	280.00	0.00
5	REMOVE & RENEW RR BUMPER	New	2,000.00	560.00
6	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	1,500.00	450.00
Gross Labour Cost (\$\$)			4,160.00	1,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >