

ASS. REC. BY:

REF: CS3/C1219007483/ Gcd3⁵²

Special Instruction:

Surveyor: GA

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of

C12

Date/Time: 26.4.19 5.00pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDH 8266H

Insured:

SR 27312

at Workshop m/s

Hiap Lek

Tel:

96601347

of 160 sin ming drive # 05 - 17

Policy No:

DMPLEN30416818000

Claim No:

SNM19D201771C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

21/4/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

mvp

H.O.D. Endorsement:

Date/Time:

29.4.19 1.39pm

Person Contacted:

HAN WL

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SDH 8266H - X

SR 27312 - X

No Mention

Dismantle: 15/5/2019

After repair: 17/5/2019

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 26 April 2019 5:00 PM
To: Oracle Law Corp
Cc: 'assignments'
Subject: RE: Our Ref: SB/PO/Acc/2019-8971 Your Ref: Insurer of SLR 2731Z / our ref: SNM19D201771

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Oracle Law Corp [mailto:mail@oraclelaw.sg]
Sent: Friday, 26 April, 2019 4:41 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: Our Ref: SB/PO/Acc/2019-8971 Your Ref: Insurer of SLR 2731Z / our ref: SNM19D201771

Dear Boon Sen,

ACCIDENT INVOLVING SDH 8266H & SLR 2731Z ALONG KARIKAL LANE TOWARDS ST. PATRICK'S ROAD ON 21-04-2019 @ 11.30 A.M.

Kindly refer to attachment the contents of which are self-explanatory for your kind attention and immediate action.

Regards

Alvin Ong

96601347 Hannui

64531743

Sin Ming Auto (Pty)

160 Sin Ming drive #05-17

Time 10 53 am

Person:

V. DW

E

From: Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]

Sent: Friday, 26 April 2019 4:17 PM

To: Oracle Law Corp <mail@oraclelaw.sg>

Subject: RE: Our Ref: SB/PO/Acc/2019-8971 Your Ref: Insurer of SLR 2731Z / our ref: SNM19D201771

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Oracle Law Corp [mailto:mail@oraclelaw.sg]
Sent: Thursday, 25 April, 2019 3:03 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Our Ref: SB/PO/Acc/2019-8971 Your Ref: Insurer of SLR 2731Z

Dear Boon Sen,


PRE-REPAIR INSPECTION

ACCIDENT INVOLVING SDH 8266H & SLR 2731Z ALONG KARIKAL LANE TOWARDS ST. PATRICK'S ROAD ON 21-04-2019 @ 11.30 A.M.

As spoken earlier, kindly refer to attachment the contents of which are self-explanatory for your kind attention and immediate action.

Regards

Alvin Ong

 **Oracle Law Corporation**

• Advocates & Solicitors • UEN/GST Reg No. 200904572Z

237 Alexandra Road #04-11
The Alexcier, Singapore 159929
Telephone: 6538 6250 Facsimile: 6538 1860

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/04/2019 19:11
Date Of Accident	21/04/2019 11:30
Exact Location Of Accident	KARIKAL LANE TOWARDS ST.PATRICK'S ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDH8266H
Insured/Policyholder	
Name Of Registered Owner	THNG BEE WAH
NRIC No	S1527804H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97533774
Alternative Phone No	OFFICE-97533774

Vehicle Particulars

Manufacturer	BMW
Model	116
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1654155
Cover Note Number	

Driver

Name of Driver	THNG BEE WAH
NRIC No	S1527804H
Date Of Birth	27/01/1962
Occupation	INDOOR
Date Of Driving Pass	10/10/1985
Driving Experience	33 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97533774
Fax Number	
Contact Number	OFFICE-97533774
EEmail Address	NOEMAIL

Address	4 ST.PATRICK'S ROAD
Postcode	424117
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLR2731Z
Vehicle Make/Model/Colour	HONDA VEZEL
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	M JAI PRAKASH
NRIC/Passport Number	
Contact Number	91194066
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 21/04/19 @ about 11:30am, I am travelling along Karikal Lane. I am going home which is at 4, St Patrick's Road. When I reached the row of houses along Karikal lane, I stopped as I noticed that ahead of me, there is a red color Honda veeza (SLR 2731Z) stopped, but suddenly, vehicle started to reverse quickly. And I pressed the horn very hard to alert the driver. But vehicle (B) SLR 2731Z continued to reverse and it's rear portion hit onto my vehicle front stationary portion. After which, we moved ahead of the road to exchange particulars. At that point of time, He admitted that he did a reverse and hit onto my vehicle. He told me that he was looking for a friend at No. 14 Karikal Lane. I also contacted my husband to come and assist me. The driver also claimed that the reverse sensors of his vehicle may not be working and he did not notice that my vehicle (SPH 8266H) was behind him that's why the vehicle (SLR 2731Z) hit onto my vehicle (SPH 8266H).

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/ID No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7804H
Vehicle Details	
Vehicle No.:	SDH8266H
Vehicle to be Exported:	No
Intended Deregistration Date:	14 May 2019
Vehicle Make:	B.M.W.
Vehicle Model:	116D 5DR HATCHBACK DSC LED
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	33209315B37D15A
Chassis No.:	WBA1V72070V249567
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$23,958.00
Original Registration Date:	31 Aug 2015
First Registration Date:	31 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$10,542.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2025
PARF Rebate Amount:	\$7,906.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,498.00
COE Rebate Amount:	\$36,183.00
Total Rebate Amount:	\$44,089.00

The information contained herein is correct as at 14 May 2019

OK

► bmw 116d Used Vehicle List (3 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
BMW 1 Series 116d (Diesel - Euro 5 Engine and Above)	\$75,800	\$11,180 /yr	14-Sep-2015	1,496 cc	54,000 km	MK Autohaus Pte Ltd	Available

Lady Owner. PML Maintained And Accident Free. Mileage 54,000 And Recent Change Runflat Tyres. Paint Protection By CSII Ceramic Coatings And Car Wash Maintain By CSII Only. Beautiful White Exterior With ...

Office No. - -

Mr Ng - 92705621

BMW 1 Series 116d (Diesel - Euro 5 Engine and Above)	\$75,800	\$10,810 /yr	28-Oct-2015	1,496 cc	81,000 km	Supreme Cars Pte Ltd	Available
---	-----------------	--------------	-------------	----------	-----------	----------------------	-----------

5 Yrs/200,000Km Warranty And 5 Yrs/200,000Km Free Servicing From Agent PML! Attractive Financing Available. Gorgeous Mineral Grey Paintwork With Black Leather Interior! Trade In Available. Come And Vi...

Office No. - 64796280

Ice Chan - 82986355 | Johnathan Kong - 94599554 | Eugene Seoh - 86861770 | Marcus Tan - 96588475

BMW 1 Series 116d (Diesel - Euro 5 Engine and Above)	\$75,800	\$10,850 /yr	27-Nov-2015	1,496 cc	70,688 km	Benefit Auto Enterprise Pte Ltd	Available
---	-----------------	--------------	-------------	----------	-----------	---------------------------------	-----------

Offer Best Price For Trade In! Offer Best Interest Rate With High Loan! Hurry Please Call For Availability, High Loan Discussion Or Viewing Appointment! Please Call Sales Person!

Office No. - 68444161

Andy Ng - 90222757 | Razali - 90405005 | Thom Lai - 97493638

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Aug 2019		01 Aug 2019 18:49 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	THNG BEE WAH , ID: S1527804H		
Vehicle Reg. No.:	SDH8266H	Date of Loss:	21/04/2019 11:00 - :59 [43 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D201771C02	Policy/Cover Note No.:	DMPCSN30416818000
Vehicle Reg. No. (Insured):	SLR2731Z	Policy No. (Claimant):	VPA/P1654155
		Excess:	S\$0.00
Repairer:	Hiap Lek Automobile Trading () Blk 14 #01-19 Sector B, Sin Ming Industrial Est, 575658 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 14/08/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SDH8266H (SNM19D201771C02)**
[SLR2731Z]

TP
THNG BEE WAH
Apr 21 2019 11:00AM
[-]

Hiap Lek Automobile Trading

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)






























View
[View in Browser](#)



Assessment Reports

No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	1 per page	Thumbnail	Print
1	22/04/19 19:15	Accident Statement	1	Load HTM	












Photos/Images

No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	3 per page	Thumbnail	Print
1	22/04/19 19:15	Accident Photo [Linked Accident Report Documents]	1	Load JPG	
2	22/04/19 19:15	Accident Photo [Linked Accident Report Documents]	1	Load JPG	
3	22/04/19 19:15	Accident Photo [Linked Accident Report Documents]	1	Load JPG	
4	22/04/19 19:15	Accident Photo [Linked Accident Report Documents]	1	Load JPG	
5	22/04/19 19:15	Accident Photo [Linked Accident Report Documents]	1	Load JPG	
6	22/04/19 19:15	Accident Photo [Linked Accident Report Documents]	1	Load JPG	
7	22/04/19 19:15	Accident Photo [Linked Accident Report Documents]	1	Load JPG	
8	22/04/19 19:15	Accident Photo [Linked Accident Report Documents]	1	Load JPG	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/08/19 09:38	General View	1	Load JPG	
2	02/08/19 09:38	General View	1	Load JPG	
3	02/08/19 09:38	General View	1	Load JPG	
4	02/08/19 09:38	General View	1	Load JPG	
5	02/08/19 09:38	General View	1	Load JPG	
6	02/08/19 09:38	General View	1	Load JPG	
7	02/08/19 09:38	General View	1	Load JPG	
8	02/08/19 09:38	General View	1	Load JPG	
9	02/08/19 09:38	General View	1	Load JPG	
10	02/08/19 09:38	General View	1	Load JPG	
11	02/08/19 09:38	General View	1	Load JPG	
12	02/08/19 09:38	General View	1	Load JPG	
13	02/08/19 09:38	General View	1	Load JPG	
14	02/08/19 09:38	General View	1	Load JPG	
15	02/08/19 09:38	General View	1	Load JPG	
16	02/08/19 09:38	General View	1	Load JPG	
17	02/08/19 09:38	General View	1	Load JPG	
18	02/08/19 09:38	General View	1	Load JPG	
19	02/08/19 09:38	General View	1	Load JPG	
20	02/08/19 09:38	General View	1	Load JPG	

Assessment Reports			1 per page ▼	✓
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
21	02/08/19 09:38	General View	 Load JPG	✓
22	02/08/19 09:38	General View	 Load JPG	✓
23	02/08/19 09:38	General View	 Load JPG	✓
24	02/08/19 09:38	General View	 Load JPG	✓
25	02/08/19 09:38	General View	 Load JPG	✓
26	02/08/19 09:38	General View	 Load JPG	✓
27	02/08/19 09:38	General View	 Load JPG	✓
28	02/08/19 09:38	General View	 Load JPG	✓
29	02/08/19 09:38	General View	 Load JPG	✓
30	02/08/19 09:38	General View	 Load JPG	✓
31	02/08/19 09:38	General View	 Load JPG	✓
32	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
33	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
34	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
35	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
36	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
37	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
38	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
39	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
40	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
41	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
42	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
43	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
44	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
45	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
46	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
47	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
48	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
49	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
50	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
51	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
52	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
53	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
54	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
55	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
56	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
57	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
58	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
59	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
60	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
61	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
62	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
63	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
64	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
65	02/08/19 09:39	Photographs of Damaged Parts	 Load JPG	✓
66	02/08/19 09:39	Photo After Spray	 Load JPG	✓
67	02/08/19 09:39	Photo After Spray	 Load JPG	✓
68	02/08/19 09:39	Photo After Spray	Load JPG	✓

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
69	02/08/19 09:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	02/08/19 09:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	02/08/19 09:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	22/04/19 19:14	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	22/04/19 19:14	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	22/04/19 19:15	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	22/04/19 19:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	22/04/19 19:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	22/04/19 19:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	22/04/19 19:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	22/04/19 19:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	22/04/19 19:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	22/04/19 19:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	22/04/19 19:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	22/04/19 19:14	Sketch Plan	 Load TIF	
2	22/04/19 19:14	Sketch Plan #2	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19007483/GCD3S2

Date: 06/08/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30416818000
Claimant Vehicle No :	SDH8266H	Insured Vehicle No :	SLR2731Z
Date of Loss:	21/04/2019	Nature of Claim:	TP
		Claim No:	SNM19D201771C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDH8266H	Engine No:	33209315B37D15A
Make & Model:	BMW 116D, 1.5 (A)	Chassis No:	WBA1V72070V249567
Reg. Date:	31/08/2015 (Man. Year: 2015)	Odometer:	52584 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	01/08/2019		
Date Inspected:	13/05/2019	Inspected At:	160 SIN MING DRIVE #05-17
Estimated Period of Repair:	4.0 days		Repairer: Hiap Lek Automobile Trading

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Aug 2019)
Parts:	144	BMW 116D 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDH8266H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >