



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SLL4878C

CLAIM TYPE : THIRD PARTY

TP INS. CO. : FWD SINGAPORE PTE LTD

ACCIDENT DATE : 24/04/2019

TP VEH REG NO : SLL4878C

ESTIMATE

NO : QUOT201904-000097(00)

DATE : 26/04/2019

POLICY NO : 999995580

VEH REG NO : GBD3295B

MAKE/MODEL : PEUGEOT PARTNER 1.6 HDI
ETG LWB

CHASSIS NO : VF37F9HF8EJ735567

ENGINE NO : 10JBFR0012800

REG. DATE : 2014

Estimate Repair Cost to Vehicle No : GBD3295B

Description	Quantity	Unit Price	Amount
		S\$	S\$
LIST PRICE			
1 Rear door - RH	1	1,200.00	1,200.00
2 Rear door 'PARTNER' emblem - RH	1	122.00	122.00
3 Rear door 'e HDi' emblem - RH	1	102.00	102.00
4 Rear door trimboard - RH	1	355.00	355.00
5 Rear door inner trimboard clips - RH	10	6.00	60.00
6 Rear door - LH	1	1,320.00	1,320.00
7 Rear door 'PEUGEOT' emblem - LH	1	123.00	123.00
8 Rear door inner trimboard clips - LH	10	6.00	60.00
9 Rear end panel (outer)	1	380.00	380.00
10 Rear bumper	1	550.00	550.00
11 Rear bumper pad - RH / LH	2	280.00	560.00
12 Rear bumper tow cover	1	39.00	39.00
			4,871.00
		Less 10%	487.10
			4,383.90
SPECIAL NET			
13 Rear door glass sealant - RH	1	50.00	50.00
14 Rear door glass sealant - LH	1	50.00	50.00
15 Rear bumper reverse sensor (set)	1	380.00	380.00
16 Rear door '70km/h' sticker - LH	1	25.00	25.00
17 Rear door '6pax' sticker - RH	1	15.00	15.00
18 Rear number plate	1	40.00	40.00
			560.00
LABOUR			
19 To check and rectify wiring system	1	80.00	80.00
20 To remove and refix both side door glass	1	200.00	200.00
21 To transfer both side rear door interior mechanism to new door	1	200.00	200.00
22 To panel beat rear floorboard panel, rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
23 To putty and spray paint on affected areas	1	1,000.00	1,000.00
24 To apply rust-proofing on repaired and replaced panels	1	120.00	120.00
25 To supply and paste sticker on both side rear door	1	680.00	680.00
			3,280.00



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SLL4878C

CLAIM TYPE : THIRD PARTY

TP INS. CO. : FWD SINGAPORE PTE LTD

ACCIDENT DATE : 24/04/2019

TP VEH REG NO : SLL4878C

ESTIMATE

NO : QUOT201904-000097(00)

DATE : 26/04/2019

POLICY NO : 999995580

VEH REG NO : GBD3295B

MAKE/MODEL : PEUGEOT PARTNER 1.6 HDI
ETG LWB

CHASSIS NO : VF37F9HF8EJ735567

ENGINE NO : 10JBFR0012800

REG. DATE : 2014

Estimate Repair Cost to Vehicle No : GBD3295B

Description	Quantity	Unit Price	Amount
		S\$	S\$
		TOTAL	S\$ 8,223.90
		ADD GST @ 7%	575.67
		GRAND TOTAL	S\$ 8,799.57

SINGAPORE DOLLAR EIGHT THOUSAND SEVEN HUNDRED NINETY-NINE AND CENTS FIFTY-SEVEN ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
SUNTEC TOWER 4 #18-01
SINGAPORE 038986

26 April 2019

Attn: MOTOR CLAIMS DEPT

Dear Sirs / Madam,

RE: ACCIDENT INVOLVING VEHICLE NO.: GBD3295B & SLL4878C ON 24/04/2019 @ 09:20 HRS
FILTERING FROM PIE(TUAS) INTO UPPER JURONG ROAD

We hereby authorized by our client **DAIMLER FLEET MANAGEMENT S'PORE PTE LTD**, the owner/driver of the above mentioned vehicle No.: **GBD3295B**

We notice that the above accident was caused by your insured/driver negligent driving and/or management of motor vehicle No.: **SLL4878C**

Therefore we are instructed by our client to claim against you/your insured driver in connection with the above captioned accident involving our client's vehicle No.: **GBD3295B** and vehicle No.: **SLL4878C** by your insured/driver at the material time. As a result, our client's vehicle was damaged and our client has been put to loss and expenses. Please assign your surveyor to inspect the above mentioned vehicle in the next 48hrs. Filling which, we will proceed to the repair of the vehicle. Details of claim will submitted to you in due course.

The vehicle is now garage at: **TONG LUCK AUTO PTE LTD**
160 Sin Ming Drive
#07-01/06 Sin Ming Autocity
Singapore 575722
Tel: 6250 0088

Your kind attention to the matter would be much appreciated.

Yours faithfully,



TONG LUCK AUTO PTE LTD

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/04/2019 15:46
Date Of Accident	24/04/2019 09:20
Exact Location Of Accident	FILTERING FROM PIE(TUAS) INTO UPPER JURONG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD3295B
Insured/Policyholder	
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.
Co Reg No	199803778Z
Email Address	DERRICK.LEE@DAIMLER.COM
Mobile Phone No	
Alternative Phone No	OFFICE-82821711

Vehicle Particulars

Manufacturer	PEUGEOT
Model	PARTNER 1.6 HDI ETG LWB
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995580
Cover Note Number	

Driver

Name of Driver	MYO THWE
NRIC No	S8081880G
Date Of Birth	20/11/1980
Occupation	INDOOR
Date Of Driving Pass	25/10/2012
Driving Experience	6 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98718135
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was coming from PIE(Tuas). I stopped my vehicle before the give way line before filtering out into Upper Jurong Road to check for traffic on my right when car SLL4878C from behind collided onto the rear of my vehicle. Damages to my vehicle were on the rear portion. No injuries were involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL4878C
Vehicle Make/Model/Colour	MITSUBISHI/ATTRAGE 1.2 CVT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN DRIVER
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

Passenger 1

NAME: : PASSENGER 1

GENDER: : FEMALE

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER

Muhammad Faizal


Bin Fabila

Witnessed by Reporting Centre
Personnel

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I was coming from PIE(Tuas). I stopped my vehicle before the give way line before filtering out into Upper Jurong Road to check for traffic on my right when car SLL4878C from behind collided onto the rear of my vehicle. Damages to my vehicle were on the rear portion. No injuries were involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MUHAMMAD FAIZAL BIN PABILA



MARS Officer

Registered Owner or Driver's Signature

Job Complete Date/Time

24 April 2019 at 1:12 PM

Date/Time:

24 April 2019 at 1:12 PM