

Assignment
Assigned To

REF 083/AIG19007504 / Act 307

Action/Instruction

Assigned By
Assigned Person

Adrian
chin lee ying

ASSIGNMENT (Office)

AIG

Date/Time 29/4/19 @ 11:58am

Estimated Cost

Bill to

OD ① WS/TIP RIG / OD RIG / EVA / INV / MY TCS

To Inspect Vehicle No

SDV 8133J

Insured

SJL 1446J

At Workshop no

Yap Lee Motor

Tel

6844 1555

at

11caki Bkt Ave 6 # 01-26

Policy No

Claim No

271073763786

Sum Insured

Excess

Make of Veh
(Client's Record)

D.O.A 22/4/2019

CA / REV / REP. / REV 21ERS

lup

H.O.D. Endorsement

Date/Time 10:50pm @ 29/4/19

Person Contacted

Shirley

Vehicle ① IN / OHP

Date/Time

Action/Instruction (+) Estimate

SDV 8133J - x

SJL 1446J - x

Dismantle: 30/4/2019

After repair: 2/5/2019

ASS. REC. BY: ..

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: 8DV8133J Yr Regt: 2016, July.Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Harrier c.c. 1986Colour: Blue A/C: Insured / Std / Nil / NASp. Reading 46567 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: 284600074371Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 235/55R18R: 235/55R18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 29/04/19.Survey held at Tap LeeDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP ALG. PRS.

RECEIVED 09 MAY 2019

MV:

PV:

Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

180

10

190

1)

3)

5)

Prel. Report:

Final Report:

2)

4)

6)

Your password will expire in 14 days. [Click here to change it.](#)

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 29/4/2019 11:58:22 AM

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: Ruby Ong [mailto:ruby@htapartners.com.sg]
Sent: Tuesday, April 23, 2019 11:39 AM
To: Supramaniam, Darshene; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Lim, Sheng Yang; Hor, Yinrul
Cc: Yap Lee Motor
Subject: [EXTERNAL] Your Ref. SJL 1446J : REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SDV 8133J [OUR REF. TCL.GCN.RO.50248.19.YLM]
Importance: High

This message is from an external sender; be cautious with links and attachments.

Our Reference : TCL.GCN.ro.50248.19.ylm
Your Reference : SJL 1446J

Dear Sirs

WITHOUT

PREJUDICE

We refer to your email of even date informing that you wish to conduct a pre-repair survey and to your List of Motor Surveyors.

TAKE NOTICE that we object to all your surveyors stated in your said List, for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose for appointment as Single Joint Expert the following List of Motor Surveyors for your consideration:-

1. Andrew How Prominent Appraiser Services Pte Ltd

2. Alan

CL Appraiser Pte Ltd

Please make the necessary arrangements with the contact person on the survey of our client's vehicle. The details are as follows :

Venue : **Yap Lee Motor**
1 Kaki Bukit Avenue 6
#01-26 Autobay@Kaki Bukit (417883)

Contact Person : **Mrs Chua / Shirley : 6844 1555**

In the event that the pre-repair survey was not conducted during the prescribed time or already conducted at your end previously, we reserve our client's right to claim for compensation for loss of use for your current request for re-survey.

Best regards,
Ruby Ong
Secretary
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext 278
Fax : 6338 3536 / 6533 0313
www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

From: Ruby Ong
Sent: Monday, April 22, 2019 3:39 PM
To: darshene.supramaniam@aig.com; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>
Subject: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SDV 8133J [OUR REF. TCL.GCN.RO.50248.19.ELM]
Importance: High

Your ref: SJL 1446J
Our ref : TCL.GCN.ro.50248.19.ylm

WITHOUT PREJUDICE

22 April 2019

AIG Asia Pacific Insurance Pte Ltd
Motor Claims Department
78 Shenton Way
#08-16 AIG Building
Singapore 079120

By Email Only

VERY URGENT

Dear Sirs,

CLAIMANT: YEO ZHENLIANG

**ACCIDENT INVOLVING SDV 8133J & SJL 1446J ALONG COLLYER QUAY TOWARDS CLIFFORD CENTRE ON
22 APRIL 2019 @ 0841HRS**

We are instructed by Yeo Zhenliang to notify you of a road traffic accident on 22 April 2019 at about 0841hrs along Collyer Quay towards Clifford Centre involving our client's vehicle registration number SDV 8133J and vehicle registration number SJL 1446J driven by your insured/insured's driver at the material time.

As a result of the accident, our clients' vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,
Ruby Ong
Secretary
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext 278
Fax : 6338 3536 / 6533 0313
www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6602F
Vehicle Details	
Vehicle No.:	SDV8133J
Vehicle to be Exported:	No
Intended Deregistration Date:	09 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER PREMIUM STYLE MAUVE 2.0 CVT
Primary Colour:	Green
Manufacturing Year:	2016
Engine No.:	3ZRB748044
Chassis No.:	ZSU600074371
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$32,142.00
Original Registration Date:	27 Jul 2016
First Registration Date:	27 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$36,999.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jul 2026
PARF Rebate Amount:	\$27,749.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jul 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$57,390.00
COE Rebate Amount:	\$41,117.00
Total Rebate Amount:	\$68,866.00

The information contained herein is correct as at 09 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/04/2019 16:12
Date Of Accident	22/04/2019 08:40
Exact Location Of Accident	COLLYER QUAY TOWARDS CLIFFORD CENTRE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDV8133J
Insured/Policyholder	
Name Of Registered Owner	YEO ZHENLIANG
NRIC No	S8126602F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93373795
Alternative Phone No	OFFICE-93373795

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A29086470QMX
Cover Note Number	

Driver

Name of Driver	YEO ZHENLIANG
NRIC No	S8126602F
Date Of Birth	13/08/1981
Occupation	INDOOR
Date Of Driving Pass	23/11/2007
Driving Experience	11 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93373795
Fax Number	
Contact Number	OFFICE-93373795
EMail Address	NOEMAIL

Address	APT BLK 19 DOVER CRESCENT #07-24
Postcode	130019
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJL1446J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEOW CHYE KWANG KEVIN
NRIC/Passport Number	
Contact Number	96718967
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name
NRIC/FIN No:

Sketch Plan #2

SKETCH PLAN



A SDV8133J

B ST-1446J

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was going straight in my lane towards Clifton Centre, when I heard a loud bump. The car had bumped into my car while he was trying to change lane. I have a video clip to witness the whole incident.

I have gotten a quote for private settlement with the driver of car B but he prefer to claim insurance instead.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature:
(if driver is not the policyholder)
Date & Time:

Report Making Person's Signature
Name:
Company:

SDV 8133J

Toyota Harrier. 1986 CC.

ZSU600074371

Rees	Bumper	torn	✓
Rees	Bumper Clips-	Mer	✓
Rees	Bumper Side Holder RH.	Mer	✓
Rees	Wheel Rim.	Cut	✓
Rees	Fenders RH	Repair	+
Rees	Door RH.	Repair	+

04 Days.

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Apr 2019 Edit Reg		29 Apr 2019 00:00 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LEOW CHYE KWANG KEVIN, ID: S7713777G		
Main Claimant:	-		
Vehicle Reg. No.:	SDV8133J	Date of Loss:	22/04/2019 00:00 - :59 [33 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 2710737637SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SJL1446J	Policy No. (Claimant):	
		Excess:	
Repairer:	Yap Lee Motor (HQ) 1 Kaki Bukit Avenue 6, #01-26 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 09/05/2019]		
Claimant's Solicitor:	HIN TAT AUGUSTINE & PARTNERS - Tel: 65330212		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG (30/04/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									






































Claim Documents


























***SDV8133J (2710737637SG)**
[SJL1446J]

TP

-

Apr 22 2019 12:00AM
[LEOW CHYE KWANG KEVIN]
Yap Lee Motor

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	09/05/19 12:15	General View														Load JPG	<input checked="" type="checkbox"/>	
2	09/05/19 12:15	General View														Load JPG	<input checked="" type="checkbox"/>	
3	09/05/19 12:15	General View														Load JPG	<input checked="" type="checkbox"/>	
4	09/05/19 12:15	General View														Load JPG	<input checked="" type="checkbox"/>	
5	09/05/19 12:15	General View														Load JPG	<input checked="" type="checkbox"/>	
6	09/05/19 12:15	General View														Load JPG	<input checked="" type="checkbox"/>	
7	09/05/19 12:15	General View														Load JPG	<input checked="" type="checkbox"/>	
8	09/05/19 12:15	General View														Load JPG	<input checked="" type="checkbox"/>	
9	09/05/19 12:15	General View														Load JPG	<input checked="" type="checkbox"/>	
10	09/05/19 12:15	General View														Load JPG	<input checked="" type="checkbox"/>	
11	09/05/19 12:15	General View														Load JPG	<input checked="" type="checkbox"/>	
12	09/05/19 12:15	General View														Load JPG	<input checked="" type="checkbox"/>	
13	09/05/19 12:15	General View														Load JPG	<input checked="" type="checkbox"/>	
14	09/05/19 12:15	General View														Load JPG	<input checked="" type="checkbox"/>	
15	09/05/19 12:15	General View														Load JPG	<input checked="" type="checkbox"/>	
16	09/05/19 12:15	General View														Load JPG	<input checked="" type="checkbox"/>	
17	09/05/19 12:15	General View														Load JPG	<input checked="" type="checkbox"/>	
18	09/05/19 12:16	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
19	09/05/19 12:16	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
20	09/05/19 12:16	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
21	09/05/19 12:16	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
22	09/05/19 12:16	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
23	09/05/19 12:16	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
24	09/05/19 12:16	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
25	09/05/19 12:16	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
26	09/05/19 12:16	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
27	09/05/19 12:16	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
28	09/05/19 12:16	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
29	09/05/19 12:16	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
30	09/05/19 12:16	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
31	09/05/19 12:16	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
32	09/05/19 12:16	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
33	09/05/19 12:16	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
34	09/05/19 12:16	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
35	09/05/19 12:16	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
36	09/05/19 12:16	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
37	09/05/19 12:16	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	09/05/19 12:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	09/05/19 12:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	09/05/19 12:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	09/05/19 12:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	09/05/19 12:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	09/05/19 12:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	09/05/19 12:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	09/05/19 12:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	09/05/19 12:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	09/05/19 12:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	09/05/19 12:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	09/05/19 12:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	09/05/19 12:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	09/05/19 12:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	09/05/19 12:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	09/05/19 12:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	09/05/19 12:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	09/05/19 12:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	09/05/19 12:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	09/05/19 12:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	09/05/19 12:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	09/05/19 12:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	09/05/19 12:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	09/05/19 12:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	30/04/19 10:47	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19007504/ACD3E2

Date: 14/05/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SDV8133J

Insured Vehicle No : SJL1446J

Date of Loss: 22/04/2019

Nature of Claim: TP

Claim No: 2710737637SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDV8133J

Make & Model: TOYOTA HARRIER, 2.0 Premium Style Mauve CVT (A)

Engine No: 3ZRB748044

Reg. Date: 27/06/2016 (Man. Year: 2016)

Chassis No: ZSU600074371

Colour: Blue

Odometer: 46567 km

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18

Rear Tyre Size: 235/55 R18

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/04/2019

Date Inspected: 29/04/2019 Inspected At:

Yap Lee Motor (HQ)

1 Kaki Bukit Avenue 6, #01-26 Autobay @

Kaki Bukit

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER SIDE HOLDER RH	Necessary	0.00 F	*- F
4	1		*REAR WHEEL RIM	Cut	0.00 F	*- F
5	1		*REAR FENDER RH	Repair	0.00 F	*- F
6	1		*REAR DOOR RH	Repair	0.00 F	*- F
F=Franchise part.						
				Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >