

Ref: [unclear]

Age: 100%

SA: [unclear]

**men**

Star

Chin Lee Ying

REF: CS3/ALG19007506/Ecd302

ASSIGNMENT (Office)

ALG

Date/Time

24/4/19 @ 10:22am

Estimated Cost

Bill to

OD / TP / RS / OD / RS / KVA / INV / MY / CS

To Inspect Vehicle No

SKV 4641C

Insured

SKG 6530E

at Workshop no

Preelse Auto

Tel

67457367

of

11 Kaki Bukit Ave 6 #02-34/36

Policy No

Claim No

3683947380SG

Sum Insured

Excess

Make of Veh

D.O.A

26/4/19

Client's Record

CA / REV / REP / REV 24 HRS

HOI Endorsement

Date/Time

1:20pm

Person Contacted

Ariel

Vehicle

**IN** / OUT

Date/Time

Action/Instruction (X) Estimate

SKV 4641C - NA / TMI 19007397 / K1

D.O.A: 26/4/19

SKG 6530E - NA / TMI 19007397 / K1

D.O.A: 26/4/19

Dismantle: 30/4/2019

After repair: 6/5/2019

08/11/14

Bureau

Steve

REF: AIG

## ASSIGNMENT

From:

Date:

29/4/19

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKV 4641C

at Workshop m/s

Precise Auto

of

1 Kaki Bukit Ave 6 #02-34/36

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S
XXX	XXX

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>hup</sup>

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKV 4641C

Yr Regn:

18/09/15

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Elantra

c.c

1591

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

124096

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KM F10 141 CMIG4 624468

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

V

BS / DUN / EXNOVA / ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

26/4/19

D.O.I.

29/4/19

Survey held at

Precise Auto

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV - 57,000

PV - 47,873

MV - 9127

6 days

RECEIVED 09 MAY 2019

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Survey Fee:

180

Transportation:

S + RS, SI

Photos

Others

10

TOTAL


190

Report Format: DAR

Lump Sum / I.B.I. (\$) )

Your password will expire in 14 days. [Click here to change it.](#)

**PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...**

From: Chin, Lee-Ying  
To: assignments, admin-a@lkkauto.com  
Cc: Fong, Andy-SY  
Sent: 29/4/2019 10:22:54 AM  
Attachments:  26042019142914.pdf

---

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

Date: 26/4/19 @ 2:30pm.

M/s AIG Asia Pacific Insurance Pte Ltd  
M/S Chartis Singapore Insurance Pte Ltd  
78 Shenton Way  
#08-16 CHARTIS Building  
Singapore 079120

By Fax 6835 7416 Only

Dear Sirs

ACCIDENT BETWEEN VEHICLE NO. SKV 4641 C AND VEHICLE NO. SKG 6530 E ON 26/4/19 @ 10:43am. AT From PIE Towards KPE Tunnel.

We refer to the above matter.

We are the appointed repair workshop of vehicle no. SKV 4641 C.

We understand that you are the insurer of vehicle no. SKG 6530 E.

The owner of vehicle no. SKV 4641 C has authorised us to carry out the repairs to his vehicle which was damaged by your insured's vehicle. The owner intends to make a claim against your insured and/or insured's authorised driver for the accident which is caused wholly and/or contributed by your insured and/or your insured's authorised driver's negligence.

We hereby give you notice of the accident and an opportunity to inspect the damaged to the vehicle prior to the commencement of the repairs.

Kindly take note that we hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle no. SKV 4641 C at my premises.

  
Yours faithfully

**Enquire Vehicle & Owner Information ( Vehicle No. SKG6530E As At 26 Apr 2019 / 10:43:00 )****Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: PRECISE-SKV4641C

**Current Owner Details**

Owner ID Type: Singapore NRIC

Owner ID: S7686168D

Owner Name: HUANG WEN I

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 26

Registered Street Name: JALAN LEMPENG

Registered Unit No.: # 08 - 13

Registered Building Name: -

Registered Postal Code: 128805

**Current Vehicle Details**

Vehicle No.: SKG6530E

Make Description/Model: KIA / SORENTO 2.2(A) CRDI 2WD S/R

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	1515H
<b>Vehicle Details</b>	
Vehicle No.:	SKV4641C
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Apr 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	G4FGFU024171
Chassis No.:	KMHDH41CMGU624468
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$15,223.00
Original Registration Date:	18 Sep 2015
First Registration Date:	18 Sep 2015
Transfer Count:	0
Actual ARF Paid:	\$15,223.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Sep 2025
PARF Rebate Amount:	\$11,417.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	17 Sep 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,089.00
COE Rebate Amount:	\$36,456.00
<b>Total Rebate Amount:</b>	<b>\$47,873.00</b>

The information contained herein is correct as at 29 Apr 2019

OK



**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

Primer Brand New Boomed Toyota Dyna 150 @ \$72,800!



GET Incentive! No Hidden Cost!  
No Deposit? Immediate Stock!  
See 'In Gallery'  
Hot Link Partners Search





Browse by Category

Sort by Date Posted 20 results/page

12 vehicles

Hyundai Elantra

Advanced Search

Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	Hyundai Elantra	Any	Any	2015	Any	Any	Available
	Hyundai Elantra 1.6A	\$55,800	\$8,070 /yr	16-Jul-2015	1,591 cc	67,000 km	Sedan Available
1 Owner,100% Loan Available,Ex-Bankruptcy And Bad Credit Welcome,High Trade In. Faster Auto Trading							
Posted: 23-Apr-2019 Tags: 2015 Hyundai Elantra, 2015 Hyundai elantra, Hyundai Elantra, Hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai							
	Hyundai Elantra 1.6A	\$76,800	\$11,130 /yr	27-Jul-2015	1,591 cc	-	Sedan Available
One Owner, Elite Model, Accident Free! Fully Serviced/Maintained By Komoco! Come With Agent Warranty Till 2020, Beautiful White Stylish Yet Spacious To Fits The Family Size, Most Popular Sedan Among L...							
Posted: 28-Mar-2019 Tags: 2015 Hyundai Elantra, 2015 Hyundai elantra, Hyundai Elantra, Hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai							
	Hyundai Elantra 1.6A GLS	\$57,800	\$8,150 /yr	27-Aug-2015	1,591 cc	75,900 km	Sedan Available
Low Interest Of 1.98%, In House Loan Available, Only 1 Owner, Extended Warranty Available! Excellent Fuel Economy As 14.9Km/L Fuel Saver, View And Believe! Buy With A Peace Of Mind From A Company Acc...							
Dickson Automobile							
Posted: 28-Mar-2019 Tags: 2015 Hyundai Elantra, 2015 Hyundai elantra, Hyundai Elantra, Hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai							
	Hyundai Elantra 1.6A	\$62,800	\$8,710 /yr	02-Sep-2015	1,591 cc	50,796 km	Sedan Available
\$2,000 Republic Auto Warranty Workshop Credit! Low Mileage High Spec Model, Authorized Bank Loan At 2.48%, Call Us To Arrange For A Viewing.							
Republic Auto							
Posted: 28-Apr-2019 Tags: 2015 Hyundai Elantra, 2015 Hyundai elantra, Hyundai Elantra, Hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai							
	COE Bidding Results						
Find out more about the latest results of our Certificate of Entitlement (COE).							
Find out more!							
	Hyundai Elantra 1.6A Elite	\$58,800	\$8,090 /yr	02-Sep-2015	1,591 cc	58,193 km	Sedan Available
Meticulously Well Maintained By One Fussy Owner! One Of The Lowest Price In The Market With High Paper Value, Low Mileage Done! Guaranteed Accident Free! Premium Elite Model With Various HI Specs Feat...							
Creative Auto							
Posted: 25-Apr-2019 Tags: 2015 Hyundai Elantra, 2015 Hyundai elantra, Hyundai Elantra, Hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai							
	Hyundai Elantra 1.6A Elite	\$58,800	\$8,020 /yr	17-Sep-2015	1,591 cc	67,000 km	Sedan Available
1 Owner Only,Vehicle In Show Room Condition, Full Agent Service Record, Still Under Warranty, High Paper Value, Low Down Payment, Various Loan Option Provided, Selling Cheap, Call Now Don't Miss							
Posted: 08-Apr-2019 Tags: 2015 Hyundai Elantra, 2015 Hyundai elantra, Hyundai Elantra, Hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai							
	Hyundai Elantra 1.6A GLS	\$56,800	\$7,840 /yr	30-Sep-2015	1,591 cc	-	Sedan Available
1 Owner! Selling Cheap! Low Depreciation For A Spacious And Reliable Car Brand, Clean And Neat Interior With Fresh New Servicing.							
Posted: 18-Apr-2019 Tags: 2015 Hyundai Elantra, 2015 Hyundai elantra, Hyundai Elantra, Hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai							
	Hyundai Elantra 1.6A Elite (OPC)	\$49,800	\$6,520 /yr	16-Oct-2015	1,591 cc	34,000 km	Sedan Available
Well Maintain By 1 Owner, Low Mileage, Agent Service By Komoco Motors, Low Fuel Consumption And Low Maintenance, Trade In Welcome. Different Loan Packages Suit To Your Needs. Please Visit Us Now For F...							
Pure Motors Pte Ltd							
Posted: 19-Apr-2019 Tags: 2015 Hyundai Elantra, 2015 Hyundai elantra, Hyundai Elantra, Hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai							
	Hyundai Elantra 1.6A GLS	\$55,800	\$7,630 /yr	20-Oct-2015	1,591 cc	45,000 km	Sedan Available
New Arrival, Only 1 Owner, Fully Serviced And Maintained By Komoco Agents, Very Low Mileage Done Of Only 45,000km, Original Paint Work, Very Clean Interiors, Elegant Grey Silver With Black Leather Sea...							
Posted: 28-Apr-2019 Tags: 2015 Hyundai Elantra, 2015 Hyundai elantra, Hyundai Elantra, Hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai							
	Hyundai Elantra 1.6A Elite	\$57,000	\$7,600 /yr	02-Nov-2015	1,591 cc	66,000 km	Sedan Available
Very Well Maintained Agent Unit With Extended Warranty Till Nov 2022 By Komoco Motors! Free 2 Years Servicing Package That Goes Along With Car, Superb Fuel Consumption, Spacious And Stylish With Full...							
360 VR Cars							
Posted: 12-Mar-2019 Tags: 2015 Hyundai Elantra, 2015 Hyundai elantra, Hyundai Elantra, Hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai							

Save up to 24%



Save on petrol with UOB One card!

Enjoy huge petrol savings of up to 24%, attractive cashback on your monthly spend, and 1-year annual fee waiver. Apply now and start enjoying today.

Find out more!



**Save on petrol with UOB One card!**

Enjoy huge petrol savings of up to 24%, attractive cashback on your monthly spend, and 1-year annual fee waiver. Apply now and start enjoying today.

Find out more!

Compare

Hyundai Elantra 1.6A Elite \$60,800 \$8,130 /yr 13-Nov-2015 1,591 cc 66,254 km Sedan Available  
High Specs Elite Model! With Push Start And Electric Seat! Agent Serviced With Low Mileage Done! Beautiful Black Paintwork! Selling Cheap! High/Full

VEHICLE NO : SKV 4641C

MAKE &amp; MODEL : Hyundai Elantra


Date of Accident	26 / 04 / 2019.	
Time of Accident	10:42 AM / PM	
Location of Accident	From PIE To KPE Tunnel.	
Exact Purpose Usage	Personal / <del>Private Hire</del> (Uber / <del>Grab</del> ) / Commercial	
NAME OF OWNER :	Tan Kiong Yeow. (wife: 93660495-MS-Tan)	
Contact No.	9759 4819.	
Nric No	S0141515H.	
Type Of Claim	<u>Third Party</u> / Own Damage / Reporting only	
Insurance Co.	Tokio Marine Insurance	
Type of Coverage	<u>Comprehensive</u> / Third Party / Third Party Fire & Theft	
Policy No	19-MJ 000199-R01.	
NAME OF DRIVER :	As above / If No: Lee Boon Keong	
Nric No	S8109574D.	Any Passenger: +2.
Date Of Birth	28 / 03 / 1981.	Name: -
Location	<u>Outdoor</u> / Indoor	Gender: Female
Date Of Driving Pass	20 / 04 / 2005.	Name: -
Gender	<u>Male</u> / Female	Gender: Female.
Contact no	96600590	Office: - Home: -
Address	Blk 32 Cassia Crescent #04-56 S(390032).	
Driver Have Any Own Vehicle	<u>NO</u> / If Yes (Reg no):	
Relationship	Employee / If No: Father In Law / Son In Law.	
Weather Condition	Clear / <u>Raining</u> / Other:	
Road Surface	Dry / <u>Wet</u> / Other:	
Any Injuries	NO / If Yes Who?	
Name		Contact:
Name		Contact:
Police Report	No / If Yes: Where?	

Vehicle B No :	SKG 6530E.	Any Passenger: Unknown.
Name Of Driver	Grace	
Contact No :	9816 8181.	
Vehicle C No :		Any Passenger:
Vehicle D No :		Any Passenger:
Vehicle E No :		Any Passenger:
Vehicle F No :		Any Passenger:
Any Witness		
Witness Contact No		
Have you been approach by unknow person soliciting (s) / offering accident claims assistance?		
YES / NO		

PARTICULAR WORKSHOP	PRECISE AUTO SERVICE
Address	1 Kaki Bukit Ave 6 #02-34
	Kaki Bukit @ Auto Bay
	Singapore 417883
Email : benke_0710@yahoo.com.sg	Tel : 6745 7367 Fax : 6841 3390



# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 26-04-2019 @ about 10:43 am, I was driving my car (SKV 4641C) with 2 passengers from PIE to KPE. While just entering to KPE Tunnel, vehicles in front of me apply brake and stop so I slow down & stop too. Suddenly I felt an impact from behind and I realized that vehicle B (SKG 6530E) could not stop in time and collided onto rear portion of my car. Hence, I hereby lodge this report to claim against Veh B's Insurance for my accident damages. I will go to see doctor if feel any uncomfortable after this.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

NOTES: (1) Bent (2) Denied (3) Distorted (4) Cracked (5) Cut (6) Scratched  
(7) Deformed (8) Shifted (9) Buckled (10) Broken (11) Necessary  
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

## MOTORCAR (Rear)

EXPLANATION:  
(1) Replace (✓) (2) Repair (X) (3) Check (Ø)  
(4) Not Consistent (NC)

Vehicle No:

SKV 4641C

### Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	UT	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	NR	✓	2
1149	993045	Rear Bumper Reinforcement	NR	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	UT	✓	2
1157	993023	Rear Bumper Lower Spoiler	UT	✓	
1158	994023	Reverse Sensor	NR	✓	
1159	993327	Rear End Panel	NR	✓	
1160	993339	Rear End Panel Top Garnish	NR	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	UT	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	SCR	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	NR	✓	
1171	991328	Bootlid Emblem	NEC	✓	3
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH	NR	✓	
1176	992899	Bootlid Lamp RH	NR	✓	
1177	995243	Bootlid Lock	NR	✓	
1178	990377	Bootlid Rubber	NR	✓	
1179	990382	Bootlid Hinge	NR	✓	2
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board	TM	✓	
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993423	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

30/4/2019

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Apr 2019 <a href="#">Edit Reg</a>		29 Apr 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS**

Insured:

**HUANG WEN I**, ID: S7686168D

Main Claimant:

-

Vehicle Reg. No.:

**SKV4641C**

Date of Loss:

26/04/2019 00:00 - :59  
[43 Months and 8 Days From LTA Reg Date (Man Yr)]

Claim Type:

**TP / 3683947380SG**

Policy/Cover Note No.:

(Comprehensive)

Vehicle Reg. No. (Insured):

**SKG6530E**

Policy No. (Claimant):

Excess:

Repairer:

**Precise Auto Service (HQ)** No 1 Kaki Bukit Ave 6, #02-34/36, 417883 Kaki Bukit - Tel: 67457367

Handling Insurer:

**AIG Asia Pacific Insurance Pte. Ltd. (Express)** - Tel: 65-6419-3000 ... [Handled by **MdNoor, Norsiah**] Norsiah.MdNoor@aig.com

Adjuster:

**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **CHEN TSUE YEE**] ... **[Final Rpt due 09/05/2019]**

**ASSOCIATED MAIL RECEIVED**

[View All](#)
[Compose Case Mail](#)

- AIG\_SG (30/04/2019): **Request To Upload TP GIA Report**
- AIG\_SG (30/04/2019): **No OI GIA Report**

**ALL ASSOCIATED TASKS**

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SKV4641C (3683947380SG)**

**[SKG6530E]**






































**TP**


















































-

**Apr 26 2019 12:00AM**

























**[HUANG WEN I]**

**Precise Auto Service**

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
2	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
3	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
4	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
5	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
6	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
7	29/04/19 18:09	Odometer Reading														Load JPG	<input checked="" type="checkbox"/>	
8	29/04/19 18:09	Chassis Number														Load JPG	<input checked="" type="checkbox"/>	
9	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
10	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
11	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
12	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
13	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
14	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
15	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
16	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
17	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
18	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
19	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
20	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
21	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
22	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
23	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
24	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
25	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
26	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
27	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
28	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
29	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
30	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
31	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
32	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
33	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
34	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
35	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
36	29/04/19 18:09	General View														Load JPG	<input checked="" type="checkbox"/>	
37	30/04/19 19:52	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	30/04/19 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	06/05/19 18:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
89	06/05/19 18:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
90	06/05/19 18:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
91	06/05/19 18:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
92	06/05/19 18:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
93	06/05/19 18:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
94	06/05/19 18:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
95	06/05/19 18:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
96	06/05/19 18:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
97	06/05/19 18:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
98	06/05/19 18:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
99	06/05/19 18:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
100	06/05/19 18:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
101	06/05/19 18:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
102	06/05/19 18:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	06/05/19 18:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
104	06/05/19 18:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
105	06/05/19 18:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
106	06/05/19 18:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
107	06/05/19 18:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
108	06/05/19 18:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
109	06/05/19 18:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
110	06/05/19 18:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
111	06/05/19 18:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19007506/ECD3E2

Date: 14/05/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SKV4641C

**Insured Vehicle No :** SKG6530E

Date of Loss: 26/04/2019

Nature of Claim: TP

Claim No: 3683947380SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKV4641C**

Make &amp; Model: HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD 4DR (A)

Engine No: G4FGFU024171

Reg. Date: 18/09/2015 (Man. Year: 2015)

Chassis No: KMHDH41CMGU624468

Colour: Silver

Odometer: 124096 km

Engine Capacity: 1591 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Goodyear 5 mm

Rear Left Side: Goodyear 5 mm

Front Right Side: Goodyear 5 mm

Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 29/04/2019

Date Inspected: 29/04/2019 Inspected At:

 Precise Auto Service (HQ)  
 No 1 Kaki Bukit Ave 6, #02-34/36  
 Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
4	1		*REAR BUMPER REINFORCEMENT	Broken	0.00 F	*- F
5	2		*REAR BUMPER REFLECTOR	Cut	0.00 F	*- F
6	1		*REAR BUMPER LOWER SPOILER	Cut	0.00 F	*- F
7	1		*REVERSE SENSOR	Broken	0.00 F	*- F
8	1		*REAR END PANEL	Dented	0.00 F	*- F
9	1		*REAR END PANEL TOP GARNISH	Crushed	0.00 F	*- F
10	1		*REAR LH TAILLAMP	Cut	0.00 F	*- F
11	1		*REAR RH TAILLAMP	Scratched	0.00 F	*- F
12	1		*BOOTLID	Dented	0.00 F	*- F
13	3		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
14	1		*BOOTLID LAMP LH	Broken	0.00 F	*- F
15	1		*BOOTLID LAMP RH	Broken	0.00 F	*- F
16	1		*BOOTLID LOCK	Bent	0.00 F	*- F
17	1		*BOOTLID RUBBER	Crushed	0.00 F	*- F
18	1		*SPARE TYRE BOARD	Torn	0.00 F	*- F
19	1		*REAR LH FENDER INNER TRIM	* Check	0.00 F	*- F
20	1		*REAR RH FENDER INNER TRIM	* Check	0.00 F	*- F

F=Franchise part.

<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.
---



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >