

2/13/2019

ASS REC BY:

REF: CS/Smo/9007510/71sd352

Special Instruction:

Survey: 7/11/19

ASSIGNMENT (Office)

Date/Time: 29.4.2019 16:37pm

From (Person): Agnes Chan Shu Hui of Smo

Bill to:

Estimated Cost:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLL 7895H

Insured:

at Workshop m/s Accord Auto Service

of 10 MK Ind Park 2A, # 03-11

Tel:

64819517 / 6271 7433 (accid.g)

Policy No: D19MTPV01003356

Claim No:

(MID) 1902082

Sum Insured:

Excess:

3000/-

Make of Veh:  
(Client's Record)

D.O.A.

26.4.2019

30.6.2019

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Person Contacted: Jessie

Vehicle:

IN/OUT

Date/Time: 29.4.19 5:00pm

Person Contacted:

Inspector: BIK 1009 Bulky Murah Lane 3 #01-80

Date/Time	Action/Instruction	Estimate?
	<u>SLL 7895H - X</u>	<input checked="" type="checkbox"/>
<u>2/5@11:43am</u>	<u>Revert menimen preli advise.</u>	
<u>2/5@15:48pm</u>	<u>Mandate approve by Chan Shu Hui Agnes</u>	
<u>2/5@4pm</u>	<u>email to Accord auto proceed authorise repair excess 3000</u>	

CS/SM019007510/71503

Taufik

REF: SMD

ASSIGNMENT

Customer

Date: 30.4.2019

Veh No: SLL 7895H. Yt Regn: 217, Moch.

Front: Estimated Cost:

Type:  Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or Make: Honda vezel. C.G. 1496.

To inspect Vehicle No: SLL 7895H  
at Workshop n/s: Accord Auto Service  
of BIC 1009 Bukit Merah Lane 3 #01-80

Colour: Blue. A/C: Insured / Std / NI / NA

Insured:

Sp. Reading: 73764. T/Radio: Insured / Std / NI / NA

Policy No:

Eng/No: C/No: R4/120292

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess: IBA \$300/-

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / SRim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 215/55R17. R: -

Remark: The veh had commenced its repair at the time of inspection.

<del>N/S</del>	<del>O/S</del>
N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO /  YOKO or

Bal. or Market Value:

\$74K

Front R/Bal. 6 mm. Rear R/Bal. 6 mm

IDAC Accident Rport:

Consistent? : Yes or No

L/Bal. 6 mm. D.O.I. 30/4/19

GIA / PR Seen:

Consistent? : Yes or No

Survey held at: Accord Auto.

Est. Repairs:

days Res.: Yes or No

Des. of Damages:  Frt / Rear / O/S / N/S / UIC / Rooftop or

Lump Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date:

Person Contacted:

Date / Time Action / Instruction  
25/06/19 Confirmed P/P \$ 18,806.00 @ 10 days with Taufik  
( \$ 3,153.50 Red - 14% )

RECEIVED 6 JUN 2019

Signature: M. Manito  
25/6/2019

Date/Time, File Pass to?

06/06/19

1) Typist

Date/Time, File Return to?

2)

: Preli. Report

: Final Report

Days Of Repair: 10

Resurvey No. of Trip: 2

Add Fee:  Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee:

Transportation:

\$ + RS, SI

) Photos

) Others

TOTAL

450
11

Report Format:

Lump Sum (L.B.I) \$ 18,806/- P/P

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Apr 2019 Sendback Est	29 Apr 2019 16:23 S\$17,414.70	29 Apr 2019 16:37 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	<b>PIRAGASAM S/O MUNISAMY</b> , ID: S1669907A, Tel: +6597838360		26/04/2019 19:00 - :59 [25 Months and 16 Days From LTA Reg Date (Man Yr)]						
Vehicle Reg. No.:	<b>SLL7895H</b>	Date of Loss:	D19MTPV01003356 (Comprehensive)						
Claim Type:	<b>OD / CMTD1902082</b>	Policy/Cover Note No.:	Excess:						
Repairer:	<b>Accord Auto Services Pte Ltd (HQ)</b> 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point, 568047 Ang Mo Kio - Tel: 64819517/85715140								
Handling Insurer:	<b>Sompo Insurance Singapore Pte. Ltd. (HQ)</b> - Tel: 6461 6555 ... [Handled by <b>CHAN SHU HUI AGNES</b> - 6329 5327]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Final Rpt due 09/05/2019]								
Driver/Custodian:	RAVEEN PIRAGASAM (21 / Male), NRIC: S9715223C, Tel: +6593880794 Email: raveen97@gmail.com								
Adj Asg. Remarks:	VEH IN AT BUKIT MERAH - FOR EXCESS & AUTHORISATION, PLEASE REFER TO THE HANDLER								
			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
<b>ASSOCIATED MAIL RECEIVED</b>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>									
<input type="checkbox"/> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Shirley Hiew (LKK Auto)

---

**From:** Accord Claims(AV) <avclaims@mycarworkshop.com.sg>  
**Sent:** Wednesday, 26 June 2019 12:12 PM  
**To:** Shirley Hiew (LKK Auto)  
**Cc:** SUR  
**Subject:** Re: SLL 7895H OD (SOMPO) DOA 26/04/2019

Dear Shirley,

Confirmed the amount.

Thank you.

Kind regards,  
Celia Lai

Accord Auto Services Pte Ltd  
Blk 1009 Bukit Merah Lane 3  
#01-80  
Singapore 159723

Mobile: (65) 9274 0999  
Tel : (65) 6271 7433  
Fax : (65) 6274 5715

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

On Wed, Jun 26, 2019 at 9:19 AM Shirley Hiew (LKK Auto) <[ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com)> wrote:

Dear Celia,

Supplementary 2, 3 & 4 approved by SOMPO.

Please confirm final fig \$ 18,806.00 @ 10 days of repairs before excess \$ 3,000/- & GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Accord Claims(AV) [mailto:[avclaims@mycarworkshop.com.sg](mailto:avclaims@mycarworkshop.com.sg)]  
**Sent:** Tuesday, 25 June 2019 8:43 PM  
**To:** Shirley Hiew (LKK Auto) <[ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com)>  
**Subject:** Re: SLL 7895H OD (SOMPO) DOA 26/04/2019

Dear Shirley,

As tel-communication, Kindly let me have your figure.

Thank you.

Kind regards,  
Celia Lai

Accord Auto Services Pte Ltd

Blk 1009 Bukit Merah Lane 3

#01-80

Singapore 159723

Mobile: (65) 9274 0999  
Tel : (65) 6271 7433  
Fax : (65) 6274 5715

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Friday, 17 May 2019 1:35 PM  
**To:** 'Accord Claims(AV)'  
**Cc:** 'SUR'  
**Subject:** RE: SLL 7895H / OD / SOMPO / EXCESS \$3000  
**Attachments:** SUPPLEMENTARY.pdf

Dear Celia,

Insurance has approved the supplementary.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Denise Tay (LKKAuto) [mailto:[denisetay@lkkauto.com](mailto:denisetay@lkkauto.com)]  
**Sent:** Thursday, 2 May 2019 4:00 PM  
**To:** Accord Claims(AV) <[avclaims@mycarworkshop.com.sg](mailto:avclaims@mycarworkshop.com.sg)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** SLL 7895H / OD / SOMPO / EXCESS \$3000

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLL 7895H (Excess \$3000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Thursday, 2 May 2019 4:00 PM  
**To:** 'Accord Claims(AV)'  
**Cc:** SUR  
**Subject:** SLL 7895H / OD / SOMPO / EXCESS \$3000

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLL 7895H (Excess \$3000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### View Received Message

This mail is associated with :

**SLL7895H (CMTD1902082)**

OD

Apr 26 2019 7:00PM

[PIRAGASAM S/O MUNISAMY]  
Accord Auto Services Pte Ltd

Reply   Reply All   Mark as Unread   Print Message   Delete Message   Forward

**From** Sompo Insurance Singapore Pte. Ltd. (SOMPO\_SG), sent on 25/06/2019 13:04 PM.  
**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$20134.50) - SLL7895H - Claim Handler: CHAN SHU HUI AGNES

Approved:20134.50.

#### DOCUMENTS SUMMARY

There are no documents.

## View Received Message

This mail is associated with :

**SLL7895H (CMTD1902082)**

OD

Apr 26 2019 7:00PM

[PIRAGASAM S/O MUNISAMY]  
Accord Auto Services Pte Ltd

Reply   Reply All   Mark as Unread   Print Message   Delete Message   Forward

**From** Sampo Insurance Singapore Pte. Ltd. (SOMPO\_SG), sent on 17/05/2019 13:29 PM.  
**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$18915.00) - SLL7895H - Claim Handler: CHAN SHU HUI AGNES

Approved:18915.00.

### DOCUMENTS SUMMARY

There are no documents.

## View Received Message

This mail is associated with :

**SLL7895H (CMTD1902082)**

OD

Apr 26 2019 7:00PM

[PIRAGASAM S/O MUNISAMY]

Accord Auto Services Pte Ltd

Reply

Reply All

Mark as Unread

Print Message

Delete Message

Forward

**From** Sampo Insurance Singapore Pte. Ltd. (SOMPO\_SG), sent on 02/05/2019 15:48 PM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$15589.70) - SLL7895H - Claim Handler: CHAN SHU HUI AGNES

Approved:15589.70.

### DOCUMENTS SUMMARY

There are no documents.

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	29 Apr 2019 10:46	<b>Clim Veh Model Changed</b>	(204586) HONDA VEZEL 1.5 X CVT (A).	[ ] Merimen Administrator
2	29 Apr 2019 10:46	<b>Clim Created</b>	Reg No: SLL7895H. Policy No: D19MTPV01003356. Acct Date: 2019/04/26. Claim Type: SC. Insurer: Sompo Insurance Singapore Pte. Ltd. (HQ). Ins.Status => Notification. Created from SAS:MAAS19054490	[I] Merimen Administrator
3	29 Apr 2019 10:46	<b>Clim Registration Modified</b>	Setl.Type:3->0. Claim Type:SC->0D.	[ ] Soe Jie Yi
4	29 Apr 2019 12:46	<b>Clim Registration Modified</b>	Acct Time:19:45:00->19:00:00.	[I] Lim Sze Hwee
5	29 Apr 2019 16:23	<b>Clim Submitted</b>	17414.70.	[R] Soe Jie Yi
6	29 Apr 2019 16:37	<b>Adj Co Assigned</b>	LKK Auto Consultants Pte Ltd (HQ):VEH IN AT BUKIT MERAH - FOR EXCESS & AUT HORISATION, PLEASE REFER TO THE HANDLER	[I] GRACE TEO
7	29 Apr 2019 16:37	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2019/05/09	[I] GRACE TEO
8	29 Apr 2019 16:37	<b>Adj Mandate Set</b>	Approved:0.00.	[I] GRACE TEO
9	29 Apr 2019 16:40	<b>Assignment 1st Accessed</b>		[A] LEE SU THING
10	29 Apr 2019 17:17	<b>Adj Adjuster Assigned</b>	[None] -> MOHD TAUFIKH BIN HAMID	[A] LEE SU THING
11	29 Apr 2019 19:04	<b>Clim Registration Modified</b>	Excess: -> 0.00. Excess Waived: -> 500.00. 2F: -> 3000.00.	[I] CHAN SHU HUI AGNES
12	02 May 2019 11:33	<b>Adj Rpt Initiated</b>		[A] DENISE TAY KWEE CHENG
13	02 May 2019 11:39	<b>Adj Im. Advice Submitted</b>	Next Rpt:Final Rpt.Due Date:2019/05/09	[A] DENISE TAY KWEE CHENG
14	02 May 2019 11:43	<b>Adj Mandate Request</b>	Cur.Req:15589.70;DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
15	02 May 2019 15:48	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2019/05/09	[I] CHAN SHU HUI AGNES
16	02 May 2019 15:48	<b>Adj Mandate Set</b>	Approved:15589.70.	[I] CHAN SHU HUI AGNES

Date From     Date To     Audit Type

### ACTIVITY

No record

### Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2129499	29/04/2019 10:46	Motor	Sompo Insurance Singapore Pte. Ltd. (HQ)	Sompo Insurance Singapore Pte. Ltd. (HQ)	SLL7895H	PIRAGASAM S/O MUNISAMY	xx.xx
2129503	29/04/2019 10:46	Motor	Accord Auto Services Pte Ltd (HQ)	Accord Auto Services Pte Ltd (HQ)	SLL7895H		xx.xx
2133462	02/05/2019 11:33	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLL7895H		10.70

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 25 Jun 2019

**Preliminary Advice**

Vehicle No	: SLL7895H	Accident Date	: 26/04/2019
Make	: HONDA VEZEL	Policy No.	: D19MTPV01003356
Assignment Date	: 29/04/2019	Excess	: S\$0.00
		Additional Excess	: S\$3,000.00
Date of Inspection	: 30/04/2019	Est. Duration of Repair	: 10.00
Inspection At	: ACCORD AUTO SERVICES PTE LTD (HQ) 10 ANG MO KIO IND PARK 2A #03-11, AMK AUTO POINT SINGAPORE 568047		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	21,959.50 (inclusive supp)
Revised Amount	:S\$	17,229.70 (inclusive supp)
Check Items (Estimated)	:S\$	2,904.80
Total	:S\$	20,134.50
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	74,000.00
COE / PARF Rebate	:S\$	46,175.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,825.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Supplementary amount is \$ 1,219.50.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 15 May 2019

**Preliminary Advice**

Vehicle No	: SLL7895H	Accident Date	: 26/04/2019
Make	: HONDA VEZEL	Policy No.	: D19MTPV01003356
Assignment Date	: 29/04/2019	Excess	: S\$0.00
		Additional Excess	: S\$3,000.00
Date of Inspection	: 30/04/2019	Est. Duration of Repair	: 10.00
Inspection At	: ACCORD AUTO SERVICES PTE LTD (HQ) 10 ANG MO KIO IND PARK 2A #03-11, AMK AUTO POINT SINGAPORE 568047		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,740.00 (inclusive supplementary)
Revised Amount	:S\$	16,010.20 (inclusive supplementary)
Check Items (Estimated)	:S\$	2,904.80
Total	:S\$	18,915.00

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	74,000.00
COE / PARF Rebate	:S\$	46,175.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,825.00

**Remarks**

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : Supplementary amount is \$ 3,325.30.

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 02 May 2019

**Preliminary Advice**

Vehicle No	: SLL7895H	Accident Date	: 26/04/2019
Make	: HONDA VEZEL	Policy No.	: D19MTPV01003356
Assignment Date	: 29/04/2019	Excess	: S\$0.00
		Additional Excess	: S\$3,000.00
Date of Inspection	: 30/04/2019	Est. Duration of Repair	: 10.00
Inspection At	: ACCORD AUTO SERVICES PTE LTD (HQ) 10 ANG MO KIO IND PARK 2A #03-11, AMK AUTO POINT SINGAPORE 568047		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,414.70
Revised Amount	:S\$	12,684.90
Check Items (Estimated)	:S\$	2,904.80
Total	:S\$	15,589.70

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	74,000.00
COE / PARF Rebate	:S\$	46,175.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,825.00

**Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation and confirm excess.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/04/2019 12:44
Date Of Accident	26/04/2019 19:45
Exact Location Of Accident	AYE ALEXANDRA EXIT (LAMPOST 314)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL7895H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	PIRAGASAM S/O MUNISAMY
NRIC No	S1669907A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97838360
Alternative Phone No	OFFICE-97838360

### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 X CVT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D19MTPV01003356
Cover Note Number	

### Driver

Name of Driver	RAVEEN PIRAGASAM
NRIC No	S9715223C
Date Of Birth	11/05/1997
Occupation	INDOOR
Date Of Driving Pass	21/07/2017
Driving Experience	1 YEAR AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93880794
Fax Number	
Contact Number	
Email Address	RAVEEN97@GMAIL.COM

Address	BLK 714 JURONG WEST STREET 71 #04-139
Postcode	640714
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

On 26/04/2019 about 7.48pm, I was driving along AYE around Alexandra exit. Car in front of me brake to a complete stop, I followed. However my car could not stop in time and bump onto is rear. We suppose to exchange our particulars at the road shoulder. But the other party drove away ignoring me. EMAS went looking for them but could not found.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDZ1531T
Vehicle Make/Model/Colour	HYUNDAI TUCSON
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan Pg. 1

SKETCH PLAN

Veh A: SLL78954  
Veh B: SDZ15317

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.



Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 27.04.2019

1145 HRJ

 

Reporting Centre Personnel's Signature  
Name: Jessy Soe  
NRIC/FIN No.: G2081072W



> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9907A
Vehicle Details	
Vehicle No.:	SLL7895H
Vehicle to be Exported:	No
Intended Deregistration Date:	02 May 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	L15B4408293
Chassis No.:	RU11208292
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,816.00
Original Registration Date:	10 Mar 2017
First Registration Date:	10 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$9,816.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Mar 2027
PARF Rebate Amount:	\$7,362.00
Intended COE Rebate Details	
COE Expiry Date:	09 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,430.00
COE Rebate Amount:	\$38,813.00
<b>Total Rebate Amount:</b>	<b>\$46,175.00</b>

The information contained herein is correct as at 02 May 2019

OK

**Accord Auto Services Pte Ltd** (Co.Reg.No 201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point  
Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

INSURER:

**Sompo Insurance Singapore Pte. Ltd. (HQ)**

**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	26/04/2019
Policy No:	D19MTPV01003356	Date of Loss:	NO
Vehicle Reg. No.:	SLL7895H	Driveable?	UNKNOWN
Driver Age/Info:	21 / MALE	Party At Fault:	YES
TP Injury Involved?	NO	Third Party Involved?	+6597838360
Insured/Claimant:	PIRAGASAM S/O MUNISAMY	Contact No:	
Driver:	RAVEEN PIRAGASAM		

Make/Model:	HONDA VEZEL, 1.5 X CVT (A)	Vehicle Reg. Date:	10/03/2017
Vehicle Colour:	BLUE	Chassis No:	RU11208292
Engine No:	L15B4408293		
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	20

*part by part.  
Resurvey before paint  
surv take up own*

*Tanpin 97495749/6741813  
Not authorized  
Ex: to be advise.  
10 days*

Description of Accident/Loss

ON 26/04/2019 ABOUT 7.48PM, I WAS DRIVING ALONG AYE AROUND ALEXANDRA EXIT. CAR IN FRONT OF ME BRAKE TO A COMPLETE STOP, I FOLLOWED. HOWEVER MY CAR COULD NOT STOP IN TIME AND BUMP ONTO IS REAR. WE SUPPOSE TO EXCHANGE OUR PARTICULARS AT THE ROAD SHOULDER. BUT THE OTHER PARTY DROVE AWAY IGNORING ME. EMAS WENT LOOKING FOR THEM BUT COULD NOT FOUND.

Present Location:

ACCORD AUTO SERVICES PTE LTD (AV) TEL: 6271 7433

**COST OF CLAIMS**

Parts  
Miscellaneous Items  
Labour  
Paintwork Labour  
Towing

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

	Amount
	12,481.70
	383.00
	4,550.00
	0.00
	0.00
<b>Gross Total (S\$)</b>	<b>17,414.70</b>
<b>+ GST 7.00% (S\$)</b>	<b>1,219.03</b>
<b>Nett Amount (S\$)</b>	<b>18,633.73</b>

This claim is handled by: SOE JIE YI (JESSY)

# REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Apr 2019)  
 Parts: M1-SUV HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: Accord Auto Services Pte Ltd/SLL7895H/29/04/2019 16:23  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front windscreen glass	0.00	0.00	1,300.00 F
2	1		*Front windscreen glass moulding (top)	0.00	0.00	30.00 F
3	1		*Front windscreen glass moulding (lower)	0.00	0.00	30.00 F
4	1		*Front wiper garnish	0.00	0.00	135.00 F
5	1		*Bonnet	0.00	0.00	400.00 F
6	2		*Bonnet hinge	0.00	0.00	60.00 F
7	1		*Bonnet insulator pad	0.00	0.00	85.00 F
8	4		*Bonnet seal	0.00	0.00	72.00 F
9	1		*Bonnet lock	0.00	0.00	60.00 F
10	1		*Bonnet lock cable	0.00	0.00	25.00 F
11	1		*Bonnet stand	0.00	0.00	3.00 F
12	1		*Bonnet stand clip	0.00	0.00	50.00 F
13	2		*Horn	0.00	0.00	190.00 F
14	1		*Front grille	0.00	0.00	130.00 F
15	1		*Front grille outer garnish	0.00	0.00	35.00 F
16	1		*Front grille lower moulding	0.00	0.00	15.00 F
17	1		*Front grille logo	0.00	0.00	15.00 F
18	1		*Front grille upp center beam	0.00	0.00	10.00 F
19	1		*Front grille up RH beam	0.00	0.00	10.00 F
20	1		*Front grille up LH beam	0.00	0.00	800.00 F
21	1		*LH headlamp (LED)	0.00	0.00	20.00 F
22	1		*LH headlamp bracket	0.00	0.00	800.00 F
23	1		*RH headlamp (LED)	0.00	0.00	20.00 F
24	1		*RH headlamp bracket	0.00	0.00	190.00 F
25	1		*Front bumper	0.00	0.00	40.00 F
26	1		*Front bumper low grille	0.00	0.00	120.00 F
27	1		*Front bumper fog lamp (RH)	0.00	0.00	15.00 F
28	1		*Front bumper fog lamp cover (RH)	0.00	0.00	110.00 F
29	1		*Front bumper low lid	0.00	0.00	10.00 F
30	1		*Front bumper tow cover	0.00	0.00	24.00 F
31	2		*Front bumper air guide	0.00	0.00	180.00 F
32	1		*Front bumper reinforcement	0.00	0.00	30.00 F
33	2		*Front bumper reinforcement moulding	0.00	0.00	20.00 F
34	2		*Front bumper side retainer	0.00	0.00	280.00 F
35	1		*Support panel	0.00	0.00	38.00 F
36	1		*Support panel top garnish	0.00	0.00	170.00 F
37	1		*Front LH fender	0.00	0.00	170.00 F
38	1		*Front RH fender	0.00	0.00	55.00 F
39	1		*Front RH fender splash shield	0.00	0.00	35.00 F
40	1		*Front RH fender protector	0.00	0.00	300.00 F
41	1		*Air-con condenser assy	0.00	0.00	10.00 F
42	2		*Air-con condenser top bush	0.00	0.00	10.00 F
43	2		*Air-con condenser bottom bush	0.00	0.00	90.00 F
44	1		*Air-con suction hose	0.00	0.00	

The Repairer of the following:  
 • To remove damaged parts and re-secure  
 • To replace damaged parts and re-secure  
 • Parts prices are subject to confirmation  
 • The body work is on a Vehicle Preparation base  
 • No heavy modifications is allowed  
 • Subsequently items that are re-secured and  
 is subject to final approval from Insurance Company  
 Acknowledged by Repairer  
 Signature:  
 Date:

Accord Auto Services Pte Ltd/SLL7895H/29/04/2019 16:23. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

No.	Particulars	Repairer Estimates	%Disc	%Depr	Amount
	*Air-con discharge hose		0.00	0.00	<i>C</i> *110.00F
	*Air-con pipe (receiver)		0.00	0.00	<i>C</i> *90.00F
	*Air-con ambient sensor		0.00	0.00	<i>C</i> *25.00F
	*Air-con ambient sensor clip		0.00	0.00	<i>C</i> *10.00F
	*Radiator assy		0.00	0.00	<i>C</i> *700.00F
	*Radiator top bracket		0.00	0.00	<i>C</i> *30.00F
	*Radiator bottom bush		0.00	0.00	<i>C</i> *20.00F
	*Radiator top hose		0.00	0.00	<i>C</i> *15.00F
	*Radiator bottom hose		0.00	0.00	<i>C</i> *15.00F
	*Air-con fan cowling		0.00	0.00	<i>C</i> *60.00F
	*Air-con fan balde		0.00	0.00	<i>C</i> *35.00F
	*Air-con fan motor		0.00	0.00	<i>C</i> *150.00F
	*Radiator fan cowling		0.00	0.00	<i>C</i> *70.00F
	*Radiator fan blade		0.00	0.00	<i>C</i> *40.00F
	*Radiator fan motor		0.00	0.00	<i>C</i> *190.00F
	*Radiator spare tank		0.00	0.00	<i>C</i> *25.00F
	*Washer tank		0.00	0.00	<i>de</i> *45.00F
	*Washer tank neck		0.00	0.00	<i>de</i> *20.00F
	*Washer tank cover		0.00	0.00	<i>de</i> *10.00F
	*Washer tank motor		0.00	0.00	<i>de</i> *70.00F
	*Front LH air bag (passenger side)		0.00	0.00	<i>aut</i> *1,100.00F
	*Front RH air bag (driver side)		0.00	0.00	<i>aut</i> *720.00F
	*Front LH seat belt		0.00	0.00	<i>aut</i> *380.00F
	*Front RH seat belt		0.00	0.00	<i>aut</i> *380.00F
	*Airbag sensor		0.00	0.00	<i>aut</i> *90.00F
	*Steering angle sensor		0.00	0.00	<i>?</i> *130.00F
	*Dashbaord		0.00	0.00	<i>de</i> *600.00F
					<hr/>
		Sub Total (S\$)			11,347.00
		+ Margin on L,N Items 10.00% (S\$)			1,134.70
					<hr/>
		Total Parts (S\$)			12,481.70

rt.

Accord Auto Services Pte Ltd/SLL7895H/29/04/2019 16:23. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

4/29/2019

Repairer Estimates

Estimates on Miscellaneous Items

No Qty Particulars

Miscellaneous Items

1	1	Bonnet insulator pad clip
2	1	Front bumper clip
3	1	Front number plate with holder
4	1	Front RH fender protector clip
5	1	Front RH fender splash shield clip
6	1	Front windscreen glass sealant/gum
7	1	IU bracket sticker
8	1	Radiator coolant
9	1	Support panel top garnish clip

	30 ne	50.00
	ne / 20	50.00
	bt - 45	55.00
	ne	18.00
	ne / 10	50.00
	ne	80.00
	ne	10.00
	ne	40.00
	ne / 10	30.00
<b>Sub Total (\$\$)</b>		<b>383.00</b>

Estimates on Labour

No Particulars

Lab.Type Amount

Labour Items

1	Spray painting on all affected area.	New	800	900.00
2	Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	New	800	1,200.00
3	To check wiring system & light.	New	30	120.00
4	To remove and replace front windscreen glass.	New	120	150.00
5	To remove and replace air-con condenser, hoses, piping, fan assy & etc., vacuum and top up gas.	New	120	300.00
6	To remove and replace radiator, hoses, fan assy & etc..	New	100	250.00
7	To remove and replace front LH & RH airbag assy, airbag sensor, steering angle sensor.	New	200	350.00
8	To remove and replace front LH & RH seat belt.	New	100	300.00
9	To remove and replace dashboard.	New	180	380.00
10	To remain and adjust front main chassis.	New	200	300.00
11	Computer diagnostic	New	150	300.00
<b>Gross Labour Cost (\$\$)</b>				<b>4,550.00</b>

Accord Auto Services Pte Ltd/SLL7895H/29/04/2019 16:23. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

**Accord Auto Services Pte Ltd** (Co.Reg.No.201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point

Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

INSURER:

**Sompo Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D19MTPV01003356	Date of Loss:	26/04/2019
Vehicle Reg. No.:	<b>SLL7895H</b>	Driveable?	NO
Driver Age/Info:	21 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	PIRAGASAM S/O MUNISAMY	Contact No:	+6597838360
Driver:	RAVEEN PIRAGASAM		

Make/Model:	HONDA VEZEL, 1.5 X CVT (A)	Vehicle Reg. Date:	10/03/2017
Vehicle Colour:	BLUE		
Engine No:	L15B4408293	Chassis No:	RU11208292
Odometer:	0 KM		

Paint Type:	
Total Loss?	<b>NO</b>
Est. Duration of Repair (day)	20

*part by part.  
Reserving before paint  
sure the work*

*Tanpin 97495749/674184  
Not Authorise  
Ex: to be advise.  
10 days*

Description of Accident/Loss

ON 26/04/2019 ABOUT 7.48PM, I WAS DRIVING ALONG AYE AROUND ALEXANDRA EXIT. CAR IN FRONT OF ME BRAKE TO A COMPLETE STOP, I FOLLOWED. HOWEVER MY CAR COULD NOT STOP IN TIME AND BUMP ONTO IS REAR. WE SUPPOSE TO EXCHANGE OUR PARTICULARS AT THE ROAD SHOULDER. BUT THE OTHER PARTY DROVE AWAY IGNORING ME. EMAS WENT LOOKING FOR THEM BUT COULD NOT FOUND.

Present Location:

ACCORD AUTO SERVICES PTE LTD (AV) TEL: 6271 7433

**COST OF CLAIMS**

	<b>Amount</b>
Parts	12,481.70
Miscellaneous Items	383.00
Labour	4,550.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>17,414.70</b>
<b>+ GST 7.00% (S\$)</b>	<b>1,219.03</b>
<b>Nett Amount (S\$)</b>	<b>18,633.73</b>

This claim is handled by: **SOE JIE YI (JESSY)**

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
45	1		*Air-con discharge hose	0.00	0.00	*110.00 F
46	1		*Air-con pipe (receiver)	0.00	0.00	*90.00 F
47	1		*Air-con ambient sensor	0.00	0.00	*25.00 F
48	1		*Air-con ambient sensor clip	0.00	0.00	*10.00 F
49	1		*Radiator assy	0.00	0.00	*700.00 F
50	2		*Radiator top bracket	0.00	0.00	*30.00 F
51	2		*Radiator bottom bush	0.00	0.00	*20.00 F
52	1		*Radiator top hose	0.00	0.00	*15.00 F
53	1		*Radiator bottom hose	0.00	0.00	*15.00 F
54	1		*Air-con fan cowling	0.00	0.00	*60.00 F
55	1		*Air-con fan balde	0.00	0.00	*35.00 F
56	1		*Air-con fan motor	0.00	0.00	*150.00 F
57	1		*Radiator fan cowling	0.00	0.00	*70.00 F
58	1		*Radiator fan blade	0.00	0.00	*40.00 F
59	1		*Radiator fan motor	0.00	0.00	*190.00 F
60	1		*Radiator spare tank	0.00	0.00	*25.00 F
61	1		*Washer tank (\$40)	0.00	0.00	*45.00 F
62	1		*Washer tank neck (\$15)	0.00	0.00	*20.00 F
63	1		*Washer tank cover	0.00	0.00	*10.00 F
64	2		*Washer tank motor	0.00	0.00	*70.00 F
65	1		*Front LH air bag (passenger side)	0.00	0.00	*1,100.00 F
66	1		*Front RH air bag (driver side)	0.00	0.00	*720.00 F
67	1		*Front LH seat belt	0.00	0.00	*380.00 F
68	1		*Front RH seat belt	0.00	0.00	*380.00 F
69	1		*Airbag sensor	0.00	0.00	*90.00 F
70	1		*Steering angle sensor	0.00	0.00	*130.00 F
71	1		*Dashbaord	0.00	0.00	*600.00 F

F=Franchise part.

Sub Total (\$\$)	11,347.00
+ Margin on L,N Items 10.00% (\$\$)	1,134.70
<b>Total Parts (\$\$)</b>	<b>12,481.70</b>

Accord Auto Services Pte Ltd/SLL7895H/29/04/2019 16:23. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

Total \$3270

## Supply Est

- |  |                                    |
|--|------------------------------------|
| 1) Bumper Grille moulding Chrome \$35        | 14) Nozzle Hose \$10               |
| 2) Front LH Fender wheel Arch \$50           | 15) Front RH Fender Enclosure \$15 |
| 3) Tube (from manifold) \$15                 | 16) Intake Manifold \$260          |
| 4) Cover Relay Block upper \$5               |                                    |
| 5) Millimeter Wave Radar \$1850              |                                    |
| 6) Radar Bracket \$480                       |                                    |
| 7) Radiator Side Air Guide RH \$20           |                                    |
| 8) Radiator Side Air Guide LH \$28           |                                    |
| 9) Lock Cover (Top Garnish) \$40             |                                    |
| 10) Air Intake duct \$40                     |                                    |
| 11) Air Intake Tube \$40                     |                                    |
| 12) Filter Cover Lower \$95                  |                                    |
| 13) Windscreen Moulding Side LH & RH \$20 x2 |                                    |

**Accord Auto Services Pte Ltd** (Co.Reg.No.201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point  
Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

**INSURER: Sompoo Insurance Singapore Pte. Ltd. (HQ)**

**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D19MTPV01003356	Date of Loss:	26/04/2019
Vehicle Reg. No.:	<b>SLL7895H</b>	Driveable?	NO
Driver Age/Info:	21 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	PIRAGASAM S/O MUNISAMY	Contact No:	+6597838360
Driver:	RAVEEN PIRAGASAM		

Make/Model:	HONDA VEZEL, 1.5 X CVT (A)	Vehicle Reg. Date:	10/03/2017
Vehicle Colour:	BLUE		
Engine No:	L15B4408293	Chassis No:	RU11208292
Odometer:	0 KM		

Paint Type:  
Total Loss? **NO**  
Est. Duration of Repair (day) 20

*Handwritten notes:*  
 Part by part - Resurvey before paint sure take care w.u.  
 Tauplin 97495749/67418134  
 Not authorized Ex: to be advise 10 days

Description of Accident/Loss

ON 26/04/2019 ABOUT 7.48PM, I WAS DRIVING ALONG AYE AROUND ALEXANDRA EXIT. CAR IN FRONT OF ME BRAKE TO A COMPLETE STOP, I FOLLOWED. HOWEVER MY CAR COULD NOT STOP IN TIME AND BUMP ONTO IS REAR. WE SUPPOSE TO EXCHANGE OUR PARTICULARS AT THE ROAD SHOULDER. BUT THE OTHER PARTY DROVE AWAY IGNORING ME. EMAS WENT LOOKING FOR THEM BUT COULD NOT FOUND.

Present Location: ACCORD AUTO SERVICES PTE LTD (AV) TEL: 6271 7433

**COST OF CLAIMS**

	<b>Amount</b>
Parts	12,481.70
Miscellaneous Items	383.00
Labour	4,550.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>17,414.70</b>
<b>+ GST 7.00% (S\$)</b>	<b>1,219.03</b>
<b>Nett Amount (S\$)</b>	<b>18,633.73</b>

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

This claim is handled by: **SOE JIE YI (JESSY)**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
45	1		*Air-con discharge hose	0.00	0.00	? *110.00 F
46	1		*Air-con pipe (receiver)	0.00	0.00	? *90.00 F
47	1		*Air-con ambient sensor	0.00	0.00	? *25.00 F
48	1		*Air-con ambient sensor clip	0.00	0.00	? *10.00 F
49	1		*Radiator assy	0.00	0.00	bt *700.00 F ✓
50	2		*Radiator top bracket	0.00	0.00	bt *30.00 F ✓
51	2		*Radiator bottom bush	0.00	0.00	? *20.00 F
52	1		*Radiator top hose	0.00	0.00	? *15.00 F
53	1		*Radiator bottom hose	0.00	0.00	? *15.00 F
54	1		*Air-con fan cowling	0.00	0.00	? com *60.00 F ✓
55	1		*Air-con fan balde	0.00	0.00	? *35.00 Fx ✓
56	1		*Air-con fan motor	0.00	0.00	? *150.00 F ✓
57	1		*Radiator fan cowling	0.00	0.00	? *70.00 F ✓
58	1		*Radiator fan blade	0.00	0.00	? *40.00 F xun ✓
59	1		*Radiator fan motor	0.00	0.00	? *190.00 F ✓
60	1		*Radiator spare tank	0.00	55	dev *25.00 F ✓
61	1		*Washer tank	0.00	40	de *45.00 F ✓
62	1		*Washer tank neck	0.00	15	de *20.00 F ✓
63	1		*Washer tank cover	0.00	0.00	deis *10.00 F ✓
64	2		*Washer tank motor	0.00	0.00	xun *70.00 F ✓
65	1		*Front LH air bag (passenger side)	0.00	0.00	act *1,100.00 F ✓
66	1		*Front RH air bag (driver side)	0.00	0.00	act *720.00 F ✓
67	1		*Front LH seat belt	0.00	0.00	act *380.00 F ✓
68	1		*Front RH seat belt	0.00	0.00	act *380.00 F ✓
69	1		*Airbag sensor	0.00	0.00	act *90.00 F ✓
70	1		*Steering angle sensor	0.00	70	act *130.00 F ✓
71	1		*Dashbaord	0.00	0.00	de *600.00 F ✓

F=Franchise part.

<b>Sub Total (S\$)</b>	<b>11,347.00</b>
<b>+ Margin on L,N Items 10.00% (S\$)</b>	<b>1,134.70</b>
<b>Total Parts (S\$)</b>	<b>12,481.70</b>

Accord Auto Services Pte Ltd/SLL7895H/29/04/2019 16:23. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

**(SUPPLEMENTARY)**

**INSURER: Somp Insurance Singapore Pte. Ltd. (HQ)**

**PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	D19MTPV01003356	Date of Loss:	26/04/2019
Vehicle Reg. No.:	SLL7895H	Driveable?	NO
Driver Age/Info:	21 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	PIRAGASAM S/O MUNISAMY	Contact No:	+6597838360
Driver:	RAVEEN PIRAGASAM		
<hr/>			
Make/Model:	HONDA VEZEL, 1.5 X CVT (A)	Vehicle Reg. Date:	10/03/2017
Vehicle Colour:	Blue		
Engine No:	L15B4408293	Chassis No:	RU11208292
Odometer:	0 KM		

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) 20

Description of Accident/Loss ON 26/04/2019 ABOUT 7.48PM, I WAS DRIVING ALONG AYE AROUND ALEXANDRA EXIT. CAR IN FRONT OF ME BRAKE TO A COMPLETE STOP, I FOLLOWED. HOWEVER MY CAR COULD NOT STOP IN TIME AND BUMP ONTO IS REAR. WE SUPPOSE TO EXCHANGE OUR PARTICULARS AT THE ROAD SHOULDER. BUT THE OTHER PARTY DROVE AWAY IGNORING ME. EMAS WENT LOOKING FOR THEM BUT COULD NOT FOUND.

Present Location: ACCORD AUTO SERVICES PTE LTD (AV) TEL: 6271 7433

COST OF CLAIMS	Amount
Parts	3,325.30
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
	<b>Gross Total (S\$) 3,325.30</b>
	<b>+ GST 7.00% (S\$) 232.77</b>
	<b>Nett Amount (S\$) 3,558.07</b>
	<b>+ Previous Estimates (S\$) 18,633.73</b>
	<b>Claim Total (S\$) 22,191.80</b>

# REPAIR DETAILS

## Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 13 May 2019)  
**Parts:** M1-SUV      HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** Accord Auto Services Pte Ltd/SLL7895H/13/05/2019 20:07  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER GRILLE MOULDING CHROME / MIS	0.00	0.00	*35.00 F ✓ A
2	1		*FRONT LH FENDER WHEEL ARCH / RR	0.00	0.00	*50.00 F ✓ A
3	1		*MANIFOLD TUBE / TN	0.00	0.00	*15.00 F ✓ A
4	1		*MANIFOLD / RR	0.00	0.00	*260.00 F ✓ A
5	1		*COVER RELAY BLOCK UPPER / RR	0.00	0.00	*5.00 F ✓ A
6	1		*MILLIMETER WAVE RADAR / RR	0.00	0.00	*1,850.00 F ✓ A
7	1		*MILLIMETER WAVE RADAR RACKET / OT	0.00	0.00	*480.00 F ✓ A
8	1		*RADIATOR SIDE AIR GUIDE RH / CRV	0.00	0.00	*20.00 F ✓ A
9	1		*RADIATOR SIDE AIR GUIDE LH / CRV	0.00	0.00	*28.00 F ✓ A
10	1		*LOCK COVER / MIS	0.00	0.00	*40.00 F ✓ A
11	1		*AIR INTAKE DUCT / CRV	0.00	0.00	*40.00 F ✓ A
12	1		*AIR INTAKE TUBE / CRV	0.00	0.00	*40.00 F ✓ A
13	1		*FILTER COVER LOWER / RR	0.00	0.00	*95.00 F ✓ A
14	2		*WINDSCREEN MOULDING SIDE LH & RH / A12C	0.00	0.00	*40.00 F ✓ A
15	1		*TOP RH NOZZLE HOSE / TN	0.00	0.00	*10.00 F ✓ A
16	1		*FRONT RH FENDER ENCLOSURE / RR	0.00	0.00	*15.00 F ✓ A

F=Franchise part.

Sub Total (S\$)      **3,023.00**  
 + Margin on L,N Items 10.00% (S\$)      302.30  


---

**Total Parts (S\$)      3,325.30**

Accord Auto Services Pte Ltd/SLL7895H/13/05/2019 20:07. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

*Steve*      14/5/19

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

There are no labour items selected.

**Accord Auto Services Pte Ltd/SLL7895H/13/05/2019 20:07. Not valid without Reference section.**  
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >