

Assigned To: Mr Lim chin lee ying
 Assignment (Police): AIG
 Date/Time: 29/4/198 10:21am
 Estimated Cost: Bill for
 O.D. / T.WS / T.P. RES / O.D. RES / E.V.A / I.N.V / M.Y.T.C.S
 To Inspect Vehicle No: SDA 7777 T
 at Workshop of: Motor Intel
 of: 13 Kaki Bukit Rd 4 #01-20
 Policy No: Claim No: 305440348186
 Sum Insured: Excess:
 Make of Veh: D.O.A
 (Client's Record): 25/4/2019

CA / REV / REP / REV 24 HRS
 Date/Time: 12:41pm 29/4/19 Person Contacted: Wilson
 H.O.D. Endorsement: Vehicle: ☒ IN / ☐ OUT

Date/Time	Action/Instruction (X) Estimate	
	SDA 7777T-CC4/ 6023394/R106392	DOA: 1/12/16
	SL2972R-X	
	Dismantle: 2/5/2019	

ASSIGNMENT

PRS

From: Date: 30/4/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDA 7777T

at Workshop m/s Motor Intel

of 13 Kalki Bkt Road 4 #01-20

Insured: Bartley Biz Centre

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SDA 7777T Yr Regn: 28/7/2017

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Peugeot 508 1.6 c.c. 1560

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 48099 T/Radio: Insured / Std / NI / NA

Eng/No: 10JBHX3021062

C/No: VF38DBHXTGL045253

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55/17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 25/4/19 D.O.I. 30/4/19

Survey held at Motor Intel

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range 4,000/- = 5,000/-
	MV 85,000/2
	PV 47,711/2
	NV 37,289/2
	2/5/2019
	TCRM hit 2/5/50

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: DAR

Lump Sum / I.B.I: (\$)

180

10

190

Your password will expire in 14 days. [Click here to change it.](#)

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 29/4/2019 10:21:16 AM
Attachments:  tmp440D.TIF

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: bonnie kwok [mailto:litigation@bonniekwok.com]
Sent: Friday, April 26, 2019 11:42 AM
To: Hor, Yinrul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Sales MIA
Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLZ972R AND SDA7777T ON 25/04/2019

This message is from an external sender; be cautious with links and attachments.

Dear Sirs,

Our client disagrees to your proposed surveyor.

We have been instructed to propose the following list of surveyors for the Single Joint Expert:-

1. Andrew How
2. S. Kumanam
3. Alan Cheong
4. Lim Yong Tian
5. Fong Kok Heng Stanley
6. Lawrence Ng Chun Kee
7. Ng Kong Beng Patrick

8. Sim Siak Tong
9. Tan Chin Suan
10. Matthew Ng

Kindly contact Mr. Wilson at 88383318 or Mr. Daniel at 93858911 of the repairers, Motor Intelligence Automo Pte. Ltd. for pre-repair inspection arrangements.

Regards,
Ms. Tan

--

BONNIE KWOK LLC

Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Fri, 26 Apr 2019 at 11:05, Hor, Yinrul <Yinrul.Hor@aig.com> wrote:



This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้เปิด
ไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려
면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya,
membuka attachment.

[Click here](#) by 2019-05-03 11:05 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the
addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights
reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not
use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply"
command and permanently delete the original and any copies or printouts thereof. Although this email and any
attachments are believed to be free of any virus or other defect that might affect any computer system into which it is
received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is
accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or
damage arising in any way from its use.

BONNIE KWOK LLC*Advocates & Solicitors*

101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358

Tel : (65) 6536 6026
Fax : (65) 6536 2279
[Not for service of court documents]
GST Reg No. 2012035472

Your Vehicle: SLZ 972 R
Our Vehicle: MIA-SDA 7777 T

Date : 26 April 2019

M/s AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#07-16 AIG Building
Singapore 079120

By Fax 6835 7416 only

Dear Sirs,

ACCIDENT INVOLVING SDA 7777 T & SLZ 972 R ON 25 APRIL 2019

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle **SDA 7777 T** at M/s Motor Intelligence Automo Pte. Ltd., No. 13 Kaki Bukit Road 4 #01-20 Bartley Biz Centre Singapore 417807.

Your faithfully


BONNIE KWOK
c.c. Client

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0919A
Vehicle Details	
Vehicle No.:	SDA7777T
Vehicle to be Exported:	No
Intended Deregistration Date:	02 May 2019
Vehicle Make:	PEUGEOT
Vehicle Model:	508 ALLURE 1.6 BLUEHDI EAT6
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	10JBHX3021062
Chassis No.:	VF38DBHXTGL045253
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$27,363.00
Original Registration Date:	28 Jul 2017
First Registration Date:	28 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$15,309.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jul 2027
PARF Rebate Amount:	\$11,481.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jul 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$44,002.00
COE Rebate Amount:	\$36,230.00
Total Rebate Amount:	\$47,711.00


The information contained herein is correct as at 02 May 2019

OK

MV 85,000/2
PV 47,711/2
NV 37,289/2


2/5/19

CHEAPEST CAR
INSURANCE RENEWAL



Choice of
\$0 excess



Option of any
workshop

GET A CHEAPER QUOTE NOW!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Coe Renewal Toyota Vios 1.5A



2.98%P.A \$0 Admin Fees@GV
Finance, 2 Years Warranty, \$1500
Down Monthly From \$448
GV Credit Pte Ltd StarAd



Browse by Category ▼

Sort by Date Posted ▼

20 results/page ▼

1 vehicles

Peugeot 508

Advanced Search 🔍

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Peugeot 508		Any	Any	2017	Any	Any	Any	All
	Peugeot 508 1.6A Turbo Allure Plus		\$86,800	\$8,940 /yr	22-Aug-2017	1,598 cc	43,200 km	Luxury	Available
10% Downpayment Available! Agent Unit. 5 Years Warranty Intact. Well Taken Care Of. Own With A Peace Of Mind From Vantage Pre-owned, A Member Of The Sime Darby Group. An Additional Peace Of Mind With ...									
Vantage Pre-Owned									
Posted: 01-May-2019 Tags: 2017 Peugeot 508, 2017 peugeot 508, Peugeot 508, peugeot 508, Peugeot, 508, Used Peugeot									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Peugeot, Peugeot Singapore, used Peugeot Singapore, used Peugeot, used vehicles Singapore or even buy used Peugeot Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	25/04/2019 17:03
Date Of Accident	25/04/2019 06:30
Exact Location Of Accident	TWIN FOUNTAINS BASEMENT CARPARK
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SDA7777T
Insured/Policyholder	
Name Of Registered Owner	YEO SONG MENG
NRIC No	S1650919A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97331989
Alternative Phone No	OTHERS-97331989
Vehicle Particulars	
Manufacturer	PEUGEOT
Model	508 ALLURE 1.6 BLUEHDI EAT6
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD17V09773/VPC2/R00
Cover Note Number	
Driver	
Name of Driver	YEO SONG MENG
NRIC No	S1650919A
Date Of Birth	02/06/1964
Occupation	INDOOR
Date Of Driving Pass	20/10/2014
Driving Experience	4 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97331989
Fax Number	
Contact Number	OTHERS-97331989
Email Address	NOEMAIL

Address	11A WOODLANDS AVENUE 06 #13-06 TWIN FOUNTAINS
Postcode	738993
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : YEO ZHI LONG GENDER: : MALE
Passenger 2	NAME: : YEO ZHI LIN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN:

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLZ972R
Vehicle Make/Model/Colour	NISSAN NOTE 1.2 CVT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


25 APR 2019


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If Driver is not the policyholder)
 Date & Time:

IDAC KAKI BUKIT (VAC)
 23 KAKI BUKIT AVE 4
 Singapore 415913
 Reporting Centre
 Name: Tel: 67416697
 NRIC/FIN No.: Fax: 67492305
 Email: vackb@singnet.com.sg

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving at TWIN FOUNTAINS Basement Carpark suddenly I got a impact from my left so I stopped my vehicle and alighted and saw vehicle B which parking at the parking lot move out and collided onto my left portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
Policyholder's Signature
Date & Time:

[Signature]
Driver's Signature
(If driver is not the policyholder)
Date & Time:

25 APR 2019

IDAC KAKI BUKIT (VAC),
23 KAKI BUKIT AVE 4

Reporting Centre Singapore 435033
Name: Tel: 67416697
NRIC/FIN No.: Fax: 67492305
Email: vackb@singnet.com.sg

MOTORCAR (Rear)

Rear Portion

Vehicle No: SDA 7777T

NAC	INC	Item	CON	AC	Qb
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower	DL	✓	
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	LH	BU	✓
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	LH	CRA	✓
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	UT	✓	2
1159	993327	Rear End Panel	DD	R	
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	CRA	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qt
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender	DD	R	
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille	LH	CRA	✓
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items: 8

Assessor: JG

2/5/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Apr 2019 Edit Reg		29 Apr 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

























Main		Reference		Claim Details		Documents		Show All	
CLAIM SUBFOLDER DETAILS								[Created by adjuster]	
Insured:	LIM MING YONG (LIN MING YONG), ID: S8743111H								
Main Claimant:	-								
Vehicle Reg. No.:	SDA7777T			Date of Loss:	25/04/2019 00:00 - :59 [20 Months and 28 Days From LTA Reg Date (Man Yr)]				
Claim Type:	TP / 3054403481SG			Policy/Cover Note No.:	(Comprehensive)				
Vehicle Reg. No. (Insured):	SLZ972R			Policy No. (Claimant):					
				Excess:					
Repairer:	Motor Intelligence Automo Pte Ltd (HQ) 13 KAKI BUKIT ROAD 4, #01-20 BARTLEY BIZ CENTRE, 417807 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 09/05/2019]								
Claimant's Solicitor:	BONNIE KWOK LLC - Tel: 65366026								
ASSOCIATED MAIL RECEIVED								View All Compose Case Mail	
<ul style="list-style-type: none"> AIG_SG (30/04/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS								View All Search Tasks Create New Task Complete	
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SDA7777T (3054403481SG)**
[SLZ972R]
TP
-

Apr 25 2019 12:00AM
[LIM MING YONG (LIN MING YONG)]
Motor Intelligence Automo Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser		v
Photos/Images															3 per page		v	✓	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print		
1	10/05/19 12:45	General View													i	Load JPG	✓		
2	10/05/19 12:45	General View													i	Load JPG	✓		
3	10/05/19 12:45	General View													i	Load JPG	✓		
4	10/05/19 12:45	General View													i	Load JPG	✓		
5	10/05/19 12:45	General View													i	Load JPG	✓		
6	10/05/19 12:45	General View													i	Load JPG	✓		
7	10/05/19 12:45	General View													i	Load JPG	✓		
8	10/05/19 12:45	General View													i	Load JPG	✓		
9	10/05/19 12:45	General View													i	Load JPG	✓		
10	10/05/19 12:45	General View													i	Load JPG	✓		
11	10/05/19 12:45	General View													i	Load JPG	✓		
12	10/05/19 12:45	General View													i	Load JPG	✓		
13	10/05/19 12:45	General View													i	Load JPG	✓		
14	10/05/19 12:45	General View													i	Load JPG	✓		
15	10/05/19 12:45	General View													i	Load JPG	✓		
16	10/05/19 12:45	General View													i	Load JPG	✓		
17	10/05/19 12:45	General View													i	Load JPG	✓		
18	10/05/19 12:45	General View													i	Load JPG	✓		
19	10/05/19 12:45	General View													i	Load JPG	✓		
20	10/05/19 12:45	General View													i	Load JPG	✓		
21	10/05/19 12:45	General View													i	Load JPG	✓		
22	10/05/19 12:45	General View													i	Load JPG	✓		
23	10/05/19 12:45	Photographs of Damaged Parts													i	Load JPG	✓		
24	10/05/19 12:45	Photographs of Damaged Parts													i	Load JPG	✓		
25	10/05/19 12:45	Photographs of Damaged Parts													i	Load JPG	✓		
26	10/05/19 12:45	Photographs of Damaged Parts													i	Load JPG	✓		
27	10/05/19 12:45	Photographs of Damaged Parts													i	Load JPG	✓		
28	10/05/19 12:45	Photographs of Damaged Parts													i	Load JPG	✓		
29	10/05/19 12:45	Photographs of Damaged Parts													i	Load JPG	✓		
30	10/05/19 12:45	Photographs of Damaged Parts													i	Load JPG	✓		
31	10/05/19 12:45	Photographs of Damaged Parts													i	Load JPG	✓		
32	10/05/19 12:45	Photographs of Damaged Parts													i	Load JPG	✓		
33	10/05/19 12:45	Photographs of Damaged Parts													i	Load JPG	✓		
34	10/05/19 12:45	Photographs of Damaged Parts													i	Load JPG	✓		
35	10/05/19 12:45	Photographs of Damaged Parts													i	Load JPG	✓		
36	10/05/19 12:45	Photographs of Damaged Parts													i	Load JPG	✓		
37	10/05/19 12:45	Photographs of Damaged Parts													i	Load JPG	✓		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	10/05/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	10/05/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	10/05/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	10/05/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	10/05/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	10/05/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	10/05/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	10/05/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	10/05/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	10/05/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	10/05/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	10/05/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	10/05/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	10/05/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	10/05/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	10/05/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	10/05/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	10/05/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	10/05/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	10/05/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	10/05/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	10/05/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	10/05/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	30/04/19 09:48	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19007513/BCD3E2

Date: 27/05/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SDA7777T

Insured Vehicle No : SLZ972R

Date of Loss: 25/04/2019

Nature of Claim: TP

Claim No: 3054403481SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDA7777T

Make & Model: PEUGEOT 508, 1.6 Turbo (A)

Engine No: 10JBHX3021062

Reg. Date: 28/07/2017 (Man. Year: 2016)

Chassis No: VF38DBHZTGL045253

Colour: White

Odometer: 48099 km

Engine Capacity: 1560 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/04/2019

Date Inspected: 30/04/2019 Inspected At:

Motor Intelligence Automo Pte Ltd (HQ)
13 KAKI BUKIT ROAD 4, #01-20
BARTLEY BIZ CENTRE
Singapore 417807

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER LOWER	Dislodged	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR BUMPER SIDE RETAINER LH	Distorted	0.00 F	*- F
5	1		*REAR BUMPER REFLECTOR LH	Cracked	0.00 F	*- F
6	2		*REVERSE SENSOR	Cut	0.00 F	*- F
7	1		*REAR END PANEL	Repair	0.00 F	*- F
8	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
9	1		*REAR LH FENDER	Repair	0.00 F	*- F
10	1		*REAR FENDER AIR GRILLE LH	Cracked	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >