

REC. BY:

REF: CS/MSG190075181 Jg d3

Special Instruction:

By: Winnie JieASSIGNMENT (Office)From (Person): Monica Chung Rizun of MSGDate/Time: 29.4.19 16:41 PM

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PC746BInsured: XE 3188Lat Workshop m/s Connect 3Tel: 98509666of 566 Woodland RoadPolicy No: 27918707MCCClaim No: 591949

Sum Insured: _____

Excess: _____

Make of Veh:

(Client's Record)

D.O.A. 27.4.201930.4.2019 (mor)

CA / REV / REP. / REV 24 HRS

"mwp"

H.O.D. Endorsement: _____

Date/Time: 29.4.19 5:28 pmPerson Contacted: Winnie ChaiVehicle IN/OUT

Date/Time	Action/Instruction	Estimate
	PC746B-X	
	XE 3188L-X	
03/05/19 @	10.07am revised to Monica Chung via Meimien.	

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Apr 2019 13:48		29 Apr 2019 16:41 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	SNL LOGISTICS PTE LTD, Co. Reg. No.: 199407022Z								
Main Claimant:	LAM HO TRANSPORT PTE LTD, Co. Reg. No.: 201112769N								
Vehicle Reg. No.:	PC746B	Date of Loss: 27/04/2019 00:00 - :59 [93 Months and 5 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP	Policy/Cover Note No.: 2791B707MKC Coverage: 17/06/2018 - 16/06/2019							
Vehicle Reg. No. (Insured):	XE3188L	Policy No. (Claimant): Excess:							
Repairer:	Connect3 (HQ) 566 Woodlands Road, 728697 Woodlands - Tel: 98509666								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/04/2019]								
Driver/Custodian (Insured):	WANG ZHIHONG (), NRIC: G2259472P Email:								
Adj Asp. Remarks:	LIABILITY:DISPUTE (OI NON-REPORTING) CONTACT: WINNIE CHAI 9850 9666, Car in 30/04/19. Please survey by morning. Tks.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 03 May 2019

Preliminary Advice

Insured Vehicle No	: XE3188L	Accident Date	: 27/04/2019
TP Vehicle No	: PC746B	Assignment Date	: 29/04/2019
Make	: GOLDEN DRAGON XML6957J14	Est. Duration of Repair	: 7.00
Date of Inspection	: 30/04/2019		
Inspection At	: CONNECT3 (HQ) 566 WOODLANDS ROAD SINGAPORE 728697		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,978.00
Revised Amount	:S\$	14,128.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	14,128.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2769N
Vehicle Details	
Vehicle No.:	PC746B
Vehicle to be Exported:	No
Intended Deregistration Date:	02 May 2019
Vehicle Make:	GOLDEN DRAGON
Vehicle Model:	XML6957J14
Primary Colour:	Multi-Colour
Manufacturing Year:	2011
Engine No.:	ISBE422521984673
Chassis No.:	LL3BECDH2BA011468
Maximum Power Output:	-
Open Market Value:	\$84,797.00
Original Registration Date:	22 Jul 2011
First Registration Date:	22 Jul 2011
Transfer Count:	0
Actual ARF Paid:	\$4,240.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jul 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$31,089.00
COE Rebate Amount:	\$6,894.00
Total Rebate Amount:	\$6,894.00

The information contained herein is correct as at 02 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/04/2019 13:32
Date Of Accident	27/04/2019 08:30
Exact Location Of Accident	AT FOURTH CHIN BEE RD CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC746B
Insured/Policyholder	
Name Of Registered Owner	LAM HO TRANSPORT PTE LTD
Co Reg No	201112769N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98381418
Vehicle Particulars	
Manufacturer	GOLDEN DRAGON
Model	XML6957J14
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5072530758-04
Cover Note Number	
Driver	
Name of Driver	WEE CHIANG HOCK
NRIC No	S2666010F
Date Of Birth	09/03/1962
Occupation	OUTDOOR
Date Of Driving Pass	17/09/2012
Driving Experience	6 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93884131
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	APT BLK 447 JURONG WEST ST 42 #05-284
Postcode	640447
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE3188L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed.
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/ID No.:

Accident Sketch Plan Pg. 1

PRELIMINARY

R: PC 746B
R: XE3188L

* pls ref to attached sketch *

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27/04/2019 @ 08:30hrs, I was driving my car PC 746B into Fourth
 Chin Bee Road Carpark intend to park my car. While I was driving
 straight, a lorry XE3188L suddenly reversed out from the lot & hit
 onto my car LH pylon while I was driving past.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan Pg. 1



Acc
 was getting home
 5-20-2019

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697
 Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1
 GST:53360061L

QT19/PC746B/TPC-455

MSIG Insurance (Singapore) Pte Ltd
 4 Shenton Way
 #21-01
 SGX Centre 2
 Singapore 068807

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

[Handwritten Signature]
 3/5/19

QUOTATION

Hwee Jie - LKK
 30/4/19
 L/S 7 days

Dear Sir,
 Cost of Repair to Vehicle PC746B

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Front LH reflector lamp assy <i>CRA</i>	1	118.00	118.00 ✓
2.	Front LH entrance door rubber moulding <i>rel</i>	1	680.00	550 680.00 ✓
3.	Front LH entrance door <i>BUC</i>	1	2,550.00	2000 2,550.00 ✓
4.	Front LH fuel compartment cover <i>BUC</i>	1	1,300.00	1,300.00 ✓
5.	LH compartment cover <i>BUC</i>	2	1500 1,850.00	3000 3,700.00 ✓
6.	LH compartment cover outer handle <i>Om</i>	1	250.00	200 250.00 ✓
7.	Front LH wheel cover <i>CRA</i>	1	1,650.00	1350 1,650.00 ✓
8.	Front LH wheel cover hinge <i>BT</i>	2	185.00	370.00 ✓
9.	Front LH wheel mud flap <i>DEF</i>	1	650.00	650.00 ✓
10.	Check wiring	1	30.00	30.00 ✓
11.	Sealant	2	40.00	80.00 ✓ <i>rel</i>
12.	Labour to transfer door fittings	1	300.00	300.00 50
13.	Labour charges	1	1,500.00	1,500.00 1200
14.	Spray painting	1	1,800.00	1,800.00 1500
			SUB-TOTAL	S\$14,978.00

10% Discount on parts

Total - \$9100/-

- Price before 7% gst

Thank you.

Yours faithfully,



Winnie Chai
HP: 9850-9666

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Apr 2019 13:48		29 Apr 2019 16:41 Edit Adj Rpt	S\$9,100.00 Edit Estimates	S\$9,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	SNL LOGISTICS PTE LTD, Co. Reg. No.: 1994070222								
Main Claimant:	LAM HO TRANSPORT PTE LTD, Co. Reg. No.: 201112769N								
Vehicle Reg. No.:	PC746B	Date of Loss:	27/04/2019 08:00 - :59 [93 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 591949	Policy/Cover Note No.:	27918707 (Comprehensive) Coverage: 17/06/2018 - 16/06/2019						
Vehicle Reg. No. (Insured):	XE3188L	Policy No. (Claimant):							
		Excess:							
Repairer:	Connect3 (HQ) 566 Woodlands Road, 728697 Woodlands - Tel: 98509666								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 29/05/2019]								
Driver/Custodian (Insured):	WANG ZHIHONG (), NRIC: G2259472P Email:								
Adj Asg. Remarks:	LIABILITY:DISPUTE (OI NON-REPORTING) CONTACT: WINNIE CHAI 9850 9666. Car in 30/04/19. Please survey by morning. Tks.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*PC746B (591949)
[XE3188L]
TP
LAM HO TRANSPORT PTE LTD
Apr 27 2019 8:00AM
[SNL LOGISTICS PTE LTD]
Connect3

Upload Documents Upload Photos Compose New Letter			View <input type="button" value="View in Browser"/>
Assessment Reports			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	03/05/19 10:07	Adjuster Immediate Advice	 Load HTM <input checked="" type="checkbox"/>
Photos/Images			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
2	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
3	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
4	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
5	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
6	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
7	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
8	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
9	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
10	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
11	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
12	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
13	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
14	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
15	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
16	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
17	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
18	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
19	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
20	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
21	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
22	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
23	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
24	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
25	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
26	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
27	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
28	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
29	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
30	02/05/19 09:30	General View	 Load JPG <input checked="" type="checkbox"/>
31	10/05/19 08:48	Photo After Spray	 Load JPG <input checked="" type="checkbox"/>
32	10/05/19 08:48	Photo After Spray	 Load JPG <input checked="" type="checkbox"/>
33	10/05/19 08:48	Photo After Spray	 Load JPG <input checked="" type="checkbox"/>
34	10/05/19 08:48	Photo After Spray	 Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	10/05/19 08:48	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
36	10/05/19 08:48	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
37	10/05/19 08:48	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/04/19 13:50	Estimate (1)	 Load JPG	<input checked="" type="checkbox"/>
2	29/04/19 13:50	Estimate (2)	 Load JPG	<input checked="" type="checkbox"/>
3	29/04/19 13:51	TP GIA Sketch 3	 Load JPG	<input checked="" type="checkbox"/>
4	29/04/19 13:51	TP GIA Sketch 2	 Load JPG	<input checked="" type="checkbox"/>
5	29/04/19 13:51	TP GIA Sketch 1	 Load PDF	
6	29/04/19 13:56	EMAIL FROM TP TO ARRANGE FOR SURVEY	 Load PDF	
7	29/04/19 14:23	PC746B TP E-FILE REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19007518/JQD3Q2
Date: 17/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 27918707
Claimant Vehicle No : PC746B	Insured Vehicle No : XE3188L
Date of Loss: 27/04/2019	Nature of Claim: TP Claim No: 591949

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PC746B	Engine No: ISBE422521984673
Make & Model: GOLDEN DRAGON XML6957J14, 6.7 D (A)	Chassis No: LL3BECDH2BA011468
Reg. Date: 22/07/2011 (Man. Year: 2011)	Odometer: 283079 km
Colour: Multi-colour	
Engine Capacity: 6893 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/80 R22.5	Rear Tyre Size: 275/80 R22.5 (D)
Front Left Side: Bridgestone 7 mm	Rear Left Side: Bridgestone 7/7 mm
Front Right Side: Bridgestone 7 mm	Rear Right Side: Bridgestone 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,348.00	8,664.20	2,683.80	23.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,630.00	2,780.00	850.00	23.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,978.00	11,444.20	3,533.80	23.59
Approved Total (Overridden) (S\$)		9,100.00		
Nett Amount (S\$)	14,978.00	9,100.00	5,878.00	39.24

INSPECTION

Date of Assignment: 29/04/2019	Inspected At: Connect3 (HQ)
Date Inspected: 30/04/2019	566 Woodlands Road
	Singapore 728697
Estimated Period of Repair: 7.0 days	

Adjuster: ONG HWEE JIE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 17 May 2019)	
Parts:	N/A	GOLDEN DRAGON XML6957J14 6.7 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC746B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH REFLECTOR LAMP ASSY	Cracked	118.00 F	*118.00 FL
2	1		*FRONT LH ENTRANCE DOOR RUBBER MOULDING	Necessary	680.00 F	*550.00 FL
3	1		*FRONT LH ENTRANCE DOOR	Buckled	2,550.00 F	*2,000.00 FL
4	1		*FRONT LH FUEL COMPARTMENT COVER	Buckled	1,300.00 F	*1,300.00 FL
5	2		*LH COMPARTMENT COVER	Buckled	3,700.00 F	*3,000.00 FL
6	1		*LH COMPARTMENT COVER OUTER HANDLE	Damaged	250.00 F	*200.00 FL
7	1		*FRONT LH WHEEL COVER	Cracked	1,650.00 F	*1,350.00 FL
8	2		*FRONT LH WHEEL COVER HINGE	Bent	370.00 F	*370.00 FL
9	1		*FRONT LH WHEEL MUD FLAP	Deformed	650.00 F	*650.00 FL
10	2		*SEALANT	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,348.00	9,618.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	953.80
Total Parts (S\$)	11,348.00	8,664.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING	New	30.00	30.00
2	LABOUR TO TRANSFER DOOR FITTINGS	New	300.00	50.00
3	LABOUR CHARGES	New	1,500.00	1,200.00
4	SPRAY PAINTING	New	1,800.00	1,500.00
Gross Labour Cost (S\$)			3,630.00	2,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >