

22/03/2012

ASS. REC. BY:

REF: CS3/MSG 19007570/ Jcd 302

Special Instruction:

Surveyor: Hmle JieASSIGNMENT (Office)From (Person): Jasmine Lok Hong Kwai of MSGDate/Time: 29.4.19 16.38p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: WXA 312Insured: YN 6514Aat Workshop m/s Sincere Lead AutomotiveTel: 9815 8858of 38 woodlands Ind Park EI #05-13Policy No: B 2862 5376 MKCClaim No: 591779

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A. 18.4.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement: _____

Date/Time: 20.4.19 9.56a.mPerson Contacted: RaymondVehicle IN/OUT

Date/Time	Action/Instruction	Estimate (X)	Inspection: 38 woodland #05-16
	WXA 312 - X		
	YN 6514A - X		

REF: MSLG

Hwee Jie

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No. WXA312 Yr Regn: 03 / 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Pulsar N3200 c.c. 200Colour: Black A/C: Insured / Std / NI / NASp. Reading: 548 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: PMNNS200NJML03913Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / SRM / STD A/Rim orTyre Size: F: 160/80-17R: 130/70-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nylogrip Zapper

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. - mm L/Bal. - mmD.O.A. 18/4/19 D.O.I. 30/4/19Survey held at Sincere LeadDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	PRS
	Range: \$2000-\$3000 3 days
	<i>[Signature]</i> 2/5/2019

Date/Time. File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time. File Return to?

2)

Report Format:

PRS

Lump Sum / I.B.I. (\$) _____

Days Of Repair: 3Resurvey No. of Trip: -

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

) \$ + PS. \$ SI

) Photos

) Others

TOTAL

120

10

130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Apr 2019		29 Apr 2019 16:38 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	JA LAN TIONG PTE LTD, Co. Reg. No.: 199303540G		
Main Claimant:	LEOW CHUAN CHIEW, ID: G2941409U		
Vehicle Reg. No.:	WXA312	Date of Loss:	18/04/2019 07:00 - :59 [231 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 591779	Policy/Cover Note No.:	B28625376MKC (Comprehensive) Coverage: 29/10/2018 - 28/10/2019
Vehicle Reg. No. (Insured):	YN6514A	Policy No. (Claimant):	
		Excess:	
Repairer:	Sincere Lead Automotive (Woodlands 3) 38 Woodlands Ind. Park E1 #05-13, 757710 Woodlands - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/04/2019]		
Driver/Custodian (Insured):	KARUNANITHI DHARMALINGAM (), NRIC: G5227677U, Tel: +6583583100 Email:		
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY:100%. CONTACT: MR RAYMOND CHUA 9815 8858		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

NSTXODMN

No. Pendaftaran : WXA312
No. ID : 940321085763
Nama Pemunya Berdaftar : LEOW CHUAN CHIEW
Alamat : NO 40 LORONG CEMPAKA 1 FELDA IJOK
34120 SELAMA PERAK

No. Chasis/No. Enjin : PMNNS200NJML03913 / JLYCJE53732
Buatan>Nama Model : MODENAS / PULSAR-NS200FI NS200
Keupayaan Enjin : 200
Bahan Bakar : PETROL
Status Asal : PEMASANGAN TEMPATAN
Kelas Kegunaan : MOTOSIKAL
Jenis Badan/Tahun Dibuat : MOTOSIKAL / 2018
Tarikh Pendaftaran : 31/03/2019
B. D. M/B. G. K/BTM : -
Syarat Pendaftaran 1 : -
Syarat Pendaftaran 2 : -
Syarat Pendaftaran 3 : -



SINGAPORE POLICE FORCE



T/20190422/2106

1 of 3

Report No. T/20190422/2106

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
22/04/2019 16:23

Vide Report No.:

Station Diary No.:
164

Informant's Particulars

Name of Informant: LEOW CHUAN CHIEW			Address: 09 Jalan 29 Seroja Johor Jaya		
ID Type / ID No.: FIN NO / G2941409U			Contact No.: Home/Office: Mobile: 9132 5116		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 25	Date of Birth: 21/03/1994	Type of Informant: Rider		
Race: Chinese			Language: English		Institution / School Name:
Occupation: MECHANICAL TECHNICIAN			Driving Licence Information: Class: 2B		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 18/04/2019 07:20	Type of Location: X-Junction
Location: Along Road 1 JOO KOON WAY JOO KOON CIRCLE				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
WXA312	Motorcycle	BAJAJ CHETAK	PULSAR NS 200	Black	Seriously Damaged	0
YN6514A	Trailer Truck	MITSUBISHI		White	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



1/20190422/2106

Police Station Of Origin:
Nanyang N.P.C.
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

2 of 2

Report No: 1/20190422/2106

CONTINUATION OF REPORT

Rider			
Name	LEOW CHUAN CHEW	ID No	G2941409U
Related Vehicle	WXA312 (Motorcycle)	Contact No	9132 5116
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	18/04/2019	Date Discharge	18/04/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On 18/04/2019 at about 0720hrs, while proceeding to work, I was travelling along Joo Koon Way. When approaching the junction at Joo Koon Circle, a Trailer Truck bearing YN6514A did not look out for other vehicles and inched out from Joo Koon Circle. Thus, I collided into the left side wheel of the trailer truck. Upon collision, I fell off my motorbike and landed on my right side, injuring my right leg and shoulder. The said trailer driver then called for ambulance. Soon, ambulance arrived and I was being conveyed. I was being conveyed to Ng Teng Fong General Hospital and was given 05 days of MC. I do not know the damages of my motorbike as it was being towed by the traffic police.

I wish to state that I did not manage to get the other party's particulars as we did not get to converse.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /
TAN RUI JIE

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
22/04/2019 16:23

Officer In Charge Of Case:
TP / GIT /
Insp TAN CHIN YONG
Contact No.: 65476178

Classification Of Case:

Authentication Stamp
NP168



Signature :

SN 127

Singapore Police Force

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Apr 2019		29 Apr 2019 16:38 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	JA LAN TIONG PTE LTD, Co. Reg. No.: 199303540G								
Main Claimant:	LEOW CHUAN CHIEW, ID: G2941409U								
Vehicle Reg. No.:	WXA312	Date of Loss:	18/04/2019 07:00 - :59 [18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 591779	Policy/Cover Note No.:	B28625376MKC (Comprehensive) Coverage: 29/10/2018 - 28/10/2019						
Vehicle Reg. No. (Insured):	YN6514A	Policy No. (Claimant):							
		Excess:							
Repairer:	Sincere Lead Automotive (Woodlands 3) 38 Woodlands Ind. Park E1 #05-13, 757710 Woodlands - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Imm.Advice due 30/04/2019]								
Driver/Custodian (Insured):	KARUNANITHI DHARMALINGAM (), NRIC: G5227677U, Tel: +6583583100 Email:								
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY:100%. CONTACT: MR RAYMOND CHUA 9815 8858								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***WXA312 (591779)**
[YN6514A]
TP
LEOW CHUAN CHIEW
Apr 18 2019 7:00AM
[JA LAN TIONG PTE LTD]
Sincere Lead Automotive

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/04/19 10:09	Accident Statement From: SC - Reg. No: YN6514A, Claimant: JA LAN TIONG PTE LTD	 Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/05/19 09:06	General View	 Load JPG	☒
2	02/05/19 09:06	General View	 Load JPG	☒
3	02/05/19 09:06	General View	 Load JPG	☒
4	02/05/19 09:06	General View	 Load JPG	☒
5	02/05/19 09:06	General View	 Load JPG	☒
6	02/05/19 09:06	General View	 Load JPG	☒
7	02/05/19 09:06	General View	 Load JPG	☒
8	02/05/19 09:06	General View	 Load JPG	☒
9	02/05/19 09:06	General View	 Load JPG	☒
10	02/05/19 09:06	General View	 Load JPG	☒
11	02/05/19 09:06	General View	 Load JPG	☒
12	02/05/19 09:06	General View	 Load JPG	☒
13	02/05/19 09:06	General View	 Load JPG	☒
14	02/05/19 09:06	General View	 Load JPG	☒
15	02/05/19 09:06	General View	 Load JPG	☒
16	02/05/19 09:06	General View	 Load JPG	☒
17	02/05/19 09:06	General View	 Load JPG	☒
18	02/05/19 09:06	General View	 Load JPG	☒
19	02/05/19 09:06	General View	 Load JPG	☒
20	02/05/19 09:06	General View	 Load JPG	☒
21	02/05/19 09:06	General View	 Load JPG	☒
22	02/05/19 09:06	General View	 Load JPG	☒
23	02/05/19 09:06	General View	 Load JPG	☒
24	02/05/19 09:06	General View	 Load JPG	☒
25	02/05/19 09:06	General View	 Load JPG	☒
26	02/05/19 09:06	General View	 Load JPG	☒
27	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
28	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
29	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
30	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
31	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
32	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
33	23/05/19 08:44	Dismantled Parts	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
35	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
36	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
37	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
38	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
39	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
40	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
41	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
42	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
43	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
44	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
45	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
46	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
47	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
48	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
49	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
50	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
51	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
52	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
53	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
54	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
55	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
56	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
57	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
58	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
59	23/05/19 08:44	Dismantled Parts	 Load JPG	☒
60	23/05/19 08:45	Dismantled Parts	 Load JPG	☒
61	23/05/19 08:45	Dismantled Parts	 Load JPG	☒
62	23/05/19 08:45	Dismantled Parts	 Load JPG	☒
63	23/05/19 08:45	Dismantled Parts	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/04/19 10:10	TP Police Rpt	 Load PDF	
2	29/04/19 10:18	SURVEY DISAGREE ON SJE - ASSIGN LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19007570/JCD3E2

Date: 24/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B28625376MKC

Claimant Vehicle No : WXA312

Insured Vehicle No : YN6514A

Date of Loss: 18/04/2019

Nature of Claim: TP

Claim No: 591779

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: WXA312

Make & Model: BAJAJ PULSAR 200 NS, 200cc

Engine No: JLYCJE53732

Reg. Date: 31/03/2019 (Man. Year: 2018)

Chassis No: PMNNS200NJML03913

Colour: Black

Odometer: 548 km

Engine Capacity: 200 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 100/80-17

Rear Tyre Size: 130/70-17

Front Left Side: Nylogrip Zapper 6 mm

Rear Left Side: Nylogrip Zapper 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/04/2019

Date Inspected: 30/04/2019 Inspected At:

Sincere Lead Automotive (Woodlands 3)
38 Woodlands Ind. Park E1 #05-13
Singapore 757710

Estimated Period of Repair: 3.0 days

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 -\$3,000.00

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 24 May 2019)
Parts:	N/A	BAJAJ PULSAR 200 NS 200cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for WXA312)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >