

12/00000

ASS. REC. BY:

REF: CS3/MSG19005167/E-103-07

Special Instructions:

Surveyor: Heve

ASSIGNMENT (Office)

Minimum

From (Person): Monica Chung Beizhu of MSIG Date/Time: 21.3.19 16.50p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKR 7014P Insured: SLE 8828H

at Workshop m/s Jemantah motor works Tel: 92996636

of 14 Dafu Lane 10 #01-406

Policy No: A28270069 MCX Claim No: 587841

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A 16.3.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS "w/p" H.O.D. Endorsement: _____

Date/Time: 22.3.19 9.15 a.m Person Contacted: AN chuan Vehicle (IN) OUT

Date/Time	Action/Instruction	Estimate (X)
	SKR 7014P - X	lump sum 6150
	SLE 8828H - X	(Red: 350, 5%), 7 days
	Dismantle: 25/3/2019	
	Steve,	
	Pls check parts prices & see my remarks.	

RECEIVED 03 MAY 2019

Do Not Finalise

[Signature]
21/5/2019

ASSIGNMENT

From
Estimated Cost
QD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No
at Workshop ins
of
Insured
Policy No
Claims No
Sum Insured
(Client's Record)
Make of Veh.

Date:

Excess:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

(days) Res.: Yes or No

Lump Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No **SKR 7014P** Yr Regn. **15/05/09**
Type: **M.Cop** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: **Nissan Bishpa** C.C. **1997**
Colour **White** A/C Insured / Std / NI / NA
Sp. Reading **79730** T/Rvlin: Insured / Std / NI / NA
Eng/No:
Ctno: **14R7073041 7A** KJ **90705743**
Gen. Cond: **Good** / Fair / Poor / Burnt
Steering: **Order** / Jammed / Leaked / Burnt or
Brake: **Order** / Jammed / Leaked / Burnt or
Modl: **Nil** / SRim / STD AJRim or
Tyre Size: F: **215/60R17**
R: **11**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / OKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.A.

Survey held at

Jemulah Mat 11

Des. of Damages: Frt / **Rear** / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time / Action / Instruction

PRS

Page 1000 6K - 7K 7 days

MV- 18,000

PV- 15,488

NV- 2512

27/3/2019

Date/Time, File Pass to?

☐

: Procl. Report

4)

☐

: Final Report

Date/Time, File Return to?

5)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Insp (\$

☐

: Week-end (\$

Days Of Repair: **7**

Resurvey No. of Trip: **1**

Survey Fee:

(transportation

) 5-RS 2

) Photo

) Value

)

(Total)

120
10
130

Report Format: **PRS**

Lump Sum / I.B.E. (\$

Nivitha (LKK Auto)

From: Accounts (LKKAuto) <account@lkkauto.com>
Sent: Tuesday, 30 April 2019 8:54 AM
To: Admin-D (LKKAuto)
Cc: Accounts (LKKAuto)
Subject: Report Send Back Alerts - SKR7014P (TP)

Dear Nivitha,

FYNA Please,

18 26 Apr 2019 11:24	Ins Send Back Adj Rpt	Paper adjustment	[I] Monica Chung Pei Zhen
19 26 Apr 2019 11:24	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/04/30	[I] Merimen Administrator
20 26 Apr 2019 11:24	Adj Mandate Set	Maintained.	[I] Merimen Administrator

Thank You

Best Regards,

SuthaShelia (Shelia) | Accounts Dept.

LKK Auto Consultants Pte Ltd

Phone: 6841 1891 | email: account@lkkauto.com | fax: 6844-8805

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Do-Not-Reply [mailto:do-not-reply@merimen.com]
Sent: Friday, 26 April 2019 11:40 AM
To: account@lkkauto.com
Subject: Report Send Back Alerts - SKR7014P (TP)

Dear Sir / Madam,

Please login to Merimen Online at www.merimen.com.sg for more information.

Thanks,
The Merimen Team



This email has been checked for viruses by AVG antivirus software.
www.avg.com

SUPREME

NEW CARS | PRE-LOVED CARS | INSURANCE | FINANCING

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years COE Renewal Toyota Altis 1.6A.



3.98% P.A \$0 Admin Fees At GV
Finance. 2 Years Warranty.
Monthly From \$488.
GV Credit Pte Ltd. [Starke](#)



PRIME MOTOR & LEASING

JOHNS YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES

With over 200 units of vehicles
to choose from, ranging from
all European to Japanese Makes.



Browse by Category ▼

Sort by Date Posted ▼




20 results/page

4 vehicles

Nissan Qashqai

Advanced Search



	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Nissan Qashqai		Any	Any	2010	Any	Any	Any	Available
	Nissan	Nissan Qashqai 2.0A	\$19,700	\$10,200 /yr	15-Jan-2010	1,997 cc	115,000 km	SUV	Available
Best Selling Japanese Crossover SUV In The Market, Decent Mileage Done, Well Maintained Taken Care By Owner, Best Use For Short Term Driving, Or With 5 Years COE At \$38700, 10 Years COE At \$56700, STA...									
Posted: 16-Apr-2019 Tags: 2010 Nissan Qashqai, 2010 nissan qashqai, Nissan Qashqai, nissan qashqai, Nissan, Qashqai, qashqai, Used Nissan									
	Nissan	Nissan Qashqai +2 2.0A	\$28,500	\$10,360 /yr	15-Sep-2010	1,997 cc	130,000 km	SUV	Available
COE On The Rise, Best Buy To Ride Over And Wait For COE To Drop. Cheapest SUV With 7 Seats. Selectable Drive 2WD/4WD For Fuel Saving Or Needed Traction. Original Condition Inside Out. Wear And Tear Done...									
Posted: 01-May-2019 Tags: 2010 Nissan Qashqai, 2010 nissan qashqai, Nissan Qashqai, nissan qashqai, Nissan, Qashqai, qashqai, Used Nissan									
	Nissan	Nissan Qashqai +2 2.0A	\$28,000	\$10,100 /yr	29-Sep-2010	1,997 cc	75,000 km	SUV	Available
Beautiful 2.0L 7 Seater SUV, Regularly Serviced. Clean And Neat Interior. Flexible Loan Scheme. Reliable, Practical, With Spacious Cabin! Interested, Call Us To Arrange For Viewing!									
Car Empire Automobiles Pte Ltd									
Posted: 30-Apr-2019 Tags: 2010 Nissan Qashqai, 2010 nissan qashqai, Nissan Qashqai, nissan qashqai, Nissan, Qashqai, qashqai, Used Nissan									
	Nissan	Nissan Qashqai 2.0A	\$27,200	\$10,230 /yr	30-Nov-2010	1,997 cc	53,000 km	SUV	Available
Cheapest In Town, Reliable, Practical, With Spacious Cabin! Well Maintained By A Careful Owner, Mint Condition.									
Posted: 30-Apr-2019 Tags: 2010 Nissan Qashqai, 2010 nissan qashqai, Nissan Qashqai, nissan qashqai, Nissan, Qashqai, qashqai, Used Nissan									

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rate, insurance. Find buy used Nissan Qashqai, Nissan Qashqai Singapore, used Nissan Qashqai Singapore, used Nissan Qashqai, used vehicles Singapore or even buy used Nissan Qashqai Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE result.

Compare

Das WeltAuto.
Used cars you can trust. Guaranteed.

Low on mileage. High on savings.



Nissan Qashqai

Price Range ▼

Depreciation ▼

2009 ▼

Vehicle Type ▼


[Advanced Search](#)
[Home](#) » [Used Cars](#) » [Cars Tradition Pte Ltd](#) » Nissan Qashqai 2.0A Premium

Nissan Qashqai 2.0A Premium

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)

Price	\$17,800		
Depreciation ⓘ	N.A.	Reg Date	21-Jul-2009 (2mths 18days COE left)
Mileage	N.A.	Manufactured ⓘ	2008
Road Tax ⓘ	\$1,210 /yr	Transmission	Auto
Dereg Value ⓘ	\$13,022 as of today (change)	OMV ⓘ	\$25,317
COE ⓘ	\$16,801	ARF ⓘ	\$25,317
Engine Cap	1,997 cc	Power	101.0 kW (135 bhp)
Curb Weight ⓘ	1,450 kg	No. of Owners ⓘ	3
Type of Vehicle	SUV		

Features

Responsive 2.0L 4 Cylinders Inline DOHC Engine, CVT Transmission Gear, SRS Airbags, Keyless Entry/Start, Multi Steering Control. View specs of the Nissan Qashqai (2008-2014)

Accessories

Panoramic Glass Roof, Retractable Side Mirror, Electric Driver Seat, Sports Rims, Leather Seats, Audio System.

Description

As It Is Condition! Owner Selling Low Price. Now Scrap \$16k! Enjoy Your Daily Drive. Best Selling Japanese Crossover SUV In The Market. The Best Of Condition For Your Next 5 Years Drive! At \$36,800. Or 10 Year At \$53,800.

Category

PARF Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started

[Compare](#)

[Location Map](#)
[Shortlist](#)
[Compare](#)
[Add note](#)
[Report Error](#)
[More Actions](#)

Seller Information

Company	Cars Tradition Pte Ltd • dealer's pricelist • 20 vehs sold 12 vehs available	
Address	61 Woodlands Industrial Park E9 # 36 Search cars nearby this location	
Location	E9 Premium	
Office No	63527288 / 63528525	
Contact Person(s)	Sim	98224
	Kage	92778
	Joanna	85001

1

1

Our Ref : CY.10425.19.JM(HW).wp(PT)

Your Ref : 587841

22 April 2019

BY HAND

MSIG Insurance (Singapore) Pte Ltd
Claims Department
4 Shenton Way #21-01
SGX Centre 2
Singapore 068807

Dear Sirs

**ROAD TRAFFIC ACCIDENT INVOLVING SKR7014P & SLE8828H ON 16/03/2019 @ 13:20HRS
ALONG GRANGE ROAD**

We are instructed by Tregold Jamie Paul to claim damages and losses against you in connection with the above-captioned road traffic accident which our client's vehicle **SKR 7014P** was damaged by vehicle **SLE 8828H** by your insured at the material time.

We are instructed that the said accident was caused by your insured's negligent driving and/or management of the vehicle no. **SLE8828H**. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

1) Repair Costs	\$ 6,500.00
2) Rental	\$ 1,027.00
3) Loss of Use	\$ 200.00
4) Survey Fee	\$ 741.00
5) LTA fee	\$ 7.49
6) Accident report fee	\$ 29.00
7) Costs & Incidental	\$ 1,000.00
8) GST on costs & Incidentals	\$ 70.00
	<u>\$ 9,574.49</u>

A copy each of the following supporting documents is enclosed:-

- 1) Accident report on our client's vehicle
- 2) Survey Report on **SKR7014P** with **96** coloured photographs
- 3) Vehicle's Rental official invoice
- 4) Final repair bill
- 5) LTA search on **SLE 8828H**

We had on **20 March 2019** notified your company of the above accident and a pre-repair inspection was carried out by your appointed surveyor.

Please let us know within the next seven (7) days upon receipt of this letter whether you intend to re-inspect our client's vehicle failing which the said vehicle will no longer be available for the same.


CY.10425.19.JM(HW).wp(PT)

Page 2

Please note that you should send to us an acknowledgment of receipt of this letter within fourteen(14) days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against your insured without further notice to you.

Please note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

Yours faithfully



C. YOGARAJAH LLC
Enc

Cc Chandran Pallaniappan
c/o Automate Genuine Parts Pte. Ltd.
Block 48 Toh Guan Road East
#04 - 104
Singapore 608586
(Documents were enclosed to your insurers)

CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

INVOICE

Tregold Jamie Paul
C/o: Jementah Motor Works
Blk 14 Defu Lane 10
#01-406 Singapore 539195

Invoice No: CL/190385

Ref No: JMW/03/1906/TP

Date: 1 April 2019

DESCRIPTION	AMOUNT
OUR SERVICE FEE CHARGES:	
<ul style="list-style-type: none">SURVEY INSPECTION FOR VEHICLE NO. <u>SKR 7014 P</u>RESURVEY INSPECTIONDIGITAL PHOTOGRAPHS SERVICES (INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)TRANSPORTATION	
GRAND TOTAL	S\$ 741.00

E & O. E

All cheque payment should be "Crossed" and made payable to " C L APPRAISER PTE LTD "

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd

CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Tregold Jamie Paul
C/o: Jementah Motor Works
Blk 14 Defu Lane 10
#01-406 Singapore 539195

Date : 1 April 2019
Our ref : JMW/03/1906/TP

Accident Date : 16 March 2019
Inspection Date : 21 March 2019
Repairer Name : Jementah Motor Works
Blk 14 Defu Lane 10
#01-406 Singapore 539195

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : SKR 7014 P
Make / Model : Nissan Qashqai
Chassis No : KJ10205743
Engine No : MR20730417A

Year / Capacity : 2009 / 1997 cc
Colour : White
Mileage : 79730

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Yokohama	215/60 R17	5 mm	Sport
Front Offside	: Yokohama	215/60 R17	5 mm	Sport
Rear Nearside	: Yokohama	215/60 R17	5 mm	Sport
Rear Offside	: Yokohama	215/60 R17	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 96 copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis
and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 6,500.00** on a contractual basis.

Under normal circumstances, the repair period would be about 8 (Eight) working days.

SCL APPRAISER PTE. LTD

Vehicle Registration No: SKR 7014 P

Our Ref No: JMW63/1206/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

NETT ITEMS

1	Rear windscreen moulding	Necessary	\$ 95.00	\$ 95.00 /
1	Rear tailgate	Damage	\$ 2,256.90	\$ 2,256.90 /
2	Rear tailgate dampers	Intact	\$ 368.00	
2	Rear tailgate reflectors	Damage	\$ 390.00	\$ 390.00 X NAI
1	Rear tailgate lock	Damage	\$ 165.00	\$ 135 165.00 /
1	Rear tailgate logo	Necessary	\$ 55.60	\$ 55.60 /
1	Rear tailgate rubber	Necessary	\$ 150.70	\$ 150.70 /
1	Rear tailgate "QASHQAI" emblem	Necessary	\$ 77.00	\$ 63 77.00 /
1	Rear tailgate "XTRONIC CVT" emblem	Necessary	\$ 75.00	\$ 63 75.00 /
2	Rear taillamps	Damage	\$ 971.20	\$ 971.20 X NAI
1	Rear end panel	Damage	\$ 740.90	\$ 50 740.90 /
1	Rear end panel inner garnish	Damage	\$ 145.00	\$ 145.00 /
1	Rear bumper	Damage	\$ 885.40	\$ 885.40 /
2	Rear bumper brackets	Damage	\$ 183.40	\$ 183.40 X NAI
2	Rear bumper lower brackets	Damage	\$ 80.00	\$ 80.00 X NAI
2	Rear bumper reflectors	Damage	\$ 170.00	\$ 170.00 X NAI
2	Rear bumper side retainers	Necessary	\$ 87.20	\$ 87.20 /
1	Rear exhaust silencer	Damage	\$ 871.90	\$ 708 871.90 /
2	Rear exhaust mountings	Necessary	\$ 97.20	\$ 97.20 /
1	Rear exhaust heat shield	Damage	\$ 142.10	\$ 142.10 /
2	Rear fender arch garnishes	Damage	\$ 1,082.80	\$ 1,082.80 X NAI
2	Rear fender inner shields	Damage	\$ 190.00	\$ 190.00 /
1	Rear floor board (inner fender)	Damage	\$ 385.00	\$ 385.00 /
1	Rear floor panel	Damage	\$ 1,083.00	\$ 1,083.00 X R
1	Rear spare tyre side board	Damage	\$ 185.00	\$ 185.00 X NAI
1	Rear spare wheel retainer	Damage	\$ 58.00	\$ 58.00 /
			\$ 10,991.30	\$ 10,623.30
Less 10%			\$ 1,099.13	\$ 1,062.33
Total Cost - Nett Items			\$ 9,892.17	\$ 9,560.97

6097.10
- 10%
5487.39

Vehicle Registration No: SKR 7014 P

Our Ref No: JMW/03/1906/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
	Spare Parts Sub Total c/f		\$ 9,892.17	\$ 9,560.97

SPECIAL NETT ITEMS

1	Rear windscreen sealant	Necessary	\$ 80.00	\$ 50.00 /
1	Rear bumper clip (1 set)	Necessary	\$ 60.00	\$ 60.00 30 /
1	Rear reverse sensor (1 set)	Damage	\$ 350.00	\$ 280.00 200 /
Total Cost - Special Nett items			\$ 490.00	\$ 390.00

280

Total cost of parts

\$ 10,382.17 \$ 9,950.97

Vehicle Registration No: SKR 7014 P

Our Ref No: JMW/03/1906/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 10,382.17	\$ 9,950.97

LABOUR

1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	\$ ³⁰ 50.00/
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 180.00	\$ 120.00 ³⁰
3	To remove and refit rear reverse sensor.	\$ 120.00	\$ 80.00 ²⁰
4	To transfer rear tailgate mechanism and wiring assembly to assist repair.	\$ 80.00	\$ 60.00 ³⁰
5	To remove and refit rear windscreen glass.	\$ 180.00	\$ 120.00 ¹⁰⁰
6	To remove, refit and replace exhaust silencer and mountings.	\$ 150.00	\$ 120.00 ⁸⁰
7	To apply undercoating on repaired and replaced panel.	\$ 180.00	\$ 120.00 ⁴⁰
8	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,600.00	\$ 1,250.00 ⁹⁰⁰
9	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,500.00	\$ 1,100.00 ⁷⁰⁰

GRAND TOTAL

\$ 14,452.17 \$ 12,970.97

1930

8 days /

P-5487-39
 AI-280
 L-1930
 7697-39
 L15-6157-91
 = 6150

Vehicle Registration No: SKR 7014 P

Our Ref No: JMW/03/1906/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 6,500.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H
Automotive Appraiser



Accident claim
for SKR 70149

Presto Expat Motoring Services Pte Ltd

491 River Valley Road #01-04
Valley Point Shopping Centre Singapore 248371
Tel: 67327737 Fax: 67347737
Email: info@prestoexpatmotoring.com
Website: www.prestoexpatmotoring.com

Tax Invoice

GST Reg No: 200713089K

Tredgold Jamie Paul
261 River Valley Road
#06-08
Singapore 238307

Invoice No. PEMS-R18559
Date 21/3/2019
Vehicle No. SKR1323L
Make/Model Honda Odyssey
Terms Due on receipt

S/N	Description	Qty	Unit Price	Amount
1	Agreement no:PEMS-R-190321 Rental Payment Period: 21/03/19 - 29/03/19			960.00
Remark:		SUBTOTAL		\$960.00
		Tax Total		\$67.20
		Total		\$1,027.20

Payment mode:

- 1) Crossed Cheque payable to Presto Expat Motoring Services Pte Ltd
- 2) Cash
- 3) Bank Transfer

Bank Name: Standard Chartered Bank
Account Name: Presto Expat Motoring Services Pte Ltd
Account No: 0310043689
Bank Code: 7144
Branch Code: 003
Swift Code: SCBLSGSG

If payment is not received on invoice date a late payment fee of 5% will be charged on overdue account.



for Presto Expat Motoring Services Pte Ltd

JEMENTAH MOTOR WORKS

Blk 14 Defu Lane 10 #01-406
Singapore 539195
H/P : 9299 6636 Fax : 6285 7054

Date of accident : 16-Mar-19


Name : Tregold Jamie Paul

Address : C/O Blk 14 Defu Lane 10 #01-406
Singapore 539195

Final repair cost of SKR 7014 P Nissan Qashqai

Lump Sum Repair Costs

\$ 6,500.00



JEMENTAH MOTOR WORKS
14 Defu Lane 10 #01-406
Singapore 539195

Singapore Dollars : Six Thousand And Five Hundred Only.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy-liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/03/2019 09:49
Date Of Accident	16/03/2019 13:20
Exact Location Of Accident	GRANGE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKR7014P
Insured/Policyholder	
Name Of Registered Owner	TREGOLD JAMIE PAUL
NRIC No	S8287461E
Email Address	JAMINETREDGOLD@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96752504
Alternative Phone No	OTHERS-97235551

Vehicle Particulars

Manufacturer	NISSAN
Model	QASHQAI PREMIUM 2.0L SMT ABS D/AB HID SR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA252197/1
Cover Note Number	

Driver

Name of Driver	EMILIA RUTH LAW
NRIC No	S8368459C
Date Of Birth	20/04/1983
Occupation	INDOOR
Date Of Driving Pass	04/08/2015
Driving Experience	3 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97235551
Fax Number	
Contact Number	
Email Address	EMILIATREGOLD@GMAIL.COM

Address	261 RIVER VALLEY ROAD #06-08
Postcode	238309
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CAMILLA ALICE TREDGOLD GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLE8828H
Vehicle Make/Model/Colour	TOYOTA / ESTIMA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHANDRAN PALLANIAPPAN
NRIC/Passport Number	S7018828G
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to revoke policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false response may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHMENTS

EMILIA (A) WAS REQUIRED TO TRAVEL TO EUROPE FOR BUSINESS ON 17 MARCH 2019. AS SUCH, HER HUSBAND (JAMIE TREID(OLD)) REPORTED THE ACCIDENT IN HER ABSENCE.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Incident report:

Date: 16 March 2019

Time: circa 1.20pm

Location: Grange Road - near junction of Grange Road and Rochalie Drive (next to construction site on Grange Road).

I was stationery at a red light on Grange Road (approaching Tanglin Mall on my right). After the lights turned green, I started to move away and was hit by another car from behind.

The driver of the other vehicle apologised and said he was not concentrating. He admitted that it was his fault and repsonsibimity and that his insurance company would cover the cost of all repairs.

We exchanged details and information and he requested to leave the scene. I agreed and he left.

JAMIE TREDGOLD
58287461E





redefining / insurance

AXA Insurance Pte Ltd
 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 (65) 6880 4740
 customer.care@axa.com.sg
 www.axa.com.sg

Certificate of Insurance

Account number
 15276

Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 188)- Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960-Road Transport Act, 1987 (Malaysia)
 Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	TREDGOLD JAMIE PAUL	Certificate number	GA252197 / 1
Cover	Comprehensive	Chassis number	KJ30205743
Plan name	Peace	Engine number	MR20730417A
ICB applicable	30%		
Vehicle registration number	SKR7014P		
Period of insurance	from 15/08/2018 to 14/08/2019 (both dates inclusive)		
Finance loan company	UNITED OVERSEAS BANK LIMITED		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
 (b) Any Named Driver as stated in the Policy:
 1. LAW EMILIA RUTH
 (c) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 188) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess
	Windscreen Excess

SGD 500.00
 SGD 100.00

An Additional Excess is applicable as follows:

1. S\$500 for unnamed Authorised Driver
2. S\$500 for declared Young and Inexperienced Driver
3. S\$5,000 for undeclared Young and Inexperienced Drivers. This additional excess is reduced to S\$2,500 if you have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 188) and Part IV of the Road Transport Act, 1987 (Malaysia).



AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company, if the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 188).
 The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8368459C



Name
EMILIA RUTH LAW

Race
CAUCASIAN

Date of birth
20-04-1983

Sex
F

Country/Place of birth
UNITED KINGDOM



Driver

9474389



NRIC No. S8368459C



Nationality
BRITISH

Date of issue
07-02-2018

Address
**261 RIVER VALLEY ROAD
#08-08
SINGAPORE 238307**



Driver

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	EFFECTIVE DATE
Class 2 Motor cars with unladen weight $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq 2500\text{kg}$	04 Aug 2018

NP 429A



Date: 18/03/19

To: Owner of Vehicle Number: SR 7014P

The following has been advised to you via your workshop, CDGE through their staff, Terence Ng

Please tick the applicable box if you had been advised on the content as seen below:

- ☒ You had been advised by the workshop that in the event that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
- ☐ You had been advised by the workshop on the liability and merits of the case accordingly.
- ☐ You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
- ☐ There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.
- ☐ The Estimation waiting time for the spare parts to arrive is _____
The estimated arrival time does not include the repair period.
- ☐ You will be driving the vehicle out despite being advised by the workshop mechanic/ personnel that the vehicle may not be road worthy.
- ☐ For vehicles below Three (3) years old, your insurance company will use only genuine original parts to repair your vehicle.
- For vehicles above Three (3) years old, your insurance company will be carrying out repairs using any combination of genuine original parts and/or original equipment manufacturer (OEM) parts.
- ☐ You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.
- ☐ For vehicles below Five (5) years old, you had been advised by the workshop to check with the local distributor on your warranty status.
- ☐ Others _____

Signed and acknowledge by:


Name and signature of policyholder/authorized driver


Name and signature of workshop personnel including company stamp

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/03/2019 15:27
Date Of Accident	16/03/2019 13:45
Exact Location Of Accident	JUNCTION OF ROEHATIE DRIVE & GRANGE ROAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE8828H
Insured/Policyholder	
Name Of Registered Owner	AUTOMATE GEUNINE PARTS PTE LTD
Co Reg No	0
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96610227
Alternative Phone No	OFFICE-96610227

Vehicle Particulars

Manufacturer	TOYOTA
Model	ESTIMA-2.4 E X (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 28770069 MCX
Cover Note Number	

Driver

Name of Driver	PALLANIAPPAN CHANDRAN
NRIC No	S7018828G
Date Of Birth	06/06/1970
Occupation	OUTDOOR
Date Of Driving Pass	16/07/2000
Driving Experience	18 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96610227
Fax Number	
Contact Number	OFFICE-96610227
EEmail Address	NOEMAIL

Address	342 CLEMENTI AVE 5 #04-186
Postcode	S120342
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	SENT TO INSURANCE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKR7014P
Vehicle Make/Model/Colour	NISSAN QASHQAI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	EMILIA RUTH LAW
NRIC/Passport Number	S8368459C
Contact Number	81336972
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

16 MAR 2019


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC BUREAU
511 Bukit Batok Street 23
Singapore 659345
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Date: 16/3/19 at 1:45 pm.

Was Driving along Grange Road & hit vehicle no. SKR 7014P

Hit Vehicle number is SKR 7014P, Nissan QASHQAI

Owner name is: EMILIA RUTH LAW, NALC SB368459C

Contact Number : 81336972.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

U.S. *James*

Policyholder's Signature

Date & Time:

Driver's Signature _____

(If driver is not the policyholder)

Date & Time:

IDAC BUKIT DATOH (2004)

511 Gulit Batch Street 23

Singapore 659545

Tel: 6560 3312 Fax: 6569 0722

Email: vacbb@singnet.com.sg

Reporting Centre Personnel's Signature

Name: _____

NRIC/FIN No.:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



01/15/2018 22:10

Accident Photo



Accident Photo





































...CLAIM SUBFOLDER...(Pending for Survey Report)















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Mar 2019		21 Mar 2019 16:50 Edit Adj Rpt	S\$6,150.00 Edit Estimates	S\$6,150.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: AUTOMATE GENUINE PARTS PTE LTD , Co. Reg. No.: 200815448D, Tel: +6596610227									
Main Claimant: TREGOLD JAMIE PAUL , ID: S8287461E									
Vehicle Reg. No.: SKR7014P		Date of Loss: 16/03/2019 13:00 - :59 [115 Months and 1 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 587841		Policy/Cover Note No.: A28770069MCX (Comprehensive) Coverage: 15/06/2018 - 14/06/2019							
Vehicle Reg. No. (Insured): SLE8828H		Policy No. (Claimant):							
		Excess: S\$1,000.00							
Repairer: Jementah Motor Works (HQ) 14 Defu Lane 10, #01-406, 539195 Defu Lane - Tel: 92996636									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 30/04/2019]									
Driver/Custodian (Insured): PALLANIAPPAN CHANDRAN () . NRIC: S7018828G Email:									
Adj Asg. Remarks: LIAB 100% SJE DISAGREE APPOINT LKK, PLS CONTACT MR AH CHUAN @ 9299 6636									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (26/04/2019): Report Send Back Alerts - SKR7014P (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKR7014P (587841)
[SLE8828H]
TP
TREGOLD JAMIE PAUL
Mar 16 2019 1:00PM
[AUTOMATE GENUINE PARTS PTE LTD]
Jementah Motor Works

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
2	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
3	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
4	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
5	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
6	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
7	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
8	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
9	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
10	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
11	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
12	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
13	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
14	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
15	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
16	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
17	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
18	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
19	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
20	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
21	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
22	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
23	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
24	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
25	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
26	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
27	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
28	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
29	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
30	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
31	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
32	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
33	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
34	25/03/19 09:20	Odometer Reading						Load JPG	<input checked="" type="checkbox"/>	
35	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
36	25/03/19 09:20	General View						Load JPG	<input checked="" type="checkbox"/>	
37	25/03/19 09:20	Chassis Number						Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	25/03/19 09:20	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
39	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	28/03/19 14:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
85	28/03/19 14:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
86	28/03/19 14:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
87	28/03/19 14:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/03/19 17:11	OI GIA Report From:OD - Reg. No: SLE882SH, Claimant: AUTOMATE GEUNINE PARTS PTE LTD	 Load PDF	
2	20/03/19 17:11	TP GIA Report - SKR7014P From:OD - Reg. No: SLE882SH, Claimant: AUTOMATE GEUNINE PARTS PTE LTD	 Load PDF	
3	20/03/19 17:12	PRI	 Load PDF	
4	21/03/19 10:22	fax to lawyer - SJE DISAGREE APPOINT LKK	 Load PDF	
5	26/04/19 10:59	LOD	 Load PDF	
6	26/04/19 10:59	SURVEY BILL & SURVEY REPORT	 Load PDF	
7	26/04/19 10:59	RENTAL TAX INVOICE & REPAIR BILL	 Load PDF	
8	26/04/19 10:59	SURVEY PHOTOS 1	 Load PDF	
9	26/04/19 10:59	SURVEY PHOTOS 2	 Load PDF	
10	26/04/19 10:59	SURVEY PHOTOS 3	 Load PDF	
11	26/04/19 10:59	SURVEY PHOTOS 4	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/05/19 11:29	PRS Invoice	 Load PDF	
2	06/05/19 11:29	Colour Photo	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19005167/ETD3E2-1

Date: 06/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: A28770069MCX
Claimant Vehicle No: SKR7014P	Insured Vehicle No: SLE8828H
Date of Loss: 16/03/2019	Nature of Claim: TP Claim No: 587841

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR7014P	Engine No:	MR20730417A
Make & Model:	NISSAN QASHQAI, 2.0 PREMIUM (J10) (A)	Chassis No:	KJ10205743
Reg. Date:	15/08/2009 (Man. Year: 2008)	Odometer:	79730 km
Colour:	White		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,382.17	5,767.39	4,614.78	44.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,070.00	1,930.00	2,140.00	52.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,452.17	7,697.39	6,754.78	46.74
Approved Total (Overridden) (S\$)		6,150.00		
Nett Amount (S\$)	14,452.17	6,150.00	8,302.17	57.45

INSPECTION

Date of Assignment:	21/03/2019	
Date Inspected:	22/03/2019	Inspected At: Jementah Motor Works (HQ) 14 Defu Lane 10, #01-406 Singapore 539195
Estimated Period of Repair:	8.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 May 2019)
Parts: M1-SUV	NISSAN QASHQAI 2.0 PREMIUM (J10) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKR7014P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	95.00 FL	*95.00 FL
2	1		*REAR TAILGATE	Damaged	2,256.90 FL	*2,256.90 FL
3	2		*REAR TAILGATE DAMPERS	Intact	368.00 FL	*- FL
4	2		*REAR TAILGATE REFLECTORS	Not Necessary	390.00 FL	*- FL
5	1		*REAR TAILGATE LOCK	Damaged	165.00 FL	*135.00 FL
6	1		*REAR TAILGATE LOGO	Necessary	55.60 FL	*55.60 FL
7	1		*REAR TAILGATE RUBBER	Necessary	150.70 FL	*150.70 FL
8	1		*REAR TAILGATE QASHQAI EMBLEM	Necessary	77.00 FL	*63.00 FL
9	1		*REAR TAILGATE XTRONIC CVT EMBLEM	Necessary	75.00 FL	*63.00 FL
10	2		*REAR TAILLAMP	Not Necessary	971.20 FL	*- FL
11	1		*REAR END PANEL	Damaged	740.90 FL	*580.00 FL
12	1		*REAR END PANEL INNER GARNISH	Damaged	145.00 FL	*145.00 FL
13	1		*REAR BUMPER	Damaged	885.40 FL	*885.40 FL
14	2		*REAR BUMPER BRACKETS	Not Necessary	183.40 FL	*- FL
15	2		*REAR BUMPER LOWER BRACKETS	Not Necessary	80.00 FL	*- FL
16	2		*REAR BUMPER REFLECTORS	Not Necessary	170.00 FL	*- FL
17	2		*REAR BUMPER SIDE RETAINERS	Necessary	87.20 FL	*87.20 FL
18	1		*REAR EXHAUST SILENCER	Damaged	871.90 FL	*708.00 FL
19	2		*REAR EXHAUST MOUNTINGS	Necessary	97.20 FL	*97.20 FL
20	1		*REAR EXHAUST HEAT SHIELD	Damaged	142.10 FL	*142.10 FL
21	2		*REAR FENDER ARCH GARNISHES	Not Necessary	1,082.80 FL	*- FL
22	2		*REAR FENDER INNER SHIELDS	Damaged	190.00 FL	*190.00 FL
23	1		*REAR FLOOR BOARD	Damaged	385.00 FL	*385.00 FL
24	1		*REAR FLOOR PANEL	Repair	1,083.00 FL	*- FL
25	1		*REAR SPARE TYRE SIDE BOARD	Not Necessary	185.00 FL	*- FL
26	1		*REAR SPARE WHEEL RETAINER	Damaged	58.00 FL	*58.00 FL
27	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*50.00 FS
28	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
29	1		*SET REAR REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,481.30	6,377.10
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,099.13	609.71
Total Parts (\$\$)	10,382.17	5,767.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM TO ASSIST REPAIR	New	180.00	30.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	120.00	20.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY TO ASSIST REPAIR	New	80.00	30.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	100.00
6	TO REMOVE, REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	150.00	80.00
7	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL	New	180.00	40.00
8	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,600.00	900.00
9	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	1,500.00	700.00
Gross Labour Cost (S\$)			4,070.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >