

ASS. REC. BY:

REF: CS / CT119007572 / USD312

Special Instruction:

Surveyor: Marcus

mining

ASSIGNMENT (Office)From (Person): ong chin kiat of CT1 Date/Time: 30.4.19 10.00a.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMK 4273R Insured: GBG 3110Kat Workshop m/s Stytech AUTO Tel: 644 48126of 2 Kaki Bukit Ave 2 # 02-30Policy No: DMK VSN 30406118000Claim No: SNM19D 20187402

Sum Insured: _____

Excess: _____

Make of Veh: _____

(Client's Record)

D.O.A. 27.4.2019

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement: _____

Date/Time: 30.4.19 11.00a.m

Person Contacted: _____

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
	SMK 4273R - NA / CT119007485 / K4	D.O.A - 27/04/2019
	GBG 3110K - NA / CT119007485 / K4	D.O.A - 27/04/2019

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Apr 2019		30 Apr 2019 10:00 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ASIA FROGS FARM PTE LTD, Co. Reg. No.: 198101633R								
Main Claimant:	TEO THIAM SOON, ID: S1676529E								
Vehicle Reg. No.:	SMK4273R	Date of Loss:	27/04/2019 16:00 - :59 [17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201874C02	Policy/Cover Note No.:	DMCVSN30406118000 (Comprehensive) Coverage: 13/07/2018 - 12/07/2019						
Vehicle Reg. No. (Insured):	GBG3110K	Policy No. (Claimant):	CN040304						
		Excess:	S\$0.00						
Repairer:	Stytech Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #02-30, Kaki Bukit Autohub, 417921 Kaki Bukit - Tel: 64448125								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/05/2019]								
Driver/Custodian (Insured):	AW WEE XIANG, WINSTON (HU WEIXIANG) (27 / Male) , NRIC: S9144288D Email:								
Adj Asg. Remarks:	please assign Mr Marcus chua for SJE. thank you.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6529E
Vehicle Details	
Vehicle No.:	SMK4273R
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Apr 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	AD AVANTE 1.6 GLS (A) S
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	G4FGKU124900
Chassis No.:	KMHD841CMKU891831
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$14,555.00
Original Registration Date:	10 Apr 2019
First Registration Date:	10 Apr 2019
Transfer Count:	0
Actual ARF Paid:	\$14,555.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Apr 2029
PARF Rebate Amount:	\$10,916.00
Intended COE Rebate Details	
COE Expiry Date:	09 Apr 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$26,309.00
COE Rebate Amount:	\$26,155.00
Total Rebate Amount:	\$37,071.00

The information contained herein is correct as at 30 Apr 2019

OK

MSME10055236 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 29/04/2019 15:35
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/04/2019 15:35
Date Of Accident	27/04/2019 16:15
Exact Location Of Accident	IMM CARPARK LEVEL 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMK4273R
Insured/Policyholder	
Name Of Registered Owner	TEO THIAM SOON
NRIC No	S1676529E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90939050
Alternative Phone No	OFFICE-90939050

Vehicle Particulars

Manufacturer	HYUNDAI
Model	AVANTE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN040304
Cover Note Number	

Driver

Name of Driver	TEO JIN HAO
NRIC No	S9914881J
Date Of Birth	17/05/1999
Occupation	INDOOR
Date Of Driving Pass	10/11/2017
Driving Experience	1 YEAR AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96449907
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 213 PETIR ROAD #09-501
 Postcode 670213
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured CHILDREN
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : SHEN YI
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 27/04/2019 AT AROUND 1615HRS, I WAS DRIVING MY CAR (SMK4273R) INSIDE IMM CARPARK LEVEL 3. I WAS DRIVING BEHIND LORRY (GBG3110K) WHILE LOOKING FOR A PARKING LOT. AS WE CAME TO A 'L' SHAPE TURN, I WAS HALFWAY THROUGH THE TURN AND I NOTICED A LORRY (GBG3110K) HAD STOPPED. HENCE, I STOP MY CAR. LORRY (GBG3110K) THEN REVERSED SUDDENLY AND HIT ONTO MY CAR. DRIVER OF (GBG3110K) THEN REVERSED SUDDENLY AND HIT ONTO MY CAR. DRIVER OF LORRY (GBG3110K) SIGNED AGREEMENT LETTER TO COMPENSATE MY VEHICLE DAMAGE.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: WITH TP WORKSHOP
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBG3110K
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver AW WEE XIANG WINSTON
 NRIC/Passport Number S9144288D
 Contact Number 90068235

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


Sketch Plan Pg. 1


SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:



 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

IMM CAR PARK LEVEL 3



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27th April 2019 at around 1615 hours, I as driving my car SMK 4 273R inside IMM Carpark level 3. I was driving behind lorry GBB 3110K while looking for a parking lot. As we came to an 'L' shape turn, I was halfway through the turn and I noticed lorry GBB 3110K has stopped hence I stopped my car. Lorry GBB 3110K then reversed suddenly and hit onto my car. Drive at lorry GBB 3110K signed agreement letter to compensate my vehicle damage.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #4 Pg. 1

**REPUBLIC
POLYTECHNIC**

Location : IMM Carpark Level 3, Infront of Auto make over car detailing

Vehicle G86G 3110K reverse and knocked into SUK 4273R.

Damage to SUK 4273R Front right bumper and car driver side door unable to open.

No damage to G86G 3110K.

Agreed to settle privately if the amount is below 5 thousand Singapore dollars. After Komoco assess the vehicle damages, will decide to claim privately or by insurance.

Teo Jin Hee

Teo Jin

27/4/2019

WATSON AU

W

27 04 19

Submit to insurance.

Vehicle: SMK4273R

Make & Model: Hyundai Avante (S)

Chassis No:

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend	
1	Front Right Headlamp	1		1856.00	one ✓	1756
2	Front Bumper			574.00	Dis ✓	425
3	Front Bumper Chips		*	30.00SV	me ✓	
4	Front Bumper Right Retainer			67.00	3rd ✓	
5	Front Bumper Right Fog Lamp Garnish			62.00	cut ✓	
6	Front Bumper Right Fog Lamp			184.50	11 X	
7	Front Fender			986.40	Dis ✓	966
8	Front Fender Inner shield			195.70	70m ✓	
9	Front Fender Inner shield Chips		*	30.00SV	me ✓	
10	Front Right Sports Rim		*	871.30	cut 450s. ✓	
11	Front Right Door			1851.00	20/2nd ✓	1831
12	Front Right Door Glass Moulding			68.90	11 X	
13	Front Right Door Sticker (Black)			84.00	me ✓	
14	Front Right Door Inner Rubber			189.00	me ✓	
15				20%		
16						
17	Not Authorized				P-5625.70	
18	MLL				20%	
19	29/4/19 Hdy				P-4500.56	
20	Take ph. before pa. dy.				S.N 510.00	
21	P/p 6/50.56				1wh 1140.00	
22					2MAL 6/50.56	

Labour					
1	Check Wiring			\$ 120.00	20
2	Anti Rust Proofing			\$ 100.00	60
3	Transfer Door			\$ 150.00	60
4	Panel Beating			\$ 800.00	400
5	Paint Work			\$900	600

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19007572/USD3N2

Date: 28/05/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30406118000	
Claimant Vehicle No :	SMK4273R	Insured Vehicle No :	GBG3110K	
Date of Loss:	27/04/2019	Nature of Claim:	TP	Claim No: SNM19D201874C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK4273R	Engine No:	G4FGKU124900
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Chassis No:	KMHD841CMKU891831
Reg. Date:	10/04/2019 (Man. Year: 2019)	Odometer:	1528 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Kumho 9 mm	Rear Left Side:	Kumho 9 mm
Front Right Side:	Kumho 9 mm	Rear Right Side:	Kumho 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,049.80	5,010.56	2,039.24	28.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,070.00	1,140.00	930.00	44.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	9,119.80	6,150.56	2,969.24	32.56

INSPECTION

Date of Assignment:	30/04/2019	
Date Inspected:	29/04/2019	Inspected At: Stytech Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #02-30, Kaki Bukit Autohub Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 May 2019)
Parts: 143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMK4273R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RIGHT HEADLAMP	Cracked	1,856.00 F	*1,756.00 FL
2	1		*FRONT BUMPER	Distorted	574.00 F	*475.00 FL
3	1		*FRONT BUMPER RIGHT RETAINER	Bent	67.00 F	*67.00 FL
4	1		*FRONT BUMPER RIGHT FOG LAMP GARNISH	Cut	62.00 F	*62.00 FL
5	1		*FRONT BUMPER RIGHT FOG LAMP	Not Necessary	184.50 F	*- FL
6	1		*FRONT FENDER	Distorted	986.40 F	*966.00 FL
7	1		*FRONT FENDER INNER SHIELD	Torn	195.70 F	*195.70 FL
8	1		*FRONT RIGHT DOOR	Dented/Bent	1,851.00 F	*1,831.00 FL
9	1		*FRONT RIGHT DOOR GLASS MOULDING	Not Necessary	68.90 F	*- FL
10	1		*FRONT RIGHT DOOR STICKER (BLACK)	Necessary	84.00 F	*84.00 FL
11	1		*FRONT RIGHT DOOR INNER RUBBER	Necessary	189.00 F	*189.00 FL
12	1		*FRONT BUMPER CHIPS	Necessary	30.00 FS	*30.00 FS
13	1		*FRONT FENDER INNER SHIELD CHIPS	Necessary	30.00 FS	*30.00 FS
14	1		*FRONT RIGHT SPORTS RIM	Cut	871.30 FS	*450.00 FS
					Sub Total (S\$)	7,049.80
					- List Item Discount on L Items 0.00/20.00% (S\$)	0.00
					Total Parts (S\$)	7,049.80
						5,010.56

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING	New	120.00	20.00
2	ANTI RUST PROOFING	New	100.00	60.00
3	TRANSFER DOOR	New	150.00	60.00
4	PANEL BEATING	New	800.00	400.00
5	PAINT WORK	New	900.00	600.00
Gross Labour Cost (S\$)			2,070.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >