

2019/04/19
Last Modified

FILE CS3/AIG19007580/Ccd309

ASSIGNMENT (Office)

Chin Lee Ying
Minimen

AIG

Date/Time 30/4/19 @ 11:06am

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / RYA / INV / MY / CS

To Inspect Vehicle No.

PC8863T

Insured

SLV 2569E

at Workshop no.

Yang Sing

Tel

9182 0027

of

53 Defu lane 12

Policy No.

Claim No.

05251364748G

Sum Insured

Excess

Make of Veh.

D.O.A

26/4/2019

Client's Record

CA / REV / REP. / REV. 24 HRS

H.O.D. Endorsement

Date/Time

11:20am @ 30/4/19

Person Contacted

Sam

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

PC8863T - X

SLV 2569E - X

Dismantle: 3/5/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Apr 2019 Edit Reg		30 Apr 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	BLUE STAR CONCIERGE PTE LTD, Co. Reg. No.: 201506692D								
Main Claimant:	TOK'S SCHOOL BUS SERVICE, Co. Reg. No.: 28666000L								
Vehicle Reg. No.:	PC8863T	Date of Loss:	26/04/2019 16:00 - :59						
Claim Type:	TP / 0525136474SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SLV2569E	Policy No. (Claimant):							
		Excess:							
Repairer:	Yong Sing Motor Works (HQ) No. 10 Defu Lane Singapore 539315, 539315 Defu Lane - Tel: 82677782								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 10/05/2019]								
Claimant's Solicitor:	KURU & CO - Tel: 65322009								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
<ul style="list-style-type: none"> AIG_SG (02/05/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS <input type="checkbox"/>			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Your password will expire in 13 days. [Click here to change it.](#)

ACCIDENT INVOLVING OUR INSURED VEHICLE SLV2569E AND P...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 30/4/2019 11:06:25 AM
Attachments:  SAS PC8863T.PDF

Hi LKK,

Kindly assist to survey today, vehicle in Yong Sing, 53, Defu Lane 12, (S) 539144, contact person is Sam, 91820027.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: Monday, April 29, 2019 8:08 PM
To: Hor, Yinrul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur
Subject: [EXTERNAL] L19.0534.cj (please quote of ref) - ACCIDENT INVOLVING OUR INSURED VEHICLE SLV2569E AND PC8863T ON 26/04/2019

This message is from an external sender; be cautious with links and attachments.

Dear Sirs

We confirm that you have objected to our client's list of surveyors. Our client's vehicle is at the following address:

AUTO GEAR PTE LTD
23 Kaki Bukit Rd 4

#01-22 Synergy @ KB
Singapore 417801
Tel: Pierre 94599091

Please inform your surveyor to conduct the pre-repair survey within 2 working days, failing which our client will have no alternative but to proceed with the repair of his vehicle.

Regards

Irene

Kuru & Co

150 South Bridge Road

#04-06 Fook Hai Building

Singapore 058727

Tel: 6532 2009

Fax: 6532 2007

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	PC8863T		
Vehicle Type :	Z20 - Private Hire (Chauffeur) Bus/Coach/Minibus		
Vehicle Attachment 1 :	Air-Conditioned		
Vehicle Scheme :	Public Service Vehicle (Others)		
Vehicle Make :	TOYOTA		
Vehicle Model :	HIACE COMMUTER GL 3.0 A		
Chassis No. :	KDH2230017384		
Propellant :	Diesel		
Engine No. :	1KD2307590		
Engine Capacity :	2982 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	2990 kg		
Unladen Weight :	2140 kg		
Year Of Manufacture :	2013		
Original Registration Date :	11 Nov 2013		
Lifespan Expiry Date :	10 Nov 2033		
COE Category :	C - Goods Vehicle & Bus		
Quota Premium :	\$73,999.00		
COE Expiry Date :	10 Nov 2023		
Road Tax Expiry Date :	10 Nov 2019		
Inspection Due Date :	10 Nov 2019		
Intended Transfer Date :	19 Jun 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	6000L
Vehicle Details	
Vehicle No.:	PC8863T
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE COMMUTER GL 3.0 A
Primary Colour:	Silver
Manufacturing Year:	2013
Engine No.:	1KD2307590
Chassis No.:	KDH2230017384
Maximum Power Output:	-
Open Market Value:	\$40,596.00
Original Registration Date:	11 Nov 2013
First Registration Date:	11 Nov 2013
Transfer Count:	1
Actual ARF Paid:	\$2,030.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	10 Nov 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$73,999.00
COE Rebate Amount:	\$32,510.00
Total Rebate Amount:	\$32,510.00

The information contained herein is correct as at 19 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/04/2019 13:27
Date Of Accident	26/04/2019 16:15
Exact Location Of Accident	LI HWAN DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC8863T
Insured/Policyholder	
Name Of Registered Owner	TOK'S SCHOOL BUS SERVICE
Co Reg No	28666000L
Email Address	PA@EZBUZZ.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-94599091

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE COMMUTER GL 3.0 A
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	DMCFHQ18-000076
Cover Note Number	

Driver

Name of Driver	LIM SIAK LAI
NRIC No	S6831168C
Date Of Birth	02/08/1968
Occupation	OUTDOOR
Date Of Driving Pass	14/03/1998
Driving Experience	21 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91415518
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 44 CIRCUIT ROAD #06-619
Postcode	370044
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : N/A GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLV2569E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2


Vehicle Registration Number	GBH1612L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan #2 Pg. 1

B → SLV 2569E

C → GBH 1612L

A → PL 8863T



On the 26th April 2019, at about 16:15 hrs. While I was driving from CHIS (out lobby of Good Council). Serving student back from CCA session. While I was driving along Li Hwan Dr. I was hit by vehicle (B) ~~SLV 2569E~~ SLV 2569E from Tai Hwan Height. into the yellow box from my right hand side direction.

My vehicle started to skid as vehicle (B) hit on my rear right side of my tyre & body. I started to step on the brakes and my vehicle swing toward the right side of the road and hit on a van (Vehicle C.) GBH 1612L).

Which stop outside 28 Li Hwan Dr from opposite direction

I check on my student on board at the bus. if ~~the~~ there is any injuries. ~~It~~ then I continue to take photo of the scene & exchange Driver Detail.

Towing Service was called as my rear tyre was damage.

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:





EQ Insurance Company Limited
 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
 tel 65 6223 9433 | fax 65 6224 3903 | www.eqinsurance.com.sg
 reg no. 1978-00490-N



CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 (MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
 (REPUBLIC OF SINGAPORE)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

COMMERCIAL VEHICLE FLEET Comprehensive

Certificate No.: DMCFHQ18-000076

Form: HL1-1

Excess:

1. Index Mark and Registration Number of Vehicles
 PC8863T

Section 1 SGD2,000.00

Section 2 SGD2,000.00

YEID-AC Additional SGD3,000.00

Windscreen SGD200.00

2. Name of Policyholder
 Tok's School Bus Service

3. Effective Date of the Commencement of Insurance for the purpose of the Act
 28/04/2018

4. Date of Expiry of Insurance
 27/04/2019

5. Person or Classes of Persons entitled to drive*

1. The Policyholder

2. Any person on the order or with the permission of the Policyholder

*Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act has not been cancelled at the time of accident loss or damage.

6. Limitations as to use*

Use only for the carriage of passenger in connection with the Insured & their subsidiary or associated company's business as described in the Schedule.

THE POLICY DOES NOT COVER

- (1) Use for racing, pace-making, reliability trial or speed-testing.
- (2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.
- (3) Liability arising from or in connection with the carriage of hazardous materials, high explosives, inflammable liquid or gases including LPG in cylinders.
- (4) Use for any purpose in connection with the Motor Trade.

*Limitations rendered inoperative by Section 8 of the Motor vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or and Amendment, Act or Acts passed in substitution thereof.

Authorized Signatory
 EQ Insurance Company Limited

nisjb/HO/A000255/Winner Consultancy P



A Member of Citystate

Condition (CON)
 (01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched (07) Deformed
 (08) Shifted (09) Buckled (10) Broken (11) Necessary (12) Missing (13) Torn
 (14) Unconfirmed (15) Not Working

VAN / LORRY (Frt)

ACTION (AC)
 (1) Replace (✓) (2) Repair (N) (3) Check (P)
 (4) Not Consistent (NC)

Aug 2005

Vehicle No: **PC 8863T**

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frnt Number Plate			
1002	991887	Frnt Number Plate Base			
1004	991300	Frnt Bumper			
2001	991477	Frnt Bumper Upper clips	De	✓	
2002	991387	Frnt Bumper Lower	Ma	✓	
2003	991449	Frnt Bumper Side Cover			
2004	991443	Frnt Bumper Side retainer RH	Re	✓	
1006	991325	Frnt Bumper Bracket			
1008	991433	Frnt Bumper Reinforcement	BT	✓	
2005	991466	Frnt Bumper Signal Lamp			
1017	995100	Frnt LH Bumper Fog Lamp Cover			
1018	991355	Frnt RH Bumper Fog Lamp Cover	Re	✓	
1019	995079	Frnt LH Bumper Fog Lamp			
1020	995080	Frnt RH Bumper Fog Lamp			
1021	991793	Frnt Grille			
1022	991328	Frnt Grille Emblem			
2006	990247	Frnt Grille Sticker			
1023	991799	Frnt Grille Chrome Moulding			
2007	991891	Frnt Panel			
2008	991874	Frnt Lower Panel			
2009	991328	Frnt Panel Emblem			
2010	990247	Frnt Panel Sticker			
2011	991893	Frnt Panel Garnish			
1024	991222	Frnt Apron Panel			
2012	991527	Frnt Corner Panel	buc	✓	
2013	991532	Frnt Corner Panel Signal Lamp			
2014	995245	Frnt Signal Lamp LH			
2015	995246	Frnt Signal Lamp RH			
1029	995153	Frnt LH Headlamp Assy			
1030	991821	Frnt RH Headlamp Assy	CRA	✓	
1031	995088	Frnt LH Side Lamp			
1032	995089	Frnt RH Side Lamp			
2016	992149	Frnt Wiper Panel			
2017	995043	Frnt Wiper Nozzle			
1120	992140	Frnt Wiper Arm			
1121	992142	Frnt Wiper Blade			
2018	992145	Frnt Wiper Link			
2019	992148	Frnt Wiper Motor			
1122	995045	Wiper Panel Garnish			
1114	992093	Frnt Windscreen			
1115	992097	Frnt Windscreen Rubber			
1117	992098	Frnt Windscreen Sealant			
2020	992114	Frnt Windscreen Outer Pillar			
2021	992113	Frnt Windscreen Inner Pillar			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
2022	991958	Frnt Side Mirror (Big)			
2023	991959	Frnt Side Mirror (Small)			
2024	991962	Frnt Side Mirror (Round)			
2025	995015	Frnt Wing Mirror Stay			
1025	992013	Frnt Support Panel			
1033	990248	Bonnet	repair		
1035	990287	Bonnet Lock			
1037	990273	Bonnet Hinge Emblem	MC	✓	
1039	990305	Bonnet Rubber			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1056	992758	Radiator Hose Top			
1058	992741	Radiator Expansion Tank			
2026	992596	Oil Cooler			
1079	994431	Power Steering Cooler Pipe			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy	CRA	✓	
1067	990219	Battery			
1069	990223	Battery Bracket			

NAC	INC	Item	CON	AC	Qty
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
2027	991500	Frnt Cabin Assy			
2028	991501	Frnt Cabin Mounting			
2029	991502	Frnt Cabin Rear Panel			
1092	991520	Frnt LH Chassis Member			
1093	991520	Frnt RH Chassis Member			
1094	990728	Frnt Vertical Cross Member			
1095	991863	Frnt Lower Cross Member			
2030	990143	Air Con Evaporator Assy			
2031	990106	Air Con Blower			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
2032	990431	Brake Pedal			
2033	990021	Accelerator Pedal			
2034	990627	Clutch Pedal			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1131	990029	Airbag Control Unit			
1133	991922	Frnt RH Seat Belt Assy			
1135	995182	Frnt LH Seat Belt Assy			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1096	995070	Frnt LH Fender			
1097	995072	Frnt LH Fender Inner Panel			
1100	991740	Frnt LH Fender Inner Shield			
1101	995179	Frnt LH Mudflap			
2035	994966	Frnt LH Wheel Guard			
1102	995170	Frnt LH Wheel Rim			
1104	995065	Frnt LH Tyre			
1105	995071	Frnt RH Fender			
1106	991739	Frnt RH Fender Inner Panel			
1109	991740	Frnt RH Fender Inner Shield			
1110	991884	Frnt RH Mudflap			
2036	994966	Frnt RH Wheel Guard			
1111	992087	Frnt RH Wheel Rim			
1113	995065	Frnt RH Tyre			
1255	995326	Frnt LH Door			
1256	995140	Frnt LH Door Protector			
1257	995104	Frnt LH Door Hinge			
1258	995142	Frnt LH Door Wing Mirror			
1262	995103	Frnt LH Door Glass			
1263	991595	Frnt LH Door Glass Regulator			
1264	991596	Frnt LH Door Glass Regulator Motor			
1265	991662	Frnt LH Door Rubber			
1266	991636	Frnt LH Door Outer Handle			
1272	991617	Frnt LH Door Inner Trim Board			
1316	995327	Frnt RH Door	repair		
1317	991654	Frnt RH Door Protector			
1318	991601	Frnt RH Door Hinge			
1319	991685	Frnt RH Door Wing Mirror	Cut	✓	
1323	991584	Frnt RH Door Glass			
1324	991595	Frnt RH Door Glass Regulator			
1325	991596	Frnt RH Door Glass Regulator Motor			
1326	991662	Frnt RH Door Rubber			
1327	991636	Frnt RH Door Outer Handle			
1333	991617	Frnt RH Door Inner Trim Board			
2037	991644	Frnt Door Frnt Pillar	repair		
2038	991657	Frnt Door Rear Pillar			
2039	992072	Frnt Wheel Arch Panel			
2040	992069	Frnt Wheel Arch Panel Garnish			
2041	991996	Frnt Step Panel	repair		
2042	994498	Frnt Step Panel Top Garnish	Cut	✓	
2043	994495	Frnt Step Panel Inner Garnish			
1073	995053	Wiper Washer Tank			
1136	990247	Sticker	MC	✓	
		Body panel RH	repair		
		Rear RH wheel Rim	BT	✓	

No of Items: _____

Assessor: **18 Mys.**

original copy

" " " " cover / Cut
 " " Tyre - ~~MC~~ Cut
 " " wheel bearing - MC

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Apr 2019 Edit Reg		30 Apr 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	BLUE STAR CONCIERGE PTE LTD , Co. Reg. No.: 201506692D		
Main Claimant:	TOK'S SCHOOL BUS SERVICE , Co. Reg. No.: 28666000L		
Vehicle Reg. No.:	PC8863T	Date of Loss:	26/04/2019 16:00 - :59 [65 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 0525136474SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SLV2569E	Policy No. (Claimant):	
		Excess:	
Repairer:	Yong Sing Motor Works (HQ) No. 10 Defu Lane Singapore 539315, 539315 Defu Lane - Tel: 82677782		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 10/05/2019]		
Claimant's Solicitor:	KURU & CO - Tel: 65322009		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (02/05/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*PC8863T (0525136474SG)
[SLV2569E]
TP
TOK'S SCHOOL BUS SERVICE
Apr 26 2019 4:00PM
[BLUE STAR CONCIERGE PTE LTD]
Yong Sing Motor Works

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser <input type="button" value="v"/>		
Photos/Images										3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	02/05/19 09:21	General View							Load JPG	<input checked="" type="checkbox"/>		
2	02/05/19 09:21	General View							Load JPG	<input checked="" type="checkbox"/>		
3	02/05/19 09:21	General View							Load JPG	<input checked="" type="checkbox"/>		
4	02/05/19 09:21	General View							Load JPG	<input checked="" type="checkbox"/>		
5	02/05/19 09:21	General View							Load JPG	<input checked="" type="checkbox"/>		
6	02/05/19 09:21	General View							Load JPG	<input checked="" type="checkbox"/>		
7	02/05/19 09:21	General View							Load JPG	<input checked="" type="checkbox"/>		
8	02/05/19 09:21	General View							Load JPG	<input checked="" type="checkbox"/>		
9	02/05/19 09:21	General View							Load JPG	<input checked="" type="checkbox"/>		
10	02/05/19 09:21	General View							Load JPG	<input checked="" type="checkbox"/>		
11	02/05/19 09:21	General View							Load JPG	<input checked="" type="checkbox"/>		
12	02/05/19 09:21	General View							Load JPG	<input checked="" type="checkbox"/>		
13	02/05/19 09:21	General View							Load JPG	<input checked="" type="checkbox"/>		
14	02/05/19 09:21	General View							Load JPG	<input checked="" type="checkbox"/>		
15	02/05/19 09:21	General View							Load JPG	<input checked="" type="checkbox"/>		
16	02/05/19 09:21	General View							Load JPG	<input checked="" type="checkbox"/>		
17	02/05/19 09:21	General View							Load JPG	<input checked="" type="checkbox"/>		
18	02/05/19 09:21	General View							Load JPG	<input checked="" type="checkbox"/>		
19	02/05/19 09:21	General View							Load JPG	<input checked="" type="checkbox"/>		
20	02/05/19 09:21	General View							Load JPG	<input checked="" type="checkbox"/>		
21	02/05/19 09:21	General View							Load JPG	<input checked="" type="checkbox"/>		
22	02/05/19 09:21	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>		
23	19/06/19 12:48	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
24	19/06/19 12:48	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
25	19/06/19 12:48	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
26	19/06/19 12:48	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
27	19/06/19 12:48	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
28	19/06/19 12:48	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
29	19/06/19 12:48	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
30	19/06/19 12:48	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
31	19/06/19 12:48	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
32	19/06/19 12:48	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
33	19/06/19 12:48	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
34	19/06/19 12:48	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
35	19/06/19 12:48	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
36	19/06/19 12:48	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
37	19/06/19 12:48	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
38	19/06/19 12:48	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
39	19/06/19 12:48	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
40	19/06/19 12:48	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
41	19/06/19 12:48	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
42	19/06/19 12:48	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
43	19/06/19 12:48	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	19/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	19/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	19/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	19/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	19/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	19/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	19/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	19/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	19/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	19/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	19/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	19/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19007580/GCD3E2

Date: 07/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : PC8863T **Insured Vehicle No :** SLV2569E

Date of Loss: 26/04/2019 **Nature of Claim:** TP **Claim No:** 0525136474SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC8863T		
Make & Model:	TOYOTA HIACE, 3.0 COMMUTER GL (A)	Engine No:	1KD2307590
Reg. Date:	11/11/2013 (Man. Year: 2013)	Chassis No:	KDH2230017384
Colour:	Silver	Odometer:	436531 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 30/04/2019

Date Inspected: 30/04/2019 Inspected At: 53 DEFU LANE 12
 Repairer : Yong Sing Motor Works (HQ)

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRT BUMPER	Deformed	0.00 F	*- F	
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F	
3	1		*FRT BUMPER SIDE RETAINER RH	Deformed	0.00 F	*- F	
4	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F	
5	1		*FRT RH BUMPER FOG LAMP COVER	Deformed	0.00 F	*- F	
6	1		*FRT CORNER PANEL	Buckled	0.00 F	*- F	
7	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F	
8	1		*BONNET	Repair	0.00 F	*- F	
9	1		*BONNET EMBLEM	Necessary	0.00 F	*- F	
10	1		*AIR CLEANER ASSY	Cracked	0.00 F	*- F	
11	1		*FRT RH DOOR	Repair	0.00 F	*- F	
12	1		*FRT RH DOOR WING MIRROR	Cut	0.00 F	*- F	
13	1		*FRT DOOR FRT PILLAR	Repair	0.00 F	*- F	
14	1		*FRT STEP PANEL	Repair	0.00 F	*- F	
15	1		*FRT STEP PANEL TOP GARNISH	Cut	0.00 F	*- F	
16	1		*STICKER	Necessary	0.00 F	*- F	
17	1		*BODY PANEL RH	Repair	0.00 F	*- F	
18	1		*REAR RH WHEEL RIM	Bent	0.00 F	*- F	
19	1		*REAR RH WHEEL RIM COVER	Cut	0.00 F	*- F	
20	1		*REAR RH TYRE	Cut	0.00 F	*- F	
21	1		*REAR RH WHEEL BEARING	Necessary	0.00 F	*- F	
					Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >