

Assigned By: *3/ave* REP: CS3/AIG19007581 / Ecd3⁸²
 Assignment Office: AIG Date/Time: 30/4/19 @ 10:41am
 Insured: *mun chin lee ying* Insured: SJD 1982
 Estimated Cost: Bill to: 6786 2884
 To Insure Vehicle No: SKQ 6754
 at Workshop no: Tampines Auto
 of: B1K 9002 Tampines St. 93 # 01-36
 Policy No: 1800017990 Claim No: 815768569386
 Sum Insured: Excess:
 Make of Vehicle: DOA: 27/04/2019
 (Client's Record)


CA / REV / REP / REV 24 HRS		H.O.D. Endorsement	
Date/Time: 11:10am @ 30/4/19	Person Contacted: <i>Linda</i>	Vehicle: <u>IRU</u> / <u>MTT</u>	
Date/Time	Action/Instruction (X) Estimate		
	SKQ 6754 - NA / INC19007548 / 24	DOA: 27/4/2019	
	SJD 1982 - NA / INC19007548 / 24	DOA: 27/4/2019	
	Dismantle: 2/5/2019		
	After repair: 6/5/2019		

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 QD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 at: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: 6 Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time : Action / Instruction

MV- 193,000 Repair days - 6 days
 PV- 75,384
 MV- 27,616

Veh No: SKR 675H Yr Regn: 31/10/14
 Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota vellfire CC: 2362
 Colour: Black A/C Insured / Std / NI / N/
 Sp. Reading: 193315 T/Ratio: Insured / Std / NI / N.
 Eng/No: _____
 CiNo: ANH 208309026
 Gen. Cond: Good (Fair) / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 235/55ZR18
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Kin forest
 Front: _____ Rear: _____
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 27/4/19 D.O.I. 30/4/19
 Survey held at Tampines Auto
 Des. of Damages: Frt / (Rear) / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date/Time. File Pass to?

☐ : Prel. Report
☐ : Final Report

4) Date/Time. File Return to?
 3)

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee: 180

Transportation

) 3 + R. 01

) 100000

) 100000

) 100000

) 100000

Report Format: DAR

Lump Sum / I.B.I. (\$)

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : Weekend (\$

100000

...CLAIM SUBFOLDER...(Pending for Survey Report)

PR1

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Apr 2019 Edit Reg		30 Apr 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	BARATHAN S/O PASUPATHI, ID: S6818469Z		
Main Claimant:	Unknown		
Vehicle Reg. No.:	SKQ675H	Date of Loss:	27/04/2019 15:00 - :59
Claim Type:	TP / 8157635693SG	Policy/Cover Note No.:	1800017990 (Comprehensive) Coverage: 28/02/2019 - 27/02/2020
Vehicle Reg. No. (Insured):	SJD198Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Tampines Auto Services (HQ) BLK 9002 TAMPINES ST 93, #01-34/36 INDUSTRIAL PARK A, 528836 Tampines - Tel: 67862884		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 10/05/2019]		
Claimant's Solicitor:	LEGAL OPTIONS LLC - Tel: 64388039		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG (02/05/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Your password will expire in 13 days. [Click here to change it.](#)

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 30/4/2019 10:41:54 AM
Attachments:  SKQ675H vs SJD198Z.PDF

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: Joycelyn [mailto:joycelyn@legaloptions.biz]
Sent: Tuesday, April 30, 2019 9:07 AM
To: Hor, Yinrul
Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJD198Z AND SKQ675H ON 27/04/2019

This message is from an external sender; be cautious with links and attachments.

Dear Sir/Mdm,
We refer to your
Our client rejected your list of surveyors.

We provide you herewith our client's surveyors:-

	CONTACT PERSON
1	HOW ANDREW
2	LEE KOK WENG
3	SEAH KWANG BOON

Your said surveyor may liaise directly with our client's repairer,
Ms Linda at 6786 2884 for
the pre-repair inspection to be carried out.

The workshop is located at M/s Tampines Auto Services, [Block 9002 Tampines Street 93, #01-36](#) Tampines Industrial Park A, Singapore 528836.

*

If we do not hear from you within 2 days of this email, our clients shall deem that you have agreed that the surveyor appointed by our clients shall be our single joint expert for this matter.

Thanks n regards,

Joycelyn Sim

Legal Secretary

LEGAL OPTIONS LLC

(GST Registration/UEN No. 201203825R)

Tel (65) 6513-2800 DID (65) 6513-2807 Fax (65) 6438-8275

Information in this message is confidential and may be legally privileged. It is intended solely for the person(s) to whom it is addressed. If you are not the intended recipient, please delete the message and any other record of it from your system, and notify the sender immediately.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/04/2019 12:23
Date Of Accident	27/04/2019 16:00
Exact Location Of Accident	JUNC PAYA LEBAR RD & EUNOS AVE 5
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKQ675H
Insured/Policyholder	
Name Of Registered Owner	FRIENDLY LIMOUSINE SERVICES
Co Reg No	52932025L
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93807269
Alternative Phone No	OFFICE-93807269

Vehicle Particulars

Manufacturer	TOYOTA
Model	VELLFIRE 2.4Z G-EDITION CVT 2WD 5DR
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5068255877-04
Cover Note Number	

Driver

Name of Driver	MOHAMMAD REDZWAN BIN JAMIL
NRIC No	S8020411F
Date Of Birth	13/07/1980
Occupation	OUTDOOR
Date Of Driving Pass	12/05/2005
Driving Experience	13 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93807269
Fax Number	
Contact Number	OFFICE-93807269
EMail Address	NOEMAIL

Address	BLK 388 TAMPINES STREET 32 #03-75
Postcode	520388
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : - GENDER: : MALE
Passenger 2	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON STATED DATE AND TIME, MY VEHICLE WAS STATIONARY STOPPED ALONG THE STATED VENUE AS TRAFFIC JUNCTION WAS RED. SUDDENLY I FELT AN IMPACT OF MY VEHICLE AND REALIZE THAT VEHICLE B HIT ONTO MY VEHICLE REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJD198Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	BARATHAN S/O PASUPATHI
NRIC/Passport Number	S6818469Z
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for compliance with requirements under any regulations, laws or court orders.

Friendly Limousine Service

10 Anson Road #21-02 International Plaza
Singapore 079903
Off +65 9666 2692 Fax +65 6764 4832
Mobile +65 9380 7269 Reg No 52932025L
www.friendlylimo.com.sg

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to statement.

Friendly Limousine Service

10 Anson Road #21-02 International Plaza
Singapore 079903
Off +65 9666 2692 Fax +65 6784 4832
Mobile +65 9360 7256 Reg No 52932025L
www.friendlylimo.com.sg

Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Inquire PARF/COE Rebate for Registered Vehicle	
Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	2025L
Vehicle Details	
Vehicle No.:	SKQ675H
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VELLFIRE 2.4Z G-EDITION CVT 2WD 5DR
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	2AZG286677
Chassis No.:	ANH208309026
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$39,818.00
Original Registration Date:	31 Oct 2014
First Registration Date:	31 Oct 2014
Transfer Count:	0
Actual ARF Paid:	\$47,746.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Oct 2024
PARF Rebate Amount:	\$35,809.00
Intended COE Rebate Details	
COE Expiry Date:	30 Oct 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$71,990.00
COE Rebate Amount:	\$39,575.00
Total Rebate Amount:	\$75,384.00

The information contained herein is correct as at 30 Apr 2019

OK

- Is it alright to pay more for the Toyota brand?
- Two discount voucher
- Foldable bicycle

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Car Rental Honda Stream 1.8i
2.0i 1600cc 1500cc 1600cc
Finance 2 years (Monthly \$1,200)
Down Monthly from \$1,200
GV Credit Pte Ltd - Shared

KA-HUP
VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND
HOTLINE: 6741 9997 [VIEW OUR CARS](#)

Browse by Category

Sort by Date Posted 20 results/page

11 vehicles

Toyota Vellfire

Advanced Search

Model	Price	Depreciation	Reg. Cost	Eng. Cap.	Mileage	Veh. Type	Status
-------	-------	--------------	-----------	-----------	---------	-----------	--------

Search Selection: Toyota Vellfire Any Any 2014 Any Any Any Available

 **Toyota Vellfire 2.4A Z G-Edition** \$101,800 \$16,720 /yr 02-Jan-2014 2,362 cc 113,286 km MPV Available

Luxury Toyota Vellfire 2.4A Z G-Edition 7 Seater, GPS/DVD, Twin Sunroof, Dual Power Sliding Doors, Rear Captain Seats, Keyless Entry/Start/Stop, Auto HID Headlights, LED Tail Lamp, Trade-In Welcome! ...

Motor-Way Credit Pte Ltd

Posted: 29-Apr-2019 Tags: 2014 Toyota Vellfire, 2014 toyota vellfire, Toyota Vellfire, toyota vellfire, Toyota, Vellfire, vellfire, Used Toyota

 **Toyota Vellfire 2.4A Z Platinum Selection** \$103,000 \$16,950 /yr 11-Feb-2014 2,362 cc 72,800 km MPV Available

One Owner With Low Mileage Of 72.8k KM Mileage, Non - Lino Unit, A Deal Not To Be Missed, 160 Point Assurance Check Done. Please Call Our Sales Consultant For More Enquiries Now.

Inchcape Pre-Owned

Posted: 30-Apr-2019 Tags: 2014 Toyota Vellfire, 2014 toyota vellfire, Toyota Vellfire, toyota vellfire, Toyota, Vellfire, vellfire, Used Toyota

 **Toyota Vellfire 3.5A Z Golden Eyes II** \$106,500 \$16,590 /yr 28-Mar-2014 3,456 cc 28,000 km MPV Available

Only 1 Owner, Rare Unit In The Market, 3.5 Auto Golden Eye II With Low Mileage, Excellent Condition, Please Call Our Sale For More Info And Test Drive To Believe, In House Loan And Bank Loan Available...

Posted: 13-Apr-2019 Tags: 2014 Toyota Vellfire, 2014 toyota vellfire, Toyota Vellfire, toyota vellfire, Toyota, Vellfire, vellfire, Used Toyota

 **Toyota Vellfire 3.5A Z G-Edition** \$112,000 \$16,990 /yr 07-Apr-2014 3,456 cc 42,000 km MPV Available

Genuine Mileage Done At 42,000KM! Under Utilize Like New Inside Out! Owner's Second Car, Always Parked Under Shade, 100% Accident Free! Warranty On All Major Parts After Sales For Your Peace Of Mind, ...

Posted: 01-Apr-2019 Tags: 2014 Toyota Vellfire, 2014 toyota vellfire, Toyota Vellfire, toyota vellfire, Toyota, Vellfire, vellfire, Used Toyota

Car Buying Car Selling Car Ownership Buying a pre-owned car, but unsure of its condition? Get STA Car Evaluation

 **Toyota Vellfire 2.4A Z** \$99,800 \$15,630 /yr 10-May-2014 2,362 cc MPV Available

Excellent Condition And Very Well Maintained, 1 Owner Only, Low Mileage, View To Believe, Bank Loan/Loan In House Loan Available! Trade In Most Welcome! Call/SMS/WhatsApp Our Friendly Sales Reps Today...

Posted: 06-Apr-2019 Tags: 2014 Toyota Vellfire, 2014 toyota vellfire, Toyota Vellfire, toyota vellfire, Toyota, Vellfire, vellfire, Used Toyota

 **Toyota Vellfire 2.4A Z** \$104,800 \$16,550 /yr 22-May-2014 2,362 cc 104,000 km MPV Available

Evaluated By VCDM, Free 6 Months Maintenance And 1 Grooming, Special 8 Seater

Yong Lee Seng Motor

Posted: 19-Apr-2019 Tags: 2014 Toyota Vellfire, 2014 toyota vellfire, Toyota Vellfire, toyota vellfire, Toyota, Vellfire, vellfire, Used Toyota

 **Toyota Vellfire 2.4A Z G-Edition** \$102,800 \$15,590 /yr 23-May-2014 2,362 cc 62,113 km MPV Available

Black Vellfire 2.4A Z G-Edition, 7 Seater MPV, Twin Power Sliding Doors. Call Us For More Info And Viewing.

Posted: 26-Apr-2019 Tags: 2014 Toyota Vellfire, 2014 toyota vellfire, Toyota Vellfire, toyota vellfire, Toyota, Vellfire, vellfire, Used Toyota

 **Toyota Vellfire 2.4A Z G-Edition** \$99,000 \$14,210 /yr 06-Aug-2014 2,362 cc 88,000 km MPV Available

Comes With Bided 333k Rate! Extremely Competitively Priced! Come Find Out Why This Is One Of The Hottest Selling 7 Seater MPVs Around! Sleek White Exterior Against Clean And Neat Interior! Immense C...

Car Buyers Automotive Pte Ltd

Posted: 05-Apr-2019 Tags: 2014 Toyota Vellfire, 2014 toyota vellfire, Toyota Vellfire, toyota vellfire, Toyota, Vellfire, vellfire, Used Toyota

 **Toyota Vellfire 2.4A Z Welcab** \$109,800 \$16,780 /yr 12-Sep-2014 2,362 cc 61,000 km MPV Available

1 Owner! Rare 8 Seaters Welcab In The Market For Your Assistant For Handicap/Old Age Usage. Special Indent Wheel Chair Seat At Front Passenger. True MPV That Offers Supreme Comfort And Power From 08...

Roadlink Auto Pte Ltd

Posted: 09-Apr-2019 Tags: 2014 Toyota Vellfire, 2014 toyota vellfire, Toyota Vellfire, toyota vellfire, Toyota, Vellfire, vellfire, Used Toyota

 **Toyota Vellfire 2.4A Z Golden Eyes II** \$103,800 \$15,010 /yr 07-Dec-2014 2,362 cc 55,000 km MPV Available

1 Owner, Excellent Condition, 7 Seater MPV For Sale! Low Mileage, Regularly Serviced By Previous Owner. Call To View Now Before It Is Too Late! In House Loan Available.

Hui Hwa Credit Pte Ltd

Posted: 25-Apr-2019 Tags: 2014 Toyota Vellfire, 2014 toyota vellfire, Toyota Vellfire, toyota vellfire, Toyota, Vellfire, vellfire, Used Toyota

 **Sell your Car for \$3,000 More**
With over 15K cars sold via Auction and a 500+ Dealer Network, cars on sgCarMart Quetz typically receive up to \$3,000 above market value. Quetz Guarantees the Highest Selling Price in Singapore - If we fail, you get \$100 cash from us. Get your Car Listed Today.

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish	DR	✓	
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	MEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	DR	✓	2
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DR	✓	
1159	993327	Rear End Panel	DD	✓	
1160	993339	Rear End Panel Top Garnish	CRV	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	DD	✓	
1182	991328	Tailgate Emblem	MEC	✓	2
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding (Hinge)	DR	✓	
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp	DR	✓	
1188	994646	Tailgate Protector <i>opening cover</i>	MIS	✓	
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	MEC	✓	
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock	UT	✓	
1198	994651	Tailgate Rubber	CRV	✓	
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper <i>trim board</i>	DR	✓	

Vehicle No:

SKR 675 H

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

[Signature]
2/5/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed
Main	30 Apr 2019 Edit Reg		30 Apr 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt	
						Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	BARATHAN S/O PASUPATHI, ID: S6818469Z								
Main Claimant:	Unknown								
Vehicle Reg. No.:	SKQ675H	Date of Loss:	27/04/2019 15:00 - :59 [53 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8157635693SG	Policy/Cover Note No.:	1800017990 (Comprehensive) Coverage: 28/02/2019 - 27/02/2020						
Vehicle Reg. No. (Insured):	SJD198Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Tampines Auto Services (HQ) BLK 9002 TAMPINES ST 93, #01-34/36 INDUSTRIAL PARK A, 528836 Tampines - Tel: 67862884								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ]								
Adjuster:	BernardJiQian.Ler@aig.com								
Claimant's Solicitor:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 10/05/2019]								
	LEGAL OPTIONS LLC - Tel: 64388039								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (02/05/2019): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKQ675H (8157635693SG)**
[SJD198Z]

TP

Unknown

Apr 27 2019 3:00PM

[BARATHAN S/O PASUPATHI]

Tampines Auto Services

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	13/05/19 11:14	Video - Accident From: OD - Reg. No: SJD198Z, Claimant: BARATHAN S/O PASUPATHI	Load MP4	☒
Assessment Reports			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	13/05/19 11:14	Accident Statement From: OD - Reg. No: SJD198Z, Claimant: BARATHAN S/O PASUPATHI	Load HTM	☒
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/04/19 19:42	General View	Load JPG	☒
2	30/04/19 19:42	General View	Load JPG	☒
3	30/04/19 19:42	General View	Load JPG	☒
4	30/04/19 19:42	General View	Load JPG	☒
5	30/04/19 19:42	General View	Load JPG	☒
6	30/04/19 19:42	General View	Load JPG	☒
7	30/04/19 19:42	General View	Load JPG	☒
8	30/04/19 19:42	General View	Load JPG	☒
9	30/04/19 19:42	General View	Load JPG	☒
10	30/04/19 19:42	General View	Load JPG	☒
11	30/04/19 19:42	General View	Load JPG	☒
12	30/04/19 19:42	General View	Load JPG	☒
13	30/04/19 19:42	General View	Load JPG	☒
14	30/04/19 19:42	General View	Load JPG	☒
15	30/04/19 19:42	General View	Load JPG	☒
16	30/04/19 19:42	General View	Load JPG	☒
17	30/04/19 19:42	General View	Load JPG	☒
18	30/04/19 19:43	General View	Load JPG	☒
19	30/04/19 19:43	General View	Load JPG	☒
20	30/04/19 19:43	General View	Load JPG	☒
21	30/04/19 19:43	General View	Load JPG	☒
22	30/04/19 19:43	General View	Load JPG	☒
23	30/04/19 19:43	General View	Load JPG	☒
24	30/04/19 19:43	General View	Load JPG	☒
25	30/04/19 19:43	General View	Load JPG	☒
26	30/04/19 19:43	General View	Load JPG	☒
27	30/04/19 19:43	General View	Load JPG	☒

Video			1 per page ▾	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
28	30/04/19 19:43	Odometer Reading	 Load JPG	☒
29	30/04/19 19:43	Chassis Number	 Load JPG	☒
30	30/04/19 19:43	General View	 Load JPG	☒
31	30/04/19 19:43	General View	 Load JPG	☒
32	30/04/19 19:43	General View	 Load JPG	☒
33	30/04/19 19:43	General View	 Load JPG	☒
34	30/04/19 19:43	General View	 Load JPG	☒
35	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
36	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
37	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
38	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
39	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
40	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
41	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
42	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
43	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
44	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
45	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
46	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
47	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
48	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
49	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
50	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
51	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
52	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
53	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
54	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
55	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
56	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
57	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
58	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
59	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
60	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
61	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
62	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
63	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
64	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
65	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
66	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
67	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
68	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
69	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
70	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
71	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
72	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
73	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
74	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
75	02/05/19 18:52	Photographs of Damaged Parts	Load JPG	☒

Video			1 per page ▼	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
76	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
77	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
78	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
79	02/05/19 18:52	Photographs of Damaged Parts	 Load JPG	☒
80	10/05/19 18:39	Photo After Spray	 Load JPG	☒
81	10/05/19 18:39	Photo After Spray	 Load JPG	☒
82	10/05/19 18:39	Photo After Spray	 Load JPG	☒
83	10/05/19 18:39	Photo After Spray	 Load JPG	☒
84	10/05/19 18:39	Photo After Spray	 Load JPG	☒
85	10/05/19 18:39	Photo After Spray	 Load JPG	☒
86	10/05/19 18:39	Photo After Spray	 Load JPG	☒
87	10/05/19 18:39	Photo After Spray	 Load JPG	☒
88	10/05/19 18:39	Photo After Spray	 Load JPG	☒
89	10/05/19 18:39	Photo After Spray	 Load JPG	☒
90	10/05/19 18:39	Photo After Spray	 Load JPG	☒
91	10/05/19 18:39	Photo After Spray	 Load JPG	☒
92	10/05/19 18:39	Photo After Spray	 Load JPG	☒
93	10/05/19 18:39	Photo After Spray	 Load JPG	☒
94	10/05/19 18:39	Photo After Spray	 Load JPG	☒
95	10/05/19 18:39	Photo After Spray	 Load JPG	☒
96	10/05/19 18:39	Photo After Spray	 Load JPG	☒
97	10/05/19 18:39	Photo After Spray	 Load JPG	☒
98	10/05/19 18:39	Photo After Spray	 Load JPG	☒
99	10/05/19 18:39	Photo After Spray	 Load JPG	☒
100	10/05/19 18:39	Photo After Spray	 Load JPG	☒
101	10/05/19 18:39	Photo After Spray	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19007581/ECD3S2
 Date: 16/05/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800017990
 Claimant Vehicle No: SKQ675H Insured Vehicle No: SJD198Z
 Date of Loss: 27/04/2019 Nature of Claim: TP Claim No: 8157635693SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKQ675H
 Make & Model: TOYOTA VELLFIRE, 2.4 Z G-Edition (A) Engine No: 2AZG286677
 Reg. Date: 31/10/2014 (Man. Year: 2013) Chassis No: ANH208309026
 Colour: Black Odometer: 193315 km
 Engine Capacity: 2362 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55ZR18 Rear Tyre Size: 235/55ZR18
 Front Left Side: Kinforest 7 mm Rear Left Side: Kinforest 7 mm
 Front Right Side: Kinforest 7 mm Rear Right Side: Kinforest 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 30/04/2019
 Date Inspected: 30/04/2019 Inspected At: Tampines Auto Services (HQ)
 BLK 9002 TAMPINES ST 93, #01-34/36 INDUSTRIAL PARK A
 Singapore 528836
 Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE GARNISH	Broken	0.00 F	*- F
2	1		*REAR BUMPER	Dented	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	2		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
5	1		*REVERSE SENSOR	Broken	0.00 F	*- F
6	1		*REAR END PANEL	Dented	0.00 F	*- F
7	1		*REAR END PANEL TOP GARNISH	Crushed	0.00 F	*- F
8	1		*TAILGATE	Dented	0.00 F	*- F
9	2		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
10	1		*TAILGATE MOULDING (CHROME)	Broken	0.00 F	*- F
11	1		*TAILGATE LAMP	Broken	0.00 F	*- F
12	1		*TAILGATE OPENER COVER	Missing	0.00 F	*- F
13	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
14	1		*TAILGATE LOCK	Bent	0.00 F	*- F
15	1		*TAILGATE RUBBER	Crushed	0.00 F	*- F
16	1		*TAILGATE TRIMBOARD	Broken	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)

0.00

0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >